

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 5 July 2018 4:34 PM
To: 'Wui, Shawnkaijie'; SUR
Cc: assignments; Admin A
Subject: RE: Our ref.: 1151729189SG -003; Accident involving SKL 135B and SKS 2P on 18/07/2017

Dear Shawn,

We review and found out the cracked bumper was indeed repaired, thus paper survey report to submit soon.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 4 July 2018 2:48 PM
To: 'Wui, Shawnkaijie' <Shawnkaijie.Wui@aig.com>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Our ref.: 1151729189SG -003; Accident involving SKL 135B and SKS 2P on 18/07/2017

Dear Shawn,

Thank you for the email.

We will check and revert to you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 4 July 2018 1:19 PM
To: 'Wui, Shawnkaijie' <Shawnkaijie.Wui@aig.com>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Our ref.: 1151729189SG -003; Accident involving SKL 135B and SKS 2P on 18/07/2017

Dear Shawn,

Thank you for your email.

Dear Shiau Chan,

Kindly assist. Our Ref: CS3/AIG17014721/Cqbe2-1

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wui, Shawnkaiye [<mailto:Shawnkaiye.Wui@aig.com>]

Sent: Wednesday, 4 July, 2018 12:08 PM

To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: Our ref.: 1151729189SG -003; Accident involving SKL 135B and SKS 2P on 18/07/2017

Dear Sirs,

We refer to aforementioned matter.

PRS and Paper RI was conducted by your company.

As my colleague is having maternity leave, we would like to request a full paper RI report in order for us to contest third party claims.

At the same time, please advise whether third party repairer has changed the bumper as we found from the picture that the bumper sustained same crack line before repair and after repair.

Please see below photo,



31/66: Photographs of Damaged Parts



Kindly advise and provide the document as soon as possible.

Thanks and Regards,

Shawn Wui
AIG

Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

Shawnkaijie.Wui@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.