


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5457C  
 Ref. No : TAX/11/17/2188  
 Reg. Date : 12/10/2017  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS4  
 Name of Driver : ROSLAN BIN TAPRI  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 30/11/2017 05:55:00 PM  
 Accident Reported Date / Time : 01/12/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024093388  
 Special Instruction to ARC, if any :  
 DROVE IN /SLG5429K  
 Prepared Date : 01/12/2017 11:31:34 AM



Sebastian.  
 1/12/2017.  
 - Part by part repair.  
 - Question Mark Item Photo  
 - Photo After Paint

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

#### Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU503573120

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates****Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges	:	338.00	0.00
Total Spray Painting Charges	:	378.00	0.00
Total Material Charges	:	1,402.18	1,402.18
Other Charges	:	360.00	0.00
<b>TOTAL</b>	:	<b>2,478.18</b>	<b>0.00</b>
<b>Lum Sum Total</b>	:	<b>0.00</b>	<b>0.00</b>
No. of Repair Days	:	3.00	0.00
Prepared / Adjusted By	:		2 day
Arc / Surveyor Sign Off Date	:	01/12/2017 11:42:48 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/12/2017 11:42:48 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
<b>Total Labour</b>	<b>338.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>378.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>360.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace <i>R</i>	No
5256547900			FILLER, RR BUMPER, RH	1	119.90	25.00	89.92	Replace	Replace <i>R</i>	No
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace <i>R</i>	No
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace ?	No
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace <i>Deform</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>✓</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
<b>TOTAL MATERIALS</b>							<b>1,222.20</b>	<b>1,222.18</b>		
<b>TOTAL MATERIALS(Discounted)</b>							<b>1,402.18</b>	<b>1,402.18</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									