

INS. CASE OWNER:

CC 6/ICS170 22945, Kea3 9

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

1-12-17

Date / Time:

1-12-17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJG 1402L

Name of Insured:

Zaili Bin Amin

Insured Tel No.:

HP: 97615896

Excess Sec II :SS

D.O.A: 30-11-17

Is driver the owner?

(YES / NO)

Nature of Accident:

Lor 1

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SJK 7311E



INSRS:

WSP: Wei Lee

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
12/12	Non-Reporting ltr (1st):	
12/12	Non-Reporting ltr (2nd):	
12/12	Non-Reporting ltr (Final):	
12/12	Notification ltr (if non-pickup):	
12/12	Call OI:	
12/12	After call ltr to OI:	
18/12	Documentation Check List:	Handler Typist
18/12	Notification ltr (if non-pickup):	
18/12	After call ltr to OI:	
18/12	Authorisation To Act:	
18/12	Release Voucher:	
18/12	Final Repair Bill:	
18/12	Car Rental Invoice:	
18/12	Towing Invoice:	
18/12	LTA / GIA:	
18/12	Medical Bill:	
18/12	PIR:	
18/12	Mandate/Reject Instruction:	
18/12	LOD:	
18/12	Payment Breakdown Form:	
18/12	Post-Repair Photos:	
18/12	Others:	

<b>PRELIMINARY ADVICE</b> Date/Time: 12/12/17 Sent By: Hm		STAGE Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI: Documentation Check List: Handler Typist Notification ltr (if non-pickup): After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA / GIA: Medical Bill: PIR: Mandate/Reject Instruction: LOD: Payment Breakdown Form: Post-Repair Photos: Others:	
<b>FINALIZATION</b> Date/Time: 14/12/17 Confirm with: - Confirm by: KSK		Repair Cost: US \$53,000 ( 5 days) Reduction: 25 % Email <input type="checkbox"/> Call <input type="checkbox"/>	
<b>FINAL SETTLEMENT</b> Date/Time: 18/12/17 Confirm with: WSA Email <input type="checkbox"/> Call <input type="checkbox"/>		Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 Repair Cost: \$53,000 OI: REPAIR ENDED TP Loss of Rental (LOR): \$5 - ( 5 days) Loss of Use (LOU): \$5 300 (\$60 x 5 days) Loss of Income (LOI): \$5 - (\$ x 5 days) LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one] GIA/LTA Search: \$535 Medical: \$5 - Disbursement: \$5 - (e.g. Tow/ Independent) Legal Cost: \$5 - Total: \$53,305-35 Global Sum \$5: <b>FINAL PAYMENT</b> Date/Time: 18/12/17 Confirm with: WSA Email <input type="checkbox"/> Call <input type="checkbox"/> Payee 1: \$53,305-35 Name 1: WSA LIA MOTOR WORKS. Payee 2: (Strike if N.A.) \$5 Name 2: Payee 3: (Strike if N.A.) \$5 Name 3:	

ASS. REC. BY:

REF: 1051

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 815K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJK 7311E Yr Regn: 101 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M7 Lancer c.c. 1584

Colour: M. Red A/C: Insured / Std / NI / NA

Sp. Reading: 222162 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JMYSTC'S 348.4011208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Feller 195/80R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 6 mm

L/Bal. 4 mm L/Bal. 6 mm

D.O.A. 30/11/17 D.O.I. 1/12/17

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/12 with pass to Catherine

4/12 @ 3k email

(RED - 1.07 25%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CC6/ICS17022945/Kua3		
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 04-12-2017		
		Code : ICS		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJG 1402L	Veh. Inspected	SJK 7311E	
Policy No.	MPC17A00332501	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	30/11/2017	Inspection Date	01/12/2017	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC6/ICS17022945/Kua3

Date: 04.11.2017

The Motor Claims Department  
M/s ECICS LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SJK 7311E**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01-12-2017 at the premises of M/s Wei Lee Motor Works - Sin Ming have the following to report:-

Workshop Estimate Amount	: S\$	4,017.00
Revised Estimate Amount	: S\$	3,019.20
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the  
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 day

Yours faithfully,

KENNETH KONG  
Licensed Appraiser

# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~456 3986~~

Business Regn No : 269436/00J

01, December 2017

Ecics Limited

7 Temasek Boulevard

#10-01 Suntec Tower One

S 038987

*Not Authored  
L1 Sy @ 3000  
Paying After Paying  
5 days*

Att: Motor claim dept-3<sup>rd</sup> party claim

Claiming against your insured vehicle No: SJG1402L

Accident involving vehicle No: SJK7311E/SJG1402L

DOA: 30112017 AT Slip Rd From PIE To Lor 1 Toa Payoh

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SJK7311E

To supply—

Description	Qty	Amount
Lid	1	Ref 593.00 N ✓
Lid lock	1	Ref 64.00 N X
Lid-GLX emblem	1	Ref 28.00 N ✓
Lid-Lancer emblem	1	Ref 32.00 N ✓
Lid-Mit loo	1	Ref 44.00 N ✓
Rear bumper	1	Bm 697.00 N ✓
Rear bumper retainer @50 N	2	W/D 100.00 N ✓
End panel	1	Ref 495.00 N ✓
End panel top garnish	1	Ref 156.00 N X
Taillamp, Rh	1	Ref 421.00 N ✓
	Parts	2,630.00
	Parts less 10%	263.00
		2,367.00

Reverse sensor

CR 220.00 200in

To remove damaged parts and attachemnts.

750.00 650

Repair/reshape spare tyre panel, rear fender, Rh and dented areas.

Renew/align all parts into position.

To spray paint.

900.00 800

LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-managed and is subject to final approval from Insurance Company.

Acknowledged by Repairer  
Signature:  
Date:

4,017.00

## Asher Sng (LKKAUTO)

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Monday, 18 December, 2017 12:05 PM  
**To:** 'weileemotorworks@gmail.com'  
**Cc:** Vic (LKKAUTO)  
**Subject:** Accident Involving SJK 7311E & SJG 1402L on 30/11/2017

WITHOUT PREJUDICE

Your Ref: SJK 7311E  
Our Ref: CC6/ICS17022945/Kea3

Dear Sir/Madam,

### **Accident Involving SJK 7311E & SJG 1402L on 30/11/2017**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	1813C

### Vehicle Details

Vehicle No.	SJK7311E
Vehicle to be Exported	No
Intended De-registration Date	04 Dec 2017
Vehicle Make	MITSUBISHI
Vehicle Model	LANCER 1.6 A
Primary Colour	Red
Manufacturing Year	2008
Engine No.	4G18JT5821
Chassis No.	JMY5TC53A8U011208
Maximum Power Output	79.0 kW (105 bhp)
Open Market Value	\$11,931.00
Original Registration Date	31 Oct 2008
First Registration Date	31 Oct 2008
Transfer Count	1
Actual ARF Paid	\$11,931.00

### Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	30 Oct 2018
PARF Rebate Amount	\$5,965.00

### Intended COE Rebate Details

COE Expiry Date	30 Oct 2018
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$12,001.00
COE Rebate Amount	\$992.00
<b>Total Rebate Amount</b>	<b>\$6,957.00</b>

The information contained herein is correct as at 04 Dec 2017

OK



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

**Mei Kwan (LKKAUTO)**

---

**From:** Janice Goh Siew Geok (ECICS, Claims) <Janice\_Goh@ecics.com.sg>  
**Sent:** Monday, 4 December, 2017 3:32 PM  
**To:** Mei Kwan (LKKAUTO); ECICS Claims  
**Cc:** Phoebe Jay Xie (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Asher Sng (LKKAUTO); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving SJG1402L (OI : CAI - TBA) and SJK7311E (TP : LKK REF - CC6/ICS17022945/Kua3) on 30/11/2017  
**Attachments:** SJG1402L.PDF  
  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
  
**Categories:** HMK

Dear Mei Kwan

As requested, please see attachment.  
Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

***\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\****

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Monday, 4 December, 2017 3:24 PM  
**To:** ECICS Claims  
**Cc:** Phoebe Jay Xie (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Asher Sng (LKKAUTO); Admin A  
**Subject:** Direct Settlement - Accident Involving SJG1402L (OI : CAI - TBA) and SJK7311E (TP : LKK REF - CC6/ICS17022945/Kua3) on 30/11/2017

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SJK 7311E at M/s Wei Lee Motor Works - Sin Ming.

Enclosed for your perusal is:



# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,

SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~455-3986~~ 6458 0128

Business Regn No : 269436/00J

22, Dec 2017

Ecics Limited

Attn: Motor claim dept-3<sup>rd</sup> party claim

Claiming against your insured vehicle no: SJG1402L

Accident involving vehicle no: SJK7311E/SJG1402L

ON 30112017 AT Slip Road from PIE TO Lor 1 Toa Payoh

Dear officer incharge

We are the workshop for the owner of vehicle no: SJK7311E

Regarding the claim for the case above, this is a liability clear case considering that your client's vehicle collided into the rear portion of our client's vehicle.

The claim for vehicle No: SJK7311E as follow:-

Cost of repair to SJK7311E	\$ 3,000.00	finalised with your surveyor
Loss of use	\$ 300.00	\$60x5d
LTA search fee	\$ 5.35	

---

\$ 3,305.35

Enclosed with all the necessary document for your reference.

Kindly let us have your reply soonest possible.

Thank you.



## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Thursday, 18 January 2018 2:21 PM  
**To:** 'ZAILIBINAMAN@GMAIL.COM'  
**Subject:** ACCIDENT INVOLVING SJG 1402L & SJK 7311E AT / ALONG SLIP ROAD FROM PIE TO LOR 1 TOA PAYOH ON 30/11/2017.

Hi ZAILI BIN AMAN,

[Without Prejudice]

By Email Only

**ACCIDENT INVOLVING SJG 1402L & SJK 7311E AT / ALONG SLIP ROAD FROM PIE TO LOR 1 TOA PAYOH ON 30/11/2017.**

We refer to the above accident matter.

As spoken, we are the loss adjusters acting on behalf of M/s ECICS Limited, the Motor Insurer of SJG 1402L on the reported accident on 30/11/2017.

Our Principal has received a Third Party property damage claim from the owner of SJK 7311E with regards to the above accident.

We will try our best to negotiate for an amicable settlement on best possible terms with Third Party under the terms and conditions of your motor policy. In this respect, the vehicle's premium/NCD may be affected as a result of the above claim.

In the event that you receive any letters/ court documents regards to the above accident matter, please do not reply or respond, you may forward to us directly for further handling and we will reply on your behalf.

Thank you.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## AUTHORISATION TO ACT

I, KH Leasing Pte Ltd ("the third party claimant") of  
261A Upp Thomson Rd (address), owner of  
8SK73116 (vehicle no.) hereby authorize Wei Lee Motor Works  
the (workshop) to act for me with respect to my claim for repair costs and/or rental and/or loss of  
use ("claim") for my vehicle no. 8SK7311E that was damaged pursuant to the accident  
which occurred 30/11/17 (date) at Slip Road from PIE to Lor 1 Toa Payoh (location)  
involving vehicle no/s. 8TG1402L This ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit  
and the workshop is further authorized to receive payment further to settlement of my claim with  
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without  
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 30 (day) of Nov (month) 2017 (year)


Signed by "the third party claimant"  
(with chop if applicable)


Signed by "the workshop"  
(with chop)

## DISCHARGE VOUCHER

CLAIM NO:

In consideration of the payment of the sum of DOLLAR THREE THOUSAND THREE HUNDRED FIVE AND CENTS THIRTY FIVE ONLY. (S\$3,305.35), I/We, hereby accept such sum in full and final settlement of all claims, present or future, that I/We have or may have against ECICS Limited, ZAILI BIN AMAN as Insurers, owner and driver of Vehicle no. SJG 1402L in connection with or in any way arising from the accident involving the said vehicle which occurred on 30/11/2017 at ALONG SLIP RD GOING TOWARDS TOA PAYOH LOR 1 with SJK 7311E.

I/We further agree that this payment is made without any admission of liability on the part of the said insurers, owner and driver of the vehicle no. SJG 1402L and this settlement does not in any way prejudice or prevent any party from making any claim whatsoever which may arise from the damage caused to the vehicle no. SJK 7311E in the above mentioned accident. I/We further undertake not to make any reference to the settlement herein mentioned in respect of such claim.

\*I/We authorize you to pay the above settlement sum to WEI LEE MOTOR WORKS.

\*DATED THIS 18 DAY OF Jan 2018

Signature &/or  
Co Stamp:

Signature  
&/or Co  
Stamp:

Name of  
Claimant :

Name of  
Witness:

Address:

Address:

Occupation:

Occupation:

NRIC No:

NRIC No:

\* Delete if not applicable

\* Please ensure the date is duly filled in

DV TPD (Ver Jan 16)

威利摩嘜  
**WEI LEE MOTOR WORKS**

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128  
Business Regn No: 269436/00J

Ecics Limited  
7, Temasek Boulevard  
#10-01 Suntec Tower One  
S 038987

INVOICE NO: 12512

DATE: 22, Dec 2017

PARTICULARS	AMOUNT (S\$)
Vehicle No: SJK7311E	
Cost of repair for vehicle No: SJK7311E	3,000.00
Lump sum repaired as recommended by your appointed surveyor-LKK Auto Consultants	<u>3,000.00</u> =====



Payments to be made by crossed cheque in favour of WEI LEE MOTOR WORKS



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 30 Nov 2017 / 17:59:32

Receipt Date/Time : 30 Nov 2017 / 17:59:32

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-171130-002063

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SJG1402L

As at 30 Nov 2017/10:35:00

Insurance Co: ECICS LIMITED

1 Insurance Enquiry - SJG1402L

Enquiry Fee

20171130175823087549

5.00 0.35 5.35

Sub-Total 5.00 0.35 5.35

Total Before Rounding 5.00 0.35 5.35

Rounding Difference 0.00

Total Amount Payable 5.35

Paid By

20171130175837575 Direct Debit: eNETS  
Debit (Internet Banking) 5.35

Total 5.35

Cash Change 0.00

Tendered Amount 5.35

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s ECICS LTD

Date: 30/01/2018

**THIRD PARTY DIRECT SETTLEMENT**

Vehicle No.	SJG 1402L (Insd Veh)	Your Ref. No. : MPC17A00332501
	SJK 7311E (TP Veh)	Our Ref. No. : CC6/ICS17022945/Kea3q2
Date of Accident	30/11/2017	

0

Liability	100%	
Final Repair Cost	: \$ 3,000.00	
Loss of Use	: \$ 300.00	5 days
Rental (If any)	: \$	days
Others:	: \$ 5.35	
	: \$	
	3,305.35	
Final Settlement Sum	: \$ 3,305.35	
Remarks	:	

**Payment Instruction: Payee's Breakdown**

1)	WEI LEE MOTOR WORKS	: \$ 3,305.35
		: \$

JOANNE LEE


LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CC6/ICS17022945/Kea3q2		
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 30-01-2018		
		Code : ICS		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJG 1402L	Veh. Inspected	SJK 7311E	
Policy No.	MPC17A00332501	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	01/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI LANCER (A)	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JMYSTCS3A8U011208	Colour	METALLIC RED	
Odometer	222162	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	FALKEN	4 mm	
L/H Front Tyre	195/60 R15	FALKEN	4 mm	
R/H Rear Tyre	195/60 R15	FALKEN	6 mm	
L/H Rear Tyre	195/60 R15	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	30/11/2017	Inspection Date	01/12/2017	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 7311E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	LID (N)	BENT	593.00	593.00
1	LID LOCK (N)	TO REPAIR SEE LABOUR	64.00	-
1	LID -GLX EMBLEM (N)	NECESSARY	28.00	28.00
1	LID -LANCER EMBLEM (N)	NECESSARY	32.00	32.00
1	LID -MIT LOO (N)	NECESSARY	44.00	44.00
1	REAR BUMPER (N)	BUCKLED	697.00	697.00
2	REAR BUMPER RETAINER @\$50.00 (N)	O/S DISTORTED	100.00	50.00
1	END PANEL (N)	BENT	495.00	495.00
1	END PANEL TOP GARNISH (N)	SERVICEABLE	156.00	-
1	TAILLAMP ,RH (N)	BROKEN	421.00	421.00
	LESS 10% DISCOUNT		-263.00	-236.00
			2,367.00	2,124.00
<b>SPECIAL NETT ITEMS</b>				
1	REVERSE SENSOR (SN)	CRACKED	220.00	200.00
			220.00	200.00
<b>LABOUR</b>				
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS .REPAIR /RESHAPE SPARE TYRE PANEL .REAR FENDER ,RH AND DENTED AREAS .RENEW /ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF LID LOCK .		750.00	650.00
	TO SPRAY PAINT .		900.00	800.00
			1,650.00	1,450.00
<b>GRAND TOTAL</b>			<b>4,237.00</b>	<b>3,774.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,000.00</b>

Report Ref No. CC6/ICS17022945/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.