

22/03/2002

ASS. REC. BY:

REF: CS3/ALH17022949/Sberz

Special Instruction:

DAR 2 days

Surveyor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time: 04/12/07 244pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 3001Z

Insured:

SLG 6773J

at Workshop m/s

Seng Hwee Motor

Tel:

9786 5675

of

Bik 1018 Yishun Ind Park A # 01-350

Policy No:

Claim No:

128321263086

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/22017

(Client's Record)

CA / REV / REP. / REV 24 HRS WP1

H.O.D. Endorsement:

Date/Time:

04/12/07 253pm

Person Contacted:

Mr. Kueh

Vehicle IN OUT

Date/Time

Action/Instruction ( X ) Estimate

SLG 3001Z - X

SLG 6773J - CS3 / ALH17008633 / Klyu392

DAR: 28/12/07

After repair: 6/12/2017

DAR

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP: / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLG 3001Z

Yr Regn:

2016 Sep 27

Type: ☒ M/Co / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 216D

cc

1496

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp Reading:

25017

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W 1314213 320400791 456

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ M / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60R16

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

2/12/17

D.O.I.

4/12/17

Survey held at:

Seng Hwee

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time:

Action / Instruction

25/5

Submit DAR report.

RECEIVED 30 MAY 2018

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

180

Transportation

1) \$ + PS \$

2) Photos

3) Others

4)

TOTAL

20

200

Report Format :

DAR

Lump Sum / I.B.I: (\$)

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech Invs (\$)



: Weekend (\$)



**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED  
VEHICLE SLG6773J AND SLG3001Z ON 02/12/2017**

From: Chin, Lee-Ying

To: 'assignments', 'Admin A'

Cc: Fong, Andy-SY

Sent: Monday, 4 December, 2017 2:44:27 PM

Attachments:  PRS.SW.1st notice.AIG.SCG3001Z.SLG6773J.PDF  PRS.SW.2nd notice.AIG.SLG3001Z.SLG6773J.PDF

---

Hi LKK,

Kindly assist to survey, vehicle is in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Insured's vehicle : SLG 6773J  
Our client's vehicle / ref: SLG 3001Z ; SW/sy  
Date : 4 December 2017

AIG Asia Pacific Insurance Pte. Ltd.

By Email

Dear Sirs,

**DATE OF ACCIDENT: 2 DECEMBER 2017**  
**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to your email dated 4 December 2017.

Please be informed that our client is not agreeable to your proposed motor surveyor. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Foo Philip	Precision Appraisal Services
2.	Ronald Ng	Precision Appraisal Services
3.	Lee Kok Weng	Lee Automobile Appraisals Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which we will commence repairs thereafter without any further notice or reference to you. Please also let us know if you required a Post-Repair Survey/Inspection for our client's consideration. Please be informed that the said vehicle can be surveyed / inspected at:

Workshop Address: Seng Hwee Motor  
Block 1018 Yishun Industrial Park A  
#01-350  
Singapore 768760  
Contact person/Tel/Hp/Fax: Mr. Kueh / 6755 5205 / 9786 5675 / 6753 4407

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,



Your Insured's vehicle : ref: SLG 6773J

Our client's vehicle : ref: SLG 3001Z ; SW/sy

Date : 4 December 2017

### Acknowledgement

This is to confirm that I \_\_\_\_\_ *[Full Name of Surveyor]* of  
\_\_\_\_\_ *[Surveyor's Company]* have completed as  
follows:-

(a) Pre- Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(b) Pre- Repair Survey/Inspection (after dismantling) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(c) Re-inspection of new replacement part (party by part) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(d) Post – Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	3083Z
<b>Vehicle Details</b>	
Vehicle No.:	SLG3001Z
Vehicle to be Exported:	No
Intended De-registration Date:	25 May 2018
Vehicle Make:	B.M.W.
Vehicle Model:	216D ACTIVE TOURER D/AB LED
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	32389705B37C15A
Chassis No.:	WBA2B32040V791456
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$27,843.00
Original Registration Date:	27 Sep 2016
First Registration Date:	27 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$20,981.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2026
PARF Rebate Amount:	\$15,735.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$41,680.00
<b>Total Rebate Amount:</b>	<b>\$57,415.00</b>

The information contained herein is correct as at 25 May 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/12/2017 11:07
Date Of Accident	02/12/2017 11:00
Exact Location Of Accident	CLEMENTI OPEN CARAPRK (CLC020)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG3001Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WONG TOON HONG
NRIC No	S1463083Z
Email Address	TOONHONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97508495
Alternative Phone No	OTHERS-97508495
<b>Vehicle Particulars</b>	
Manufacturer	BMW
Model	216D ACTIVE TOURER D/AB LED
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	C0061703
Cover Note Number	27/9/2016 - 26/9/2018
<b>Driver</b>	
Name of Driver	OON KIM KUAN
NRIC No	S1565724C
Date Of Birth	10/06/1962
Occupation	INDOOR
Date Of Driving Pass	05/01/1988
Driving Experience	29 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97529490
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 32 DOVER RISE #10-11  
 Postcode 138886  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - OPENING DOOR OF VEHICLE  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACH. \* THIRD PARTY CLAIM BY SENG HWEE MOTOR \*

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLG6773J  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver LOH YEW THIAM  
 NRIC/Passport Number S1823980I  
 Contact Number 96906822  
 Address 128 JALAN JURONG KECHIL  
 (S)2159

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name

Phone Number

Email Address



### Sketch Plan #3

#### Car Accident Reporting

Location: Clementi Open Car park C1C020 on 2 Dec around 1040 hrs. Vehicles involved:

1. White Mitsubishi Car SLG 67731  
Driver: Loh Yew Thiam NRIC S18239801
2. Blue BMW AT 2160 SLG 3003Z Chassis number WBA2B32040V791456  
Authorized Driver: Mdm Oon Kim Kuan NRIC S1565724C  
Owner: Wong Toon Hong S1463083Z

Liberty Insurance Cover Note: C006173 from 27 Sep 2016 to 26 Sep 2019

#### Statement of Authorized Driver Mdm Oon Kim Kuan S1565724C

1. Before I drove out of car park lot 166, I checked and ensured that there were no obstructions on both sides of my car and in front of my car.
2. My car was parked to the extreme right side curb of parking lot 166 (See Photo D), and there was a big safety distance between the 2 cars
3. However, while my car was moving slowly out of parking lot, heading straight out without turning left or right, the right rear door of the white car (parked in lot 167) was opened from the outside and it hit against my rear left door. I immediately stopped the car and came out to investigate.
4. My door handle was stuck by the door of the white car. My door suffered a major dent (Photo G, H) and the door handle was damaged too. See Photo C, D, E, F, G, H. The white car door was opened from the outside by the elderly mother of the driver into my path
5. The white car's rear right door suffered a slight dent. See Photo J
6. I noticed the white car was parked off centre to his right - Photo A, L, M. When the rear right door was opened from the outside, it intruded into my parking lot and hit my car door handle while I was driving slowly straight out of the parking lot. See Photo D & N
7. There were no passengers in the white car at that time and it was stationary. No one was injured in this incident. We exchanged particulars for insurance claim purposes
8. I concluded that the elderly lady did not exercised a proper lookout nor noticed my car was moving slowly out of the parking lot when she opened the door from the outside into the path of my moving car.
9. I proceeded to take pictures as evidence for insurance claim against them and left the scene after that.

My claim is supported by:

Road Traffic Act, (CHAPTER 276, Section 112), Highway Code

Clause 92. Before opening the door of a vehicle make sure that it will not endanger or inconvenience anybody on the road or footpath. Get out on the side nearest to the kerb whenever it is possible.

  
A Dec 2017

# Sketch Plan #2

## SKETCH PLAN

A. SLG3001Z

B. SLG1773J




Vehicle B spot Rear Door


## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please refer to the detail report attached

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:  
 4 Dec 2017

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:  
 4 Dec 2017

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/PRN No.: YS

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

4 Dec 2017

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

4 Dec 2017

Reporting Centre Personnel's Signature  
Name:  
NAKYM No.:

Wendy 4/12/2017  
(75)

Veh. SLG 3001Z

DOI 4/12/17

1. Rear N/S Door	- BU	1076.75
2. Rear N/S Door weather strip.	- nec	89.55
3. Rear N/S Door lock, assy.	- dm	235.95
4. Rear N/S outer door handle	- dm	108.00
5. Rear N/S glass guide	- nec	116.70
6. Rear door regulator gear, N/S	- dm	391.00
7. Rear door frame chrome moulding N/S	- nec	138.00

Painting 1 panel  
labour 3 days

## PRI

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured:	Loh Yew Thiam, Co. Reg. No.: -								
Main Claimant:	WONG TOON HONG								
Vehicle Reg. No.:	SLG3001Z	Date of Loss:	02/12/2017 00:00 - :59 [14 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1283212630SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLG6773J	Policy No. (Claimant):							
		Excess:							
Repairer:	Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350, 768760 Yishun - Tel: 67555205								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 12/04/2018]								
Claimant's Solicitor:	KSCGP JURIS LLP - Tel: 65383611								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
• AIG_SG (04/04/2018): TP GIA REPORT									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLG3001Z (12832126305G)

[SLG6773J]

TP

WONG TOON HONG

Dec 2 2017 12:00AM

[Loh Yew Thiam]

Seng Hwee Motor

Upload Documents			Upload Photos	Compose New Letter	Upload Video	Upload Audio	View <span>View in Browser</span>	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
2	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
3	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
4	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
5	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
6	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
7	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
8	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
9	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
10	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
11	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
12	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
13	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
14	03/04/18 16:08	General View		Load JPG	<input checked="" type="checkbox"/>			
15	03/04/18 16:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>			
16	03/04/18 16:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>			
17	03/04/18 16:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>			
18	03/04/18 16:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>			
19	03/04/18 16:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>			
20	03/04/18 16:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>			
21	03/04/18 16:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>			

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

**LKK Auto Consultants Pte Ltd** (Co. Reg. No: 199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17022949/SBE2  
 Date: 31/05/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
 Claimant Vehicle No: SLG3001Z Insured Vehicle No: SLG6773J  
 Date of Loss: 02/12/2017 Nature of Claim: TP Claim No: 1283212630SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG3001Z**  
 Make & Model: BMW 216I, 1.5 (A)  
 Reg. Date: 27/09/2016 (Man. Year: 2016)  
 Colour: Blue  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**  
 Engine No: 32389705B37C15A  
 Chassis No: WBA2B32040V791456  
 Odometer: 25017 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16  
 Front Left Side: Continental 6 mm  
 Front Right Side: Continental 6 mm  
 Rear Tyre Size: 205/60 R16  
 Rear Left Side: Continental 6 mm  
 Rear Right Side: Continental 6 mm  
*The above values represent the remaining tyre treads depth*

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 04/12/2017  
 Date Inspected: 04/12/2017 Inspected At:

Estimated Period of Repair: 3.0 days

Seng Hwee Motor (HQ)  
 Blk 1018 Yishun Industrial Park A #01-350  
 Singapore 768760

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR N/S DOOR	Buckled	0.00 F	*- F
2	1		*REAR N/S DOOR WEATHER STRIP	Necessary	0.00 F	*- F
3	1		*REAR N/S DOOR LOCK ASSY	Damaged	0.00 F	*- F
4	1		*REAR N/S OUTER DOOR HANDLE	Damaged	0.00 F	*- F
5	1		*REAR N/S GLASS GUIDE	Necessary	0.00 F	*- F
6	1		*REAR DOOR REGULATOR GEAR N/S	Damaged	0.00 F	*- F
7	1		*REAR DOOR FRAME CHROME MOULDING N/S	Necessary	0.00 F	*- F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >