

Surveyor:

Kalvin

DOI:

ASSIGNMENT

4/12/17

Date / Time:

04/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SGD 401M

Name of Insured :

MWHT 9544 CAR HERE

Insured Tel No. :

HP:

Excess Sec II :SS

D.O.A :

02/12/17

Is driver the owner?

(YES (NO))

Nature of Accident :

If NO, Driver Name / Age :

MR. TUAO KAMKODEN

Driver Tel No. :

90128494

(V/L: YES / NO)

Claim No. :

Dmpul 17006 401M / JG

Policy No. :

mpul 17005 2000

Make / Model :

N. Lotus

Place of Accident :

Traffic Junc. of. River Valley Rd & Zon Rd

Of GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SHB 4734J



INSRS:

WSP: COGE (Loyang)

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

12/17
KHW

SHB 4734J - CC3/ATG09017423/DNI DUA: 02/08/09
- CC3/ATG09017423/DNI DUA: 26/07/09
- CC3/ATG18011423/DNI DUA: 31/06/12
- CC3/ATG18011423/DNI DUA: 24/05/12
- NS/IN/12000725/HHA1 DUA: 10/01/12
- NS/IN/12000725/HHA2 DUA: 13/07/12
SGD 401M - X

STAGE DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:

After call ltr to OI

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

9/3/18 EMAIL TO ICS TO SUBMIT REPORT AS TP DID NOT REPAIR THE VEHICLE.

RECEIVED 12 JAN 2010

REPORT TERN:

PLEASE INCLUDE THE FOLLOW SENTENCE IN THE REPORT.

- AT THE TIME OF INSPECTION, NO DAMAGE FOUND TO THE RENTAL VEHICLE.

PRELIMINARY ADVICE		Date/Time:	Sent By:	
FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	() days	Reduction:	%
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	SS			
Loss of Rental (LOR):	SS	() days		
Loss of Use (LOU):	SS	(\$ x days)		
Loss of Income (LOI):	SS	(\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]			
GIA/LTA Search	SS			
Medical:	SS			
Disbursement:	SS	(e.g. Tow/ Independent)		
Legal Cost	SS			
Total:	SS	Global Sum SS:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS	Name 1:		
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

COPY SENT 12/12/17

1) Claim status: Normal/Reject/Private Settle /WP

2) Report Format: TP

3) Survey fee: P 350

Kalvin

SHB 473XJ

5 Feb 2017

Veh No: 3AB 475 25 Yr Regn

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda 200 cc 165

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading 90972 T/Ratio: Insured / Std / NI / NA

End/Na

C/No: KMHLB4/YMH4 097896

Gen. Cond: Good / ~~Fair~~ / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

Re: _____ 4

TOYO / YOKO *or*

Front

22 mm 22 mm 7 mm

L Bai. 7 mm L Bai. 7 mm

D.O.A. 2/12/12 D.O.I. 4/24/12

Survey held at: CDE (10/2/2017)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle IN / OUT

o/s wing ~~air~~ Mirror

The U/C / Chassis frame / Body Structure affected due to collision.

At time of survey, found no damage to RH Wing Mirror

ELZCS
P/P

No Betting.

P/P: 0 (RED: 99440 100%)

☐: Prel. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Add Fee: Site Insp (\$

Transportation:

Interview **S** Photos

<div>  Tech </div>	<div>  Invs </div>	<div>  IS </div>	<div>  Y </div>	<div>  Others </div>
---	---	---	--	---

Week 5	5
--------	---



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CC4/ICS17022952/K1ea3

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 04-12-2017



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGD 4011M	Veh. Inspected	SHB 4734J
Policy No.	MPU17A00052000	Coverage (\$)	0.00
Claim No.	DMPU1700640H/JG	Excess (\$)	0.00
Assign From		Assign Date	04/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/12/2017	Inspection Date	04/12/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/ICS17022952/K1ea3

Date: 05.12.2017

The Motor Claims Department
M/s ECICS LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 4734J

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04-12-2017 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) have the following to report:-

Workshop Estimate Amount	: S\$	994.40
Revised Estimate Amount	: S\$	-
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
*** NO DAMAGE FOUND ***



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: - day

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Team: ARC Repair TP(CFSO)1		JOB CARD Sales Order:		JC NO:305094212
CUSTOMER		REGN NO	SHB4734J	MILEAGE
CITYCAB PTE LTD		MAKE	HYUNDAI	FUEL
7010070		MODEL	I-40	02.12.2017 05:20
CUSTOMER NO		YR OF MANU	05.01.2017	TARGET DATE
383 SIN MING DRIVE		CHASSIS CODE	KMHLB41UMHU097896	COMPLETION DATE/TIME
Singapore SINGAPORE 575717				
65551188				
(P)				
(P)				
COUNT CARD NO.				

JOB DESCRIPTION

Accident Date: 02.12.2017
NATURE: 3P.02.12.12017

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR	CUSTOMER'S SIGNATURE
-----------------	----------------------

Acknowledgement Slip		Exit Pass	
Vehicle No.: SHB4734J		Vehicle No.: SHB4734J	
Signature/Date		Date	
Name of Service Advisor		Name of Service Advisor	
To be returned to Service Reception upon collection		To be kept by Security Guard	

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 04.12.2017

Time: 15:10:22

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305094212
 REGN NO : SHB4734J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 05.01.2017
 DATE/TIME IN : 02.12.2017 05:20
 ACCIDENT DATE : 02.12.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0594-G I40VC MIRROR ASSY-RR VIEW 1 980.50 20.00 784.40 X *see*
 SUB-TOTAL : 784.40

JOB NATURE

0000 L PANEL BEATING 120.00 X
 0001 23-502 SPRAYPAINT ON AFFECTED AREA 90.00 X
Towing fee
 SUB-TOTAL : 210.00 X
 TOTAL : 994.40

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

the Repairer hence notify the following:
 • To resurvey after spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications is allowed
 • Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kahin (LICK)

4/12/17 1600hrs.

At the time of survey, found no damage
 to RH wing mirror.

高 GAO

Express Towing Services

You Call, We Tow - Fast . Secured . Reliable



5.24am
6.00am
6.45am

Blk 27 Marine Crescent Ville #10-01 Singapore 440027 Co. Reg. No. 53152603L HP: 900 900 92 Email: jim.koh@hotmail.com Website: http://www.gaoexpress towing.sg

CASH SALE/WORK ORDER

No. 137812

Date: 2/12/2017

寶號 Messrs: Carhart

車號 Vehicle No: S4B4724J 車型 Model No: B17140

時間(日/夜) Time (day/night): Night Contact No: 98558911

由 Location: 602 Clementi St 1

... Loyang

Cash \$: 40 其他 Others: Accident

經手人 Authorised By: Jim Tow Truck Driver Name: Moms 97

注意本公司對所拖之車輛,在進行中如有任何損失或破壞,一概由車主自行負責。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damage to

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 9 March 2018 9:33 AM
To: 'Janice Goh Siew Geok (ECICS, Claims)'
Cc: ECICS Claims; Phoebe Jay Xie (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims); Admin A
Subject: RE: SHB4734J VS SGD4011M THIRD PARTY CLAIM *** LKK REF: LKK ref: CC4/ICS17022952/K1ea3

Hi Janice,

We refer to the above matter.

We were informed by TP workshop that claimant do not come back to their workshop for repair up to date as there is no damage found to third party vehicle at the time of survey.

In view of the above, We will proceed to close file and submit our without prejudice report to your office.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Goh Siew Geok (ECICS, Claims) [mailto:Janice_Goh@ecics.com.sg]
Sent: Tuesday, 6 February 2018 2:20 PM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; motorsurvey <motorsurvey@ecics.com.sg>
Cc: ECICS Claims <claims@ecics.com.sg>; Carrie Tan Chi Hui (ECICS, Claims) <Carrie_Tan@ecics.com.sg>; Phoebe Jay Xie (ECICS, Claims) <PhoebeJay_Xie@ecics.com.sg>; Lionel Chua Kok Keong (ECICS, Claims) <Lionel_Chua@ecics.com.sg>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: SHB4734J VS SGD4011M THIRD PARTY CLAIM *** LKK REF: LKK ref: CC4/ICS17022952/K1ea3

OUR CLAIM NO. DMPU1700640H/JG

Dear Mei Kwan

Please see attachment.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Tuesday, 6 February, 2018 10:49 AM
To: Janice Goh Siew Geok (ECICS, Claims); motorsurvey
Cc: ECICS Claims; Carrie Tan Chi Hui (ECICS, Claims); Phoebe Jay Xie (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims); Asher Sng (LKKAuto); Admin A
Subject: RE: SHB4734J VS SGD4011M THIRD PARTY CLAIM *** LKK REF: LKK ref: CC4/ICS17022952/K1ea3

URGENT

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Friday, 19 January, 2018 2:03 PM
To: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>; motorsurvey <motorsurvey@ecics.com.sg>
Cc: ECICS Claims <claims@ecics.com.sg>; Carrie Tan Chi Hui (ECICS, Claims) <Carrie_Tan@ecics.com.sg>; Phoebe Jay Xie (ECICS, Claims) <PhoebeJay_Xie@ecics.com.sg>; Lionel Chua Kok Keong (ECICS, Claims) <Lionel_Chua@ecics.com.sg>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: SHB4734J VS SGD4011M THIRD PARTY CLAIM *** LKK REF: LKK ref: CC4/ICS17022952/K1ea3

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

From: Mei Kwan (LKKAUTO)

Sent: Monday, 18 December, 2017 9:20 AM

To: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>; motorsurvey <motorsurvey@ecics.com.sg>

Cc: ECICS Claims <claims@ecics.com.sg>; Carrie Tan Chi Hui (ECICS, Claims) <Carrie_Tan@ecics.com.sg>; Phoebe Jay Xie (ECICS, Claims) <PhoebeJay_Xie@ecics.com.sg>; Lionel Chua Kok Keong (ECICS, Claims) <Lionel_Chua@ecics.com.sg>;

Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: SHB4734J VS SGD4011M THIRD PARTY CLAIM *** LKK REF: LKK ref: CC4/ICS17022952/K1ea3

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Goh Siew Geok (ECICS, Claims) [mailto:Janice_Goh@ecics.com.sg]

Sent: Tuesday, 5 December, 2017 9:57 AM

To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; motorsurvey <motorsurvey@ecics.com.sg>

Cc: ECICS Claims <claims@ecics.com.sg>; Carrie Tan Chi Hui (ECICS, Claims) <Carrie_Tan@ecics.com.sg>; Phoebe Jay Xie (ECICS, Claims) <PhoebeJay_Xie@ecics.com.sg>; Lionel Chua Kok Keong (ECICS, Claims) <Lionel_Chua@ecics.com.sg>;

Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: SHB4734J VS SGD4011M THIRD PARTY CLAIM

Dear Mei Kwan

Our insured has not reported the accident to us yet.
We will forward to you once our insured reported.

Thank you.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.
Thank you for your kind patience and understanding.****

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Tuesday, 5 December, 2017 9:37 AM

To: motorsurvey

Cc: ECICS Claims; Janice Goh Siew Geok (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Phoebe Jay Xie (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims); Asher Sng (LKKAuto); Admin A

Subject: RE: SHB4734J VS SGD4011M THIRD PARTY CLAIM

Your ref: TBA

LKK ref: CC4/ICS17022952/K1ea3

WITHOUT PREJUDICE

Dear Sir/ Madam,

Enclosed revert of vehicle: SHB 4734J

Date of survey: 04.12.2017

Number of days: - days

We have not authorized repairs.

***** Please take note that no damage found on TP vehicle- RH wing mirror *****

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 4 December, 2017 3:21 PM

To: 'motorsurvey' <motorsurvey@ecics.com.sg>

Cc: assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: SHB4734J VS SGD4011M THIRD PARTY CLAIM

Dear Janice,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: motorsurvey [<mailto:motorsurvey@ecics.com.sg>]

Sent: Monday, 4 December, 2017 3:18 PM

To: Chiang Liat Choon <chianglc@cdge.com.sg>; 'assignments' <assignments@lkkauto.com>

Cc: motorsurvey <motorsurvey@ecics.com.sg>

Subject: RE: SHB4734J VS SGD4011M THIRD PARTY CLAIM

Without Prejudice

Dear Liat Choon

Thank you for your email.
We will assign LKK for the PRI.

Aside to LKK

Please assist and arrange TP's survey.
Our Insured has not reported the accident yet.

Thank you.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.
Thank you for your kind patience and understanding.*****

From: Chiang Liat Choon [<mailto:chianglc@cdge.com.sg>]

Sent: Monday, 4 December, 2017 3:06 PM

To: motorsurvey

Subject: Fw: SHB4734J VS SGD4011M THIRD PARTY CLAIM

Dear Sir,

Attached herewith repair estimate.

Best Regards

Chiang Liat Choon

Taxi Crash Repair ComfortDelGro Engineering Pte Ltd

Off: 62148314 Fax: 65468156

— Forwarded by Chiang Liat Choon/cdge/delgnotes on 04/12/2017 03:02 PM —

From: "ApeosPort-IV C5570" <sbs-singnalling@sbstransit.com.sg>

To: chiangliat@cdge.com.sg

Date: 04/12/2017 02:58 PM

Subject: Scan Data from CDG_LO_AW_A5570

Number of Images: 11

Attachment File Type: PDF

Device Name: ApeosPort-IV C5570

Device Location:

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CC4/ICS17022952/K1ea3q2

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 15-03-2018



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGD 4011M	Veh. Inspected	SHB 4734J
Policy No.	MPU17A00052000	Coverage (\$)	0.00
Claim No.	DMPU1700640H/JG	Excess (\$)	0.00
Assign From	JANICE	Assign Date	04/12/2017

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHLB41UMHU097896	Colour	YELLOW
Odometer	90972	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S WING MIRROR. DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/12/2017	Inspection Date	04/12/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4734J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	SERVICEABLE		
	MIRROR ASSY -RR VIEW		980.50	-
	LESS 20% DISCOUNT		-196.10	-
			784.40	-
	<u>LABOUR</u>	NOT NECESSARY		
	PANEL BEATING		120.00	-
	SPRAYPAINT ON AFFECTED AREA.		90.00	-
			210.00	-
GRAND TOTAL			994.40	-
RECOMMENDED COST OF REPAIRS				

Report Ref No. CC4/ICS17022952/K1ea3q2

AT THE TIME OF INSPECTION ,NO DAMAGE FOUND TO THE RIGHT WING MIRROR.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.