

ASS. REC. BY:

REF: CS3/AU17022969/Wbez

Special Instruction:

Surveyor:

Wilson

ASSIGNMENT (Office)

From (Person):

Wimmie Fan

of

AUG

Date/Time:

24/12/2017 4:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FA 7268M

Insured:

SFF 3366Y

at Workshop m/s

K&T Accessory

Tel:

6745 5463

of

Blk 3006 Ubi Road 1 #01-372

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15-11-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

05.12.2017

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

FA 7268M - NA / INC17022132 / A4

D.O.A: 15-11-17

SFF 3366Y - X

Dismantle Part: 14.12.2017

REF: AIG

ASSIGNMENT

From: Date: 5/12/17

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. FQ 7268 M

at Workshop no. KPT Accessory

of 81k3006 Ubi Road / #01-372

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAO Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up?

Vehicle: IN / OUT

Date: Person Contacted

Veh No. FQ 7268 M

Type: M/Car / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda

Colour: White

Sp. Reading

Eng No.

C/No

Gen. Cond: Good (Fair) Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / 8 Rim / STD A/Rim or

Tyre Size

F:

R:

120/60 R17 m/c

160/60 R17 m/c

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / RIR / SUMI /

TOYO / YOKO or

DIABLO

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Front Rear O/S N/S UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No Accident Report Given
 Mileage Not Available.
 Vehicle already de-registered.

11/17

RECEIVED 12 APR 2018

Date/Time File Pass to:

☐

Preli. Report

☐

Final Report

To

Date/Time File Return to:

By

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee

Trained Operator

1st-2nd-3rd

Photo

Other

180

20

200

Add Fee:

☐

Site Insp

S

☐

Inter. Adv

S

☐

Tech. Insp

S

☐

Res. and

S

Report Format:

Lump Sum / I.B.R. S

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No.
- C Claim No.
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

--	--

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17022969/Wb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 04-12-2017



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SFF 3366Y	Veh. Inspected	FQ 7268M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	WINNIE FAN	Assign Date	24/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/11/2017	Inspection Date	05/12/2017
Survey held at	K & T ACCESSORY TRADING PTE LTD BLK 3006 #01-372 UBI ROAD 1 SINGAPORE 408700		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SFF3366Y AND FQ7268M ON 15/11/2017**

From: Fan, Winnie-LW
To: 'assignments', 'Admin A'
Cc: Fong, Andy-SY, Chin, Lee-Ying
Sent: Friday, 24 November, 2017 4:40:42 PM
Attachments:  Fax43AE.TIF

Hi LKK,

Kindly assist to survey, vehicle in.

Thanks.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Fax +(65) 6835 7416
winnie-lw.fan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

CPc

C PAGLAR & CO

ADVOCATES & SOLICITORS

UEN NO. 53130985A GST REG NO. M90371275E

50 Chin Swee Road
#05-03 Thong Chai Building
Singapore 169874
Telephone: (65) 6536 5456
Facsimile: (65) 6836 2195
Email: pri@cpaglar.com.sg
SERVICE OF COURT DOCUMENTS BY FACSIMILE
WILL NOT BE ACCEPTED

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SFF 3366Y
Our Reference: CP/PRI/FQ7268/17.sc

Date : 24th November 2017

AIG ASIA PACIFIC INSURANCE PTE LTD
ATTN: MOTOR CLAIMS DEPT

BY FAX 6835 7416 ONLY

Dear Sirs,

CORRESPONDENCE PURSUANT TO PARAGRAPH 2.9 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES

We refer to your email/ fax dated 24th November 2017.

Please note that the said vehicle can be inspected at:

K&T ACCESSORY TRADING PTE LTD
Blk 3006 Ubi Road
#01-372
Singapore 408700
Contact No.: 6745-5463

KINDLY REPLY BY EMAIL ONLY: pri@cpaglar.com.sg

Please note that the vehicle will only be available for the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you. All our client's rights are expressly reserved.

Yours faithfully,



C PAGLAR & CO

cc. [Client by Fax 6745-3788 Only] - (FQ 7268M)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you

.....
Appointed Surveyor (Name & Signature)

.....
Date & Time of Inspection

Form 3

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2017 09:17
Date Of Accident	15/11/2017 15:00
Exact Location Of Accident	ALONG CHAI CHEE DRIVE L/P:6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FQ7268M
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD ARSYAD BIN ANWAR
NRIC No	S9229575C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83816761
Alternative Phone No	OFFICE-83816761

Vehicle Particulars

Manufacturer	HONDA
Model	RVF400
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5084152004-01
Cover Note Number	

Driver

Name of Driver	MUHAMMAD ARSYAD BIN ANWAR
NRIC No	S9229575C
Date Of Birth	22/08/1992
Occupation	INDOOR
Date Of Driving Pass	11/07/2016
Driving Experience	1 YEAR AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83816761
Fax Number	
Contact Number	OFFICE-83816761
Email Address	NOEMAIL

Address BLK 629 BEDOK RESERVOIR ROAD
#04-1630
Postcode 470629
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TRAFFIC POLICE DIVISION HQ
Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPOT - T/20171115/7022.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFF3366Y
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 1

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD ARSYAD BIN ANWAR
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	FQ7268M
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Mong Chai Drive
476

Vehicle A: P27268m
Vehicle B: SF3366

vehicle A

Refer to police report 1/20171115/7022.

Policyholder's Signature _____
Date & Time: _____

Page 5 of 18

Police Report



**SINGAPORE
POLICE FORCE**



T/20171115/7022

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20171115/7022

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/11/2017 21:57	Vide Report No.: G/20171115/0136	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: MUHAMMAD ARSYAD BIN ANWAR			Address: APT BLK 629 BEDOK RESERVOIR ROAD #04-1630 SINGAPORE 470629	
ID Type / ID No.: NRIC NO / S9229575C			Contact No.:	Mobile: 83816761
Nationality: SINGAPORE CITIZEN			Home/Office:	
			Email: muhdarsyadanwar@gmail.com	
Sex: Male	Age: 25	Date of Birth: 22/08/1992	Type of Informant: Rider	
Race: Javanese			Language: English	Institution / School Name:
Occupation: SECURITY EXECUTIVE			Driving Licence Information: Class: 2A Date of Expiry:	

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/11/2017 15:00	Type of Location: Straight Road
Location: CHAI CHEE DRIVE				
Lamp Post Number: 6				
Weather: Cloudy		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FQ7268M	Motorcycle	HONDA	RVF400	White	Seriously Damaged	1

Details of Person Involved

Any Pedestrian Involved: No
No. of Pedestrians Injured: NIL Use of Pedestrian Crossing: NA

Police Report



SINGAPORE POLICE FORCE



T/20171115/7022

2 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171115/7022

CONTINUATION OF REPORT

Rider			
Name	MUHAMMAD ARSYAD BIN ANWAR	ID No.	S9229575C
Related Vehicle	FQ7268M (Motorcycle)	Contact No.	83816761
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2A Date of Expiry: NIL
Date Treatment	15/11/2017	Date Discharge	15/11/2017
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

I was riding my bike along Chai Chee Drive towards Chai Chee Street as I was on the way to work. While I was riding my bike on a straight road, a car (SFF3366Y) ahead of me in the opposite direction made an abrupt right turn disregarding my right of way. I applied my emergency break but as our vehicles were too close due to his abruptness, the head of my bike collided with the side of his car and I was flung from my bike. I landed on my back on the road and my bike dropped. I was in pain on the ground and passerby's assisted in getting me on my feet. They also assisted in picking my bike up as it fell. The owners of the vehicle I collided with came out and were not remorseful and only mentioned what an inconvenience this was for them. They did not attempt to assist me at all seeing my condition on the ground. They did not want to contact the police to settle this matter, however, I insisted and called 999. Police from Bedok South NPC soon came out to assess the situation and control traffic. Subsequently the ambulance followed by the traffic police arrived on site. I mentioned to the police officers that he has a video recording device in his car and it would serve as evidence in this incident. I was told to go to CGH with the ambulance and left the scene. I was further examined to have abrasions over my left forearm, left knee and left anterior thigh numbness with pain to my right forearm to thumb. I was given four days of Medical Leave. The front and side of my motorbike was damaged and the left side of the car was damaged. I clearly had the right of way on the road and was very shocked at the manouvering of the car. He should have stopped and allowed me to pass before turning. The road was clear and nothing could have been constructing his view from seeing me. I was riding straight while he was turning right without care of who was ahead of him. I seek your assistance and justice on this matter. I hope the footage has been retrieved for justice to be served. I did not retrieve the driver's particulars as the traffic police were already onsite. There were a few passengers onboard the car as well. Thank you.

Police Report



POLICE FORCE



T/20171115/7022

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20171115/7022

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
ONG YONG HOCK
Contact No.: 65476436

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
15/11/2017 21:57

Classification Of Case:

Condition Codes:

(1) New (2) Damaged (3) Distorted (4) Cracked (5) Corroded (6) Scratched
 (7) Deformed (8) Spotted (9) Buckled (10) Broken (11) Non-usable
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

FOR MOTORCYCLE

ACTION CODE

1. Replace (✓) 2. Repair (X) 3. Check (Z) 4. Not Constructive (NC)

May 2005

Motorcycle

NAC	INC	Item	CON	AC	Qty
1001	991856	Front Number Plate	NEC	✓	
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	DD/CRA	✓	
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy	BT	✓	
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket	BT	✓	
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp (LHS/RHS)	SCR	✓	
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing	CRA	✓	
3017	992130	Front Windshield	CRA	✓	
3018	992134	Front Wing Mirror			
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp	SCR	✓	
3021	992556	Meter Casing			
3022	992553	Meter Assy	CRA	✓	
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone			
3028	992299	Handle Bar			
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip			
3031	995184	Handle Bar Balancer LH			
3032	992300	Handle Bar Balancer RH	SCR	✓	
1252	992179	Fuel Tank	DD/SCR	✓	
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever			
3035	992293	Hand Brake Lever	SCR	✓	
3036	991119	Side Fairing			
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing			
3043	993378	Rear Fairing (RH/LH)	SCR	✓	
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower			

Vehicle No:

RQ 7268 W

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake	SCR/BT	✓	
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest	SCR/BT	✓	
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield			
3061	991058	Exhaust Muffler Assy			
1405	993719	Rear LH Shock Absorber			
1445	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard			
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp	SCR	✓	
3074	995246	Rear RH Signal Lamp	SCR	✓	
3075	995251	Rear Taillamp			
1137	993626	Rear Number Plate	DD	✓	
3076	994192	Side Box			
3077	992927	Rear Box			
3078	992928	Rear Box Bracket			
3079	991328	Emblem			
1136	990247	Sticker			
		RHS Wing Mirror	SCR	✓	
		Radiator Top -	SCR	✓	
		-Hose			

No of Items: _____

Assessor: _____

4 Days Repairs

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Dec 2017 Edit Reg		24 Nov 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Oh Beng Kuan @Catherine Oh, Co. Reg. No.: -			
Main Claimant:	MUHAMMAD ARSYAD BIN ANWAR			
Vehicle Reg. No.:	FQ7268M	Date of Loss:	15/11/2017 15:00 - :59	
Claim Type:	TP / 8995820883SG	Policy/Cover Note No.:	2100286663-04000 (Comprehensive)	
Vehicle Reg. No. (Insured):	SFF3366Y	Policy No. (Claimant):		
		Excess:		
Repairer:	K & T Accessory Trading Pte Ltd (HQ) BLK 3006 UBI ROAD 1 #03-372, 590005 Ubi - Tel: 67455463			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 29/12/2017]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (20/12/2017): TP GIA REPORT

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

















































*FQ7268M (8995820883SG)
[SFF3366Y]









TP
MUHAMMAD ARSYAD BIN ANWAR
Nov 15 2017 3:00PM
[Oh Beng Kuan @Catherine Oh]
K & T Accessory Trading Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
------------------	--	---------------	--------------------	--------------	--------------	--

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print	
1	20/12/17 15:14	ATIG Asia Pacific Insurance Pte. Ltd. (SG) Accident Statement <small>From: SC - Reg. No: SFF3366Y, Claimant: OH BENG KUAN @CATHERINE OH</small>	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print	
LKK Auto Consultants Pte Ltd (HQ)					
1	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
2	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
3	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
4	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
5	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
6	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
7	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
8	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
9	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
10	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
11	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
12	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
13	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
14	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
15	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
16	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
17	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
18	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
19	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
20	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
21	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
22	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
23	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
24	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
25	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
26	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
27	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
28	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
29	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
30	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
31	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
32	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	
33	10/04/18 17:24	General View	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	10/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
84	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	10/04/18 17:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17022969/WBE2

Date: 13/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100286663-04000

Claimant Vehicle No : FQ7268M

Insured Vehicle No : SFF3366Y

Date of Loss: 15/11/2017

Nature of Claim: TP

Claim No: 8995820883SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FQ7268M**

Make & Model: HONDA CA125T, 125cc

Engine No: HIDDEN

Reg. Date: (Man. Year: 1900)

Chassis No: NC351102664

Colour: White

Odometer: 0 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60 R17

Rear Tyre Size: 160/60 R17

Front Left Side: DIABLO 2 mm

Rear Left Side: DIABLO 2 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/11/2017

Date Inspected: 05/12/2017 Inspected At:

K & T Accessory Trading Pte Ltd (HQ)
BLK 3006 UBI ROAD 1 #03-372
Singapore 590005

Estimated Period of Repair: 4.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REGISTRATION DATE UNABLE TO TRADE:DUE TO VEHICLE DE-REGISTER

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Necessary	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Dented / Cracked	0.00 F	*- F
3	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
4	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F
5	1		*FRONT HEADLAMP (LHS / RHS)	Scratched	0.00 F	*- F
6	1		*FRONT HEADLAMP FAIRING	Cracked	0.00 F	*- F
7	1		*FRONT WINDSHIELD	Cracked	0.00 F	*- F
8	1		*FRONT RH SIGNAL LAMP	Scratched	0.00 F	*- F
9	1		*METER ASSY	Cracked	0.00 F	*- F
10	1		*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F
11	1		*FUEL TANK	Dented / Scratched	0.00 F	*- F
12	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
13	1		*REAR FAIRING (RH/LH)	Scratched	0.00 F	*- F
14	1		*FOOT BRAKE	Scratched / Bent	0.00 F	*- F
15	1		*REAR FOOT REST	Scratched / Bent	0.00 F	*- F
16	1		*REAR LH SIGNAL LAMP	Scratched	0.00 F	*- F
17	1		*REAR RH SIGNAL LAMP	Scratched	0.00 F	*- F
18	1		*REAR NUMBER PLATE	Dented	0.00 F	*- F
19	1		*RHS WING MIRROR	Scratched	0.00 F	*- F
20	1		*RADIATOR TOP HOSE	Scratched	0.00 F	*- F

F=Franchise part.

Total Parts (S\$) **0.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >