

ASS. REC. BY:

REF: CSS /MSG170 22974 /Wb57

Special Instruction:

large

Surveyor: Wilson ASSIGNMENT (Office)From (Person): Catherine Thia of mslh Date/Time: 04-12-2017 3:18pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBJ 8288H Insured: SGJ 3636Kat Workshop m/s Asia Motorsports Tel: 6745 3811of 568 Geylang RdPolicy No: A80446841 amx Claim No: 539139

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 30-11-2017  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

05-12-2017

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 04-12-2017 3:54pm Person Contacted: Mr. Lou Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	FBJ 8288H - X
	SGJ 3636K - X
	Dismantle Part: 11.12.2017
18/12/17 3:39pm Email to Catherine Thia thru meimen	

PRS  
Bureau Wilson

REF: MSIG

# ASSIGNMENT

From: Date: 5/12/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBJ 8288 H  
at Workshop m/s: Asia Motorsports  
of: 568 Geylang Rd

Insured

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24HRS 'wp'

Date: Person Contacted:

Vehicle IN / OUT

Veh No: FBJ 8288 H Yr Regn: 2014 Nov 04

Type: M.Car / Motorcycle Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Piaggio Vespa LX 155

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 32152 T. Radio: Insured / Std / NI / NA

Eng No:

C/No: ZAPM684000004286

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim STD A/Rim or

Tyre Size: F: 110 / 70 - 11

R: 120 / 70 - 11

BS / DUN / EXNOVA / GY / FS / LIZ / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R. Bal: 3 mm

L. Bal: - mm

D.O.A. D.O.I. 5/12/2017

Survey held at: Asia Motorsport @ 4:54pm

Des. of Damages: Fnt Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Accident Report Not Given.

Range \$3900 - \$4500

RECEIVED 09 APR 2018

*[Signature]*  
9/4/2018

Date/Time File Pass to:

09/04/2018

Date/Time File Return to:

24

Report Format:

Lump Sum / I.E.U. / S

☐ : Preli. Report  
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ Site Insp: \$  
☐ Interview: \$  
☐ Tech. Insp: \$  
☐ Lab. Insp: \$

Survey Fee

Transportation

1-4-85 US

Process

Other

PRS

# Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all information created by the assignment team are **ACCURATE**

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C P.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17022974/Wb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-12-2017



Code : MSG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SGJ 3636K	Veh. Inspected	FBJ 8288H
Policy No.	A80446841QMX	Coverage (\$)	0.00
Claim No.	539139	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	04/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	30/11/2017	Inspection Date	05/12/2017
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Dec 2017		04 Dec 2017 15:18 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	WEE BOCK HUAT KELVIN, ID: S1606773C, Tel: +6596396636, Email: kelvin6363@hotmail.com								
Main Claimant:	Mohd Zahrin Bin Mohd Yusoff, ID: S9146942A								
Vehicle Reg. No.:	FBJ8288H	Date of Loss:	30/11/2017 14:00 - :59						
Claim Type:	TP / 539139	Policy/Cover Note No.:	A80446841QMX (Comprehensive) Coverage: 21/11/2017 - 20/11/2018						
Vehicle Reg. No. (Insured):	SGJ3636K	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Asia Motorsports Solution Pte Ltd (HQ) No 568 Geylang Road, 389514 Geylang - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/12/2017]								
Driver/Custodian (Insured):	WEE BOCK HUAT KELVIN (54 / Male), NRIC: S1606773C, Tel: +6596396636								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All Search Tasks Create New Task Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/12/2017 12:30
Date Of Accident	30/11/2017 14:00
Exact Location Of Accident	WOODLANDS AVE 10 TOWARDS GAMBAS AVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ8288H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHD ZHRIN BIN MOHD YUSOFF
NRIC No	S9146942A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84818141
Alternative Phone No	OFFICE-84818141

### Vehicle Particulars

Manufacturer	PIAGGIO
Model	VESPA LX 150 I.E. 3V
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095363344 COMP
Cover Note Number	

### Driver

Name of Driver	MOHD ZHRIN BIN MOHD YUSOFF
NRIC No	S9146942A
Date Of Birth	16/12/1991
Occupation	INDOOR
Date Of Driving Pass	19/11/2015
Driving Experience	2 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84818141
Fax Number	
Contact Number	OFFICE-84818141
Email Address	NOEMAIL

Address	BLK 264 TAMPINES ST 21 #05-120
Postcode	520264
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES EAST NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 263 TAMPINES STREET 21 #01-128 , POSTCODE: 520263 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7839999 - FAX NO: 67832500
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT ATTACHED. ATTENDED BY AINI

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGJ3636K
Vehicle Make/Model/Colour	MITSUBISHI LANCER 2.0L MIVEC GT 6-CVT
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	

Email Address

**DETAILS OF INJURED PERSON 1**

Name	MOHD ZAHRIN BIN MOHD YUSOFF
Approximate Age	25
Injuries Sustain	RIGHT ARM, BACK PAIN
Injured person in which vehicle?	FBJ8288H
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	YES
Address	BLK 264 TAMPINES ST 21 #05-120
Postcode	520264





SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report T/20171130/2110

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: - 2 DEC 2017

**IDAC KAKI BUKIT (VAC)**  
 23 Kaki Bukit Ave 4  
 Singapore 415933  
 Tel: 67416697 Fax: 67492305  
 Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

G-4 B/C Skendiah/Berhala, WJ



**SINGAPORE  
POLICE FORCE**



T/20171130/2110

1 of 3

Police Station Of Origin:  
Tampines East NPP  
263 Tampines Street 21 #01-138  
SINGAPORE 520263  
Tel No: 1800-7839999

Report No. T/20171130/2110

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/11/2017 17:00		Vide Report No.: F/20171130/0135		Station Diary No.: 39	
<b>Informant's Particulars</b>					
Name of Informant: MOHAMAD ZAHIRIN BIN MOHD YUSOFF			Address: APT BLK 264 TAMPINES STREET 21 #05-120 SINGAPORE 520264		
ID Type / ID No.: NRIC NO / S9146942A			Contact No.: Home/Office:		Mobile: 84818141
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 16/12/1991	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: HDB TECHNICAL EXEC			Driving Licence Information: Class: 2B,3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/11/2017 14:00	Type of Location: Y-Junction
Location: Along Road 1 WOODLANDS AVENUE 10 Towards Gambas Avenue				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBJ8288H	Car	PIAGGIO	VESPA LX 150 I.E. 3V	Black	Slightly Damaged	0
SGJ3636K	Motorcycle				Slightly Damaged	0

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBJ8288H	NTUC Income Insurance Co-Operative Limited	5095363344	23/11/2017	22/11/2018



**SINGAPORE  
POLICE FORCE**



T/20171130/2110

Police Station Of Origin:  
Tampines East NPP  
263 Tampines Street 21 #01-138  
SINGAPORE 520263  
Tel No: 1800-7839999

2 of 3

Report No. T/20171130/2110

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	MOHAMAD ZHRIN BIN MOHD YUSOFF	ID No.	S9146942A
Related Vehicle	FBJ8288H (Car)	Contact No.	84818141
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	30/11/2017	Date Discharge	30/11/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight

**Brief Details.**

On the 30/11/2017 at about 1400hrs I was riding along Woodlands Avenue 10 in my m/cycle bearing the plate number FBJ8288H and entering the slip road towards Gambas Avenue. Subsequently, there is heavy traffic on the main road of Gambas Avenue and as such, I brought my m/cycle to a stop at the slip road. Subsequently, as I was about to move off, one vehicle bearing the plate number SGJ3636K collided with me from the rear. I then fell down from the m/cycle and suffered some abrasion.

We then exchanged particulars before I was conveyed to hospital(Khoo Teck Phuat Hospital). I was given treatment for the abrasion on my right arm and back pain and was given 3 days MC.



**SINGAPORE  
POLICE FORCE**



T/20171130/2110

Police Station Of Origin:  
Tampines East NPP  
263 Tampines Street 21 #01-138  
SINGAPORE 520263  
Tel No: 1800-7839999

3 of 3

Report No. T/20171130/2110

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report

G /

Sgt 2 MOHAMAD IZWAN BIN MOHAMAD ISHAK

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

30/11/2017 17:00

Officer In Charge Of Case:

TP A/GIT /

Staff Sgt SHAHRUL NIZAM BIN SAMARRI

Contact No.: 65476904

Classification Of Case:

SN 102

Authentication Stamp

NP168



Signature:

Singapore Police Force

## View Sent Message

This mail is associated with :

**\*FBJ8288H (539139)**  
**[SGJ3636K]**

TP  
Mohd Zahrin Bin Mohd Yusoff  
Nov 30 2017 2:00PM  
[WEE BOCK HUAT KELVIN]  
Asia Motorsports Solution Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 18/12/2017 15:39 PM.  
**To** MSI\_TSY  
**Subject** Pre-repair Inspection

Dear Catherine,

Refer to your assignment on 04.12.2017 at 3.18PM.

Please be informed that we have inspected the vehicle FBJ 8288H on 05.12.2017 at 4.54PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,  
Catherine Chong | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Dec 2017		04 Dec 2017 15:18 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	WEE BOCK HUAT KELVIN, ID: S1606773C, Tel: +6596396636, Email: kelvin6363@hotmail.com		
Main Claimant:	Mohd Zahrin Bin Mohd Yusoff, ID: S9146942A		
Vehicle Reg. No.:	FBJ8288H	Date of Loss:	30/11/2017 14:00 - :59 [36 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 539139	Policy/Cover Note No.:	A80446841QMX (Comprehensive) Coverage: 21/11/2017 - 20/11/2018
Vehicle Reg. No. (Insured):	SGJ3636K	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Asia Motorsports Solution Pte Ltd (HQ) No 568 Geylang Road, 389514 Geylang - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 05/12/2017]		
Driver/Custodian (Insured):	WEE BOCK HUAT KELVIN (54 / Male), NRIC: S1606773C, Tel: +6596396636		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*FBJ8288H (539139)

[SGJ3636K]

TP

Mohd Zahrin Bin Mohd Yusoff

Nov 30 2017 2:00PM

[WEE BOCK HUAT KELVIN]

Asia Motorsports Solution Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

### Assessment Reports

1 per page ▼
































No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/12/17 14:04	<b>Accident Statement</b> From:OD - Reg. No: SGJ3636K, Claimant: WEE BOCK HUAT KELVIN	Load HTM	

### Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
2	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
3	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
4	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
5	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
6	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
7	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
8	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
9	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
10	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
11	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
12	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
13	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
14	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
15	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
16	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
17	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
18	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
19	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
20	09/04/18 16:36	General View	Load JPG	<input checked="" type="checkbox"/>
21	09/04/18 16:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
22	09/04/18 16:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
23	09/04/18 16:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
24	09/04/18 16:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
25	09/04/18 16:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
26	09/04/18 16:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
27	09/04/18 16:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
28	09/04/18 16:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	09/04/18 16:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	09/04/18 16:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
31	09/04/18 16:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	09/04/18 16:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/12/17 14:04	FBJ8288H E FILE REPORT.	 Load PDF	
2	04/12/17 15:18	TP disagree on SJE	 Load PDF	
3	06/12/17 14:16	TP invite survey for dismantled parts	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG17022974/WBS2  
**Date:** 11/04/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A80446841QMX  
**Claimant Vehicle No :** FBJ8288H **Insured Vehicle No :** SGJ3636K  
 Date of Loss: 30/11/2017 Nature of Claim: TP Claim No: 539139

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ8288H**  
 Make & Model: PIAGGIO VESPA LX, 155cc I.E. 3V Engine No: M688M1003336  
 Reg. Date: 04/11/2014 (Man. Year: 2013) Chassis No: ZAPM6840000004286  
 Colour: Black Odometer: 32182 km  
 Engine Capacity: 155 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 110/70-11 Rear Tyre Size: 120/70-10  
 Front Left Side: Michelin 3 mm Rear Left Side: Michelin 3 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 04/12/2017  
 Date Inspected: 05/12/2017 Inspected At: Asia Motorsports Solution Pte Ltd (HQ)  
 No 568 Geylang Road  
 Singapore 389514  
 Estimated Period of Repair: 0.0 days

**Adjuster:** Teo Cheng Ming Wilson

**Manager:** CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/11/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,900.00 - \$4,500.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 11 Apr 2018)

**Parts:** N/A PIAGGIO VESPA LX 155cc I.E. 3V (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FBJ8288H)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >