

22/03/2002

ASS. REC. BY:

REF:

CS/FCL 7023023 / Uv6¹²

Special Instruction:

Survivor: Marius**ASSIGNMENT (Office)**

From (Person):

CWS Joanne Yung of FCLDate/Time: 05/12/17 213pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 20187

Insured:

SH 90377

at Workshop m/s

Focus Auto

Tel:

6886 9097

of

Blk 1 Kaki Bukit Ave 6 #02-50

Policy No:

Claim No:

D17011180MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01.12.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

05/12/17 235pm

Person Contacted:

Ms. SimVehicle IN / OUT

Date/Time

Action/Instruction (☒) EstimateSLE 20187 - xSH 90377 - CS/INC 090029143 / YmDCA: 0800075/12/17Email FCI informed paneling est from repairer23/12/17Email preli revised to FCI

Surrender: marcus

701 /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 2018T
at Workshop m/s: Focusof _____
Insured: SH 9037T

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

col 27/12/17
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLE 2018T Yr Regn: 28/12 07Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Honda civic IMA c.c 1339Colour: black A/C: Insured / Std / NI / NASp. Reading: 171469 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMF03620FS-202546Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 1/12/17 D.O.I. 5/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 98219821 1h.26 h.21/12/17 Confirmed L/S \$1000 with MR way (Red 2997.68, 7410)

RECEIVED 26 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 26/12- typistReport Format: cwsLump Sum / I.B.I: (\$) 1000/2Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S+RS: \$

Photos:

Others:

TOTAL

130
50
50
63
293

Survey Department Check List (Case Handler)

Reference No.: ES/FCI 17023023/UVB
 Policy Type: OD-/TP/TP RES/TL/EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

		Y-Date	N-Date	Y-Date	N-Date
(1) Office Assign Form					
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)					
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form					
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)					
C	Resurvey photo Uploaded	✓			

Check By: VERON 23/12/17
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023023/Uvb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 9037T	Veh. Inspected	SLE 2018T
Policy No.		Coverage (\$)	0.00
Claim No.	D17011180MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	05/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/12/2017	Inspection Date	05/12/2017
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17011180MFSH
Our ref: CS/FCI17023023/Uvb

DATE: 23/12/2017

The Motor Claims Department
M/s First Capital Insurance Limited

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 2018T


We thank for your instruction on 5/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 5/12/2017 at the premises of M/s FOCUS AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,997.68
Revised Estimate Amount	: S\$1,000.00 (Lump sum)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	04-12-2017	Our Ref No. D17011180MFSH
Accident Date	01-12-2017	Claim Type. Third Party
Insured Vehicle	SH9037T	Third Party Vehicle. SLE2018T
Survey Location	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-50	
Contact Person.	MS SIN	
Contact No.	68869097/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FOCUS AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231423)



PRI Documents



Close



PRI Header Details

Claim No	D17011180MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & FO
Workshop Name	FOCUS AUTO PTE LTD (Contact Person : MS SIN)	Survey Location & Contact Details	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-50 Mobile: 0 , Phone: 68869097 , Fax: 0 EmailId: FOCUS.AUTOPTELTD@YAHOO.COM.S		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH9037T	TP Vehicle No	SLE201
PRI Recieved Date	04-12-2017 08:32:30 PM	Surveyor Appointed Date	05-12-2017 02:13:38 PM	Surveyor Accept Date	05-12-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-12-2017	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 5 December, 2017 5:08 PM
To: 'Claim Workflow System'
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011180MFSH/1, SLE 2018T

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLE 2018T on 5/12/2017.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 5 December, 2017 2:23 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011180MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 5 December, 2017 2:13 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011180MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Saturday, 23 December, 2017 11:12 AM
To: 'Claim Workflow System'
Cc: 'JOANNEYONG@FIRST-INSURANCE.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D17011180MFSH/1, SLE 2018T
Attachments: SLE 2018T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLE 2018T
Date of survey: 5/12/2017
Number of days: 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 5 December, 2017 5:08 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011180MFSH/1, SLE 2018T

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLE 2018T on 5/12/2017.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 5 December, 2017 2:23 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011180MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 5 December, 2017 2:13 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011180MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	5144H
Vehicle Details	
Vehicle No.	SLE2018T
Vehicle to be Exported	No
Intended De-registration Date	05 Dec 2017
Vehicle Make	HONDA
Vehicle Model	CIVIC IMA A
Primary Colour	Black
Manufacturing Year	2007
Engine No.	LDA23010318
Chassis No.	JHMF36208S202546
Maximum Power Output	70.0 kW (93 bhp)
Open Market Value	\$27,777.00
Original Registration Date	28 Dec 2007
First Registration Date	28 Dec 2007
Transfer Count	2
Actual ARF Paid	\$19,445.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	27 Dec 2017
PARF Rebate Amount	\$9,722.00
Intended COE Rebate Details	
COE Expiry Date	27 Dec 2017
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$16,839.00
COE Rebate Amount	\$99.00
Total Rebate Amount	\$9,821.00

The information contained herein is correct as at 05 Dec 2017

OK

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

Not Adjusted
LKK
4/5 \$1000/2
4 day.
the phl after repair

M/S :

FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 6507 3848

FAX: 6507 3849

ATTN: Motor Claim Department

Your Ref No: SLE2018T

Claim Type: Third Party

Accident Date: 01-12-2017

TP Veh Reg No: SH9037T

Estimate No: EST0000539

Date: 11 Dec 2017

Policy No: 5072524616-02

Veh Reg No: SLE2018T

Make/Model: HONDA CIVIC

Chassis No: JHMFD36208S202546

Engine No: LDA23010318

Reg. Date: 28-12-2007

Estimate Repair Cost to Vehicle No :SLE2018T

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
HONDA CIVIC IMA				
List Price				
1 Front Bonnet	575.8000	1 PC	575.80 X	
2 Front Head Lamp RH	868.7000	1 PC	868.70 ✓	
3 Front Head Lamp Lower Bracket RH	42.5000	1 PC	42.50 a	
4 Front Grille	151.9000	1 PC	151.90 x	
5 Front Bumper	638.0000	1 PC	638.00 ✓	
6 Front Bumper Side Retainer RH	14.7000	1 PC	14.70 ✓	
7 Front Bumper Reinforcement	280.3000	1 PC	280.30 X	
8 Front Bumper Fog Lamp RH	250.2000	1 PC	250.20 ✓	
			2,822.10	1771.6
	Less 20%		564.42	2,257.68
Labour				
9 Panel Beating	850.0000	1 PC	850.00 400	
10 Check Wiring	60.0000	1 PC	60.00 20	
11 Rust Proofing	80.0000	1 PC	80.00 X	
12 Spray Painting	750.0000	1 PC	750.00 500	
			1,740.00	1,740.00
			Total	SS 3,997.68

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED NINETY SEVEN AND CENTS SIXTY EIGHT

For FOCUS AUTO PTE LTD

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023023/Uvbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-12-2017		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9037T	Veh. Inspected	SLE 2018T	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011180MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	05/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC IMA (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JHMFD36208S202546	Colour	BLACK	
Odometer	171469	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	FALKEN	6 mm	
L/H Front Tyre	195/60 R16	FALKEN	6 mm	
R/H Rear Tyre	195/60 R16	FALKEN	6 mm	
L/H Rear Tyre	195/60 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2017	Inspection Date	05/12/2017	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 2018T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	TO REPAIR SEE LABOUR	575.80	-
1	FRONT HEAD LAMP RH	CRACKED	868.70	868.70
1	FRONT HEAD LAMP LOWER BRACKET RH	TO REPAIR SEE LABOUR	42.50	-
1	FRONT GRILLE	NOT NECESSARY	151.90	-
1	FRONT BUMPER	DISTORTED	638.00	638.00
1	FRONT BUMPER SIDE RETAINER RH	BENT	14.70	14.70
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	280.30	-
1	FRONT BUMPER FOG LAMP RH	BROKEN	250.20	250.20
	LESS 20% DISCOUNT		-564.42	-354.32
			2,257.68	1,417.28
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BONNET,FRONT HEAD LAMP LOWER BRACKET RH AND FRONT BUMPER REINFORCEMENT.		850.00	400.00
	CHECK WIRING.		60.00	20.00
	RUST PROOFING.	NOT NECESSARY	80.00	-
	SPRAY PAINTING.		750.00	500.00
			1,740.00	920.00
	GRAND TOTAL		3,997.68	2,337.28
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00

Report Ref No. CS/FC117023023/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.