

22/03/2002

ASS. REC. BY:

REF: CS/MSG17023040/R1qbn2 Special Instruction:

SURVAYOR:
Menmen

Ressel

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSIG

Date/Time: 5/12/17 @ 9:52am

Estimated Cost:

Bill to:

OD / ~~IP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 9323 D

Insured:

GBF 4823K

at Workshop m/s

Volvo East Asia

Tel:

9627 0391

of

12 Tuas Ave 10, 63 9136

Policy No:

A29035476MKF

Claim No:

539099

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/11/17

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

11:20am @ 5/12/17

Person Contacted:

Mr Chua

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction (✓) Estimate

XD 9323 D-X

GBF 4823K-X

06/12/17 @ 2:35pm revised to Katherine Wong via Menmen.

12/4/18 @ 1:46pm confirmed with Mr Chua final fig \$11346, 7 days

cted \$5944, 35% /

J. 02/18

ASSIGNMENT

From _____ Date _____
Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV _____
To Inspect Vehicle No: **X093230**
at Workshop via **Volvo**
of **12, Thurs eve 10**
Insured **msch / TP**
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition) *Mr. C. H. H. H.*
Remark: The veh had commenced its
repair at the time of inspection.

	N/S	O/S

Sal. or Market Value: _____

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: XD9323D Vn Regn: 2014 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
(Truck) / Trailer or

Make: VOLVO FMX370 AC: 10837

Colour: Red A.O.: Insured / Std / NI / NA

Sp. Reading: 284624 T.Radio: Insured / Std / NI / NA

Eng/No:

C.No: YU2J1E107DA 750842

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Ni / Si/Rim / STD AJRim or

Tyre Size: F: 315/80R22.5
R: D/O

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or MOTULAKE

Front	Rear
R/Bal: <u>8</u> mm	R/Bal: <u>8/8</u> mm
L/Bal: <u>8</u> mm	L/Bal: <u>2/8</u> mm
D.O.A: <u>29/11/17</u>	D.O.I: <u>05/12/17</u>

Survey held at: VOLVO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
-------------	----------------------

RECEIVED 30 APR 2018

Date/Time File Pass to: ☐ : Preli. Report
 1/30/4 trans ☐ : Final Report
 Date/Time File Return to:

Days Of Repair: 7
Resurvey No. of Trip:

[illegible]

Add Fee:		Site Fee	\$
		Inst Fee	\$
		Tech Fee	\$
		Warranty	\$

Report Format: MER-SP
Lump Sum / Bill: 11346

300
10
310

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17023040/R1qb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 05-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 4823K	Veh. Inspected	XD 9323D
Policy No.	A29035476MKF	Coverage (\$)	0.00
Claim No.	539099	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	05/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/11/2017	Inspection Date	05/12/2017
Survey held at	VOLVO EAST ASIA (PTE) LTD 12, TUAS AVENUE 10 SINGAPORE 639136		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Nov 2017		05 Dec 2017 09:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	D2D EXPRESS PTE LTD, Co. Reg. No.: 201132017D		
Main Claimant:	Chuan Lim Construction Pte Ltd, Co. Reg. No.: 199600684W		
Vehicle Reg. No.:	XD9323D	Date of Loss:	29/11/2017 17:00 - :59
Claim Type:	TP / 539099	Policy/Cover Note No.:	A29035476MKF (Comprehensive) Coverage: 10/11/2017 - 31/12/2018
Vehicle Reg. No. (Insured):	GBF4823K	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	Volvo East Asia (pte) Ltd - Tuas (HQ) 12 Tuas Avenue 10, 639136 Tuas - Tel: 6672 7537		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/12/2017]		
Driver/Custodian (Insured):	KOH ENG THIAN WILSON (), NRIC: S8516322A, Tel: +6583666655		
Adj Asg. Remarks:	Car is In. Please survey. Thank you.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nabilah Rasol

From: Joslin Lim
Sent: Monday, 4 December, 2017 10:50 AM
To: Katherine Wong; Nabilah Rasol
Cc: Christopher Chionh; Jason Sim
Subject: FW: XD9323D-TP claim against GBF4823K (MSIG)
Attachments: XD9323D-Estimate Quotation.pdf; GIA report.pdf

Follow Up Flag: Follow up
Flag Status: Flagged

Hi Katherine & Nabilah

Fyna

From: Agnes Lee
Sent: Monday, 4 December, 2017 10:13 AM
To: Joslin Lim <joslin_lim@sg.msig-asia.com>
Subject: FW: XD9323D-TP claim against GBF4823K (MSIG)

From: Chua Kim Teck [<mailto:kim.teck.chua@volvo.com>]
Sent: 02 December 2017 10:23
To: Claims <claims@sg.msig-asia.com>
Cc: Rosoiu Ciprian <ciprian.rosoiu@volvo.com>
Subject: XD9323D-TP claim against GBF4823K (MSIG)

Hi Office In-charge,

Attach estimate quotation & GIA report for your perusal & reference.

Kindly arrange your respective or appointed surveyor to Volvo workshop at 12 Tuas Ave 10 for survey.

Best Regards

Chua Kim Teck (Mr)
Workshop Supervisor
Volvo East Asia (Pte) Ltd
12 Tuas Avenue 10 Singapore 639136

Direct Line: +65 6672 7537
Mobile: +65 9627 0391
Fax: +65 6861 4132
E-mail: kim.teck.chua@volvo.com

www.volvogroup.com
www.volvotrucks.com.sg
www.udtrucks.com.sg

This email message and any attachments may contain confidential information and may be privileged. If you are not the intended recipient or otherwise not authorized to receive this message, you are prohibited to use, copy, disclose or take any action based on this email or any information contained herein. If you are not the intended recipient, please advise the sender immediately by replying to this email and permanently delete this message and any attachments from your system.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 27 April 2018 1:46 PM
To: 'Chua Kim Teck'; Rasul (LKKAUTO); SUR
Cc: Yang Bryan
Subject: RE: XD9323-TP Claim

Dear Mr Chua,

Confirm final fig \$11,346.00 before GST and 7 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chua Kim Teck [mailto:kim.teck.chua@volvo.com]
Sent: Monday, 16 April 2018 1:57 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Yang Bryan <bryan.yang@volvo.com>
Subject: RE: XD9323-TP Claim

Hi Rasul / Team,

Any update pertaining to the claim status & can we move forward to close it at the soonest?
Looking forward to your favourable reply soon.

Best Regards,

Chua Kim Teck
Workshop Supervisor & Accident / Marine Claim Handler

Volvo Trucks International Hub South East Asia, Singapore market

Telephone: +65 6672 7537
Mobile: +65 9627 0391
Fax: +65 6862 4132
Email: kim.teck.chua@volvo.com
www.volvogroup.com
www.volvotrucks.com.sg
www.udtrucks.com.sg
<https://www.facebook.com/VolvoTrucksSingapore>
<https://www.facebook.com/UDTrucksSingapore>

From: Chua Kim Teck
Sent: Wednesday, 21 March, 2018 3:26 PM
To: 'Rasul (LKKAUTO)'; SUR (sur@lkkauto.com)
Cc: Yang Bryan
Subject: RE: XD9323-TP Claim

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 06 Dec 2017

Preliminary Advice

Insured Vehicle No	: GBF4823K	Accident Date	: 29/11/2017
TP Vehicle No	: XD9323D	Assignment Date	: 05/12/2017
Make	: VOLVO FMX37064R	Est. Duration of Repair	: 7.00
Date of Inspection	: 05/12/2017		
Inspection At	: VOLVO EAST ASIA (PTE) LTD - TUAS (HQ) 12 TUAS AVENUE 10 SINGAPORE 639136		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,221.00
Revised Amount	:S\$	10,841.00
Check Items (Estimated)	:S\$	4,228.00
Total	:S\$	15,069.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	0684W
Vehicle Details	
Vehicle No.	XD9323D
Vehicle to be Exported	No
Intended De-registration Date	06 Dec 2017
Vehicle Make	VOLVO
Vehicle Model	FMX370 64R DAY CAB
Primary Colour	White
Manufacturing Year	2013
Engine No.	D11300019
Chassis No.	YV2J1E1D7DA750842
Maximum Power Output	-
Open Market Value	\$114,932.00
Original Registration Date	01 Jul 2014
First Registration Date	01 Jul 2014
Transfer Count	0
Actual ARF Paid	\$5,747.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	30 Jun 2024
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
PQP Paid	\$9,052.00
COE Rebate Amount	\$5,944.00
Total Rebate Amount	\$5,944.00

The information contained herein is correct as at 06 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/11/2017 14:29
Date Of Accident	29/11/2017 17:30
Exact Location Of Accident	ALONG TAMPINES AVE 10 TOWARDS TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD9323D
Insured/Policyholder	
Name Of Registered Owner	CHUAN LIM CONSTRUCTION PTE LTD
Co Reg No	199600684W
Email Address	CHONGLENG.YEE@CHUAMLIM.COM
Mobile Phone No	
Alternative Phone No	OFFICE-65710615

Vehicle Particulars

Manufacturer	VOLVO
Model	FMX370 64R DAY CAB
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCV17S009804
Cover Note Number	01/07/2017 - 30/06/2018

Driver

Name of Driver	TAN ENG HUAT
NRIC No	S0196654E
Date Of Birth	12/05/1952
Occupation	OUTDOOR
Date Of Driving Pass	24/10/1979
Driving Experience	38 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84880505
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 302B ANCHORVALE LINK #03-170
Postcode	542302
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS WEST NPC
Police Station Address	ROAD: 9 MARSILING LANE , POSTCODE: 739146 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED. * THIRD PARTY CLAIM BY OWN WORKSHOP *

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF4823K
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	KOH ENG THIAN, WILSON
NRIC/Passport Number	S8516322A
Contact Number	83666655
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	

Email Address

DETAILS OF INJURED PERSON 1

Name	TAN ENG HUAT
Approximate Age	
Injuries Sustain	RIGHT SHOULDER PAIN
Injured person in which vehicle?	XD9323D
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Wendy
NRIC/FIN No.: 30/11/17
(Ys)

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No: T/20171130/2017

DECLARATION

I/We declare the foregoing particulars are true in every respect




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Wendy
NRIC/FIN No: 30/11/17 (YS)

Sketch Plan #3



PR


**SINGAPORE
POLICE FORCE**


T/20171130/2027

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

1 of 3

Report No. T/20171130/2027

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/11/2017 10:48		Vide Report No.:		Station Diary No.: 23	
Informant's Particulars					
Name of Informant: TAN ENG HUAT			Address: APT BLK 302B ANCHORVALE LINK #03-170 SINGAPORE 542302		
ID Type / ID No.: NRIC NO / S0196654E			Contact No.: Home/Office: Mobile: 84880505		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 65	Date of Birth: 12/05/1952	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: DRIVER			Driving Licence Information: Class: 3,4,5 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 29/11/2017 17:30	Type of Location: Straight Road
Location: Junction of Road 1 and Road 2 TAMPINES AVENUE 10 TAMPINES AVENUE 5 TAMPINES AVENUE 10 TOWARDS TPE				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF4823K	Lorry				Slightly Damaged	0
XD9323D	Lorry				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

PR



**SINGAPORE
POLICE FORCE**



T/20171130/2027

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

2 of 3
Report No. T/20171130/2027

CONTINUATION OF REPORT

Driver			
Name	TAN ENG HUAT	ID No.	S0196654E
Related Vehicle	XD9323D (Lorry)	Contact No.	84880505
Hospital/Clinic	LIFELINK 24HRS CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	29/11/2017	Date Discharge	29/11/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the above mentioned date, time and location I was driving y company's lorry XD9323D.

On that current time I was travelling along Tampines Avenue 10 towards TPE on the most left lane. As I was approaching the filter lane I saw 01 vehicle (GBF4823K) however I thought the vehicle was going to stop. As I was at the filter lane the said vehicle then inched forward and that's when I collided with the said vehicle. my left lower side front bumper hit onto the right side of the driver seat door. As a result my vehicle had damages on the left front side, side mirror and headlight. No one else was injured and no government property damaged. I then went to the doctor as my right shoulder was in pain and was given 3 days MC.

PR



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999



T/20171130/2027

3 of 3

Report No. T/20171130/2027

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 MUHAMMAD NASRULLAH BIN KAMSANI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI 2 YEO GEAK ENG CECILIA

Contact No.: 65476404

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

30/11/2017 10:48

Classification Of Case:

Volvo East Asia

Page 1 of 4

Quotation Preview

Cust. 850940

Volvo East Asia (Pte) Ltd

MSIG INSURANCE (SINGAPORE) PTE LTD

12 TUAS AVENUE 10

4 SHENTON WAY #21-01
SGX CENTRE

Singapore

Singapore

639136

068807

Singapore

SINGAPORE

No. Quotation No. 13006186 Veh.ty FM11 64R

Date 05/12/2017 Order Dt. 30/11/2017 Chassis/SL No. A-750842

Expiry Dt 05/12/2017 Mil. 257880 Make 00 - VTC

Req. Delv. Dt Regn. XD9323D

CustRef.

Payment Desc			90Days	Payment Due Date			05/03/2018			
PC	Lab/Part	Description		Time/Qty	Price	Discount	GST		Amt	
40	VO 84004131	BUMPER		1.00	2,542.00	0.00	7.00	xsuc?	2,542.00	
40	VO 82446221	CARRIER RAIL		1.00	466.00	0.00	7.00	PA✓	466.00	
40	VO 82348988	PANEL		1.00	27.00	0.00	7.00	DE✓	27.00	
40	VO 82266433	BUMPER		1.00	196.00	0.00	7.00	PA✓	196.00	
40	VO 20398136	HINGE		1.00	113.00	0.00	7.00	PA✓	113.00	
40	VO 20398135	HINGE		1.00	113.00	0.00	7.00	xsuc?	113.00	
40	VO 20360849	DOOR FRAMEWORK, L.H.		1.00	2,133.00	0.00	7.00	PA✓	2,133.00	
40	VO 20573937	SEALING MOULDING		1.00	101.00	0.00	7.00	ms✓	101.00	
40	VO 82472612	COVER		2.00	20.00	0.00	7.00	ms✓	40.00	
40	VO 82471690	HOUSING		1.00	104.00	0.00	7.00	ms✓	104.00	
40	VO 82471689	HOUSING		1.00	90.00	0.00	7.00	ms✓	90.00	
40	VO 82440900	RUBBER SPACER		2.00	4.00	0.00	7.00	ms✓	8.00	
40	VO 82417286	ARM		1.00	267.00	0.00	7.00	ms✓	267.00	
40	VO 82417045	TRIM FRAME		1.00	24.00	0.00	7.00	ms✓	24.00	
40	VO 82417044	GLASS		1.00	103.00	0.00	7.00	ms✓	103.00	
40	VO 82417042	TRIM FRAME		1.00	28.00	0.00	7.00	ms✓	28.00	
40	VO 82417041	GLASS		1.00	110.00	0.00	7.00	ms✓	110.00	
40	VO 994787	SIX POINT SOCKET S		4.00	1.00	0.00	7.00	ms✓	4.00	
40	VO 993124	SPRING NUT		2.00	1.00	0.00	7.00	ms✓	2.00	

Volvo East Asia

Page 2 of 4

Quotation Preview

	Cust.	850940
Volvo East Asia (Pte) Ltd		MSIG INSURANCE (SINGAPORE) PTE LTD
12 TUAS AVENUE 10		4 SHENTON WAY #21-01 SGX CENTRE
Singapore		Singapore
639136		068807

Singapore

SINGAPORE

No.	Quotation No.	13006186	Veh.ty	FM11 64R
Date	05/12/2017	Order Dt.	30/11/2017	Chassis/SL No.
Expiry Dt	05/12/2017	Mil.	257880	Make
		Req. Delv. Dt		00 - VTC
			Regn.	XD9323D
			CustRef.	

Payment Desc		90Days	Payment Due Date		05/03/2018			
PC	Lab/Part	Description	Time/Qty	Price	Discount	GST	Amt	
40	VO 977166	SIX POINT SOCKET SCREW	2.00	1.00	0.00	7.00	2.00	ne /
40	VO 975357	SIX POINT SOCKET S	6.00	3.00	0.00	7.00	18.00	ne /
40	VO 84139937	DIRECTION INDICATO	1.00	81.00	0.00	7.00	81.00	bro /
40	VO 82475899	SHIELD	1.00	85.00	0.00	7.00	85.00	CRA /
40	VO 82428868	CONCEALING PANEL	1.00	86.00	0.00	7.00	86.00	CRA /
40	VO 82428801	HEADLAMP	1.00	197.00	0.00	7.00	197.00	YSL? /
40	VO 82426817	LAMP	1.00	345.00	0.00	7.00	345.00	bro /
40	VO 82423778	BRACKET	1.00	249.00	0.00	7.00	249.00	CRA /
40	VO 82375520	BRACKET	1.00	20.00	0.00	7.00	20.00	ne /
40	VO 82364738	BRACKET	1.00	28.00	0.00	7.00	28.00	ne /
40	VO 82335280	CAP	1.00	10.00	0.00	7.00	10.00	ne /
40	VO 82310407	HEADLAMP	1.00	106.00	0.00	7.00	106.00	YSL? /
40	VO 82266415	COVER PLATE	1.00	173.00	0.00	7.00	173.00	CRA /
40	VO 82266039	PROTECTION	1.00	206.00	0.00	7.00	206.00	CRA /
40	VO 82266031	INDICATOR LAMP	1.00	58.00	0.00	7.00	58.00	YSL? /
40	VO 21448885	COWL	1.00	30.00	0.00	7.00	30.00	ne /
40	VO 21441094	WIRES	1.00	65.00	0.00	7.00	65.00	YSL? /
40	VO 21404042	HEADLAMP HOUSING	1.00	135.00	0.00	7.00	135.00	CRA /
40	VO 21391217	GASKET	1.00	33.00	0.00	7.00	66.00	ne /

Volvo East Asia

Quotation Preview

	Cust.	850940
Volvo East Asia (Pte) Ltd		MSIG INSURANCE (SINGAPORE) PTE LTD
12 TUAS AVENUE 10		4 SHENTON WAY #21-01 SGX CENTRE
Singapore		Singapore
639136		068807

Singapore		SINGAPORE
No.	Quotation No.	13006186
		Veh.ty
		FM11 64R
Date	05/12/2017	Order Dt.
		30/11/2017
		Chassis/SL No.
		A-750842
Expiry Dt	05/12/2017	Mil.
		257880
		Make
		00 - VTC
		Regn.
		XD9323D
		CustRef.

Payment Desc		90Days	Payment Due Date		05/03/2018				
PC	Lab/Part	Description	Time/Qty	Price	Discount	GST	Amt		
40	VO 21369295	RUBBER EXPANDER	2.00	3.00	0.00	7.00	6.00	6.00	
40	VO 20917278	HAND PUMP	1.00	736.00	0.00	7.00	736.00	736.00	
40	VO 20529638	FOOT STEP	1.00	141.00	0.00	7.00	141.00	141.00	
40	VO 82266404	GRATING	1.00	252.00	0.00	7.00	252.00	252.00	
40	VO 21404040	PANEL	1.00	205.00	0.00	7.00	205.00	205.00	
40	VO 20379171	PANEL	1.00	250.00	0.00	7.00	250.00	250.00	
40	12345	Towing Charges	1.00		0.00	7.00	500	500	
40	12345	To dismantle & replace damage parts & transfer all LH door & glass mechanism to new door	1.00		0.00	7.00	1800	1800	
40	12345	To panel beat, jack & re-align LH door pillar	1.00		0.00	7.00	600	600	
40	12345	To spray paint on replaced parts & affected areas	1.00		0.00	7.00	2400	2400	

Document Information Lines

Total Parts Cost	10,021.00
Total Others Cost	7,200.00

Sub Total	17,221.00
7.00 % GST	1,205.47
Gross Total	18,426.47
Advance	0.00

17240

Volvo East Asia

Quotation Preview

	Cust.	850940
Volvo East Asia (Pte) Ltd		MSIG INSURANCE (SINGAPORE) PTE LTD
12 TUAS AVENUE 10		4 SHENTON WAY #21-01 SGX CENTRE
Singapore		Singapore
639136		068807

Singapore

SINGAPORE

No.	Quotation No.	13006186	Veh.ty	FM11 64R
Date	05/12/2017	Order Dt.	30/11/2017	Chassis/SL No.
Expiry Dt	05/12/2017	Mil.	257880	Make
		Regn.		00 - VTC
		Req. Delv. Dt		XD9323D
		CustRef.		

Payment Desc	90Days	Payment Due Date	05/03/2018
		Tot Amt	18,426.47
		Total Amount In	SGD 18,426.47

Description of PC 40-Insurance - VO

Authorizing Signature : _____ PO Number : _____

Resue
Up 90010068
7 days
P/P
05/12/17 @ 1620
Resue 64 part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
6/12/17

Volvo East Asia

Insurance - VO Trial Invoice

Cust.

850940

MSIG INSURANCE (SINGAPORE) PTE LTD

Volvo East Asia (Pte) Ltd

12 TUAS AVENUE 10

4 SHENTON WAY #21-01
SGX CENTRE

Singapore

Singapore

639136

068807

SINGAPORE

Singapore

Invoice No.

Ord.No.

14024659

Veh.ty

FM11 64R

Invoice Date

21/03/2018

Order Dt.

06/12/2017

Chassis/SL No.

A-750842

Mil.

257880

Make

00 - VTC

Req. Delv. Dt

06/12/2017

Regn.

XD9323D

GST Number

M2-0033544-9

CustRef.

Payment Desc

90Days

Payment Due Date

19/06/2018

PC

Lab/Part

Description

Time/Qty

Price

GST

Amt

40	VO	82446221	CARRIER RAIL	1.00	466.00	7.00	466.00
40	VO	82348988	PANEL	1.00	27.00	7.00	27.00
40	VO	82266433	BUMPER	1.00	196.00	7.00	196.00
40	VO	20398135	HINGE	1.00	113.00	7.00	113.00
40	VO	20360849	DOOR FRAMEWORK, L.H.	1.00	2,133.00	7.00	2,133.00
40	VO	20573937	SEALING MOULDING	1.00	101.00	7.00	101.00
40	VO	82472612	COVER	2.00	20.00	7.00	40.00
40	VO	82471689	HOUSING	1.00	90.00	7.00	90.00
40	VO	82440900	RUBBER SPACER	2.00	4.00	7.00	8.00
40	VO	82417286	ARM	1.00	267.00	7.00	267.00
40	VO	82417045	TRIM FRAME	1.00	24.00	7.00	24.00
40	VO	82417044	GLASS	1.00	103.00	7.00	103.00
40	VO	82417042	TRIM FRAME	1.00	28.00	7.00	28.00
40	VO	82417041	GLASS	1.00	110.00	7.00	110.00
40	VO	994787	SIX POINT SOCKET S	4.00	1.00	7.00	4.00

Volvo East Asia

Insurance - VO Trial Invoice

Cust.

850940

MSIG INSURANCE (SINGAPORE) PTE LTD

Volvo East Asia (Pte) Ltd
12 TUAS AVENUE 10

4 SHENTON WAY #21-01
SGX CENTRE

Singapore
639136

Singapore
068807

SINGAPORE

Singapore					
Invoice No.		Ord.No.	14024659	Veh.ty	FM11 64R
Invoice Date	21/03/2018	Order Dt.	06/12/2017	Chassis/SL No.	A-750842
		Mil.	257880	Make	00 - VTC
		Req. Delv. Dt	06/12/2017	Regn.	XD9323D

GST Number M2-0033544-9

CustRef.

Payment Desc	90Days	Payment Due Date	19/06/2018	
40 VO 993124 SPRING NUT	2.00	1.00	7.00	2.00
40 VO 977166 SIX POINT SOCKET SCREW	2.00	1.00	7.00	2.00
40 VO 975357 SIX POINT SOCKET S	6.00	3.00	7.00	18.00
40 VO 84139937 DIRECTION INDICATO	1.00	81.00	7.00	81.00
40 VO 82475899 SHIELD	1.00	85.00	7.00	85.00
40 VO 82428868 CONCEALING PANEL	1.00	86.00	7.00	86.00
40 VO 82426817 LAMP	1.00	345.00	7.00	345.00
40 VO 82423778 BRACKET	1.00	249.00	7.00	249.00
40 VO 82375520 BRACKET	1.00	20.00	7.00	20.00
40 VO 82364738 BRACKET	1.00	28.00	7.00	28.00
40 VO 82335280 CAP	1.00	10.00	7.00	10.00
40 VO 82266415 COVER PLATE	1.00	173.00	7.00	173.00
40 VO 82266039 PROTECTION	1.00	206.00	7.00	206.00
40 VO 21448885 COWL	1.00	30.00	7.00	30.00
40 VO 21404042 HEADLAMP HOUSING	1.00	135.00	7.00	135.00
40 VO 20529638 FOOT STEP	1.00	141.00	7.00	141.00

Volvo East Asia

Insurance - VO Trial Invoice

Cust.

850940

MSIG INSURANCE (SINGAPORE) PTE LTD

Volvo East Asia (Pte) Ltd

12 TUAS AVENUE 10

4 SHENTON WAY #21-01
SGX CENTRE

Singapore

639136

Singapore

068807

SINGAPORE

Singapore							
Invoice No.		Ord.No.	14024659	Veh.ty		FM11 64R	
Invoice Date	21/03/2018	Order Dt.	06/12/2017	Chassis/SL No.		A-750842	
		Mil.	257880	Make		00 - VTC	
		Req. Delv. Dt	06/12/2017	Regn.		XD9323D	
				CustRef.			

GST Number M2-0033544-9

Payment Desc	90Days			Payment Due Date	19/06/2018	
40 VO 82266404	GRATING	1.00	252.00	7.00	252.00	
40 VO 20379171	PANEL	1.00	250.00	7.00	250.00	
40 12345	Towing Charges	1.00		7.00	500.00	
40 12345	To dismantle & replace damage parts & transfer all LH door & glass mechanism to new door	1.00		7.00	1,800.00	
40 12345	To panel beat, jack & re-align LH door pillar	1.00		7.00	600.00	
40 12345	To spray paint on replaced parts & affected areas	1.00		7.00	2,400.00	
40 VO 930760	EXPANDING NUT	2.00	7.00	7.00	14.00	MC
40 VO 82471690	HOUSING	1.00	104.00	7.00	104.00	
40 VO 82403557	COVER	1.00	19.00	7.00	19.00	CM
40 VO 20425414	LOCK	1.00	63.00	7.00	63.00	PA
40 VO 20398256	BRACKET	1.00	23.00	7.00	23.00	MC

Document Information Lines

Total Parts Cost

6,046.00

Total Others Cost

5,300.00

Sub Total

11,346.00

7.00 % GST

794.22

Volvo East Asia

Insurance - VO Trial Invoice

Cust.

850940

MSIG INSURANCE (SINGAPORE) PTE LTD

Volvo East Asia (Pte) Ltd

12 TUAS AVENUE 10

4 SHENTON WAY #21-01
SGX CENTRE

Singapore

Singapore

639136

068807

SINGAPORE

Singapore

Invoice No.

Invoice Date

21/03/2018

Ord.No.

Order Dt.

Mil.

Req. Delv. Dt

14024659

06/12/2017

257880

06/12/2017

Veh.ty

Chassis/SL No.

Make

Regn.

CustRef.

FM11 64R

A-750842

00 - VTC

XD9323D

GST Number

M2-0033544-9

Payment Desc

90Days

Payment Due Date

19/06/2018

Gross Total

12,140.22

Advance

0.00

Tot Amt

12,140.22

Total Amount In

SGD

12,140.22

Description of PC

40-Insurance - VO

This is a computer generated document. No signature required
Any discrepancies regarding this invoice should be lodged within 7 days. Payment Instruction :-
Payable To : - Volvo East Asia (Pte) Ltd
Account No : 0-810706-007 (SGD)
Bank Name : CITIBANK , N.A
Swift Code : CITISGSG
Branch Code : 001
Bank Code : 7214

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023040/R1QBN2
Date: 30/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29035476MKF
Claimant:	XD9323D	Insured Vehicle No:	GBF4823K
Vehicle No:		Nature of Claim:	TP
Date of Loss:	29/11/2017	Claim No:	539099

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD9323D	Engine No:	D11300019
Make & Model:	VOLVO FMX37064R, 10.8 D SLEEPER CAB (M)	Chassis No:	YV2J1E1D7DA750842
Reg. Date:	01/07/2014 (Man. Year: 2013)	Odometer:	284624 km
Colour:	Red		
Engine Capacity:	10837 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D)
Front Left Side:	West Lake 8 mm	Rear Left Side:	West Lake 8/8 mm
Front Right Side:	West Lake 8 mm	Rear Right Side:	West Lake 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,140.00	6,046.00	4,094.00	40.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,200.00	5,300.00	1,900.00	26.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,340.00	11,346.00	5,994.00	34.57
+ GST 7.00/7.00% (S\$)	1,213.80	794.22	419.58	34.57
Nett Amount (S\$)	18,553.80	12,140.22	6,413.58	34.57

INSPECTION

Date of Assignment:	05/12/2017	
Date Inspected:	05/12/2017	Inspected At: Volvo East Asia (pte) Ltd - Tuas (HQ) 12 Tuas Avenue 10 Singapore 639136

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Apr 2018)	
Parts:	N/A	VOLVO FMX37064R 10.8 D SLEEPER CAB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD9323D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER	Serviceable	2,542.00 F	*- F
2	1		*CARRIER RAIL	Bent	466.00 F	*466.00 F
3	1		*PANEL	Deformed	27.00 F	*27.00 F
4	1		*BUMPER	Bent	196.00 F	*196.00 F
5	1		*HINGE	Bent	113.00 F	*113.00 F
6	1		*HINGE	Serviceable	113.00 F	*- F
7	1		*DOOR FRAMEWORK,LH	Bent	2,133.00 F	*2,133.00 F
8	1		*SEALING MOULDING	Necessary	101.00 F	*101.00 F
9	2		*COVER	Missing	40.00 F	*40.00 F
10	1		*HOUSING	Missing	104.00 F	*104.00 F
11	1		*HOUSING	Missing	90.00 F	*90.00 F
12	2		*RUBBER SPACER	Missing	8.00 F	*8.00 F
13	1		*ARM	Missing	267.00 F	*267.00 F
14	1		*TRIM FRAME	Missing	24.00 F	*24.00 F
15	1		*GLASS	Missing	103.00 F	*103.00 F
16	1		*TRIM FRAME	Missing	28.00 F	*28.00 F
17	1		*GLASS	Missing	110.00 F	*110.00 F
18	4		*SIX POINT SOCKET S	Necessary	4.00 F	*4.00 F
19	2		*SPRING NUT	Necessary	2.00 F	*2.00 F
20	2		*SIX POINT SOCKET SCREW	Necessary	2.00 F	*2.00 F
21	6		*SIX POINT SOCKET S	Necessary	18.00 F	*18.00 F
22	1		*DIRECTION INDICATO	Broken	81.00 F	*81.00 F
23	1		*SHIELD	Cracked	85.00 F	*85.00 F
24	1		*CONCEALING PANEL	Cracked	86.00 F	*86.00 F
25	1		*HEADLAMP	Serviceable	197.00 F	*- F
26	1		*LAMP	Broken	345.00 F	*345.00 F
27	1		*BRACKET	Cracked	249.00 F	*249.00 F
28	1		*BRACKET	Necessary	20.00 F	*20.00 F
29	1		*BRACKET	Necessary	28.00 F	*28.00 F
30	1		*CAP	Missing	10.00 F	*10.00 F
31	1		*HEADLAMP	Serviceable	106.00 F	*- F
32	1		*COVER PLATE	Cracked	173.00 F	*173.00 F
33	1		*PROTECTION	Cracked	206.00 F	*206.00 F
34	1		*INDICATOR LAMP	Serviceable	58.00 F	*- F
35	1		*COWL	Missing	30.00 F	*30.00 F
36	1		*WIRES	Serviceable	65.00 F	*- F
37	1		*HEADLAMP HOUSING	Cracked	135.00 F	*135.00 F
38	2		*GASKET	Serviceable	66.00 F	*- F
39	2		*RUBBER EXPANDER	Serviceable	6.00 F	*- F
40	1		*HAND PUMP	Serviceable	736.00 F	*- F
41	1		*FOOT STEP	Bent	141.00 F	*141.00 F
42	1		*GRATING	Cracked	252.00 F	*252.00 F
43	1		*PANEL	Serviceable	205.00 F	*- F
44	1		*PANEL	Bent	250.00 F	*250.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*EXPANDING NUT	Necessary	14.00 F	*14.00 F
46	1		*COVER	Cracked	19.00 F	*19.00 F
47	1		*LOCK	Bent	63.00 F	*63.00 F
48	1		*BRACKET	Necessary	23.00 F	*23.00 F
F=Franchise part.						
				Total Parts (S\$)	10,140.00	6,046.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES	New	600.00	500.00
2	TO DISMANTLE & REPLACE DAMAGE PARTS & TRANSFER ALL LH DOOR & GLASS MECHANISM TO NEW DOOR	New	2,400.00	1,800.00
3	TO PANEL BEAT,JACK & RE-ALIGN LH DOOR PILLAR	New	1,200.00	600.00
4	TO SPRAY PAINT ON REPLACED PARTS & AFFECTED AREAS	New	3,000.00	2,400.00
Gross Labour Cost (S\$)			7,200.00	5,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >