

ASS. REC. BY:

REF: CS/FCI/7023048/Gvb2

Special Instruction:

Survivor:

CWS

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

12:14pm @ 5/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGR 5889S

Insured:

SHD 3136G

at Workshop m/s

Siang Hai Motor

Tel:

65557272

of

1 Kaki Bukit Ave 6 # 02-03

Policy No:

Claim No:

D1701198MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

12:27pm @ 5/12/17

Person Contacted:

Ah Huat

Vehicle:

IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SGR 5889S - X

SHD 3136G - CC3/AIG/12010.333/H161g2g2 - D.O.A: 20/05/2012

11/12/17

Informed FCI pending workshop est by email

15/5/18

@ 3:53pm Ah Huat will fax us the estimate

Signature: Xael

REF: Fci

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To inspect Vehicle No: _____
 at Workshop m/s Siong Hai Motor
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$29k.
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGR 5889 S Yr Regn: 12 Feb 07
 Type: C M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Toyota Altis cc 1598
 Colour: Grey A/C Insured / Std / NI / NA
 Sp. Reading: 305742 T. Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: MR053 ZEC 107 / 40202
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: C In order / Jammed / Leaked / Burnt or
 Brake: C In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD C A/Rim or

Tyre Size: F: 185 / 70 R 14
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. _____		D.O.I. <u>05-12-17</u>

Survey held at W/S 11AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S FR

The C U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction (LS)
08/4/19 Finalized \$1050 with Hunt. (Ref 5738.40, 841)
mv: \$29k (EST) LTA: \$19,379 (EST) NV: \$ 9721

15/4/19 Email preli revised to FCI

RECEIVED 16 APR 2019

Date/Time File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

Date/Time File Return to?
15/4. typist

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Techn. Insp \$
☐ Weekend \$

Report Format: CWS
 Lump Sum / I.B.I: 1050/-

Survey Fee	145
Transportation	50
	50
	62
TOTAL	307



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023048/Gvb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 05-12-2017

Code : FCI2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3136G	Veh. Inspected	SGR 5889S
Policy No.		Coverage (\$)	0.00
Claim No.	D17011198MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	05/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	04/12/2017	Inspection Date	05/12/2017
Survey held at	SIONG HAI MOTOR WORKSHOP 1 KAKI BUKIT AVENUE 6 # 02-03 AUTOBAY SINGAPORE 417883.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17011198MFSH

Our ref: CS/FCI17023048/Gvb

Date: 15/4/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LIMITED

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGR 5889S


We thank you for your instruction on 5/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 5/12/2017 at the premises of M/s SIONG HAI MOTOR & TRADING and have the following to report:-

Workshop Estimate Amount	:S\$6,788.40
Revised Estimate Amount	:S\$1,050.00 (LUMP SUM)
"Check" Items Amount	:S\$
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion. The undercarriage affected due to collision



Comments/Present Status:

Damages Consistent

Yours faithfully,

XING GUO QIANG (HP 8288 0282)

M.MATAL, AMSAE-A

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-12-2017	Our Ref No. D17011198MFSH
Accident Date	04-12-2017	Claim Type. Third Party
Insured Vehicle	SHD3136G	Third Party Vehicle. SGR5889S
Survey Location	1 Kaki Bukit Avenue 6 #02-03 Autobay	
Contact Person.	MR AH HUAT	
Contact No.	65557272/ 65557272	Fax No. 0
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIONG HAI MOTOR & TRADING	Attention. NIL
Cc : TP Solicitor	HIN TAT AUGUSTINE & PARTNERS	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231442)



PRI Documents



Close



PRI Header Details

Claim No	D17011198MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & HIN TAT A
Workshop Name	SIONG HAI MOTOR & TRADING (Contact Person : MR AH HUAT)	Survey Location & Contact Details	1 Kaki Bukit Avenue 6 #02-03 Autobay Mobile: 65557272 , Phone: 65557272 , Fax: 0 EmailId: RUBY@HTAPARTNERS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3136G	TP Vehicle No	SGR5889S
PRI Recieved Date	04-12-2017 10:22:05 PM	Surveyor Appointed Date	05-12-2017 12:13:06 PM	Surveyor Accept Date	05-12-2017 1.

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 15 April 2019 11:53 AM
To: 'Claim Workflow System'
Cc: 'KARENTAN@FIRST-INSURANCE.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D17011198MFSH/1,SGR 5889S
Attachments: SGR 5889S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGR 5889S
Date of survey: 5/12/2017
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 11 December 2017 9:54 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011198MFSH/1,SGR 5889S

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGR 5889S on 5/12/2017.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 5 December, 2017 12:29 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011198MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 5 December, 2017 12:13 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; KARENTAN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011198MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 11 December, 2017 9:53 AM
To: 'Claim Workflow System'
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011198MFSH/1,SGR 5889S

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGR 5889S on 5/12/2017.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 5 December, 2017 12:29 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011198MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 5 December, 2017 12:13 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; KARENTAN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011198MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1860C
Vehicle Details	
Vehicle No.:	SGR58895
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	3ZZ4627739
Chassis No.:	MR053ZEC107140202
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,355.00
Original Registration Date:	12 Feb 2007
First Registration Date:	12 Feb 2007
Transfer Count:	1
Actual ARF Paid:	\$16,891.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,197.00
COE Rebate Amount:	\$14,240.00
Total Rebate Amount:	\$14,240.00 - 19279
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Apr 2019

OK

SIONG HAI MOTOR & TRADING

No. 1 Kaki Bukit Avenue 6, #02-03 (Autobay), Singapore 417883

06/12/2017

TEL: 65557272

H/P: 93365311 (Ah Huat)

Vehicle No:SGR5889S

Model:Corolla Altis

QTY**List Items****Prices \$**

1	Front bumper	de	389	486.6	—
1	Front bumper L/H retainer	MC	249	58.5	—
1	Front bumper reformant	X		296.5	
1	Front support panel	X		857.2	
1	Front L/H side headlamp	sub	375.2	595.8	—
1	Front L/H side fender	X repair		422.6	
1	Front L/H side fender inner shield	X		139.5	
1	Front L/H side shock absorber	X		259.6	
1	Front L/H side lower arm	X		276.2	
1	Front L/H side knuckle arm	X		\$389	
1	Front L/H side knuckle bearing	X		195.8	
1	Front L/H side door mirror			487.6	

Total 4464.4 789.1
 Less 25% 1117.4
 \$3,348.40 591.83

Nett Items

1	Front L/H tyre			500	
1	Front L/H sport rim	X NN		950	
1	Front bumper clip	MC	30	45	—
1	Front L/H fender shield clip	X NN		45	

\$1,540**Labour Charge**

To check wheel alignment	NN 100	X
To remove,refix,replaced damaged lamps and check up front electrical wiring	30	100
To apply undercoating on repaired parts	NN 250	X
To respray painting and polishing	400	650
To provide labour charges,workmanship to dismantle above damaged parts,repair including cuts and weld fender	300	800
realign body structure	730	

\$1,900

67

ESTIMATED PARTS AND LABOUR GRAND TOTAL \$\$**\$6,788.40**

1351.83
 20% 1050
 3 Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023048/Gvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3136G	Veh. Inspected	SGR 5889S	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011198MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	05/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053ZEC107140202	Colour	GREY	
Odometer	305792	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	FALKEN	6 mm	
L/H Front Tyre	185/70 R14	FALKEN	6 mm	
R/H Rear Tyre	185/70 R14	FALKEN	6 mm	
L/H Rear Tyre	185/70 R14	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/12/2017	Inspection Date	05/12/2017	
Survey held at	SIONG HAI MOTOR WORKSHOP 1 KAKI BUKIT AVENUE 6 # 02-03 AUTOBAY SINGAPORE 417883.			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 5889S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	486.60	389.00
1	FRONT BUMPER L/H RETAINER	NECESSARY	58.50	24.90
1	FRONT BUMPER REFORMENT	NOT NECESSARY	296.50	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	857.20	-
1	FRONT L/H SIDE HEADLAMP	SCRATCHED	595.80	375.20
1	FRONT L/H SIDE FENDER	TO REPAIR SEE LABOUR	422.60	-
1	FRONT L/H SIDE FENDER INNER SHIELD	NOT NECESSARY	139.50	-
1	FRONT L/H SIDE SHOCK ABSORBER	NOT NECESSARY	259.60	-
1	FRONT L/H SIDE LOWER ARM	NOT NECESSARY	276.20	-
1	FRONT L/H SIDE KNUCKLE ARM	NOT NECESSARY	389.00	-
1	FRONT L/H SIDE KNUCKLE BEARING	NOT NECESSARY	195.80	-
1	FRONT L/H SIDE DOOR MIRROR	NOT NECESSARY	487.60	-
	LESS 25% DISCOUNT		-1,116.23	-197.28
			3,348.67	591.82
SPECIAL NETT ITEMS				
1	FRONT L/H TYRE (SN)	NOT NECESSARY	500.00	-
1	FRONT L/H SPORT RIM (SN)	NOT NECESSARY	950.00	-
1	FRONT BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	FRONT L/H FENDER SHIELD CLIP (SN)	NOT NECESSARY	45.00	-
			1,540.00	30.00
LABOUR				
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO REMOVE,REFIX,REPLACED DAMAGED LAMPS AND CHECK UP FRONT ELECTRICAL WIRING.		100.00	30.00
	TO APPLY UNDERCOATING ON REPAIRED PARTS.	NOT NECESSARY	250.00	-
	TO RESPRAY PAINTING AND POLISHING.		650.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUTS AND WELD FENDER REALIGN BODY STRUCTURE. INCLUSIVE OF THE REPAIR OF FRONT L/H SIDE FENDER.		800.00	300.00
			1,900.00	730.00
GRAND TOTAL			6,788.67	1,351.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,050.00

Report Ref No. CS/FC117023048/Gvbn2

MARKET VALUE: \$29,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$19,279.00=NETT VALUE: \$9,721.00

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.