

22/03/2002

ASS. REC. BY:

REF: CS/CTI17023052/Kvb2

Special Instruction:

SURVIVOR:
MentmenASSIGNMENT (Office)

From (Person):

Jouny Tay

of

CTI

Date/Time:

5/12/17 @ 11:25am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFT 818 G

Insured:

XD 52012

at Workshop m/s

Cheng Hoe Motor

Tel:

6755 6142

of

Blk 1019 # 81-374 / 382 Yishun Ind. Prk A

Policy No:

DMCVSN1662491600

Claim No:

SNM17D06342C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/09/17

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:29 pm 05/12/17

Person Contacted:

Sharon

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SFT 818 G - CS/UCI12623907/Avn

D.O.A. 5/11/2012

XD 52012 - CC3/CTI17021333/Kwb3

D.O.A. 4/11/2017

22/12 11:50 AM Confirm E.Hol. (Rec 346.10, 239)

ASS. REC. BY:

REF:

CT21

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ 04 days Res.: Yes or No

Lum Sum: _____ 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 31-7 8186 Yr Regn: 03, 14Type: M.Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: 707 NISSAN c.c. 1500Colour: Black A/C: Insured / Std / NI / NASp. Reading: 94720 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053REH104001892Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 12/11/17 D.O.I. 12/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/12 File pass to Citylink

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 23/12 - 14pm

Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Report Format:

merimen

Lump Sum / I.B.I. (\$) 1150

TOTAL

220

Survey Department Check List (Case Handler)

Reference No. : CS | CTI 17023052 | Kvb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

| (1) Office Assign Form | | Y-Date | N-Date | Y-Date | N-Date |
|------------------------|---------------------------------------|--------|--------|--------|--------|
| C | Reference No. | ✓ | | | |
| C | Customer Code | | | | |
| N | Assign From | | | | |
| C | Assign Date | ✓ | | | |
| C | Veh No (Inspected) | ✓ | | | |
| C | Veh No (Insured) | ✓ | | | |
| C | D.O.A | ✓ | | | |
| C | Policy No | ✓ | | | |
| C | Claim No | ✓ | | | |
| C | Insurance Authorisation (CA /REV/REP) | | | | |
| C | Report Type | ✓ | | | |
| C | Weekend Charges | | | | |
| N | Survey held at/Repairer | ✓ | | | |
| C | Excess | | | | |

Surveyor (): Case handler to make sure the surveyor completed all required information.

| (1) Assignment Form | | Y-Date | N-Date | Y-Date | N-Date |
|---------------------|------------------------|--------|--------|--------|--------|
| C | Vehicle No | ✓ | | | |
| C | Regn Month/Year | ✓ | | | |
| N | Vehicle Type | ✓ | | | |
| N | Make & Model | ✓ | | | |
| C | Engine Capacity. (C.C) | ✓ | | | |
| N | Colour | ✓ | | | |
| C | Odometer. (Sp.Reading) | ✓ | | | |
| C | Chassis No | ✓ | | | |
| N | General Condition | ✓ | | | |
| N | Steering | ✓ | | | |
| N | Brake | ✓ | | | |
| N | Modification (Modi) | ✓ | | | |
| C | Tyre Size | ✓ | | | |
| N | Tyre Make | ✓ | | | |
| C | Tyre Balance | ✓ | | | |
| C | Date of Inspection | ✓ | | | |
| N | Survey held | ✓ | | | |
| N | Des.of Damages | ✓ | | | |

(2) System - (Views/Merimen)

| | | | | | |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ | | | |
|---|--------------------------------------|---|--|--|--|

(3) Workshop Estimate/Assignment Form

| | | | | | |
|---|---|---|--|--|--|
| N | ALL Parts condition | ✓ | | | |
| C | Market Value for OD cases | | | | |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) | | | | |
| C | Days of repair | ✓ | | | |
| C | Finalised Amount | ✓ | | | |
| C | Re-inspection Cases to Finalize within 5 Days | | | | |

(4) System - (Views/Merimen)

| | | | | | |
|---|-------------------------|---|--|--|--|
| C | Resurvey photo Uploaded | ✓ | | | |
|---|-------------------------|---|--|--|--|

Check By: VERON 23/2/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17023052/Kvb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 05-12-2017



Code : CTI

1. Policy Particulars : THIRD PARTY CLAIM

| | | | |
|--------------|---------------------|----------------|------------|
| Insured Veh. | XD 5201Z | Veh. Inspected | SFT 818G |
| Policy No. | DMCVSN1662491600 | Coverage (\$) | 0.00 |
| Claim No. | SNM17D06342C02 | Excess (\$) | 0.00 |
| Assign From | MERIMEN (JOWYN TAY) | Assign Date | 05/12/2017 |

2. Vehicle Particulars & Condition

| | | |
|--------------|--------|--------------|
| Make & Model | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. |
| Chassis No. | | Colour |
| Odometer | | Steering |
| Brakes | | Modification |
| General | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| | |
|--|--|
| | |
|--|--|

5. General Information

| | | | | |
|----------------|--|---------------|------------|-----------------|
| Engine No. | HIDDEN | Accident Date | 12/09/2017 | Inspection Date |
| Survey held at | CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761 | | | |

5a. Remarks

| |
|--|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. |
| B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| | | | | |
|------|-----------------------------|-------------------------------------|--------------------------------|-------------------------------|
| Main | 01 Dec 2017 Sendback Est | 01 Dec 2017 13:12 S\$1,496.10 | 05 Dec 2017 11:25 Assign | New Assignment Cancel Case |
|------|-----------------------------|-------------------------------------|--------------------------------|-------------------------------|

| | | | | |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

CLAIM SUBFOLDER DETAILS

| | | | |
|-----------------------------|---|------------------------|------------------------|
| Insured: | HOCK TRADING & TRANSPORTATION PTE LTD, Co. Reg. No.: 20137545E | | |
| Main Claimant: | THIAN CHEE SIANG, ID: S1519529 | | |
| Vehicle Reg. No.: | SFT818G | Date of Loss: | 12/09/2017 14:00 - :59 |
| Claim Type: | TP / SNM17D06342C02 | Policy/Cover Note No.: | DMCVSN1662491600 |
| Vehicle Reg. No. (Insured): | XD5201Z | Policy No. (Claimant): | |
| | | Excess: | S\$0.00 |
| Repairer: | Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142 | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/12/2017] | | |
| | | Vehicle Source: | Drive/Walk-in |
| Adj Asg. Remarks: | PLEASE PROCEED TO SURVEY AND ARRANGE FOR DIRECT SETTLEMENT. | | |

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail


There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|

No results.


[Feedback](#) | [Contact Info](#)

Text size + -



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9529J

Vehicle Details

Vehicle No.: SFT818G

Vehicle to be Exported: Yes

Intended De-registration
Date: 12 Sep 2017

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA COROLLA ALTIS 1.6L CVT

Primary Colour: Black

Manufacturing Year: 2014

Engine No.: 1ZRX398374

Chassis No.: MR053REH104001892

Maximum Power
Output: 90.0 kW (120 bhp)

Open Market Value: \$18,544.00

Original Registration
Date: 26 Mar 2014

First Registration Date: 26 Mar 2014

Transfer Count: 0

Actual ARF Paid: \$13,544.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 25 Mar 2024

PARF Rebate Amount: \$10,158.00

Intended COE Rebate Details

COE Expiry Date: 25 Mar 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$71,564.00

COE Rebate Amount: \$46,766.00

Total Rebate Amount: \$56,924.00

The information contained herein is correct as at 12 Sep 2017

OK



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------|
| Date Of Report | 13/09/2017 18:11 |
| Date Of Accident | 12/09/2017 14:15 |
| Exact Location Of Accident | SIMS WAY |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SFT818G |
| Insured/Policyholder | |
| Name Of Registered Owner | THIAN CHEE SIANG |
| NRIC No | S1519529J |
| Email Address | JTHIAN@SINGNET.COM.SG |
| Mobile Phone No | (LOCAL) +65-98330504 |
| Alternative Phone No | OTHERS-98330504 |

Vehicle Particulars

| | |
|--|-------------|
| Manufacturer | TOYOTA |
| Model | ALTIS |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|-------------------------------|
| Name of Insurance Company | UNITED OVERSEAS INSURANCE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DHOM110141591502 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | THIAN CHEE SIANG |
| NRIC No | S1519529J |
| Date Of Birth | 23/06/1962 |
| Occupation | INDOOR |
| Date Of Driving Pass | 17/07/1984 |
| Driving Experience | 33 YEARS AND 1 MONTH |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-98330504 |
| Fax Number | |
| Contact Number | OTHERS-98330504 |
| Email Address | JTHIAN@SINGNET.COM.SG |

Describe Circumstances of the Accident

Refer to Police Report .
T 12070912 / 2158

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel



SINGAPORE POLICE FORCE



T/20170912/2158

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 3

Report No. T/20170912/2158

REPORT OF A TRAFFIC ACCIDENT

| | | | | |
|--|------------|--|------------------------------|---------------------------|
| Date/Time Report Made: 12/09/2017 21:42 | | Vide Report No.: | | Station Diary No.: 100 |
| Informant's Particulars | | | | |
| Name of Informant: THIAN CHEE SIANG | | Address: APT BLK 110A PUNGGOL FIELD #12-562 SINGAPORE 821110 | | |
| ID Type / ID No.: NRIC NO / S1519529J | | Contact No.: Home/Office: Mobile: 98330504 | | |
| Nationality: SINGAPORE CITIZEN | | Email: | | |
| Sex: Male | Age: 55 | Date of Birth: 23/06/1962 | Type of Informant: Driver | |
| Race: Chinese | | Language: | Institution / School Name: | |
| Occupation: ENGINEER at SINGTEL Limited | | Driving Licence Information: Class: 2B,3 Date of Expiry: | | |

| | | | | |
|---|---------------------------|---|--|-------------------------------------|
| General Information of the Accident | | | | |
| Type of Accident: | Non-Injury Hit and Run | Drink Drive: No | Date/Time of Accident: 12/09/2017 14:15 | Type of Location: Straight Road |
| Location: Along Road 1 Traveling Toward Road 2 SIMS WAY CENTRAL EXPRESSWAY | | | | |
| Weather: Sunny | | Road Surface: Dry | | Road Speed Limit: |
| Traffic Flow: One Way | | Traffic Control: Traffic Light - Working | | Traffic Volume: Heavy |
| Type of Collision: Between Moving Vehicles - Head To Side | | | | Anyone conveyed by ambulance: No |

| Details of Vehicle Involved | | | | | | |
|------------------------------------|-------|--------|--|-------|---------------------|-----------------|
| Vehicle No | Type | Make | Model | Color | Condition | No of Passenger |
| SFT818G | Car | TOYOTA | TOYOTA COROLLA ALTIS 1.6L CVT | Black | Slightly Damaged | 1 |
| XD5201Z | Lorry | | | | Slightly Damaged | 0 |

| Details of Vehicle Insurance | | | | |
|-------------------------------------|-------------------|--------------|-----------|-------------|
| Vehicle No | Insurance Company | Insurance No | Effective | Expiry Date |



**SINGAPORE
POLICE FORCE**



T/20170912/2158

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 3

Report No. T/20170912/2158

CONTINUATION OF REPORT

| Details of Vehicle Insurance | | | | |
|------------------------------|-----------------------------------|------------------|------------|-------------|
| Vehicle No | Insurance Company | Insurance No | Effective | Expiry Date |
| SFT818G | UNITED OVERSEAS INSURANCE LIMITED | DHOM110141591502 | 26/03/2017 | 25/03/2018 |

Brief Details.

On the 12/09/2017 at about 1417hrs, I was driving along Sims Way towards CTE via PIE in my car bearing registration plate number SFT818G on the second lane. Right behind me on the first lane was a blue in colour lorry bearing registration plate number XD5201Z.

Subsequently, I passed Sims Avenue junction and was on the first lane when I felt an impact on the right side of my vehicle. I turned and saw the above mentioned lorry hit the right side of my car. I immediately horn my car, slowed down and keep left. I was expecting the lorry driver to stop and take a look to the situation however he did not do so. I start to chase after the lorry. However, due to heavy traffic condition, I did not pursue the lorry.

I would like to state that I have one car camera installed on the front and back of my car. I have retrieved the footage and it is ready to be viewed. I would like to further add that no body is injured and the right side passenger door was damaged. This report was made for the purpose of car insurance claim and necessary action.

Sketch Plan #3 Pg. 1

Thian Chee Siang
S1519529-J
Blk 110A #12-562 Punggol Field
Singapore 821110
Mobile : 9833 0504


Dear Sirs / Madam,

Re: Police Report for Hit and Run Car Accident to Vehicle Number SFT 818G on 12 September 2017

I would like to make a police report regards to a hit and run car accident which was happen today, 12 September 2017 @ 1417hrs. Location was along Sims Way heading to PIE, after the junction of Sims Avenue.

On 12 September 2017 @ 1400hrs, I drove my vehicle SFT818G from Mounbatten travel along Sims Way heading towards CTE via PIE intentionally. The only passenger on board is my spouse, Eng Siew Hwei. She was sitting next to me with safety belt fasten.
At around 1417hrs, I was along Sims Way with car speed 50 km/h. Just right after Sims Avenue junction, I felt an impact on the right side of my vehicle. I turn over my head and saw a huge lorry just next to me. I pressed horn to alert the lorry driver and meanwhile slow down speed and keep left. I was expecting lorry driver will stop and take a look to the situation but was not.
I start to chase after the lorry. However, due to heavy traffic and consider to road safety. Overtake was unsuccessful. I only can read out loud and asked my wife to write down lorry number XD52012. In blue colour. Fortunate I have car cam installed and retrieved MP4 clip for an evidence.

No body injury in this accident. My vehicle SFT 818G right side passenger door damage.
This report was made for the purpose of Car Insurance claimant and necessary action.



Attached Car Cam for reference.

Yours faithfully,

Thian Chee Saing

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chnmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
 HOCK TRADING & TRANSPORTATION PTE LTD

Singapore

PARTICULARS OF CLAIM

| | | | |
|-------------------|------------------|---------------|------------|
| Claim Type: | THIRD PARTY | Ref. No: | TP-CHINA |
| Policy No: | | Date of Loss: | 12/09/2017 |
| Vehicle Reg. No.: | SFT818G | Driveable? | NO |
| Party At Fault: | UNKNOWN | | |
| Driver (TP): | THIAN CHEE SIANG | | |

| | | | |
|-----------------|-------------------------------|--------------------|-------------------|
| Make/Model: | TOYOTA COROLLA ALTIS, 1.6 (A) | Vehicle Reg. Date: | 26/03/2014 |
| Vehicle Colour: | BLACK | Gen Condition: | FAIR |
| Engine No: | 1ZR398374 | Chassis No: | MR053REH104001892 |
| Odometer: | 0 KM | | |

Not Authorised
11 Pgs 3?
Resolving After Repair
4 days

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) **0**

Remarks: VEHICLE LAYING AT YISHUN WORKSHOP

Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS

| | Amount |
|--------------------------|-----------------|
| Parts | 506.10 |
| Miscellaneous Items | 0.00 |
| Labour | 990.00 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| Gross Total (S\$) | 1,496.10 |
| + GST 7.00% (S\$) | 104.73 |
| Nett Amount (S\$) | 1,600.83 |

This claim is handled by: NG CHENG CHOO

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 01 Dec 2017)

Parts: 143 **TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SFT818G/01/12/2017 13:12

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

SFT818G

TP/CHINA

D.A: 12/9/17

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|---|-----|----------|-----------------------------|-------|-------|---------------|
| 1 | 1 | | *REAR RH DOOR | 0.00 | 0.00 | *450.00 F |
| 2 | 1 | | *REAR RH DOOR FRAME STICKER | 0.00 | 0.00 | *32.00 F |
| Sub Total (\$) | | | | | | 482.00 |
| + Margin on L,N Items 5.00% (\$) | | | | | | 24.10 |
| Total Parts (\$) | | | | | | 506.10 |

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SFT818G/01/12/2017 13:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|-------------------------------|--|----------|---------------|
| Labour Items | | | |
| 1 | REMOVE AND REFIX REAR RH DOOR, TRANSFER DOOR ATTACHMENT. TO KNOCK AND REPAIR REAR RH FENDER AND REALIGN THE SAME | New | 450.00 |
| 2 | PUTTY AND RESPRAY ON REAR RH FENDER, REAR RH DOOR | New | 450.00 |
| 3 | REMOVE AND REFIX REAR RH DOOR GLASS AND CHECK CENTRAL LOCKING AND POWER MIRROR | New | 60.00 |
| 4 | RUSTPROOFING | New | 30.00 |
| Gross Labour Cost (\$) | | | 990.00 |

Cheng Hoe Motor Pte Ltd/SFT818G/01/12/2017 13:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|---|--|--|--|--|------------|---|
| Main | 01 Dec 2017 Sendback Est | 01 Dec 2017 13:12 S\$1,496.10 | 05 Dec 2017 11:25 Edit Adj Rpt | S\$1,150.00 Edit Estimates | S\$1,150.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

CLAIM SUBFOLDER DETAILS

| | | | |
|-----------------------------|---|------------------------|------------------------|
| Insured: | HOCK TRADING & TRANSPORTATION PTE LTD , Co. Reg. No.: 20137545E | | |
| Main Claimant: | THIAN CHEE SIANG , ID: S1519529J | | |
| Vehicle Reg. No.: | SFT818G | Date of Loss: | 12/09/2017 14:00 - :59 |
| Claim Type: | TP / SNM17D06342C02 | Policy/Cover Note No.: | DMCVSN1662491600 |
| Vehicle Reg. No. (Insured): | XD5201Z | Policy No. (Claimant): | |
| | | Excess: | S\$0.00 |
| Repairer: | Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142 | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/12/2017] | | |
| | | Vehicle Source: | Drive/Walk-in |
| Adj Asg. Remarks: | PLEASE PROCEED TO SURVEY AND ARRANGE FOR DIRECT SETTLEMENT. | | |

ASSOCIATED MAIL RECEIVED

[View All](#) | [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) | [Search Tasks](#) | [Create New Task](#) | [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

SFT818G (SNM17D06342C02)
[XD5201Z]

TP

THIAN CHEE SIANG






Sep 12 2017 2:00PM

[HOCK TRADING & TRANSPORTATION PTE LTD]

Cheng Hoe Motor Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View [View in Browser](#) ▼

| Assessment Reports | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|-----------------|--|--|-------------------------------------|
| No | Finalized On | Cheng Hoe Motor Pte Ltd (Yishun) | Thumbnail | Print |
| 1 | 01/12/17 13:12 | Repairer Estimates |  Load HTM | |
| Photos/Images | | | 3 per page ▼ | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 14/12/17 11:51 | SURVEY PHOTOS |  Load PDF | |
| 2 | 23/02/18 12:13 | RESURVEY PHOTOS |  Load PDF | |
| Documentation | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
| No | Finalized On | Cheng Hoe Motor Pte Ltd (Yishun) | Thumbnail | Print |
| 1 | 01/12/17 13:08 | E-filed GIA report |  Load PDF | |
| No | Finalized On | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 05/12/17 11:25 | E-filed GIA report |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117023052/KVBE2

Date: 28/02/2018

REFERENCE

| | | | | | |
|-----------------------|---|----------------------|------------------|-----------|----------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSN1662491600 | | |
| Claimant Vehicle No : | SFT818G | Insured Vehicle No : | XD5201Z | | |
| Date of Loss: | 12/09/2017 | Nature of Claim: | TP | Claim No: | SNM17D06342C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | | |
|-----------------------------|-----------------------------------|--|-------------|-------------------|
| Reg No: | SFT818G | | Engine No: | 1ZRX398374 |
| Make & Model: | TOYOTA COROLLA ALTIS, 1.6 (A) | | Chassis No: | MR053REH104001892 |
| Reg. Date: | 26/03/2014 (Man. Year: 2014) | | Odometer: | 94720 km |
| Colour: | Metallic Black | | | |
| Engine Capacity: | 1598 cc | | | |
| Market Value/New Car Price: | N/A | | | |
| Sum Insured (S\$): | Market Value/New Car Price | | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition: | Fair | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Yokohama 7 mm | Rear Left Side: | Yokohama 7 mm |
| Front Right Side: | Yokohama 7 mm | Rear Right Side: | Yokohama 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|---------------|--------------|
| Parts | 506.10 | 506.10 | 0.00 | 0.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 990.00 | 940.00 | 50.00 | 5.05 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 1,496.10 | 1,446.10 | 50.00 | 3.34 |
| Approved Total (Overridden) (S\$) | | 1,150.00 | | |
| (S\$) | 1,496.10 | 1,150.00 | 346.10 | 23.13 |
| + GST 7.00/7.00% (S\$) | 104.73 | 80.50 | 24.23 | 23.14 |
| Nett Amount (S\$) | 1,600.83 | 1,230.50 | 370.33 | 23.13 |

INSPECTION

| | | | |
|-----------------------------|------------|-------------------|--|
| Date of Assignment: | 05/12/2017 | Present Location: | Cheng Hoe Motor Pte Ltd (Yishun) |
| Date Inspected: | 12/12/2017 | Inspected At: | Blk 1019 #01-374/382, Yishun Industrial Park A |
| Estimated Period of Repair: | 4.0 days | | Singapore 768761 |

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 28 Feb 2018)

Parts: 143 **TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: (Unsubmitted, no print-code for SFT818G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------|-----------|---|---------------------------|
| 1 | 1 | | *REAR RH DOOR | Bent | 450.00 F | *450.00 F |
| 2 | 1 | | *REAR RH DOOR FRAME STICKER | Necessary | 32.00 F | *32.00 F |
| | | | | | <hr/> | |
| | | | | | Sub Total (S\$) | 482.00 482.00 |
| | | | | | + Margin on L,N Items 5.00/5.00% (S\$) | 24.10 24.10 |
| | | | | | <hr/> | |
| | | | | | Total Parts (S\$) | 506.10 506.10 |
| | | | | | <hr/> | |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|---------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | REMOVE AND REFIX REAR RH DOOR, TRANSFER DOOR ATTACHMENT. TO KNOCK AND REPAIR REAR RH FENDER AND REALIGN THE SAME | New | 450.00 | 400.00 |
| 2 | PUTTY AND RESPRAY ON REAR RH FENDER, REAR RH DOOR | New | 450.00 | 450.00 |
| 3 | REMOVE AND REFIX REAR RH DOOR GLASS AND CHECK CENTRAL LOCKING AND POWER MIRROR | New | 60.00 | 60.00 |
| 4 | RUSTPROOFING | New | 30.00 | 30.00 |
| Gross Labour Cost (\$\$) | | | 990.00 | 940.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >