





NTUC I	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NS/INC17023061/Svbe2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	08-01-2018		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
Ir	nsured Veh.	FT 9299U	Veh. Ir	spected	SHB 268P	
Р	Policy No.	5093226624	Covera	age (\$)	0.00	
C	Claim No.	MT/0973267-001	Exces	s (\$)	0.00	
A	Assign From		Assigr	n Date	04/12/2017	
2. Vehicle Particulars & Condition						
N	/lake & Model	TOYOTA PRIUS	c.c		1798	
E	Engine No.	HIDDEN	Year o	f Reg.	2014	
C	Chassis No.	JTDKN36UX05746853	Colour	<u> </u>	MAROON	
C	Odometer	496406	Steerin	ng	IN ORDER	
В	Brakes	IN ORDER	Modifi	cation	NIL	
G	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
R	R/H Front Tyre	195/65 R15	FALKE	N	6 mm	
L	_/H Front Tyre	195/65 R15	FALKE	N	6 mm	
	R/H Rear Tyre	195/65 R15	FALKE		6 mm	
L	_/H Rear Tyre	195/65 R15	FALKE	N	6 mm	
4. Description of Damages						
T	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
Α	Accident Date	01/12/2017	Inspec	tion Date	04/12/2017	
s	Survey held at	SMRT AUTOMOTIVE SERVICES	S PTE LT	ΓD		
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
E	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					