

LINE CASE OWNER:

Saliba

CC6 / AIG17023090 / Uka3

LKK:
IDAC:

LIVE:

MARCUS

DOI:

ASSIGNMENT

06/12/17

Date / Time:

05/12/17

Registered in Merimen:

05/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJE 9642

Claim No.:

4084673408SG

Name of Insured:

LAU HAN TIANG

Policy No.:

2100406474

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

03/12/17

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJE 7455Z



INSRS:

WSP: Jin Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

07/12/17 (THU THU)

SJE 7455Z - X : SJE 9642 - X
* OI NR - SEND FIRST LETTER TO OI.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N/A.)

S\$

Name 2:

Payee 3: (Strike if N/A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle /w/CP
 2) Report Format: ☐ ☐
 3) Survey fee: ☐ 320

13/12/17

DATE: 6/12/17

REF:

A16/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SGE 7435Z
 at Workshop m/s: J. n. Auto
 of: _____
 Insured: SGE 964Z
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 26
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN/OUT

Veh No: SGE 7435Z Yr Regn: 306
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Toyota cc: 1794
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 264245 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 2NE100290216
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/42R17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Landsail

Front: 6 mm Rear: 6 mm
 R/Bal: 6 mm L/Bal: 6 mm
 D.O.A. 3/12/17 D.O.I. 6/12/17
 Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear & Rear

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time: 6/12/17 Action / Instruction: confirmed L/S \$2250 with Jouis LTA 16781 3yrs 4mo

RED: 71A14-70 41%

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Date/Time: File Return to?

2)

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Invs (\$ _____)

☐ Weekend (\$ _____)

☐ S + RS \$ _____

☐ Photos

☐ Other

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17023090/Uua3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 05-12-2017	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJE 964Z	Veh. Inspected	SGE 7435Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/12/2017	Inspection Date	06/12/2017
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

5/12/2017

M/S AIG

ESTIMATE REPAIR COST FOR SGE 7435Z

Not AIG
N/A
1/5 \$2050/2
Total paid. After repair
3 days
6/12/17

S/N	QTY	DESCRIPTION
1	1 PC	REAR BUMPER
2	1 PC	REAR BUMPER CLIPS
3	1 PC	REAR BUMPER RETAINER
4	1 PC	REAR RH LAMP
5	1 PC	REAR RH DOOR
6		REAR RH RIM
7		SPRAY PAINT
8		TRANSFER OF REVERSE SENSOR
9		WHEEL ALIGNMENT
10		TUFF KOTE
11		LABOUR CHARGE
12		WIRING CHECK

RD	\$	470.70	✓
RD	\$	30.00	✓
RD	\$	57.10	✓
RD	\$	472.60	✓
RD/Rep	\$	1,122.80	✓
	\$	2,153.20	
LESS 25%	\$	(538.30)	
	\$	1,614.90	
RD	\$	424.80	X
	\$	400.00	✓
	\$	120.00	50
	\$	120.00	60
	\$	80.00	30
	\$	680.00	400
	\$	25.00	20
	\$	3,464.70	

2574.9

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 27 February 2019 12:19 PM
To: 'Syed-Yusoff, Saliha'; Olivia Lau (LKKAUTO)
Subject: RE: AIG ref: 4084673408SG-003
Attachments: RE: ACCIDENT INVOLVING SGE7435Z AND SJE964Z (AIG INSURED) ON 03/12/2017

Hi Saliha,

We refer to the email below.

Enclosed the confirmation from the repairer.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>

Sent: Wednesday, 27 February 2019 11:57 AM

To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>

Subject: RE: AIG ref: 4084673408SG-003

Dear Asher,

Please let us have the date of the tele-conversation with repairer.

Thank you,

Kind Regards,
Saliha

Saliha Syed Yusoff

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16, Singapore 079120
Tel +(65) 6419 1917 |
www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Asher Sng (LKKAuto) [<mailto:AsherSng@lkkauto.com>]
Sent: Tuesday, February 26, 2019 3:11 PM
To: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Subject: RE: AIG ref: 4084673408SG-003

Hi Saliha,

We refer to the email below.

According to the tele-conversation with the repairer recently mention that claimant did not come back for repair.

Therefore we are pending confirmation email from the repairer and we shall submit our w/p and close of the case.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Sent: Tuesday, 26 February 2019 2:09 PM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Subject: AIG ref: 4084673408SG-003
Importance: High

Dear Asher,

Any development on this matter? It's been more than 1 year since DOA. Please advise when was the last correspondence with repairer.

FYI- We have settled the related BI claim at 50% global sum.

Thank you

Kind Regards,
Saliha

Saliha Syed Yusoff
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16, Singapore 079120
Tel +(65) 6419 1917 |
www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Asher Sng (LKKAUTO)

From: jouis <jouis@jinauto.com.sg>
Sent: Tuesday, 26 February 2019 3:15 PM
To: Asher Sng (LKKAUTO)
Subject: RE: ACCIDENT INVOLVING SGE7435Z AND SJE964Z (AIG INSURED) ON 03/12/2017

Dear Asher,

We have close file on our ends.

Thank you & Best Regards,
Jouis Seow
Jin Auto Services Pte Ltd
Blk 14 #01-412 Defu Lane 10
Singapore 539195.

Tel : (65) 62898126
Fax : (65) 62870590
Email : jouis@jinauto.com.sg

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: Tuesday, 26 February 2019 3:08 PM
To: jouis <jouis@jinauto.com.sg>
Subject: RE: ACCIDENT INVOLVING SGE7435Z AND SJE964Z (AIG INSURED) ON 03/12/2017 :

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Jouis,

We refer to the above matter.

Please kindly advise on the status.

Thank You.

Best Regards,
Asher Sng | Case Handler
LKK Auto Consultants Pte Ltd
phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vic (LKKAUTO)

Sent: Friday, 23 February 2018 5:03 PM

To: Jouis <jouis@lkkauto.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>; Thin Thin (LKKAUTO) <thinthin@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING SGE7435Z AND SJE964Z (AIG INSURED) ON 03/12/2017 :


WITHOUT PREJUDICE

Dear Jouis,

We refer to the above matter.

We are of the opinion that this is a case of **conflicting versions**. There is no conclusive evidence yet to substantiate either party's version. Please refer to the below copy of our insured's accident report for your perusal.

ACCIDENT FORM



A - SJE 964-Z
B - SGE 7435-Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 03 Dec 17 about 9.30pm when heading back to Singapore in queue at JB C16 custom main entrance, A vehicle SGE7435Z coming from left and squeezed in my front then caused scratch on my front left panel.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, kindly forward to us with any evidence (if any) your client have to support your claim.

Thank you.


Best Regards,

Vic Alpeh | Case Handler (on behalf of Thin Thin)

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vic@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: jouis [<mailto:jouis@jinauto.com.sg>]

Sent: Friday, 23 February, 2018 4:59 PM

To: Thin Thin (LKKAuto)

Cc: Vic (LKKAuto)

Subject: RE: ACCIDENT INVOLVING SGE7435Z AND SJE964Z (AIG INSURED) ON 03/12/2017 :

Without Prejudice

Dear Thin Thin

Your insured have reported .

Please establish the liability .

Thank you & Best Regards,
Jouis Seow
Jin Auto Services Pte Ltd
Blk 14 #01-412 Defu Lane 10
Singapore 539195.

Tel : (65) 62898126
Fax : (65) 62870590
Email : jouis@jinauto.com.sg

From: Thin Thin (LKKAuto) [<mailto:thinthin@lkkauto.com>]

Sent: Tuesday, 19 December 2017 4:48 PM

To: jouis <jouis@jinauto.com.sg>

Subject: RE: ACCIDENT INVOLVING SGE7435Z AND SJE964Z (AIG INSURED) ON 03/12/2017 :

Dear Jouis,

Yes, handle by me.

Meantime, we are still pending for our insured report from our principal.

Best Regards,
Thin Thin Hlaing | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jouis [<mailto:jouis@jinauto.com.sg>]
Sent: Tuesday, 19 December, 2017 4:46 PM
To: Thin Thin (LKKAuto) <thinthin@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING SGE7435Z AND SJE964Z (AIG INSURED) ON 03/12/2017 :

Dear Thin Thin ,

Refer to the below mentioned .

Is this case handle by you ?

Able to establish liability .

Thank you & Best Regards,
Jouis Seow
Jin Auto Services Pte Ltd
Blk 14 #01-412 Defu Lane 10
Singapore 539195.

Tel : (65) 62898126
Fax : (65) 62870590
Email : jouis@jinauto.com.sg

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Tuesday, 5 December 2017 11:10 AM
To: jouis <jouis@jinauto.com.sg>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING SGE7435Z AND SJE964Z (AIG INSURED) ON 03/12/2017 :

Hi Jouis,

Thank you for your email.

By copy to Shirley.

New case. FYNA please.

Thank you.
Best Regards,
Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jouis [<mailto:jouis@jinauto.com.sg>]

Sent: Tuesday, 5 December, 2017 10:13 AM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Subject: ACCIDENT INVOLVING SGE7435Z AND SJE964Z (AIG INSURED) ON 03/12/2017 :

Dear Sir/Madam

ACCIDENT INVOLVING SGE7435Z AND SJE964Z (AIG INSURED) ON 03/12/2017

Please appoint Marcus 's to conduct SGE7435Z inspection at :

Place : Blk 14 #01-412

Defu Lane 10

Singapore 539195.

We would be appreciate if could revert to us on the liability urgently .

Thank you & Best Regards,

Jouis Seow

Jin Auto Services Pte Ltd

Blk 14 #01-412 Defu Lane 10

Singapore 539195.

Tel : (65) 62898126

Fax : (65) 62870590

Email : jouis@jinauto.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Dec 2017 Edit Reg		06 Dec 2017 00:00 Edit Adj Rpt	S\$2,050.00 Edit Estimates	S\$2,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LAU HOW TIANG, ID: S7076553E								
Main Claimant:	LIM KENG LONG, ID: S8902442J								
Vehicle Reg. No.:	SGE7435Z	Date of Loss:	03/12/2017 21:00 - :59 [140 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4084673408SG		Policy/Cover Note No.:	2100406474-02000 (Comprehensive)					
Vehicle Reg. No. (Insured):	SJE964Z	Policy No. (Claimant):	DMPC17S019526						
		Excess:							
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/12/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (06/12/2017): NO OI GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGE7435Z (4084673408SG)
[SJE964Z]**

TP

LIM KENG LONG

Dec 3 2017 9:30PM

[LAU HOW TIANG]

Jin Auto Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser <input type="button" value="v"/>	
Assessment Reports										1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print	
1	19/01/18 10:28	Accident Statement <small>From: SC - Reg. No: SJE964Z, Claimant: LAU HOW TIANG</small>								Load HTM	
Photos/Images											
										3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	06/12/17 14:12	Odometer Reading								Load JPG <input checked="" type="checkbox"/>	
2	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
3	06/12/17 14:12	Chassis Number								Load JPG <input checked="" type="checkbox"/>	
4	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
5	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
6	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
7	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
8	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
9	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
10	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
11	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
12	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
13	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
14	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
15	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
16	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
17	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
18	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
19	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
20	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
21	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
22	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
23	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
24	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
25	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
26	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
27	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
28	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
29	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
30	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
31	06/12/17 14:12	General View								Load JPG <input checked="" type="checkbox"/>	
Documentation										1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	05/12/17 17:42	TP GIA REPORT		Load PDF
2	07/12/17 09:51	TP ESTIMATE- MARKED		Load PDF
3	07/12/17 09:51	SJE 964Z - NON REPORTING LETTER		Load PDF
4	07/12/17 09:59	POLICE REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17023090/UEA3Q2
Date: 14/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100406474-02000
Claimant Vehicle No : SGE7435Z **Insured Vehicle No :** SJE964Z
Date of Loss: 03/12/2017 **Nature of Claim:** TP **Claim No:** 4084673408SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGE7435Z**
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2489933
 Reg. Date: 24/03/2006 (Man. Year: 2006) Chassis No: ZNE100290216
 Colour: Grey Odometer: 264245 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17
 Front Left Side: Landsail 6 mm Rear Left Side: Landsail 6 mm
 Front Right Side: Landsail 6 mm Rear Right Side: Landsail 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,039.70	1,614.90	424.80	20.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,425.00	960.00	465.00	32.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,464.70	2,574.90	889.80	25.68
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	3,464.70	2,050.00	1,414.70	40.83
+ GST 7.00/7.00% (S\$)	242.53	143.50	99.03	40.83
Nett Amount (S\$)	3,707.23	2,193.50	1,513.73	40.83
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 06/12/2017
 Date Inspected: 06/12/2017 Inspected At: Jin Auto Services Pte Ltd (Defu)
 Blk 14 Defu Lane 10, #01-410/412
 Singapore 539195
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	470.70 FL	*470.70 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*REAR BUMPER RETAINER	Bent	57.10 FL	*57.10 FL
4	1		*REAR RH LAMP	Scratched	472.60 FL	*472.60 FL
5	1		*REAR RH DOOR	Dented / Bent	1,122.80 FL	*1,122.80 FL
6	1		*REAR RH RIM	Repair	424.80 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,578.00	2,153.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	538.30	538.30
Total Parts (\$\$)	2,039.70	1,614.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT	New	400.00	400.00
2	TRANSFER OF REVERSE SENSOR	New	120.00	50.00
3	WHEEL ALIGNMENT	New	120.00	60.00
4	TUFF KOTE	New	80.00	30.00
5	LABOUR CHARGE	New	680.00	400.00
6	WIRING CHECK	New	25.00	20.00
Gross Labour Cost (S\$)			1,425.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >