

Messrs Grab Rentals Pte Ltd

Date : 02.12.2017

Estimate To Repair Mazda 3 Sedan 1.5 AT EU6
Vehicle No : SLN9128R
Chassis No : JM6BN22A8H0153425

Pages : 1 of 2

S/No	Quantity	Description	Unit price	Amount
<u>LIST ITEMS</u>				
1	1 pc	bootlid	\$ 958.00	\$ 958.00
2	1 pc	bootlid Mazda 3 badge	\$ 54.00	\$ 54.00
3	1 pc	bootlid Skyativ badge	\$ 64.00	\$ 64.00
4	1 pc	bootlid centre emblem	\$ 75.00	\$ 75.00
5	2 pc	bootlid reflector	\$ 265.00	\$ 530.00
6	1 pc	bootlid inner trim	\$ 121.00	\$ 121.00
7	5 pc	bootlid inner trim clips	\$ 5.00	\$ 25.00
8	2 pc	bootlid lock	\$ 153.00	\$ 306.00
9	1 pc	bootlid lock stricker	\$ 35.00	\$ 35.00
10	1 pc	bootlid weatherstirp	\$ 130.00	\$ 130.00
11	1 pc	bootlid keyless sensor	\$ 78.00	\$ 78.00
12	2 pc	bootlid licence plate lamp	\$ 72.00	\$ 144.00
13	1 pc	rear end panel	\$ 506.00	\$ 506.00
14	1 pc	rear end panel inner trim	\$ 86.00	\$ 86.00
15	1 pc	rear end panel inner trim clips	\$ 5.00	\$ 5.00
16	1 pc	rear luggage floor compartment foam	\$ 166.00	\$ 166.00
17	1 pc	rear luggage floor trimboard	\$ 350.00	\$ 350.00
18	2 pc	rear lamp	\$ 509.00	\$ 1,018.00
19	4 pc	rear lamp clips holder	\$ 8.00	\$ 32.00
20	1 pc	rear bumper	\$ 1,075.00	\$ 1,075.00
21	2 pc	rear bumper reflector	\$ 51.00	\$ 102.00
22	2 pc	rear bumper end splashshield cover	\$ 80.00	\$ 160.00
23	10 pc	rear bumper clips	\$ 5.00	\$ 50.00
24	1 pc	rear bumper reinforcement	\$ 538.00	\$ 538.00
25	2 pc	rear bumper side retainer	\$ 46.00	\$ 92.00
26	2 pc	rear bumper side holder	\$ 37.00	\$ 74.00
27	4 pc	rear bumper side holder rivets	\$ 5.00	\$ 20.00
28	2 pc	rear bumper tow cover	\$ 17.00	\$ 34.00
				\$ 6,828.00
Less 20%				\$ 1,365.60
				\$ 5,462.40
Balance C/F				\$ 5,462.40

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Estimate To Repair Mazda 3 Sedan 1.5 AT EU6
Vehicle No : SLN9128R
Chassis No : JM6BN22A8H0153425

S/No	Quantity	Description	Unit price	Amount
		Balance B/F		\$ 5,462.40
		<u>SPECIAL NETT ITEMS</u>		
29		rear licence plate	\$ 80.00	\$ 80.00
30		rear bumper parking sensor	\$ 450.00	\$ 450.00
				\$ 530.00
		<u>LABOUR & MISC. CHARGES</u>		
1		To check electrical lighting concerned.		\$ 60.00
2		To rust-proofing of the affected areas.		\$ 180.00
3		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.		\$ 150.00
4		To reinstall of rear bumper parking sensor.		\$ 120.00
5		To repair and realign rear exhaust box.		\$ 120.00
6		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.		\$ 850.00
7		Putty and spray painting of the affected portion.		\$ 850.00
				\$ 2,330.00
		Grand Total		\$ 8,322.40

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/12/2017 15:48
Date Of Accident	02/12/2017 10:30
Exact Location Of Accident	CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN9128R
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98235866

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 4 DOOR SEDAN SP (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	MTGRAB20171584

Driver

Name of Driver	TAN SENG HENG
NRIC No	S1244350A
Date Of Birth	14/11/1957
Occupation	OUTDOOR
Date Of Driving Pass	01/02/1978
Driving Experience	39 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88589272
Fax Number	
Contact Number	
Email Address	TANSENGHENGGRAB@GMAIL.COM

Address BLOCK 4 BEACH ROAD
#03-4971

Postcode 190004

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

On 02.12.2017 at about 1030hrs, I was driving my vehicle (A: SLN9128R) along 1st lane of CTE. Vehicles ahead slowed down and I followed suit. Suddenly, a vehicle (B: SHD6524A) travelling behind my vehicle came and hit the rear of my vehicle. Vehicle A (SLN9128R) – 2 passengers onboard. Vehicle B (SHD6524A) – 1 passenger onboard.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD6524A

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

Reporting Centre Personnel's Signature
Name: Yang Jing
NRIC/FIN No:

Sketch Plan Pg. 2

SKETCH PLAN

CTE

A: SLN9128R
B: SHD6524A

B A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report.

DECLARATION

1/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 07/12/2017

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	7200G

Vehicle Details

Vehicle No.	SLN9128R
Vehicle to be Exported	Yes
Intended De-registration Date	02 Dec 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour	Black
Manufacturing Year	2017
Engine No.	P520445175
Chassis No.	JM6BN22A8H0153425
Maximum Power Output	88.0 kW (118 bhp)
Open Market Value	\$14,761.00
Original Registration Date	22 May 2017
First Registration Date	22 May 2017
Transfer Count	0
Actual ARF Paid	\$9,761.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	21 May 2027
PARF Rebate Amount	\$7,320.00

Intended COE Rebate Details

COE Expiry Date	21 May 2027
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$52,000.00
COE Rebate Amount	\$41,600.00
Total Rebate Amount	\$48,920.00

The information contained herein is correct as at 02 Dec 2017

OK