

Sur:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

( days)

Loss of Use (LOU):

S\$

80.00 (220 x 4 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Bun Hock Hin Co. Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Tel Chee Wah

CC 6 / LCR170 23148, U2032

mtrous

ASSIGNMENT

6/12/17

6/12/17

- 6/12/17

SLQ 5355L

LRF P/L

HP: 6241 4992

D.O.A: 27/11/17

914751796656

0000005072

Honda Vezel

Road / Tampines Ave 4

( YES / NO )

Ng Eng Soon

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

FBK 6113L

BHH



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

1/12  
2/12

FBK 6113L - X; SLQ 5355L - X

File review, OJD going straight.  
TP turn right.P/O. OJD get charged by  
traffic police.9/1/18 - File pass to lawyer to prepare  
New BV. TP claimant same v TP wksp.  
TP do submit addendum

RECEIVED 30 JULY 2018

COPY SENT  
2017-18





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                  |                 |                            |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|-----------------|----------------------------|-------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                        |                                                                  |                 | Ref : CC6/LCR17023148/Uza3 |                                                                                     |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDINGS SINGAPORE 079120                                                                               |                                                                  |                 | Date : 06-12-2017          |  |
|                                                                                                                                           |                                                                  |                 | Code : LCR                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                  |                 |                            |                                                                                     |
| Insured Veh.                                                                                                                              | SLQ 5355L                                                        | Veh. Inspected  | FBK 6113L                  |                                                                                     |
| Policy No.                                                                                                                                |                                                                  | Coverage (\$)   | 0.00                       |                                                                                     |
| Claim No.                                                                                                                                 |                                                                  | Excess (\$)     | 0.00                       |                                                                                     |
| Assign From                                                                                                                               |                                                                  | Assign Date     | 06/12/2017                 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                  |                 |                            |                                                                                     |
| Make & Model                                                                                                                              |                                                                  | c.c             | 0                          |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                           | Year of Reg.    |                            |                                                                                     |
| Chassis No.                                                                                                                               |                                                                  | Colour          |                            |                                                                                     |
| Odometer                                                                                                                                  | -                                                                | Steering        |                            |                                                                                     |
| Brakes                                                                                                                                    |                                                                  | Modification    |                            |                                                                                     |
| General                                                                                                                                   |                                                                  |                 |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                  |                 |                            |                                                                                     |
|                                                                                                                                           | Size                                                             | Make            | Balance                    |                                                                                     |
| R/H Front Tyre                                                                                                                            |                                                                  |                 | mm                         |                                                                                     |
| L/H Front Tyre                                                                                                                            |                                                                  |                 | mm                         |                                                                                     |
| R/H Rear Tyre                                                                                                                             |                                                                  |                 | mm                         |                                                                                     |
| L/H Rear Tyre                                                                                                                             |                                                                  |                 | mm                         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                  |                 |                            |                                                                                     |
|                                                                                                                                           |                                                                  |                 |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                  |                 |                            |                                                                                     |
| Accident Date                                                                                                                             | 27/11/2017                                                       | Inspection Date | 06/12/2017                 |                                                                                     |
| Survey held at                                                                                                                            | BAN HOCK HIN CO. PTE LTD<br>NO 6 DEFU LANE 4<br>SINGAPORE 539410 |                 |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                  |                 |                            |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                  |                 |                            |                                                                                     |



**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

NO. : 32189

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120  
MOTOR CLAIMS DEPT

DATE : 30/11/2017  
CLAIM NO. : 11067  
POLICY NO. : AVFMSB0000621700  
FROM : RAYMOND

VEHICLE NO : FBK6113L  
MAKE/MODEL : YAM / YBR125

*Not Authorised  
here  
to high. Other. you  
2/17  
4/17. 6/11/17*

(Page 1 of 3)

| S/N | Description                                                                  | Action         | Qty  | Unit Price | Amount |
|-----|------------------------------------------------------------------------------|----------------|------|------------|--------|
| 1   | BAR HANDLE<br>P/N: 42062                                                     | REPLACE        | 1.00 | \$68.00    | 68.00  |
| 2   | BRACKET UNDER FORK<br>P/N: 27458                                             | REPLACE        | 1.00 | \$180.00   | 180.00 |
| 3   | CLIP TUBE INNER FORK<br>P/N: 35796                                           | REPLACE        | 2.00 | \$5.00     | 10.00  |
| 4   | COVER TAIL LH (BLACK)<br>P/N: 50952                                          | REPLACE        | 1.00 | \$85.00    | 85.00  |
| 5   | COVER TANK SIDE LH (BLACK)<br>P/N: 54458                                     | REPLACE        | 1.00 | \$98.00    | 98.00  |
| 6   | CRASH BAR<br>P/N: 35878                                                      | REPLACE        | 1.00 | \$195.00   | 195.00 |
| 7   | FOOT REST 1<br>P/N: 50005                                                    | REPLACE        | 1.00 | \$55.00    | 55.00  |
| 8   | GUIDE AIR LH<br>P/N: 48403                                                   | REPLACE        | 1.00 | \$23.00    | 23.00  |
| 9   | HANDLE SEAT<br>P/N: 42567                                                    | REPLACE        | 1.00 | \$98.00    | 98.00  |
| 10  | HEADLIGHT ASSY<br>P/N: 50950                                                 | REPLACE        | 1.00 | \$320.00   | 320.00 |
| 11  | LABOUR<br>P/N: 06766<br>- FOR DISMANTLING AND ASSEMBLING OF PARTS<br>QUOTED. | Supply/Install | 8.00 | \$35.00    | 280.00 |
| 12  | LAMP SIGNAL FRONT RH<br>P/N: 42003                                           | REPLACE        | 1.00 | \$55.00    | 55.00  |
| 13  | LAMP SIGNAL REAR LH<br>P/N: 44858                                            | REPLACE        | 1.00 | \$63.00    | 63.00  |



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2003-1-2380  
ISO 9001: 2008

| S/N | Description                                                                                                | Action  | Qty  | Unit Price | Amount   |
|-----|------------------------------------------------------------------------------------------------------------|---------|------|------------|----------|
| 14  | LEVER CLUTCH<br>P/N: 49946                                                                                 | REPLACE | 1.00 | \$18.00    | 18.00    |
| 15  | MIRROR LH<br>P/N: 49947                                                                                    | REPLACE | 1.00 | \$80.00    | 80.00    |
| 16  | MIRROR RH<br>P/N: 54029                                                                                    | REPLACE | 1.00 | \$80.00    | 80.00    |
| 17  | MUDGUARD FRONT (BLACK)<br>P/N: 45203                                                                       | REPLACE | 1.00 | \$85.00    | 85.00    |
| 18  | OIL FORK (UNICORN) MR-10<br>P/N: 54320                                                                     | REPLACE | 3.60 | \$10.00    | 36.00    |
| 19  | PIPE EXHAUST ASSY<br>P/N: 50025                                                                            | REPLACE | 1.00 | \$1,655.00 | 1,655.00 |
| 20  | PLATE NUMBER REAR (6.5 INCH X 9 INCH)<br>P/N: 26951                                                        | REPLACE | 1.00 | \$21.00    | 21.00    |
| 21  | RUBBER FOOTREST FRONT<br>P/N: 26136                                                                        | REPLACE | 2.00 | \$14.00    | 28.00    |
| 22  | SEAL DUST FORK<br>P/N: 26833                                                                               | REPLACE | 2.00 | \$7.00     | 14.00    |
| 23  | SEAL OIL (30X41X10) FORK<br>P/N: 13451                                                                     | REPLACE | 2.00 | \$24.00    | 48.00    |
| 24  | STEERING CONE SET<br>P/N: 41793                                                                            | REPLACE | 1.00 | \$66.00    | 66.00    |
| 25  | STICKER (MCDONALDS) SIDE COVER V2<br>P/N: 56222                                                            | REPLACE | 2.00 | \$16.00    | 32.00    |
| 26  | STICKER (MCDONALDS) WINDSHIELD V2<br>P/N: 56223                                                            | REPLACE | 1.00 | \$16.00    | 16.00    |
| 27  | STICKER NUMBER PLATE FRONT (BLACK)<br>STRAIGHT<br>P/N: 32921                                               | REPLACE | 1.00 | \$12.00    | 12.00    |
| 28  | TRANSPORT CHARGES<br>P/N: 07169<br>- TOW BACK BIKE FOR ACCIDENT REPAIRS.<br>- DELIVER BIKE BACK TO OUTLET. |         | 1.00 | \$35.00    | 35.00    |
| 29  | TUBE INNER FORK<br>P/N: 27114                                                                              | REPLACE | 2.00 | \$96.00    | 192.00   |
| 30  | VISOR<br>P/N: 43130                                                                                        | REPLACE | 1.00 | \$29.00    | 29.00    |

SUB TOTAL

\$3,944.60

GST @ 7 %

\$276.12

GRAND TOTAL

\$4,220.72

Validity: 30 days

For &amp; on Behalf of

BAN HOCK HIN CO PTE LTD



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Acknowledge &amp; Accepted By



CERT NO: 3002-1-580  
ISO 9001:2008

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759



**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197000288K  
MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

NO. : 32189

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120  
MOTOR CLAIMS DEPT

DATE : 30/11/2017  
CLAIM NO. : 11067  
POLICY NO. : AVFMSB0000621700  
FROM : RAYMOND

VEHICLE NO. : FBK6113L  
MAKE/MODEL : YAM / YBR125

(Page 1 of 3)

| S/N | Description                                                                  | Action         | Qty  | Unit Price | Amount |
|-----|------------------------------------------------------------------------------|----------------|------|------------|--------|
| 1   | BAR HANDLE<br>P/N: 42062                                                     | REPLACE        | 1.00 | \$68.00    | 68.00  |
| 2   | BRACKET UNDER FORK<br>P/N: 27458                                             | REPLACE        | 1.00 | \$180.00   | 180.00 |
| 3   | CLIP TUBE INNER FORK<br>P/N: 35796                                           | REPLACE        | 2.00 | \$5.00     | 10.00  |
| 4   | COVER TAIL LH (BLACK)<br>P/N: 50952                                          | REPLACE        | 1.00 | \$85.00    | 85.00  |
| 5   | COVER TANK SIDE LH (BLACK)<br>P/N: 54458                                     | REPLACE        | 1.00 | \$98.00    | 98.00  |
| 6   | CRASH BAR<br>P/N: 35878                                                      | REPLACE        | 1.00 | \$195.00   | 195.00 |
| 7   | FOOT REST 1<br>P/N: 50005                                                    | REPLACE        | 1.00 | \$55.00    | 55.00  |
| 8   | GUIDE AIR LH<br>P/N: 48403                                                   | REPLACE        | 1.00 | \$23.00    | 23.00  |
| 9   | HANDLE SEAT<br>P/N: 42567                                                    | REPLACE        | 1.00 | \$98.00    | 98.00  |
| 10  | HEADLIGHT ASSY<br>P/N: 50950                                                 | REPLACE        | 1.00 | \$320.00   | 320.00 |
| 11  | LABOUR<br>P/N: 06766<br>- FOR DISMANTLING AND ASSEMBLING OF PARTS<br>QUOTED. | Supply/Install | 8.00 | \$35.00    | 280.00 |
| 12  | LAMP SIGNAL FRONT RH<br>P/N: 42003                                           | REPLACE        | 1.00 | \$55.00    | 55.00  |
| 13  | LAMP SIGNAL REAR LH<br>P/N: 44858                                            | REPLACE        | 1.00 | \$63.00    | 63.00  |



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363  
ISO 9001: 2008

| S/N | Description                                                                                                | Action  | Qty  | Unit Price | Amount   |
|-----|------------------------------------------------------------------------------------------------------------|---------|------|------------|----------|
| 14  | LEVER CLUTCH<br>P/N: 49946                                                                                 | REPLACE | 1.00 | \$18.00    | 18.00    |
| 15  | MIRROR LH<br>P/N: 49947                                                                                    | REPLACE | 1.00 | \$80.00    | 80.00    |
| 16  | MIRROR RH<br>P/N: 54029                                                                                    | REPLACE | 1.00 | \$80.00    | 80.00    |
| 17  | MUDGUARD FRONT (BLACK)<br>P/N: 45203                                                                       | REPLACE | 1.00 | \$85.00    | 85.00    |
| 18  | OIL FORK (UNICORN) MR-10<br>P/N: 54320                                                                     | REPLACE | 0.36 | \$10.00    | 3.60     |
| 19  | PIPE EXHAUST ASSY<br>P/N: 50025                                                                            | REPLACE | 1.00 | \$1,655.00 | 1,655.00 |
| 20  | PLATE NUMBER REAR (6.5 INCH X 9 INCH)<br>P/N: 26951                                                        | REPLACE | 1.00 | \$21.00    | 21.00    |
| 21  | RUBBER FOOTREST FRONT<br>P/N: 26136                                                                        | REPLACE | 2.00 | \$14.00    | 28.00    |
| 22  | SEAL DUST FORK<br>P/N: 26833                                                                               | REPLACE | 2.00 | \$7.00     | 14.00    |
| 23  | SEAL OIL (30X41X10) FORK<br>P/N: 13451                                                                     | REPLACE | 2.00 | \$24.00    | 48.00    |
| 24  | STEERING CONE SET<br>P/N: 41793                                                                            | REPLACE | 1.00 | \$66.00    | 66.00    |
| 25  | STICKER (MCDONALDS) SIDE COVER V2<br>P/N: 56222                                                            | REPLACE | 2.00 | \$16.00    | 32.00    |
| 26  | STICKER (MCDONALDS) WINDSHIELD V2<br>P/N: 56223                                                            | REPLACE | 1.00 | \$16.00    | 16.00    |
| 27  | STICKER NUMBER PLATE FRONT (BLACK)<br>STRAIGHT<br>P/N: 32921                                               | REPLACE | 1.00 | \$12.00    | 12.00    |
| 28  | TRANSPORT CHARGES<br>P/N: 07169<br>- TOW BACK BIKE FOR ACCIDENT REPAIRS.<br>- DELIVER BIKE BACK TO OUTLET. |         | 1.00 | \$35.00    | 35.00    |
| 29  | TUBE INNER FORK<br>P/N: 27114                                                                              | REPLACE | 2.00 | \$96.00    | 192.00   |
| 30  | VISOR<br>P/N: 43130                                                                                        | REPLACE | 1.00 | \$29.00    | 29.00    |

SUB TOTAL

\$3,944.60

GST @ 7 %

\$276.12

GRAND TOTAL

\$4,220.72

Validity: 30 days

For &amp; on Behalf of

BAN HOCK HIN CO PTE LTD



LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Acknowledge &amp; Accepted By



| <u>S/N</u> | <u>Description</u> | <u>Action</u> | <u>Qty</u> | <u>Unit Price</u> | <u>Amount</u> |
|------------|--------------------|---------------|------------|-------------------|---------------|
|------------|--------------------|---------------|------------|-------------------|---------------|



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:





**SINGAPORE  
POLICE FORCE**

Traffic Police  
10 Ubi Avenue 3  
Singapore 408865  
Tel +65 6547 0000  
Fax +65 6547 6259  
www.police.gov.sg

Our Ref : TP/IP/63845/2017  
Date : 15 December, 2017

LI CHANGLIANG  
BLK 826 TAMPINES STREET 81  
#04-120  
SINGAPORE 520826

Dear Sir/Madam

**ACCIDENT INVOLVING FBK6113L & SLQ5355L ON 27/11/2017 AT 1308 HRS ALONG  
TAMPINES AVENUE 9 / TAMPINES STREET 91**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of **SLQ5355L** has committed an offence of Inconsiderate Driving under Section 65(b) Road Traffic Act, Chapter 276. Action has been initiated against the driver for the said offence.
3. If you have any queries, please contact the Investigation Officer, NORASHIKIN DAUD at telephone number 6547 6439 or email at [Norashikin\\_Daud@spf.gov.sg](mailto:Norashikin_Daud@spf.gov.sg).

Yours faithfully

  
Roslan Ahmad, Stn Insp  
For Head Investigation  
Traffic Police  
Singapore Police Force

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

| CLAIM SUBFOLDER TRACKING |                                         |               |                                                   |                                                     |                                               |             |                                                                 |
|--------------------------|-----------------------------------------|---------------|---------------------------------------------------|-----------------------------------------------------|-----------------------------------------------|-------------|-----------------------------------------------------------------|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                             | Adj Submitted                                 | Ins Auth'ed | Status                                                          |
| Main                     | 06 Dec 2017<br><a href="#">Edit Reg</a> |               | 06 Dec 2017 00:00<br><a href="#">Edit Adj Rpt</a> | <b>\$1,504.30</b><br><a href="#">Edit Estimates</a> | <b>\$1,504.30</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                                         | Reference | Claim Details          | Documents              | Show All |         |             |              |            |       |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|------------------------|------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>                                                                                                      |           |                        |                        |          |         |             |              |            |       |
| Insured: <b>LCRF PTE LTD</b> , Co. Reg. No.: 201624597K                                                                                                                                      |           |                        |                        |          |         |             |              |            |       |
| Main Claimant: <b>Ban Hock Hin Co. Pte Ltd</b> , Co. Reg. No.: 197000288K                                                                                                                    |           |                        |                        |          |         |             |              |            |       |
| Vehicle Reg. No.: <b>FBK6113L</b>                                                                                                                                                            |           | Date of Loss:          | 27/11/2017 00:00 - :59 |          |         |             |              |            |       |
| Claim Type: <b>TP / 9147517966SG</b>                                                                                                                                                         |           | Policy/Cover Note No.: | 0999995072             |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured): <b>SLQ5355L</b>                                                                                                                                                  |           | Policy No. (Claimant): | DMMFHQ16-000014        |          |         |             |              |            |       |
|                                                                                                                                                                                              |           | Excess:                |                        |          |         |             |              |            |       |
| Repairer: <b>Ban Hock Hin Co. Pte Ltd (HQ)</b> No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520                                                                                           |           |                        |                        |          |         |             |              |            |       |
| Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Tee, Chee-Wah</b> ]                                                           |           |                        |                        |          |         |             |              |            |       |
| Chee-Wah.Tee@aig.com                                                                                                                                                                         |           |                        |                        |          |         |             |              |            |       |
| Claimant's Insurer: <b>Allied World Assurance Company, Ltd (HQ)</b> - Tel: 62201188                                                                                                          |           |                        |                        |          |         |             |              |            |       |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 15/12/2017]</b>                                               |           |                        |                        |          |         |             |              |            |       |
| Driver/Custodian (Insured): <b>NG ENG SOON ()</b> , NRIC: S1461296C                                                                                                                          |           |                        |                        |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                                |           |                        |                        |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG (07/12/2017): Re: Confirmation of DOA</li> <li>AIG_SG (07/12/2017): Confirmation of DOA</li> <li>AIG_SG (07/12/2017): TP GIA REPORT</li> </ul> |           |                        |                        |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>              |           |                        |                        |          |         |             |              |            |       |
| Due Date                                                                                                                                                                                     | Priority  | Type                   | Task Group             | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                                  |           |                        |                        |          |         |             |              |            |       |

## Claim Documents

\*FBK6113L (9147517966SG)  
[SLQ5355L]

TP

Ban Hock Hin Co. Pte Ltd

Nov 27 2017 12:00AM

[LCRF PTE LTD]

Ban Hock Hin Co. Pte Ltd

|                                                                                                                                                                     |                 |                                                                                   |                                                                                                |                                     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| <a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a> |                 |                                                                                   | <b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>                   |                                     |
| <b>Letters/Correspondences</b>                                                                                                                                      |                 |                                                                                   | 1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>                |                                     |
| No                                                                                                                                                                  | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                                                 | <b>Thumbnail</b>                                                                               | <b>Print</b>                        |
| 1                                                                                                                                                                   | (Draft)         | <b>Third Party Express Settlement - Payment Breakdown</b>                         |  Edit       |                                     |
| <b>Assessment Reports</b>                                                                                                                                           |                 |                                                                                   | 1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>                |                                     |
| No                                                                                                                                                                  | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)                                         | <b>Thumbnail</b>                                                                               | <b>Print</b>                        |
| 1                                                                                                                                                                   | 07/12/17 17:21  | <b>Accident Statement</b><br>From: SC - Reg. No: SLQ5355L, Claimant: LCRF PTE LTD |  Load HTM   |                                     |
| <b>Photos/Images</b>                                                                                                                                                |                 |                                                                                   | 3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>                |                                     |
| No                                                                                                                                                                  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                                 | <b>Thumbnail</b>                                                                               | <b>Print</b>                        |
| 1                                                                                                                                                                   | 06/12/17 14:34  | <b>Chassis Number</b>                                                             |  Load JPG   | <input checked="" type="checkbox"/> |
| 2                                                                                                                                                                   | 06/12/17 14:34  | <b>Odometer Reading</b>                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 3                                                                                                                                                                   | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 4                                                                                                                                                                   | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 5                                                                                                                                                                   | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 6                                                                                                                                                                   | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 7                                                                                                                                                                   | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 8                                                                                                                                                                   | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 9                                                                                                                                                                   | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 10                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 11                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 12                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 13                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 14                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 15                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 16                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 17                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 18                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 19                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 20                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 21                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 22                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 23                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 24                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 25                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 26                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 27                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |
| 28                                                                                                                                                                  | 06/12/17 14:34  | <b>General View</b>                                                               |  Load JPG | <input checked="" type="checkbox"/> |

|    |                |                    |  |          |                                     |
|----|----------------|--------------------|--|----------|-------------------------------------|
| 29 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 30 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 31 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 32 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 33 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 34 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 35 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 36 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 37 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 38 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 39 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 40 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 41 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 42 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 43 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 44 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 45 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 46 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 47 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 48 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 49 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 50 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 51 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 52 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 53 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 54 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 55 | 06/12/17 14:34 | General View       |  | Load JPG | <input checked="" type="checkbox"/> |
| 56 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 57 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 58 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 59 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 60 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 61 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 62 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 63 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 64 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 65 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 66 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 67 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 68 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 69 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 70 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 71 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 72 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 73 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 74 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 75 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 76 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 77 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 78 | 26/12/17 09:03 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |

| Documentation |                 |                                   | 1 per page                                                                                   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                    | Print                               |
| 1             | 07/12/17 14:51  | TP ESTIMATE - MARKED              |  Load PDF |                                     |
| 2             | 07/12/17 14:51  | TP GIA REPORT                     |  Load PDF |                                     |
| 3             | 09/01/18 17:04  | TP GIA REPORT- ADDENDUM           |  Load PDF |                                     |
| 4             | 09/01/18 17:04  | RELEASE VOUCHER                   |  Load PDF |                                     |
| 5             | 15/01/18 14:44  | LETTER TO OI                      |  Load PDF |                                     |
| 6             | 15/01/18 14:44  | LTA SEARCH                        |  Load PDF |                                     |
| 7             | 15/01/18 14:44  | WORKSHOP INVOICE                  |  Load PDF |                                     |

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

#### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                         |
|-------------------|---------------------|--------|-------------------------|
| Vehicle No:       | SLQ5355L (Insd veh) | Model: | YAMAHA YBR125 124CC (M) |
|                   | FBK6113L (TP veh)   |        |                         |
| Date of Accident: | 27/11/2017          |        |                         |

|                                                                                                      |           |                                                 |                              |
|------------------------------------------------------------------------------------------------------|-----------|-------------------------------------------------|------------------------------|
| Global Sum Settlement                                                                                | : [ ] Yes | [ X ] No                                        |                              |
| Repair Estimate                                                                                      | : \$      | 4,220.72                                        |                              |
| Final Repair Cost                                                                                    | : \$      | 1,609.60                                        |                              |
| Loss of Use                                                                                          | : \$      | 80.00                                           | 4.00 days at \$20.00 per day |
| Rental (if any)                                                                                      | : \$      |                                                 | days                         |
| LTA / GIA Search Fee                                                                                 | : \$      | 5.35                                            |                              |
| Others:                                                                                              | : \$      |                                                 |                              |
|                                                                                                      | : \$      |                                                 |                              |
| Final Settlement Sum                                                                                 | : \$      | 1,694.95                                        |                              |
| Is Third Party Workshop GIA Registered? [ ] YES [ X ] NO (Kindly indicate below)                     |           |                                                 |                              |
| A) For Non GIA Registered Workshop:                                                                  |           | Agreed Liability ____ 100 ____ (%)              |                              |
| B) For GIA Registered Workshop:                                                                      |           | BOLA Applicable: Yes/ No BOLA Scenario No: ____ |                              |
| BOLA Liability: ____ (%)                                                                             |           | Assessed Liability (*): ____ (%)                |                              |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply. |           |                                                 |                              |
| Remarks _____                                                                                        |           |                                                 |                              |

| Payment Instruction: Payee's Breakdown |                          |      |          |
|----------------------------------------|--------------------------|------|----------|
| 1)                                     | Ban Hock Hin Co. Pte Ltd | : \$ | 1,694.95 |
| 2)                                     |                          | : \$ |          |
| 3)                                     |                          | : \$ |          |

NUR SHAQILAH BTE ABDOL  
WAHAB

LKK Auto Consultants Pte Ltd

15 Jan  
2018

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR17023148/UZA3S2  
Date: 15/01/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995072  
 Claimant Vehicle No: FBK6113L Insured Vehicle No: SLQ5355L  
 Date of Loss: 27/11/2017 Nature of Claim: TP Claim No: 9147517966SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBK6113L  
 Make & Model: YAMAHA YBR125, 124cc (M) Engine No: E3F5E040564  
 Reg. Date: 05/11/2015 (Man. Year: 2015) Chassis No: LBP101000055625  
 Colour: Red Odometer: 47093 km  
 Engine Capacity: 124 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 2.75-18 Rear Tyre Size: 3.00-18  
 Front Left Side: Metzeler 6 mm Rear Left Side: Metzeler 6 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 3,629.60        | 1,219.30        | 2,410.30        | 66.41        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 315.00          | 285.00          | 30.00           | 9.52         |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Gross Total (S\$)</b>                 | <b>3,944.60</b> | <b>1,504.30</b> | <b>2,440.30</b> | <b>61.86</b> |
| + GST 7.00/7.00% (S\$)                   | 276.12          | 105.30          | 170.82          | 61.86        |
| <b>Nett Amount (S\$)</b>                 | <b>4,220.72</b> | <b>1,609.60</b> | <b>2,611.12</b> | <b>61.86</b> |
| + Loss of Use (4.0 x S\$20.00/day) (S\$) |                 | 80.00           |                 |              |
| + Doc/Search Fee (S\$)                   |                 | 5.35            |                 |              |
| <b>Nett Liability (S\$)</b>              |                 | <b>1,694.95</b> |                 |              |

## INSPECTION

Date of Assignment: 06/12/2017  
 Date Inspected: 06/12/2017 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)  
 No. 6 Defu Lane 4  
 Singapore 539410

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** ZAY YER LYNN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition     | Repairer's | Amount     |
|-----|-----|----------|----------------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *BAR HANDLE                                  | Bent          | 68.00 F    | *68.00 FL  |
| 2   | 1   |          | *BRACKET UNDER FORK                          | Repair        | 180.00 F   | *- FL      |
| 3   | 2   |          | *CLIP TUBE INNER FORK                        | Not Necessary | 10.00 F    | *- FL      |
| 4   | 1   |          | *COVER TAIL LH (BLACK)                       | Cracked       | 85.00 F    | *85.00 FL  |
| 5   | 1   |          | *COVER TANK SIDE LH (BLACK)                  | Cracked       | 98.00 F    | *98.00 FL  |
| 6   | 1   |          | *CRASH BAR                                   | Bent          | 195.00 F   | *195.00 FL |
| 7   | 1   |          | *FOOT REST 1                                 | Bent          | 55.00 F    | *55.00 FL  |
| 8   | 1   |          | *GUIDE AIR LH                                | Not Necessary | 23.00 F    | *- FL      |
| 9   | 1   |          | *HANDLE SEAT                                 | Cut           | 98.00 F    | *98.00 FL  |
| 10  | 1   |          | *HEADLIGHT ASSY                              | Scratched     | 320.00 F   | *320.00 FL |
| 11  | 1   |          | *LAMP SIGNAL FRONT RH                        | Broken        | 55.00 F    | *55.00 FL  |
| 12  | 1   |          | *LAMP SIGNAL REAR LH                         | Cut           | 63.00 F    | *63.00 FL  |
| 13  | 1   |          | *LEVER CLUTCH                                | Bent          | 18.00 F    | *18.00 FL  |
| 14  | 1   |          | *MIRROR LH                                   | Scratched     | 80.00 F    | *80.00 FL  |
| 15  | 1   |          | *MIRROR RH                                   | Not Necessary | 80.00 F    | *- FL      |
| 16  | 1   |          | *MUDGUARD FRONT (BLACK)                      | Cracked       | 85.00 F    | *85.00 FL  |
| 17  | 10  |          | *OIL FORK (UNICORN) MR-10                    | Not Necessary | 3.60 F     | *- FL      |
| 18  | 1   |          | *PIPE EXHAUST ASSY                           | Repair        | 1,655.00 F | *- FL      |
| 19  | 2   |          | *RUBBER FOOTREST FRONT                       | Torn          | 28.00 F    | *28.00 FL  |
| 20  | 2   |          | *SEAL DUST FORK                              | Not Necessary | 14.00 F    | *- FL      |
| 21  | 2   |          | *SEAL OIL (30X41X10) FORK                    | Not Necessary | 48.00 F    | *- FL      |
| 22  | 1   |          | *SET STEERING CONE                           | Not Necessary | 66.00 F    | *- FL      |
| 23  | 2   |          | *TUBE INNER FORK                             | Repair        | 192.00 F   | *- FL      |
| 24  | 1   |          | *VISOR                                       | Scratched     | 29.00 F    | *29.00 FL  |
| 25  | 1   |          | *PLATE NUMBER REAR (6.5 INCH X 9 INCH)       | Bent          | 21.00 FS   | *10.00 FS  |
| 26  | 1   |          | *STICKER (MCDONALDS) SIDE COVER V2           | Necessary     | 32.00 FS   | *32.00 FS  |
| 27  | 1   |          | *STICKER (MCDONALDS) WINDSHIELD V2           | Necessary     | 16.00 FS   | *16.00 FS  |
| 28  | 1   |          | *STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT | Necessary     | 12.00 FS   | *12.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                   |                 |                 |
|---------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                            | <b>3,629.60</b> | <b>1,347.00</b> |
| - List Item Discount on L Items 0.00/10.00% (S\$) | 0.00            | 127.70          |
| <b>Total Parts (S\$)</b>                          | <b>3,629.60</b> | <b>1,219.30</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars                                                                          | Lab.Type | Repairer's    | Amount        |
|--------------------------|--------------------------------------------------------------------------------------|----------|---------------|---------------|
| <b>Labour Items</b>      |                                                                                      |          |               |               |
| 1                        | LABOUR - FOR DISMANTLING AND ASSEMBLING OF PARTS.                                    | New      | 280.00        | 250.00        |
| 2                        | TRANSPORT CHARGES - TOW BACK BIKE FOR ACCIDENT REPAIRS. DELIVER BIKE BACK TO OUTLET. | New      | 35.00         | 35.00         |
| Gross Labour Cost (\$\$) |                                                                                      |          | <b>315.00</b> | <b>285.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >