

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Bras Basah Road Singapore 179701

Mainline + 65 6383 6289 Faxline + 65 6280 6725

Workshops

59 Lorong Drive Singapore 609969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

327 Old Road Singapore 788415

24 Serangoon Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

6 Defu Avenue 1 Singapore 339537

Date/Time: 04.12.2017 15:59

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.305094695

ISTOMER

COMFORT TRANSPORTATION PTE LTD

VMS 7010045

ISTOMER NO 383 SIN MING DRIVE

IDRESS Singapore SINGAPORE 575717

L. (R) 65508755

(O)

(P)

SCOUNT CARD NO.

REGN NO:

SHC2289K

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

SONATA

04.12.2017 10:50

YR OF MANU

31.05.2012

TARGET DATE

CHASSIS CODE

KMHET41VMCA825572

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 01.12.2017

NATURE: 3P 01.12.2017

S/NO

LABOR CODE

DESCRIPTION

AXA - taxi Rear damage

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

e:

lo.:

le No.:

SHC2289K

LARRY

Vehicle No.:

SHC2289K

Larry Ng

ie of Service Advisor

Signature/Date

Name of Service Advisor

Date

e returned to Service Reception upon collection

To be kept by Security Guard