

ASS. REC. BY:

REF:

CS/AXA17023166/R1rb/y

Special Instruction:

Survivor:
Meymen

Racul

ASSIGNMENT (Office)

From (Person):

Kitty Tso

of

AXA

Date/Time:

06/2207 1053am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 7277U

Insured:

at Workshop m/s

Wearnes

Tel:

of

249 Alexandra Rd

Policy No:

GA 281758

Claim No:

C0461817

Sum Insured:

Excess:

\$ 1100.00

Make of Veh:

D.O.A.

02/2207

(Client's Record)

CA / REV / REP. / REV 24 HRS

45 Lang Kee Rd

H.O.D. Endorsement:

Date/Time:

06-12207 11:17am

Person Contacted:

Paul

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 7277U - X
7/12/17	Sent preli through me nmm

Rome

41760

ASSIGNMENT

SLB 72774

2016 APR

Estimate Date
 TRIP/WS TR/RES CD/RES/EVA IN/OUT
 To: TRIP/VEHICLE NO SLB 72774
 At: WORKS/VEHICLE NO WGARNES
 Of: 45, Lenn KEE
 Insured: AXA/00
 Policy No
 Date of Ins
 Sum Insured: 400
 Excess
 Claims Record
 Make of Ven

Policy Condition
 Remark: The ven had commenced its repair at the time of inspection.
 Sell of Market Value: 144K
 CAC Accident Report Consistent? Yes or No
 CAC PR Seen Consistent? Yes or No
 Est. Repair: 5 days Fee Yes or No
 Sum Sur: 13/18 Yes or No

REV / REP. / 24 HRS
 Date Person Contacted
 Vehicle IN/OUT

Truck/Trailer
 Type M Car M Cycle Bus Van/Conv Trail Other/Other
 Make INFINITI Q70 2.5 2496
 Colour WHITE
 Seating 12592
 Engine
 C No JN1BCA45120490037
 Gen Cond Good Fair Poor Burnt
 Steering In order Jammed Leaked Burnt
 Brake In order Jammed Leaked Burnt
 Mod Nil JCR STD A/Rum on
 Tyre Size 245/50R18
 R

BS/EXNOVA/GY/PS/LZA/MID/OHTSU/PR/SUM
 TOYO/YOKO
 Front
 R/S 6
 L/S 6
 D/OA 02/12/17
 Surveyed by WGARNES
 Date of Damages: 06/12/17
 Description of Damages: Front Rear C/S N/S U/C Roof/Door
 The U/C Chassis/frame Body Structure affected due to collision

Date/Time Action/Inspection
 Final Sig 89,161.83 (Red 10,010.27, 82%)

RECEIVED 13 JUL 2018

See Final Report
 See Final Report
 Add Fee
 Report Format OD
 Final Sum 9,161.83
 Days Of Repair 5
 Resurvey No. of Trip 1
 See Final Report

Survey Department Check List (Case Handler)

Reference No.: CA/AXA 17023166/R11b
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)				
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (Catherine): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

13/2/18 Catherine
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA17023166/R1rb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 06-12-2017



Code : AXA2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLB 7277U
Policy No.	GA281758	Coverage (\$)	0.00
Claim No.	C0461817	Excess (\$)	400.00
Assign From	MERIMEN (KITTY TEO)	Assign Date	06/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/12/2017	Inspection Date	06/12/2017
Survey held at	45 LENG KEE ROAD		
Repairer	WEARNES AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2017		06 Dec 2017 10:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GAO XIAO RUI, ID: S8574176D, Tel: +6597358621, Email: MOTOR@IVANINSURANCE.COM		
Vehicle Reg. No.:	SLB7277U	Date of Loss:	02/12/2017 00:00 - :59
Claim Type:	OD / C0461817	Policy/Cover Note No.:	GA281758 (Comprehensive)
		Excess:	S\$400.00
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Kitty Teo - 6880 4602]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/12/2017]		
Driver/Custodian:	GAO XIAO RUI (32 / Male), NRIC: S8574176D, Tel: +6597358621		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kitty Teo

Date: 07 Dec 2017

Preliminary Advice

Vehicle No	: SLB7277U	Accident Date	: 02/12/2017
Make	: INFINITI Q70	Policy No.	: GA281758
Assignment Date	: 06/12/2017	Excess	: S\$400.00
Date of Inspection	: 06/12/2017	Est. Duration of Repair	: 5.00
Inspection At	: WEARNES AUTOMOTIVE PTE LTD (ALEXANDRA ROAD) 249 ALEXANDRA ROAD SINGAPORE 159935		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,172.10
Revised Amount	:S\$	7,975.80
Check Items (Estimated)	:S\$	2,328.90
Total	:S\$	10,304.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	144,000.00
COE / PARF Rebate	:S\$	73,748.00
Salvage Value	:S\$	
Margin for Repair	:S\$	70,252.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The survey date and time : 06.12.2017 and 4.00pm. We have authorise repair.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/12/2017 15:36
Date Of Accident	02/12/2017 13:00
Exact Location Of Accident	BUKIT TIMAH THE CREEK CONDO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB7277U
Insured/Policyholder	
Name Of Registered Owner	GAO XIAO RUI
NRIC No	S8574176D
Email Address	HIGH1432004@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97358621
Alternative Phone No	OFFICE-97358621

Vehicle Particulars

Manufacturer	INFINITI
Model	Q70-2.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA281758
Cover Note Number	

Driver

Name of Driver	GAO XIAO RUI
NRIC No	S8574176D
Date Of Birth	12/04/1985
Occupation	INDOOR
Date Of Driving Pass	19/01/2008
Driving Experience	9 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97358621
Fax Number	
Contact Number	OFFICE-97358621
Email Address	HIGH1432004@GMAIL.COM

Address	172C #04-470 EDGEDALE PLAINS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

account number
 03811

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
 -Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	GAO XIAORUI	Certificate number	GA281758 / 1
Cover	Comprehensive	Chassis number	JN18CAY51Z0490037
Plan name	Flexi	Engine number	VQ258S3959A
NCD applicable	50%		
Vehicle registration number	SLB7277U		
Period of Insurance	from 21/10/2017 to 20/10/2018 (both dates inclusive)		
Finance loan company	HL BANK		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Basic Own Damage Excess
 Windscreen Excess

\$30,400.00
 \$90,100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Complete and submit this Form to Affiliated Motor's Authorized Reporting Centre (ARC) as soon as possible.
2. Please report accurately the details of the accident to speed up the claims process.
3. This Form must be completed by the Policyholder and/or the Authorized Driver.
4. Information provided must be as faithful and accurate as possible. Any false representation or withholding of material facts may allow insurance companies to repudiate policy liability.
5. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
6. Any false statement may be referred to the Traffic Police Department for investigation.

ACCIDENT STATEMENT

Date and Time of Accident

Date 2 Dec Time 13:00

Exact Location of Accident

Raffles Timah the creek condo

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLB7377 U

INSURED / POLICYHOLDER (OWN VEHICLE)

Name of Registered Owner (Show Insurance Card)

Gao Xiao Rui

Personal Identification - NRIC (Singaporeans/PR)

S9574176D

- FIC/Passport Number

- Not Applicable

VEHICLE PARTICULARS (OWN VEHICLE)

Vehicle Make / Model

Manufacturer Infiniti Model Q70

Type of Vehicle*

☒ Sedan ☐ MPV ☐ CUV ☐ Van ☐ Lorry
☐ Bus ☐ Motorcycle ☐ Others

Exact Purpose for which vehicle was being used at time of accident

Lo! drive

Are you claiming under your own insurance policy for repair to your vehicle?

☒ Yes ☐ No (If No, please select ☐ Third Party ☐ Reporting)

Vehicle Category*

☒ Private ☐ Commercial ☐ Motorcycle

INSURANCE COMPANY (OWN VEHICLE)

Name of Insurance Company*

AXA

Type of Policy

☒ Comprehensive ☐ Third Party Fire & Theft ☐ TP Only

Fleet Policy

☐ Yes ☐ No

Policy Number

Motor CI

DRIVER

☒ Same as Insured above

Name of Driver

Personal Identification - NRIC (Singaporeans/PR)

- FIC/Passport Number

Date of Birth

12 Oct 09 / 1985

Driving Date Pass

19 Oct 01 / 2008

Year of Driving Experience

Year(s)

Month(s)

Occupation

☒ Indoor ☐ Outdoor

Gender

☒ Male ☐ Female

Contact Number / Mobile Phone / Fax No.

+65 97358621

Accident Sketch Plan

(month) 20 (year)

Address of Driver		B/K172C #04-970 Edgevale	
Email Address		Plains Postcode (823172)	
Was driver an employee of the Insured's Company?		☐ Yes ☒ No	
If No, Relationship of the Driver with the Insured		high 1432009@gmail.com	
Vehicle Registration Number of Driver's Own		☒ Yes ☐ No	
Vehicle Registration Number of Driver's Own Vehicle (if applicable)			
Insurance Company of Driver's Own Vehicle (if applicable)			
GENERAL INFORMATION OF THE ACCIDENT			
Type of Collision (e.g. Chain collision, Head-On collision, Side Swipe, Front to Rear)		Rear collision	
Weather Conditions		☒ Clear ☐ Raining ☐ Others	
Road Surface		☒ Dry ☐ Wet ☐ Others	
OTHER INFORMATION			
Was any foreign vehicle involved in the accident?		☐ Yes ☒ No	
Was any body injured in the accident?		☐ Yes ☒ No	
Was any other vehicle or property damaged?		☐ Yes ☒ No	
Was there any video captured by Car Camera?		☐ Yes ☒ No	
Number of Passengers (including Driver)		1	
DETAILS OF POLICE ACTION			
Was the Accident reported to the Police?		☐ Yes ☒ No (If Yes, please state which Police Station.)	
Police Station Name			
Police Station Address			
Police Station Contact		Tel No. Fax No.	
Was notice of intended Prosecution given?		☐ Yes ☒ No (If Yes, against whom?)	
DETAILS OF OTHER VEHICLE / PROPERTY 1			
Vehicle Registration Number			
Vehicle Make/ Model/ Colour			
Details of Properties			
Name of Driver			
Personal Identification - NRIC (Singaporean/PR)			
- I N/Passport Number			
Contact Number			
Address			
Name of Insurance Company			
Nature of Damage			
No. of Passenger (including Driver)			
(Note: - Please use property if you need to add more vehicles.)			

Page

Accident Sketch Plan

Describe Circumstances of the Accident

Reversed in the dark (low visibility) car park
hit the rear left rear side of the car to the
pillar

IMPORTANT NOTE

Under General Conditions - Conduct of Claims of the Motor Policy, you have to decide within 21 days of occurrence
or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/we declare the foregoing particulars are true in every respect.

 4 Dec 2017
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre Personnel

Page 5

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy benefits.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the CAA Records Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore (GIAS) may/are permitted to collect, use, disclose and/or process my personal data/information set out in this Form and any other personal information provided by me or generated by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers who have insured vehicles involved in this accident (all Insurers) who have insured vehicle(s) involved in this accident and/or be collectively referred to as the "Insurers", the Insurers' law practice firms, the Monetary Authority of Singapore and any relevant government agencies/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of correspondence) and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all Insurers who have insured vehicle(s) involved in the accident and the Insurers' law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/are be disclosed by any of the Insurers and/or GIAS to their third party service providers or agents (including their law/firm/other firms), which may be situated outside of Singapore, for one or more of the above Purposes.


5 Dec 2017

Policyholder's Signature (Date & Time)

Driver's Signature (If Driver is not the policyholder) (Date & Time)

Witnessed by Reporting Centre Personnel

Sketch Plan



Page 1

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8574176D



Name

GAO XIAORUI

高 晓 睿

Race

CHINESE

Date of birth

12-04-1985

Sex

M

S8574176D

Country of birth

CHINA

REPUBLIC OF SINGAPORE DRIVING LICENCE


S8574176D



GAO XIAORUI

Birth Date: 12 Apr 1985

Issue Date: 19 Jan 2006



001563377F

4800376



NRIC No. S8574176D

Date of issue
08-12-2011

Address

APT BLK 172C EDGEDALE PLAINS
#04-470
SINGAPORE 823172

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 19 Jan 2008

NP 428A



Licence No. S

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	4176D
Vehicle Details	
Vehicle No.	SLB7277U
Vehicle to be Exported	No
Intended De-registration Date	07 Dec 2017
Vehicle Make	INFINITI
Vehicle Model	Q70 2.5 PREMIUM A/T S/R
Primary Colour	White
Manufacturing Year	2015
Engine No.	VQ25883959A
Chassis No.	JN1BCAY51Z0490037
Maximum Power Output	163.0 kW (218 bhp)
Open Market Value	\$38,500.00
Original Registration Date	20 Apr 2016
First Registration Date	20 Apr 2016
Transfer Count	1
Actual ARF Paid	\$45,900.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	19 Apr 2026
PARF Rebate Amount	\$34,425.00
Intended COE Rebate Details	
COE Expiry Date	19 Apr 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$47,000.00
COE Rebate Amount	\$39,323.00
Total Rebate Amount	\$73,748.00

The information contained herein is correct as at 07 Dec 2017

OK

144,000
73,748
70,252



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

SERVICE ESTIMATE

85356 - C00001 SL: SERVICE SALES - PC

Success United Pte Ltd

2 Kaki Bukit Ave 2

#01-33 Kaki Bukit Autohub

Singapore 417921

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 05/12/2017

WIP No. : 32960

Veh.In/Out:

*Tel.No. : Mobile: 97779007 Anth

Reg.No. : SLB7277U

Reg.date : 20/04/2016

Mileage : 0

Chassis No: JN1BCAY51Z0490037

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Success United Pte L

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, LHR FENDER, LH TAILLAMP, REAR REINFORCEMENT, SENSOR, REFLECTOR, REPAIR BOOTLID, ETC	0		5100.00	0	5,100.00	S 2850	3400
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, LHR FENDER, BOOTLID, ETC	0		3000.00	0	3,000.00	S 1500	3250
802	TO REPLACE REAR WINDSCREEN	0		850.00	0	850.00	S X 14	
0080	TO INSTALL REAR W/S FILM	0		280.00	0	280.00	S X 14	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0		390.00	0	390.00	S	
	FACE-RR BUMPER	1.0	EA	1166.40	1049.76	1,166.40	S	14
	ENERGY ABSORBER	1.0	EA	182.00	163.80	182.00	S	cut
	BRACKET BUMPER	1.0	EA	33.60	30.24	33.60	S	pe
	BRACKET BUMPER	1.0	EA	33.60	30.24	33.60	S	pe
	SPACER	2.0	EA	7.50	13.50	15.00	S	pe
	BUMPER BEAM REAR	1.0	EA	841.90	757.71	841.90	S	14

Kasul
Hp 90010068
5 days

Resurvey
by
part

06/12/17 @ 1600
EXCESS: 400
Authorized

14/12/17

LKK Auto Centre, hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

SERVICE ESTIMATE

85356 - C00001 SL: SERVICE SALES
Success United Pte Ltd
2 Kaki Bukit Ave 2
#01-33 Kaki Bukit Autohub

Singapore 417921

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Success United Pte L

GST Reg.No: M28920628X
Inv.No. : B&P 0 Page 2
Inv.date. : 05/12/2017
WIP No. : 32960
Veh.In/Out:
*Tel.No. : Mobile: 97779007 Anth
Reg.No. : SLB7277U
Reg.date. : 20/04/2016
Mileage : 0
Chassis No: JN1BCAY51Z0490037

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

REAR BUMPER BEAM BRA	1.0 EA	57.80			57.80 S		
REAR BUMPER BEAM BRA	1.0 EA	57.80			57.80 S		
BRACKET BUMPER REAR	1.0 EA	28.00	25.20		28.00 S		
COVER	4.0 EA	70.00			280.00 S		
SENSOR ASSY	4.0 EA	224.00			896.00 S		
ORNAMENT ASSY R	1.0 EA	56.80			56.80 S		
ORNAMENT ASSY L	1.0 EA	56.80			56.80 S		
LAMP COMB RR, LH	1.0 EA	809.90	728.91		809.90 S		
RIM-COMBI-LAMP	1.0 EA	102.30			102.30 S		
PROTECTOR	1.0 EA	112.00			112.00 S		
INNER PANEL REAR	1.0 EA	631.90			631.90 S		
FENDER-REAR LH	1.0 EA	1182.50			1,182.50 S		
EXT-FENDER RR U	1.0 EA	78.40			78.40 S		
GLASS-BACK WIND	1.0 EA	1650.00			1,650.00 S		
WINDSCREEN SEAL FRT	1.0 EA	33.80			33.80 S		
BODY PANEL SEALANT X	1.0 EA	820.20			820.20 S		
ADHESIVE SEALER FL2	1.0 EA	425.40	322.47		425.40 S		

Gross Total. 19,172.10

Labour Total 9,620.00
Parts Total 9,552.10
Package Total 0.00

Net..... 19,172.10
GST @ 7.0% 1,342.05
Total..... 20,514.15
Paid..... 0.00
Please Pay.. 20,514.15

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - A00005 SL: AXA INSURANCE (S) P/L AXA INSURANCE (S) P/L 8 SHENTON WAY, #27-01 AXA TOWER, SINGAPORE 068811	GST Reg.No: M28920628X Inv.No. : B&P 0 Page 1 Inv.date. : 19/01/2018 WIP No. : 32960 Veh.In/Out: 06/12/2017 27/12/2017 *Tel.No. : 6338 7288 Reg.No. : SLB7277U Reg.date : 20/04/2016 Mileage : 12,396 Chassis No: JN1BCAY51Z0490037
Closed by : Paul Ong Qing Yong Svc Consultant : ACC Remarks : Success United Pte L	

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, LH TAILLAMP, REAR REINFORCEMENT, SENSOR, REFLECTOR. REPAIR LHR FENDER, END PANEL	0		3400.00	0		3,400.00	S
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, LHR FENDER, END PANEL	0		2250.00	0		2,250.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0		390.00	0		390.00	S
EXC	Excess cost	0		400.00	0		-400.00	S
	FACE-RR BUMPER ^①	1.0	EA	1166.40	10		1,049.76	S
	ENERGY ABSORBER ^②	1.0	EA	182.00	10		163.80	S
	BRACKET BUMPER ^③	1.0	EA	33.60	10		30.24	S
	BRACKET BUMPER ^④	1.0	EA	33.60	10		30.24	S
	SPACER ^⑤	2.0	EA	7.50	10		13.50	S
	BUMPER BEAM REAR ^⑥	1.0	EA	841.90	10		757.71	S
	BRACKET BUMPER REAR ^⑦	1.0	EA	28.00	10		25.20	S

SERVICE ESTIMATE

0 - A00005 SL: AXA INSURANCE (S) P/L AXA INSURANCE (S) P/L 8 SHENTON WAY, #27-01 AXA TOWER, SINGAPORE 068811	GST Reg.No:M28920628X Inv.No. . : B&P 0 Page 2 Inv.date. : 19/01/2018 WIP No. . : 32960 Veh.In/Out: 06/12/2017 27/12/2017 *Tel.No. . : 6338 7288 Reg.No. . : SLB7277U Reg.date. : 20/04/2016 Mileage . : 12,396 Chassis No: JN1BCAY51Z0490037
---	---

Closed by : Paul Ong Qing Yong Svc Consultant : ACC Remarks : Success United Pte L	
---	--

Op.No	Description	Mech Qty	Price Disc%	Pkg Amount	G
	ADHESIVE SEALER FL222	1.0 EA	358.30 10	322.47 S	
	I265554AMOA/LAMP COM	1.0 EA	809.90 10	728.91 S	

		Gross Total.	9,161.83
		Less.....	400.00
Labour Total	6,040.00	Net.....	8,761.83
Parts Total	3,121.83	GST @ 7.0%	613.33
Package Total	0.00	Total.....	9,375.16
		Paid.....	0.00
		Please Pay..	9,375.16

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE TAX INVOICE

0 - A00005 SL: AXA INSURANCE (S) P/L
 AXA INSURANCE (S) P/L
 8 SHENTON WAY,
 #27-01 AXA TOWER,
 SINGAPORE 068811

GST Reg.No:M28920628X
 Inv.No. : B&P 7013414 Page 1
 Inv.date. : 30/04/2018
 WIP No. : 32960
 Veh.In/Out: 06/12/2017 27/12/2017
 *Tel.No. : 6338 7288
 Reg.No. : SLB7277U
 Reg.date : 20/04/2016
 Mileage : 13,995
 Chassis No: JN1BCAY51Z0490037

Closed by : Mandy Neo
 Svc Consultant : ACC
 Remarks : Success United Pte L

Parts/Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, LH TAILLAMP, REAR REINFORCEMENT, SENSOR, REFLECTOR. REPAIR LHR FENDER, END PANEL		0	3400.00	0		3,400.00	S
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, LHR FENDER, END PANEL		0	2250.00	0		2,250.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		0	390.00	0		390.00	S
EXC	Excess cost		0	400.00	0		-400.00	S
850224AP1H	FACE-RR BUMPER	1.0	EA	1166.40	10		1,049.76	S
850904AP0B	ENERGY ABSORBER	1.0	EA	182.00	10		163.80	S
852201MA0A	BRACKET BUMPER	1.0	EA	33.60	10		30.24	S
852211MA0A	BRACKET BUMPER	1.0	EA	33.60	10		30.24	S
620941MA0A	SPACER	2.0	EA	7.50	10		13.50	S
850321MA0B	BUMPER BEAM REAR	1.0	EA	841.90	10		757.71	S
852201MA5A	BRACKET BUMPER REAR	1.0	EA	28.00	10		25.20	S

SERVICE TAX INVOICE

0 - A00005	SL: AXA INSURANCE (S) P/L	GST Reg.No:M28920628X
AXA INSURANCE (S) P/L		Inv.No. . : B&P 7013414 Page 2
8 SHENTON WAY,		Inv.date. : 30/04/2018
#27-01 AXA TOWER,		WIP No. . : 32960
SINGAPORE 068811		Veh.In/Out: 06/12/2017 27/12/2017
		*Tel.No. . : 6338 7288
		Reg.No. . : SLB7277U
Closed by : Mandy Neo		Reg.date. : 20/04/2016
Svc Consultant : ACC		Mileage . : 13,995
Remarks : Success United Pte L		Chassis No: JN1BCAY51Z0490037

Parts/Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
265554AMOB	I265554AM0A/LAMP COM	1.0	EA	809.90	10		728.91	S
LR027871	ADHESIVE SEALER FL2	1.0	EA	358.30	10		322.47	S

		Gross Total.	9,161.83
		Less.....	400.00
Labour Total	6,040.00	Net.....	8,761.83
Parts Total	3,121.83	GST @ 7.0%	613.33
Package Total	0.00	Total.....	9,375.16
		Paid.....	0.00
		Please Pay..	9,375.16

GST: S=StdRated; O=OutOfScope; Z=ZeroRated
 Enquiries must be lodged within 14 days from the invoice date
 This is a computer generated invoice. No signature is required.

Wearnes Automotive Pte. Ltd.
SATISFACTION CERTIFICATE

I/We GAS XIAOBN hereby state that the
repairs to my/our INFINITI Q70 Vehicle No. SLB7277U have
been carried out to my/our entire satisfaction and I/We agree that the discharge
to the account of Messrs. Wearnes Automotive Pte. Ltd. for S\$ 9,375.16 by
the AYA INSURANCE shall be in full discharge of all
claims under Policy No. GA 281758 in respect of damage
to my/our vehicle, as the result of an accident which occurred on or about the
02 day of 12/17 at 1300.



Customer's Signature / Date
(PLEASE SIGN AND RETURN)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2017		06 Dec 2017 10:53 Edit Adj Rpt	S\$9,161.83 Edit Estimates	S\$9,161.83 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: GAO XIAO RUI , ID: S8574176D, Tel: +6597358621, Email: MOTOR@IVANINSURANCE.COM									
Vehicle Reg. No.: SLB7277U		Date of Loss: 02/12/2017 00:00 - :59 [19 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / C0461817		Policy/Cover Note No.: GA281758 (Comprehensive)							
		Excess: S\$400.00							
Repairer: Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370									
Handling Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Kitty Teo - 6880 4602]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/12/2017]									
Driver/Custodian: GAO XIAO RUI (32 / Male), NRIC: S8574176D, Tel: +6597358621									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AXA_SG (02/07/2018): URGENT - PLEASE ADVISE STATUS									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLB7277U (C0461817)**
OD
Dec 2 2017 12:00AM
[GAO XIAO RUI]
Wearnes Automotive Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
----------------------------------	-------------------------------	------------------------------------	------------------------------	------------------------------	---

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/12/17 19:09	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/12/17 10:12	General View		Load PDF	
2	13/07/18 09:55	Reinspection Photo		Load PDF	

Documentation				1 per page	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	06/12/17 08:49	EMAIL_ABS		Load PDF	
2	06/12/17 08:49	GIA SLB7277U INSD_ABS		Load PDF	
3	06/12/17 08:49	ESTIMATE_ABS		Load PDF	
4	06/12/17 08:49	DRIVING LICENCE_ABS		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/07/18 11:07	WORKSHOP INVOICE		Load PDF	
2	16/07/18 11:07	DISCHARGE VOUCHER		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way #24-01, AXA Tower
Singapore 068811

Our File No: CS/AXA17023166/R1RBQ2

Date: 16/07/2018

REFERENCE

Insured/Claimant: GAO XIAO RUI Policy No: GA281758
Date of Loss: 02/12/2017 Nature of Claim: OD Claim No: C0461817

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB7277U**
Make & Model: INFINITI Q70, 2.5 (A) Engine No: VQ25883959A
Reg. Date: 20/04/2016 (Man. Year: 2015) Chassis No: JN1BCAY51Z0490037
Colour: White Odometer: 12592 km
Engine Capacity: 2496 cc
Market Value/New Car Price: S\$144,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/50 R18 Rear Tyre Size: 245/50 R18
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,552.10	3,121.83	6,430.27	67.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,620.00	6,040.00	3,580.00	37.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,172.10	9,161.83	10,010.27	52.21
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	18,772.10	8,761.83	10,010.27	53.33
+ GST 7.00/7.00% (S\$)	1,314.05	613.33	700.72	53.33
Nett Amount (S\$)	20,086.15	9,375.16	10,710.99	53.33

INSPECTION

Date of Assignment: 06/12/2017

Date Inspected: 06/12/2017 Inspected At:

45 LENG KEE ROAD SINGAPORE
159103Repairer: Wearnes Automotive Pte Ltd
(Alexandra Road)

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Jul 2018)
Parts: 143	INFINITI Q70 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLB7277U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,RR BUMPER (CONSISTENT)	Torn	1,166.40 FS	*1,049.76 FS
2	1		*ENERGY ABSORBER (CONSISTENT)	Cut	182.00 FS	*163.80 FS
3	1		*BRACKET BUMPER (CONSISTENT)	Necessary	33.60 FS	*30.24 FS
4	1		*BRACKET BUMPER (CONSISTENT)	Necessary	33.60 FS	*30.24 FS
5	2		*SPACER (CONSISTENT)	Necessary	15.00 FS	*13.50 FS
6	1		*BUMPER BEAM REAR (CONSISTENT)	Bent	841.90 FS	*757.71 FS
7	1		*REAR BUMPER BEAM BRA (CONSISTENT)	Serviceable	57.80 FS	*- FS
8	1		*REAR BUMPER BEAM BRA (CONSISTENT)	Serviceable	57.80 FS	*- FS
9	1		*BRACKET BUMPER REAR (CONSISTENT)	Necessary	28.00 FS	*25.20 FS
10	4		*COVER (CONSISTENT)	Serviceable	280.00 FS	*- FS
11	4		*SENSOR ASSY (CONSISTENT)	Serviceable	896.00 FS	*- FS
12	1		*ORNAMENT ASSY R (CONSISTENT)	Serviceable	56.80 FS	*- FS
13	1		*ORNAMENT ASSY L(CONSISTENT)	Serviceable	56.80 FS	*- FS
14	1		*LAMP COMB RR ,LH (CONSISTENT)	Broken	809.90 FS	*728.91 FS
15	1		*RIM -COMBI-LAMP (CONSISTENT)	Serviceable	102.30 FS	*- FS
16	1		*PROTECTOR (CONSISTENT)	Serviceable	112.00 FS	*- FS
17	1		*INNER PANEL REAR (CONSISTENT)	Serviceable	631.90 FS	*- FS
18	1		*FENDER- REAR LH (CONSISTENT)	Repair	1,182.50 FS	*- FS
19	1		*EXT-FENDER RR U (CONSISTENT)	Serviceable	78.40 FS	*- FS
20	1		*GLAS -BACK WIND (CONSISTENT)	Serviceable	1,650.00 FS	*- FS
21	1		*WINDSCREEN SEAL FRT (CONSISTENT)	Serviceable	33.80 FS	*- FS
22	1		*BODY PANEL SEALANT X (CONSISTENT)	Serviceable	820.20 FS	*- FS
23	1		*ADHESIVE SEALER FL2 (CONSISTENT)	Necessary	425.40 FS	*322.47 FS
					Total Parts (\$\$)	9,552.10 3,121.83

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER,LHR FENDER ,LH TAILLAMP,REAR REINFORCEMENT ,SENSOR,REFLECTOR ,REPAIR BOOTLID ,ETC	New	5,100.00	3,400.00
2	TO PUTTY SPRAYPAINT ON REAR BUMPER,LHR FENDER ,BOOTLID ,ETC	New	3,000.00	2,250.00
3	TO REPLACE REAR WINDSCREEN	New	850.00	0.00
4	TO INSTALL REAR W/S FILM	New	280.00	0.00
5	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES	New	390.00	390.00
Gross Labour Cost (S\$)			9,620.00	6,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >