

ASS. REC. BY:

REF: CS3

MSG17023771

/Wbpr

Special Instruction:

range

Surveyor:

Wilson

ASSIGNMENT (Office)

Mentor

From (Person):

Lionel Tan

of

MSG

Date/Time:

6/12/17 @ 9:55am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL 7064 M

Insured:

GU4133E

at Workshop m/s

Green Star Spray Painting

Tel:

6546 8092

of

Blk 3011 Bedok North Ave 4 # 01-2004 Ind. Park E 489977

Policy No:

MSD/VCT/17-000540

Claim No:

MSC/V/17-007868

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/11/2017

7/12/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

2pm @ 6/12/17

Person Contacted:

Jayne

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

SJL 7064 M - NA / MSG17022648 / 24

D.O.A. : 28/11/2017

GU 4133 E - NA / MSG17022648 / 24

D.O.A. : 28/11/2017

After repair: 18.12.2017

19.12.17 438pm Email to Katherine Wong thru Melmen

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (

), Case handler to make sure all information created by the assignment team are ACCURATE

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (

), Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler:

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17023171/Wb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 06-12-2017		
		Code : MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GU 4133E	Veh. Inspected	SJL 7064M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (LIONEL TAN)	Assign Date	06/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/11/2017	Inspection Date	07/12/2017	
Survey held at	GREEN STAR SPRAY PAINTING BLK 3011 BEDOK NORTH AVE 4 #01-2004 BEDOK INDUSTRIAL PARK E SINGAPORE 489977			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inv Auth'd	Status
Main	28 Nov 2017		06 Dec 2017 09:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KST AUTO RENTAL PTE LTD, Co. Reg. No.: 200806860W		
Main Claimant:	AETNA PTE LTD, Co. Reg. No.: 198003861K		
Vehicle Reg. No.:	SJL7064M	Date of Loss:	28/11/2017 11:00 - :59
Claim Type:	TP / MSC/V/17-001868	Policy/Cover Note No.:	MSD/VCT/17-000540 (Third Party Only) Coverage: 13/03/2017 - 12/03/2018
Vehicle Reg. No. (Insured):	GU4133E	Policy No. (Claimant):	
		Excess:	
Repairer:	GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pel - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/12/2017]		
Driver/Custodian (Insured):	MOHAMAD SHAFFI BIN ISMAIL (), NRIC: S7213832E, Tel: +6597207510		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/11/2017 13:10
Date Of Accident	28/11/2017 12:00
Exact Location Of Accident	MACPHERSON ROAD (TOWARDS PIE, JURONG)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL7064M
Insured/Policyholder	
Name Of Registered Owner	AETNA PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91095315

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C 200 KOMPRESSOR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD16V16329/VPC/R08 (COMP)
Cover Note Number	

Driver

Name of Driver	JONATHAN QUEK ZEEN YICK (JONATHAN GUO RENYI)
NRIC No	S7439444B
Date Of Birth	24/11/1974
Occupation	OUTDOOR
Date Of Driving Pass	04/05/1995
Driving Experience	22 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91095315
Fax Number	
Contact Number	
Email Address	NOEMAIL

* Address	32 KEW HEIGHTS
Postcode	466085
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING FROM MACPHERSON ROAD TOWARDS PIE (JURONG) DIRECTION. AT THE FILTER LANE, I WAS ON THE LEFT LANE. I WANTED TO CHANGE LANE TO THE RIGHT LANE. I PUT ON MY RIGHT SIGNAL AND STARTED TO CHANGE LANE TO THE RIGHT. WHILE DOING SO, THE VAN(GU4133E) CAME APPROACHING, STARTED TO ACCELERATE UPON SEEING MY CAR FILTERING TO THE RIGHT. AS A RESULT, THE SAID VAN HIT ONTO THE REAR RIGHT SIDE OF MY CAR. ATTENDED BY AINI

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GU4133E
Vehicle Make/Model/Colour	TOYOTA HIACE DIESEL
Details Of Properties	
Name of Driver	MOHAMAD SHAFFI BIN ISMAIL
NRIC/Passport Number	S7213832E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

28 NOV 2017

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vac@idac.com.sg
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer e-file.

DECLARATION

I/We declare the foregoing particulars are true to every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

28 NOV 2017

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3861K
Vehicle Details	
Vehicle No.:	SJL7064M
Vehicle to be Exported:	No
Intended De-registration Date:	19 Dec 2017
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 200 KOMPRESSOR
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	27195031089535
Chassis No.:	WDD2040412A176791
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$41,962.00
Original Registration Date:	10 Dec 2008
First Registration Date:	10 Dec 2008
Transfer Count:	0
Actual ARF Paid:	\$41,962.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Dec 2018
PARF Rebate Amount:	\$20,981.00
Intended COE Rebate Details	

COE Expiry Date:	09 Dec 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$6,501.00
COE Rebate Amount:	\$631.00
Total Rebate Amount:	\$21,612.00

The information contained herein is correct as at 19 Dec 2017

OK

View Sent Message

This mail is associated with :

***SJL7064M (MSC/V/17-001868)**
[GU4133E]

TP
AETNA PTE LTD
Nov 28 2017 11:00AM
[KST AUTO RENTAL PTE LTD]
GREEN STAR SPRAY PAINTING

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 19/12/2017 16:38 PM.
To MSI_WCS
Subject Pre-repair Inspection

Dear Katherine,

Refer to your assignment on 06.12.2017 at 9.55AM.

Please be informed that we have inspected the vehicle SJL 7064M on 07.12.2017 at 5.49PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2017		06 Dec 2017 09:55 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KST AUTO RENTAL PTE LTD, Co. Reg. No.: 200806860W			
Main Claimant:	AETNA PTE LTD, Co. Reg. No.: 198003861K			
Vehicle Reg. No.:	SJL7064M	Date of Loss:	28/11/2017 11:00 - :59 [107 Months and 18 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / MSC/V/17-001868	Policy/Cover Note No.:	MSD/VCT/17-000540 (Third Party Only) Coverage: 13/03/2017 - 12/03/2018	
Vehicle Reg. No. (Insured):	GU4133E	Policy No. (Claimant):		
		Excess:		
Repairer:	GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 07/12/2017]			
Driver/Custodian (Insured):	MOHAMAD SHAFFI BIN ISMAIL (), NRIC: S7213832E, Tel: +6597207510			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)




































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									
















Claim Documents

*SJL7064M (MSC/V/17-001868)
[GU4133E]
TP
AETNA PTE LTD
Nov 28 2017 11:00AM
[KST AUTO RENTAL PTE LTD]
GREEN STAR SPRAY PAINTING

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 16:55	General View	 Load JPG	<input checked="" type="checkbox"/>
2	09/04/18 16:55	General View	 Load JPG	<input checked="" type="checkbox"/>
3	09/04/18 16:55	General View	 Load JPG	<input checked="" type="checkbox"/>
4	09/04/18 16:55	General View	 Load JPG	<input checked="" type="checkbox"/>
5	09/04/18 16:55	General View	 Load JPG	<input checked="" type="checkbox"/>
6	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
7	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
8	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
9	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
10	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
11	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
12	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
13	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
14	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
15	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
16	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
17	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
18	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
19	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
20	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
21	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
22	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
23	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
24	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
25	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
26	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
27	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
28	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
29	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
30	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
31	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
32	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
33	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
34	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
35	09/04/18 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	09/04/18 16:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/12/17 09:44	Disagree on SJE	 Load PDF	
2	06/12/17 09:44	Fax From Third Party	 Load PDF	
3	06/12/17 09:44	TP GIA Rep - SJL7064M	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17023171/WB

Date: 11/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VCT/17-000540
 Claimant Vehicle No: SJL7064M Insured Vehicle No: GU4133E
 Date of Loss: 28/11/2017 Nature of Claim: TP Claim No: MSC/V/17-001868

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJL7064M**
 Make & Model: MERCEDES-BENZ C200, 1.8 Kompressor (A) Engine No: 27195031089535
 Reg. Date: 10/12/2008 (Man. Year: 2008) Chassis No: WDD2040412A176791
 Colour: Purple Odometer: 138225 km
 Engine Capacity: 1796 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45ZR17 Rear Tyre Size: 225/45ZR17
 Front Left Side: VICTRA 4 mm Rear Left Side: VICTRA 3 mm
 Front Right Side: VICTRA 4 mm Rear Right Side: VICTRA 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/12/2017
 Date Inspected: 07/12/2017 Inspected At: GREEN STAR SPRAY PAINTING (HQ)
 BEDOK INDUSTRIAL PARK E
 Singapore 489977
 Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,900.00 - \$8,800.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Apr 2018)

Parts: 143 MERCEDES-BENZ C200 1.8 Kompressor (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJL7064M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >