

22/03/2002

ASS. REC. BY:

REF:

CS3/MSG17023174 / R1/bk

Special Instruction:

Range

Simulator:
Maimen

Rasul

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSIG

Date/Time:

6/12/17 @ 10.59am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL 4496X

Insured:

SFJ 2812L

at Workshop m/s

Thrice Automobile

Tel:

9622 5181

of

31K 1001 Bk / Merah Lane 3, #01-63 159718

Policy No:

27699565 TMP

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

2/12/2017

CA / REV / REP. / REV 24 HRS

up

20-12-2017

H.O.D. Endorsement:

Date/Time:

2pm @ 6/12/17

Person Contacted:

Richard

Vehicle IN / OUT

Date/Time

Action/Instruction

(X)

Estimate

SL 4496X

-NBA

INC17023027/k4

D.O.A: 2/12/17

SFJ 2812L

-NBA

INC17023027/k4

D.O.A: 2/12/17

JANIS 1:08pm

Email to


Irene Tan thru Maimen

Signature P. J. B. M.

REF: MSIG

ASSIGNMENT

From: _____ Date: 20/12/17
 Estimated Cost: _____
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLL 4496X
 at Workshop m/s Trinice Automobile
 of 31k 1001, Bkt Merah Lane 3#01-63159718
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLL 4496X Yr Regn: 2008 May 05
 Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: MAZDA 5 C.C.
 Colour: PURPLE A/O: Insured / Std / NI / NA
 Sp. Reading: 203892 T.Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM6CR10F280304367
 Gen. Cond: Good / (Fair) / Poor / Burnt
 Steering: In (order) / Jammed / Leaked / Burnt or
 Brake: In (order) / Jammed / Leaked / Burnt or
 Modi: Nil / (S) Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / (MIC) / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 02/12/17 D.O.I. 21/12/17 @ 12:34pm
 Survey held at TRINICE
 Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ESTIMATE RANGE COST OF REPAIR - (2K - 4K)

RECEIVED 29 JAN 2018

Date/Time. File Pass to? ☐ : Preli. Report

1. 27012018 ☐ : Final Report

Date/Time. File Return to?

2. _____

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee: 120

Transportation: _____

_____ \$ + RS. _____ \$

Photos: 10

Others: _____

TOTAL

Report Format : PRS

Lump Sum / I.B.I: \$ _____

Add Fee: ☐ : Site Insp. \$ _____

☐ : Interview \$ _____

☐ : Tech. Adv. \$ _____

☐ : Weekend \$ _____

130



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17023174/R1b

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 06-12-2017



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SFJ 2812L	Veh. Inspected	SLL 4496X
Policy No.	27699505TMP	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	06/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/12/2017	Inspection Date	
Survey held at	TRINICE AUTOMOBILE SERVICES BLK 1001 BUKIT MERAH LANE 3 #01-63 SINGAPORE 159724		

5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.</p> <p>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.</p> <p>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Assigned	Status
Main	06 Dec 2017		06 Dec 2017 10:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LOH KHAM HWA, ID: S0090667		
Main Claimant:	QUALITY LEASING PRIVATE LIMITED, Co. Reg. No.: 201312796G		
Vehicle Reg. No.:	SLL4496X	Date of Loss:	02/12/2017 19:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	27699505TMP (Third Party Only) Coverage: 18/05/2017 - 17/05/2018
Vehicle Reg. No. (Insured):	SFJ2812L	Policy No. (Claimant):	
		Excess:	
Repairer:	Trinice Automobile Services (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-63, 159718 Bukit Merah - Tel: 62716422		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Tan Jin Hao

From: Tan Jin Hao
Sent: Wednesday, 6 December, 2017 10:58 AM
To: 'Yvonne'
Cc: Irene Tan
Subject: RE: MSIG Insured SFJ2812L [EAL.2017.5334.EA.MK.ya - SLL4496X]

WITHOUT PREJUDICE

Dear Yvonne,

We regret to inform you that we are unable to accept your list of nominated Single Join Experts(SJE). We will proceed to appoint a surveyor from M/s LKK Auto Consultants Pte Ltd for your client's claim. His/ Her name will be made known later.

Please be informed that our surveyor will also be conducting the post repair inspection within the timeline stipulated under the protocol.

Have A Great Week Ahead!

Tan Jin Hao
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2583 | Direct fax +65 6225 7402 | jinhao_tan@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Yvonne [<mailto:yvonne@ealc.com.sg>]
Sent: Wednesday, 6 December, 2017 10:57 AM
To: Tan Jin Hao <jinhao_tan@sg.msig-asia.com>
Cc: Irene Tan <irene_tan@sg.msig-asia.com>
Subject: RE: MSIG Insured SFJ2812L [EAL.2017.5334.EA.MK.ya - SLL4496X]

Our ref : 2017.5334.EA.MK.ya - SLL4496X
Your ref : SFJ2812L

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

MSIG Insurance Singapore Pte Ltd
No. 4 Shenton Way,
#21-01 SGX Centre 2
Singapore 068807
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s MSIG Insurance Singapore Pte Ltd		
Vehicle SLL4496X inspected as follows by Name:		
Before repair	Parts removed	After repair
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE
CLAIMANT: QUALITY LEASING PRIVATE LIMITED
ACCIDENT INVOLVING SLL4496X & SFJ2812L ON 02 DECEMBER 2017 ALONG LAVENDER STREET AT ABOUT 1930 HOURS

We refer to the above matter wherein we are instructed to act for **QUALITY LEASING PRIVATE LIMITED**, the owner of vehicle no. **SLL4496X**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SLL4496X** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Trinice Automobile Services
Block 1001 Bukit Merah Lane 3,
#01-63,
Singapore 159718
Tel: 96225181 (Richard) Please call prior to inspection

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/12/2017 13:17
Date Of Accident	02/12/2017 19:30
Exact Location Of Accident	LAVENDER STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL4496X
Insured/Policyholder	
Name Of Registered Owner	QUALITY LEASING PRIVATE LIMITED
Co Reg No	201312796G
Email Address	RASHIDLAZAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93364464
Alternative Phone No	OFFICE-93364464

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRER

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088407699

Cover Note Number

Driver

Name of Driver	ABDUL RASHID BIN LAZAN
NRIC No	S1653799C
Date Of Birth	05/04/1964
Occupation	OUTDOOR
Date Of Driving Pass	21/03/1984
Driving Experience	33 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93364464
Fax Number	
Contact Number	OTHERS-93364464
Email Address	RASHIDLAZAN@GMAIL.COM

Address BLK 689B WOODLANDS DRIVE 75
#04-98
Postcode 732689
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFJ2812L
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver NG KAM CHEE
NRIC/Passport Number S0024292F
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

Sketch Plan

SLL4496X_SKETCH0001.jpg

Page 1 of 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Person**.
3. Information provided must be as **truthful and accurate as possible**. Any initial misrepresentation or withholding of material facts may allow insurance companies to **repudiate under liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any late reporting may be referred to the Police for investigations.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to request of the report being made available aforesaid.

2. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyer/s/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/s/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time: 4/12/2017

[Signature]

Reporting Centre Personnel's Signature
Name
NRK/TIR No.

[Signature]
5/12/2017

Sketch Plan #2

SLL4496X_SKETCH0002.jpg

Page 1 of 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2nd December 2017 at about 7:30 pm, I was at the junction of Laverter street traffic light. I had stopped at the traffic junction for about 1 minute waiting for the traffic light to turn green. While waiting for the light to turn green, suddenly a Toyota car knock the bumper of my car. I got out of my car and immediately took pictures of the accident and the driver's IC. There were no injury on me and the car (Toyota) driver but the rear bumper of my car was damaged. The driver of the Toyota car told me to claim his insurance for the damage on my car.

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time 4/12/2017

Reporting Centre Personnel's Signature
Name
ID No./Full No.

5/12/2017

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2796G

Vehicle Details

Vehicle No.: SLL4496X

Vehicle to be Exported: No

Intended De-registration Date: 20 Jan 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA5

Primary Colour: Purple

Manufacturing Year: 2008

Engine No.: LF10533202

Chassis No.: JM6CR10F280304367

Maximum Power Output: 107.0 kW (143 bhp)

Open Market Value: \$22,302.00

Original Registration Date: 05 May 2008

First Registration Date: 05 May 2008

Transfer Count: 1

Actual ARF Paid: \$22,302.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 04 May 2018

PARF Rebate Amount: \$11,151.00

Intended COE Rebate Details

COE Expiry Date:	04 May 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,501.00
COE Rebate Amount:	\$562.00
Total Rebate Amount:	\$11,713.00

The information contained herein is correct as at 20 Jan 2018

OK

View Sent Message

This mail is associated with :

***SLL4496X (539883)**
[SFJ2812L]

TP
QUALITY LEASING PRIVATE LIMITED
Dec 2 2017 7:00PM
[LOH KHAM HWA]
Trinice Automobile Services

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 20/01/2018 13:08 PM.
To MSI_ITAN
Subject Pre-repair Inspection

Dear Irene,

Refer to your assignment on 06.12.2017 at 10.59AM.

Please be informed that we have inspected the vehicle SLL 4496X on 21.12.2017 at 12.34PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Dec 2017		06 Dec 2017 10:59 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LOH KHAM HWA, ID: S0090667J		
Main Claimant:	QUALITY LEASING PRIVATE LIMITED, Co. Reg. No.: 201312796G		
Vehicle Reg. No.:	SLL4496X	Date of Loss:	02/12/2017 19:00 - :59
Claim Type:	TP / 539883	Policy/Cover Note No.:	27699505TMP (Third Party Only) Coverage: 18/05/2017 - 17/05/2018
Vehicle Reg. No. (Insured):	SFJ2812L	Policy No. (Claimant):	
		Excess:	
Repairer:	Trinice Automobile Services (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-63, 159718 Bukit Merah - Tel: 62716422		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 07/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLL4496X (539883)**
[SFJ2812L]
TP
QUALITY LEASING PRIVATE LIMITED
Dec 2 2017 7:00PM
[LOH KHAM HWA]
Trinice Automobile Services

Upload Documents Upload Photos Compose New Letter		View View in Browser		
Assessment Reports		1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/12/17 12:05	Accident Statement <small>From: SC - Reg. No: SFJ2812L, Claimant: LOH KHAM HWA</small>	Load HTM	<input type="checkbox"/>
Photos/Images		3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/01/18 13:07	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	20/01/18 13:07	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
4	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
5	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
6	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
7	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
8	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
9	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
10	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
11	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
12	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
13	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
14	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
15	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
16	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
17	20/01/18 13:07	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation		1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/12/17 10:56	TP GIA REPORT	Load PDF	<input type="checkbox"/>
2	06/12/17 10:59	EMAIL to TP reject their list of SJE	Load PDF	<input type="checkbox"/>
3	26/01/18 15:39	LOD	Load PDF	<input type="checkbox"/>
4	26/01/18 15:39	Final Repair Bill, Survey Fee	Load PDF	<input type="checkbox"/>
5	26/01/18 15:39	Survey Report	Load PDF	<input type="checkbox"/>
6	26/01/18 15:39	Survey Report photos	Load PDF	<input type="checkbox"/>
7	30/01/18 10:00	instruction to LKK to prepare paper survey report	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17023174/R1BE2

Date: 30/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27699505TMP

Claimant Vehicle No : SLL4496X

Insured Vehicle No : SFJ2812L

Date of Loss: 02/12/2017

Nature of Claim: TP

Claim No: 539883

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL4496X

Make & Model: MAZDA 5, 2.0 (A)

Engine No: LF10533202

Reg. Date: 05/05/2008 (Man. Year: 2008)

Chassis No: JM6CR10F280304367

Colour: Purple

Odometer: 203892 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/12/2017

Date Inspected: 21/12/2017 Inspected At:

Trinice Automobile Services (HQ)
BLK 1001 BUKIT MERAH LANE 3 #01-63
Singapore 159718

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jan 2018)
Parts: M1-MPV MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL4496X)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >