Veh. No : 56 J 3 499 PSP:	
Action/Instruction:	,
1.File 2.Submit Photo? YES / NO	Message:
3.Indicate Res. Date on Photo Page.	
If No, due to a) No addition	
others:	

Reference No.: CS TP 170 23199 UV D
Policy Type: OD / TP / TP RES / TL / EVA

Typist

lmin (): Case handler to make sure all Inf	Y-Date	N-Date	Y-Date	N-Date
Office	Assign Form Reference No.	~			
c	Customer Code				
N	Assign From				
C	Assign Date	V			
	Veh No (Inspected)	~			
С	Veh No (Inspected)				
С	Part of the Control o	~			
С	D.O.A				
С	Policy No				
С	Claim No				
С	Insurance Authorisation (CA /REV/REP)	~			
С	Report Type				
С	Weekend Charges	11000000			
N	Survey held at/Repairer				
С	Excess		1.4.1	-11 inad	informa
urvey	or (): Case handler to make su	re the surveryor c	ompleted a	ali requireu	mornia
	nment Form				_
C	Vehicle No	~			-
c	Regn Month/Year	~			
N	Vehicle Type	~			-
N	Make & Model	/			-
C	Engine Capacity. (C.C)	V			-
N	Colour	~			+
C	Odometer. (Sp.Reading)	~		-	-
C	Chassis No	~		 	-
N	General Condition	~			-
N	Steering	~			-
N	Brake	~			
	Modification (Modi)	~			
N		_			
C	Tyre Size Tyre Make	~			
N	Tyre Balance	~			
С	Date of Inspection	~			
C	Survey held	~			
N	Des.of Damages	~			
N					
	tem - (Views/Merimen)				
С	Damaged Vehicle Photographs Uploaded				
(3) Wo	rkshop Estimate/Assignment Form			7	
N	ALL Parts condition	~		-	
С	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	440			-
C	Days of repair	~	-		-
	Finalised Amount		1920		
	E. I				
С	Re-inspection Cases to Finalize Within 5 Days	100			
C	Re-inspection Cases to Finalize within 5 Days stem - (Views/Merimen) Resurvey photo Uploaded			-	

Case Handler



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	ationale Des Experts En Auton	WARRANT CO.	
FORT	TUNA MOTOR *		Ref : CS/TP1702319	9/UVD	
40 UI 4552		T ROADSINGAPORE	Date: 06-12-2017 Code: TP167		
1.		Policy Particula	ars :- THIRD PARTY CLAIM	M ale	
1000	Insured Veh.		Veh. Inspected	SGJ 3499P	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From		Assign Date	06/12/2017	
2.		Vehicle P	articulars & Condition		
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer - Brakes		Steering Modification		
	General				
3.	GENERAL SE	Cor	nditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.		Descr	ription of Damages		
_		Cou	neral Information		
5.	Accident Date	Ger	Inspection Date	06/12/2017	
_		FORTUNA MOTOR	mapedaen Este	#90500 - 1920 NUST	
	Survey held at	40 UPPER EAST COAST F SINGAPORE 455212	ROAD		
5a.			Remarks		
Jul	A)THE INSPECTION	ON WAS CONDUCTED ON CE TO YOUR INSTRUCTION	A"WITHOUT PREJUDICE" BA NS, WE HAVE NOT AUTHOR	ASIS. RISED REPAIRS.	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type	Singapore NRIC	
Owner ID	4890G	
Vehicle Details		
Vehicle No.	SGJ3499P	
Vehicle to be Exported	No	
Intended De-registration Date	07 Dec 2017	
Vehicle Make	TOYOTA	
Vehicle Model	VIOS 1.5E A	
Primary Colour	Silver	
Manufacturing Year	2006	
Engine No.	1NZX449298	
Chassis No.	MR053HY4204194602	
Maximum Power Output	80.0 kW (107 bhp)	
Open Market Value	\$12,707.00	
Original Registration Date	07 Jul 2006	
First Registration Date	07 Jul 2006	
Transfer Count	0	
Actual ARF Paid	\$13,978.00	
Intended PARF Rebate Details		
PARF Eligibility	Forfeited	
PARF Eligibility Expiry Date	(2)	
PARF Rebate Amount	\$0.00	
Intended COE Rebate Details		
COE Expiry Date	06 Jul 2026	
COE Category	A - Car (1600cc & below)	
COE Period(Years)	10	
PQP Paid	\$49,519.00	
COE Rebate Amount	\$42,487.00	
Total Rebate Amount	\$42,487.00	


The information contained herein is correct as at 07 Dec 2017

ОК





insurer's nric & license Pg. 1





insurer's nric & license Pg. 1





SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of
- Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCID	ENT STA	TEMENT
-------	---------	--------

Date Of Report 02/12/2017 11:07

Date Of Accident 01/12/2017 19:15

Exact Location Of Accident SLIP RD OF UPP EAST COAST RD TO BEDOK SOUTH AVE 1

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGJ3499P

Insured/Policyholder

Name Of Registered Owner TANG PEI PEI NRIC No S7624890G

Email Address PEIPEI_TANG@YAHOO.COM.SG

 Mobile Phone No
 (LOCAL) +65-96878430

 Alternative Phone No
 OTHERS-96878430

Vehicle Particulars

Manufacturer TOYOTA
Model VIOS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number D17MTPV01009856

Cover Note Number 07/07/2017 TO 06/07/2018

Driver

 Name of Driver
 TANG PEI PEI

 NRIC No
 \$7624890G

 Date Of Birth
 14/08/1976

 Occupation
 INDOOR

 Date Of Driving Pass
 08/12/1995

Driving Experience 21 YEARS AND 11 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-96878430

Fax Number

Contact Number OTHERS-96878430

EMail Address PEIPEI_TANG@YAHOO.COM.SG

Address

APT BLK 912 TAMPINES STREET 91 #09-117 S520912

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

-

OWNER

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance,

NO

Number of Passengers (Including Driver)

4

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACHED.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SBS3465Z

Vehicle Make/Model/Colour

NIL

Details Of Properties

NIL

Name of Driver

ZHU XUE PING

NRIC/Passport Number

G2844047U 86522618

Contact Number

NIL

Address

NIL

Postcode

NIL

Insurance Company Name

Nature Of Damage

NIL

No. Of Passenger (Including Driver)

Details of Witness

Name

NIL

Phone Number

NIL

Email Address

NIL

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: 2/12/17

11-30 am

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

SKETCH PLAN Bedok South Ave 1 upper East const Road SGJ3499P DESCRIBE CIRCUMSTANCES OF THE ACCIDENT December 2017 7.15 pm Upper East Coast Road -> slip road Bedok South Ave 1 was driving and stopped to check if the road was clear of traffic so that I can drive off. While checking for traffic, the bus driver knocked into my car 199 bale of Accident 1 . 12 him Damage Claim Third Party Claim TBA DECLARATION I/We declare the foregoing particulars are true in every respect. Policyholder's Signature Driver's Signature Reporting Centre Personnel's Signature Date & Time: 2 / 12 | 17 (If driver is not the policyholder) Name:

Date & Time:

11-30 am

NRIC/FIN No.:

Accident Sketch Plan Pg. 1

certificate of insurance Pg. 1



Sompo Insurance Singapore Pte. Ltd.

50 Reffles Place; #05-01/06 Singapore Land Tower. Singapore 048523 Ter 6461 #555 | Fax: 6221 3302 | Websits: www.sompo.com.sg Co. Reg. No. 1989054908 | CST Reg. No. M203903198

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No.

D17MTPV01009856

Insured

TANG PELPEL

Motor Car (Registration No.) SGJ3499P

: Comprehensive - ExcelDrive Gold Plan

Policy Commencement Date : 07 JULY 2017 00:00

Policy Expiry Date

: 06 JULY 2018 23:59

Maximum Liability (Section I) : Market value at time of loss

: \$500 - Section I

(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim

per policy year)

Voluntary Excess*

: Buy Up : \$500 - Section I

Windscreen Excess*

S\$100.00 - Walved if Repair at ExcelDrive Workshop

Loss of Use

: Per Policy Schedule

Persons or Classes of Persons entitled to drive*

Any other person who is driving on the Insured's order or with his permission.
 In the event of the death of the insured.

a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured, and b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been

withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration. under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward. racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323

Whe HEREBY CERTIFY that the policy to which this Certificate relativis is issued in accordance with (1), the provisions of the Motor Velvices (Third-Party Righs and Compensation) Act (Chapter 189) and Part IV of the Read Transport Act 1987 (Maleysia), and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP, 27

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 27 JUNE 2017 14:13

IMPORTANT NOTICE

Keep the Certificate in your Motor Car.

Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act,
on the sale of the Motor Car or if for any reason the trisurance is terminated during its oursersty, the insurance must sumender the Certificate of insurance and the Policy to the insurance company. If the Certificate of insurance had been lost or destroyed, a stellurary cectaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189):
This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name 11P04007 & PROMISELAND INDEPENDENT PTE LTD CI Code: 22A 4X6DLZB4K11M1HFA

^{*} Subject to GST wherever applicable

Not Allus 145 \$3800 Sday.

FURTUNA MOTOR

SGJ 3499P

BOOTLD	m/suc \$495.10	
BOOTLID HINGES @48.50	\$97.00 X	
BOOTLID WEATHERSTRIP	4 w/ \$121.10	
BOOTLID INNER LOCK	In1 \$65.10	
BOOTLID OUTER HANDLE	cre \$99.10	
BOOTLID REAR LOGO	Nec \$42.00	
BOOTLID VIOS EMBLEM	n \$31.50	
BOOTLID 1.5 EMBLEM	ner \$38.50	
BOOTLID VVTI EMBLEM	ru \$39.90	
BOOTLID E EMBLEM	M \$30.94	
TAILLAMPS @\$320.10	cm \$640.20	
TAILLAMP HOUSING PANELS @\$126.80	€ \$253.60 X	
REAR BUMPER	m/re \$360.95	
REAR BUPMER SIDE RETAINERS @\$25.50	\$1.00	
1 SET REAR BUMPER CLIPS	n \$50.00	
REAR END PANEL	3 Mgs \$719.70	
REAR END PANEL TOP GARNISH	~m \$65.90	
23.50 12.5 17.5 17.5 17.5 17.5 17.5 17.5 17.5 17		
REAR FLOOR PANEL REAR FLOOR PANEL TOP BOARD	11 \$145.50×	
REAR FLOOR PANEL TOP BOARD	\$3,959.99	
		2810.59
S.NETT		213621
3.NET1	27	C134.06
1 SET REAR BUMPER REVERSE SENSOR	shill \$280.00 200	4565.24
1 SET REAR END PANEL SEALANT	Nu 550.00 L	1-0
RAER LICENCE PLATE	cm \$30.00 20	
RAER LICENCE PLATE	330.00	
TO CHECK WIRING	\$50.00 30	
TO DISMANTLE & REPLACE REVERSE SENSOR	\$80.00 50	
TO TRANSFER BOOTLID MECHANISM	\$100.00 60	
	\$120.00 &0	
TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY	\$100.00 60	
TO SPRAY RUST PROOFING		
LABOUR FOR PANEL BEATING ETCS	44 200 00	
TO PUTTY & SPRAY PAINTING	TOTAL \$7,049.99	
	TOTAL \$7,049.99	

LYSK Auto-Consultants hence notify

- the Repairer of the following:
- To resurvey before after spray painting.
- To display damaged part(s) during resurvey
- . Purp prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- . No rilenal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Interna	ationale Des Experts En Autom	obile
FORTUNA MOTOR *		Ref : CS/TP1702319	9/Uvbn2
40 UPPER EAST COA 455212 ON BEHALF OF TANG	ST ROADSINGAPORE	Date: 28-12-2017 Code: TP167	
1.	A SA PART OF THE P	rs :- THIRD PARTY CLAI	M
Insured Veh.	•	Veh. Inspected	SGJ 3499P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/12/2017
2.	Vehicle Pa	rticulars & Condition	
Make & Model	TOYOTA VIOS (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053HY4204194602	Colour	GREY
Odometer	152215	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	175/65 R14	NEXEN	6 mm
L/H Front Tyre	175/65 R14	NEXEN	6 mm
R/H Rear Tyre	175/65 R14	NEXEN	6 mm
L/H Rear Tyre	175/65 R14	NEXEN	6 mm
4.	The state of the s	iption of Damages	NEC CONTROL CONTROL
THE VEHICLE SU	STAINED DAMAGES AT THE DETAILS.	REAR PORTION.	
5.	Gen	eral Information	
Accident Date	01/12/2017	Inspection Date	06/12/2017
Survey held at	FORTUNA MOTOR		
	40 UPPER EAST COAST R SINGAPORE 455212	OAD	
5a.		Remarks	
A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A' CE TO YOUR INSTRUCTION	S, WE HAVE NOT AUTHORI	SIS. SED REPAIRS.
5b.		ate Days of Repair	CENTRE VERNING
ESTIMATED NOF	RMAL PERIOD FOR REPAIR:	5 Working Da	iys



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 3499P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	DENTED / BUCKLED	495.10	495.10
2	BOOTLID HINGE @\$48.50	TO REPAIR SEE LABOUR	97.00	
1	BOOTLID WEATHERSTRIP	TWISTED	121.10	121.10
1	BOOTLID INNER LOCK	TWISTED	65.10	65.10
1	BOOTLID OUTER HANDLE	CRACKED	99.10	99.10
1	BOOTLID REAR LOGO	NECESSARY	42.00	42.00
1	BOOTLID VIOS EMBLEM	NECESSARY	31.50	31.50
1	BOOTLID 1.5 EMBLEM	NECESSARY	38.50	38.50
1	BOOTLID VVTI EMBLEM	NECESSARY	39.90	39.90
1	BOOTLID E EMBLEM	NECESSARY	30.94	30.94
2	TAILLAMPS @\$320.10	CRACKED	640.20	640.20
2	TAILLAMP HOUSING PANELS @\$126.80	TO REPAIR SEE LABOUR	253.60	
1	REAR BUMPER	DENTED / DEFORMED	360.95	360.95
2	REAR BUMPER SIDE RETAINERS @\$25.50	BENT	51.00	51.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	BADLY DENTED	719.70	719.70
1	REAR END PANEL TOP GARNISH	TWISTED	65.90	65.90
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	612.90	
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	145.50	
	LESS 25% DISCOUNT			-712.75
			3,959.99	2,138.24
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
	REAR LICENCE PLATE (SN)	CRACKED	30.00	20.00
			360.00	270.00
	LABOUR			
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE & REPLACE REVERSE SENSOR.		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM.		100.00	60.00

Report Ref No. CS/TP17023199/Uvbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.		100.00	60.00
	LABOUR FOR PANEL BEATING ETCS.INCLUSIVE OF THE REPAIR OF BOOTLID HINGE, TAILLAMP HOUSING PANELS AND REAR FLOOR PANEL.		1,080.00	1,000.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	1,100.00
			2,730.00	2,380.00
	GRAND TOTAL		7,049.99	4,788.24

RECOMMENDED COST OF LUMP SUM REPAIRS	3,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/TP17023199/Uvbn2

CHUA KANG SENG

Licensed Appraiser