

## SMRT Accident Vehicle Repair Estimates

EQ

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6332L  
 Ref. No : TAX/12/17/2025  
 Reg. Date : 28/06/2016  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : KOH WEE TECK  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 05/12/2017 12:42:00 PM  
 Accident Reported Date / Time : 05/12/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024093458  
 Special Instruction to ARC, if any :  
 YP198H  
 Prepared Date : 05/12/2017 02:02:51 PM



Sebastian  
6/12/2017.

- Part by part repair.
- Question Mark Item Photo
- Photo Before & After Paint

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U205768295 Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,314.00	0.00
Total Material Charges	: 1,813.09	1,813.09
Other Charges	: 580.00	0.00
<b>TOTAL</b>	<b>: 4,552.09</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 5.00	<del>0.00</del>
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sign Off Date	: 06/12/2017 09:08:53 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/12/2017 09:08:53 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :  
Quotation Date : Invoice Date :  
Invoice Amount : Prepared Date :

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	845.00	<del>0.00</del> 300
<b>Total Labour</b>	<b>845.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	<del>0.00</del> 200
TO RESPRAY VIEW MIRROR	180.00	<del>0.00</del> 50
TO RESPRAY FRONT FENDER LH	378.00	<del>0.00</del> 200
TO REPSRAY FRONT BUMPER	378.00	<del>0.00</del> 200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,314.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	<del>0.00</del> 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO REMOVE AND REFIX WING MIRROR	120.00	<del>0.00</del> 30
TO REPLACE SUNDRY PARTS	100.00	<del>0.00</del> 20
TO WASH AND VACUUM	60.00	0.00 X
TO TRANSFER DOOR MECHANISM	120.00	0.00 X
<b>Total Other Costs</b>	<b>580.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
37002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace R	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace /NEC	No
37945-74010		6505597	COVER, OUTER MIRROR, LH	1	107.40	25.00	80.55	Replace	Replace R	No
31740-52040		6505465	MIRROR LAMP LH	1	65.30	10.00	58.77	Replace	Replace /SCA	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace R	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace /NEC	No
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace R	No
<b>TOTAL MATERIALS</b>								<b>1,813.10</b>	<b>1,813.09</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>1,813.09</b>	<b>1,813.09</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									