

ASS. B.C. BY:

REF: CS/MSG17073291/Ttth

Special Instruction:

Survivor: Tawlich

ASSIGNMENT (Office)

From (Person): Eliza Ho

of

mslg

Date/Time: 09/12/2017 3:27pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

E900B

Insured:

at Workshop m/s

Borneo Motor

Tel:

9847 6178

of

2 Pandan Crescent

Policy No:

A80410564 RMY

Claim No:

Sum Insured:

Excess:

\$1000.00

Make of Veh:

D.O.A

05/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

08/12/2017 @ 10am

H.O.D. Endorsement:

Date/Time:

07/12/2017 3:36pm

Person Contacted:

Wally

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	E900B - X
14/2	Report via Wally
11/12 10:38am	authorise repair by Kenny Ong
11/12 10:56am	email to Wally authorise repair
	Part by Part 16,246.91 (Red: 2624.58: 13%)

Signature: Tanpin REF: MSU1

ASSIGNMENT

From: _____ Date: 08-12-2017

Estimated Cost: 0.00 WS / TP RES / OO RES / EVA / INV / MV

To inspect Vehicle No: E900B

at Workshop no: Borneo motor

of: 2 Pandan Crescent

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Ven: Wally - 9847 6178

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

10am owner waiting

NS	O/S

Bel. or Market Value: 9118K.

DAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: E900B Vt Regn: 2014 Jan

Type: Motor / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Lexus ES300 cc 2494

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 49848 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/Nr: 3THSW167650204471

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 55 R17 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. _____		D.O.I. <u>8/12/17 @ 1020</u>

Survey held at: Borneo Pandan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

SKS 8525 before part

4/4/2018

RECEIVED 04 APR 2018

Case Time File Pass to: ☐ Prel. Report ☒ Final Report

A/A Typist

Case Time File Return to: _____

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp \$ ☐ Interview \$ ☐ Tech Insp \$ ☐ Witness \$

Survey Fee: 200

Transportation: _____

Photo: _____

Other: _____

Report Format: OD

Lump Sum / I.B.H: 16246.91



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17023291/T1tb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 07-12-2017		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		E 900B
Policy No. A80410564QMY		Coverage (\$)		0.00
Claim No.		Excess (\$)		1,000.00
Assign From MERIMEN (ELIZA HO)		Assign Date		07/12/2017
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 05/12/2017		Inspection Date 08/12/2017		
Survey held at BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462				
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2017		07 Dec 2017 15:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHEE SIANG CHYE, ID: S1471129E, Tel: +6596190550, Email: ALFREDCHEE1003@GMAIL.COM								
Vehicle Reg. No.:	E900B	Date of Loss:	05/12/2017 14:00 - :59						
Claim Type:	OD	Policy/Cover Note No.:	A80410564QMY (Comprehensive) Coverage: 10/08/2016 - 07/01/2018						
		Excess:	S\$1,000.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/12/2017]								
Driver/Custodian:	CHEE SIANG CHYE (56 / Male), NRIC: S1471129E, Tel: +6596190550								
Adj Asg. Remarks:	REVERT - OWNER WAITING 8/12/17 @ 10AM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 11 December, 2017 10:56 AM
To: 'wally.tan@borneomotors.com.sg'
Cc: SUR
Subject: E 900B / MSIG / OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **E 900B (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***E900B (539920)**

OD

Dec 5 2017 2:00PM

[CHEE SIANG CHYE]

Borneo Motors (S) Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 11/12/2017 10:38 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14911.06) - E900B - Claim Handler: Eliza Ho Teng Boon

Approved:14911.06:a If c

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 11 Dec 2017

Preliminary Advice

Vehicle No	: E900B	Accident Date	: 05/12/2017
Make	: LEXUS ES300H	Policy No.	: A80410564QMY
Assignment Date	: 07/12/2017	Excess	: S\$1,000.00
Date of Inspection	: 08/12/2017	Est. Duration of Repair	: 10.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,871.49
Revised Amount	:S\$	14,911.06
Check Items (Estimated)	:S\$	1,335.86
Total	:S\$	16,246.92

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	118,000.00
COE / PARF Rebate	:S\$	78,761.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,239.00

Remarks

- (x) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	1129E

Vehicle Details

Vehicle No.	E900B
Vehicle to be Exported	No
Intended De-registration Date	11 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	LEXUS ES300H CVT
Primary Colour	Silver
Manufacturing Year	2013
Engine No.	2AR0975684
Chassis No.	JTHBW1GG502041971
Maximum Power Output	151.0 kW (202 bhp)
Open Market Value	\$42,006.00
Original Registration Date	08 Jan 2014
First Registration Date	08 Jan 2014
Transfer Count	1
Actual ARF Paid	\$40,809.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	07 Jan 2024
PARF Rebate Amount	\$30,606.00

Intended COE Rebate Details

COE Expiry Date	07 Jan 2024
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$79,300.00
COE Rebate Amount	\$48,155.00
Total Rebate Amount	\$78,761.00

The information contained herein is correct as at 11 Dec 2017

OK



UP TO **64% OFF***
CAR INSURANCE

Starting from **\$411.69***
Receive \$50 CapitaVouchers*
T&C's apply

BUY NOW

income

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

2008 Fully Done Up Subaru STI. No Dekit.



Engine Only 40k Km Mileage
After Full Engine Rebuild And
Overhaul.
Direct Owner

ABWIN



Browse by Category

Sort by Da

& with 113

LEXUS ES300

Advanced S

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	LEXUS ES300		Any	Any	2014	Any	Any



**Lexus ES Hybrid ES300h
Luxury**

\$120,800

\$15,880 /yr

18-Feb-2014

2,494 cc

67,103

Fuel Type: Petrol-Electric

1 Owner Only, Excellent Condition, Agent's Unit! Rare Luxury Model ES300H With Sunroof. Black Premium Leather. Powerful Efficiency! Full Agent Service With Record! View To Belle...

Posted: 04-Dec-2017 Tags: 2014 Lexus ES, 2014 Lexus ES, Lexus ES, Lexus ES, Lexus, ES, ES, Used Lexus

Save this search criteria, to get email alerts whenever a match is found

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
------	-------	-------	--------------	----------	---------	---------

For old advertisements, view Expired ads

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, to station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car bans, low mileage cars, car brands, carpark rates LEXUS ES300 Singapore, used LEXUS ES300 Singapore, used LEXUS ES300, used vehicles Singapore or even buy used LEXUS ES300 Singapore. We have new car & car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable. Information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Product's Guide
- Article
- Forum

Compare

All rights reserved.

TYPE OF CLAIM: ☒ DOD ☐ OD/UL ☐ DS

MCA:

WT

MOTOR ACCIDENT REPORT

Date Of Report: 6.12.17 Time: 1130 Date Of Accident: 5.12.17 Time: 1430
Exact Location Of Accident: 51 Bt. Batok Crescent Unity Centre car park.
Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ / Johor ☐ / Perak ☐ / Kedah ☐ / Kelantan ☐ / Terengganu ☐ / Pulau Pinang ☐ / Perlis ☐ / Thailand ☐

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: E900B Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: S1471129E
Name Of Registered Owner: Chee Siang Chye
Mobile Number: 96190550 Alternative No: Email Address:

Vehicle Particulars

Manufacturer: Toyota ☐ Lexus ☒ Suzuki ☐ Hino ☐ Model: ES300H
Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):
Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐
Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: MSIG
Any in-Car Camera? (applicable for United Overseas Insurance Limited insured only): Yes ☐ (please attach photo) No ☒
Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: A80410564 Qmy

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: Chee Siang Chye NRIC/ Passport / FIN No: S1471129E
Date Of Birth: 29.10.1961 Occupation: Indoor ☐ Outdoor ☐
Date Of Driving Pass: 18.2.1984 Gender: Male ☒ Female ☐
Mobile Number: 96190550 Fax No: Alternative No:
Address: 85 Hillview Avenue #10.03 Postal Code: 669587
Email Address: Alfredchee1003@gmail.com
Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured: Self
Vehicle Registration Number of Driver's Own Vehicle (if applicable):
Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Hit onto concrete pillar Number of Passengers in the above vehicle (including Driver): 1
Weather Conditions: Clear ☒ Raining ☐ Others ☐ (if others, please state condition):
Road Surface: Wet ☐ Dry ☒ Others ☐ (if others, please state condition):
Was any body injured in the Accident? No ☒ Yes ☐
Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:
Was any other material or property (e.g. other vehicle) damaged? No ☒ Yes ☐
Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☒ Yes ☐
Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):
Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: Vehicle Make/Model/Colour:
Details Of Properties Damage in Accident:
Name of Driver:
NRIC/Passport/FIN Number: Contact Number:
Address: Postal Code:
Insurance Company Name:
Nature Of Damage: No. Of Passenger (Including Driver):

DETAILS OF ACCIDENT INDEPENDANT WITNESS

Name: Name:
Phone Number: Phone Number:
Email Address: Email Address:

DETAILS OF INJURED PERSON 1 (Please fill Annex A if more person injured)

Name: Approximate Age:
Address: Postal Code:
Injuries Sustained: Injured person in which vehicle:
Were seat belt worn? No ☐ Yes ☒ Were injured conveyed to hospital by ambulance? No ☐ Yes ☐

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

was trying to negotiate a narrow bend but somehow misjudge the turning and therefore scratch the side of the car (driverside) ~~to~~ the pillar wall.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1989 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 185 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

MOTOR MAX PLUS
Comprehensive

Certificate No. A-304155E4 QM7

Excess : 5000.000

Windscreen Excess 500.00

1. Index Mark and Registration Number of Vehicle

東陽外刊輯

2. Name of Policyholder

3. Effective Date of the Commencement of Insurance for the purposes of the Act

4. Date of Expiry of Insurance

5. Persons or Classes of Persons entitled to drive*

Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

- ### 6. Limitations as to use¹

use only for social domestic and pleasure purposes and for the
policyholder's business.

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MGIA AUTHORIZED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 159).

(WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof)

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurer

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number **S1471129E**

Name
CHEE SIANG CHYE

Birth Date **29 Oct 1961**

Valid Until **28 May 2003**

000S20113F



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1471129E**

Name
CHEE SIANG CHYE

钱香材

Race
CHINESE

Date of birth **29-10-1961** Sex **M**

Country of birth
SINGAPORE




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
15 Feb 1984

18P-425A

License No. **S1471129E**



4788004

S1471129E

Date of issue
25-07-2011

Address
**85 HILLVIEW AVENUE
#10-03
SINGAPORE 669587**





Attn: Motor Claim Dept.

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail		Account No S1000004 / ICCUA1		Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept <i>Survey on 8/12/17 10am</i>		Document No 0		Mr Chee Siang Chye 85 Hillview Avenue #10-03 Singapore 669587 Mobile: 96190550	
		Document Date 07/12/2017			

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BEXGB	S1	AVV60R	08/01/2014	E0900B	0	14740 64OD/E0900B/051217

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBW1GG502041971	2AR0975684	60	Wally Tan G H	06/12/2017	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	3	BP-SUNDRY SUNDRIES <i>Ne</i> POLICY NO.: A 80410564 QMY ACC DATE: 05.12.17 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				✓ 80. 100.00
2	B	BP-LAB TRANSFER R/R DOOR COMPONENT AND MECHANISM TO NEW DOOR SHELL. (NETT)				✓ 816.00
3	B	BP-LAB REMOVE/REPLACE RHS ROCKER MLDG. (NETT)				✓ 204.00
4	I	BP-WS REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR. (NETT)				✓ 816.00
5	B	BP-LAB CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)				✓ 204.00
6	B	BP-LAB REMOVE/REFIX REAR LUGGAGE COMPARTMENT INTERIOR TRIM GARNISH TO ASSIST REPAIR.				✓ 612 816.00

LKK Auto Consultants hence notify the Repairer of the following:

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors

Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Customer's Signature
Please acknowledge receipt of vehicle

Change Summary
Parts
Labour
Materials
Lubrication/Fluid
Others

Total	Sur@lkkauto.com.
Less	Repair Ex \$1000
Amount Due	<i>7/12/17</i>

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 07/12/2017
TIME 08:10

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO E0900B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Chee Siang Chye 85 Hillview Avenue #10-03 Singapore 669587 Mobile: 96190550
	Document No 0	
	Document Date 07/12/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BEXGB	S1	08/01/2014	E0900B	0	14740	640D/E0900B/051217

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBW1GG502041971	2AR0975684	60	Wally Tan G H	06/12/2017	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
7	B	BP-LAB REMOVE/REFIX INTERIOR UPHOLSTERY, ROOF LINING, REAR SPEAKER BOARD, TRIMMINGS, GARNISHS, FRONT AND REAR SEATS, SEAT BELTS, FLOOR CARPETS IN ORDER TO FACILITATE REPAIR. (NETT)				816.00
8	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN RHS DOOR PILLAR, RHS ROCKER PANEL, R/R WHEEL ARCH PANEL, R/R BODY PANEL, CUT AND WELD PANEL AND FIT NEW PARTS.	1	4896.00		4896.00
9	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				2800.00
10	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
11	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)				612.00
12	1	L67003-33220 PANEL SUB-ASSY RR	1.00	1150.60	15.00	978.01
13	2	L75977-33030 STRIPE RR DOOR	1.00	36.90	15.00	31.36
14	3	L75987-33060 STRIPE RR DOOR	1.00	67.10	15.00	57.03
15	4	L67895-33030 WEATHERSTRIP RR	1.00	59.80	15.00	50.83
16	5	L67887-33040 WEATHERSTRIP RR	1.00	59.80	15.00	50.83
17	6	L67857-33040 PROTECTOR, RR DOOR	1.00	10.80	15.00	9.18

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 07/12/2017
TIME 08:10

VEHICLE NO E0900B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MB-8500000-9www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Chee Siang Chye 85 Hillview Avenue #10-03 Singapore 669587 Mobile: 96190550
	Document No 0	
	Document Date 07/12/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BEXGB	S1	08/01/2014	E0900B	0	14740	640D/E0900B/051217

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBW1GG502041971	2AR0975684	60	Wally Tan G H	06/12/2017	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
18	7	L75473-33020 PLATE, BODY SIDE RH <i>rec</i>	1.00	73.80	15.00	✓ 62.73
19	8	L75761-33070 MOULDING RR DOOR <i>rec</i>	1.00	95.30	15.00	✓ 81.00
20	9	L90269-04051 RIVET <i>rec</i>	7.00	1.20	15.00	✓ 7.14
21	0	L64801-33905 GLASS, BACK WINDOW? <i>windscreen rec - photo</i>	1.00	1571.60	15.00	✓ 1335.86 <i>rec</i>
22	1	L75573-33080 MOULDING, BACK WINDOW <i>rec</i>	1.00	58.40	15.00	✓ 49.64
23	2	L56117-50140 DAM, WINDOW GLASS <i>rec</i>	1.00	27.90	15.00	✓ 23.71
24	3	L56115-30100 STOPPER, WINDSHIELD <i>rec</i>	2.00	4.40	15.00	✓ 7.48
25	4	T56116-22050 STOPPER, WINDSHIE <i>rec</i>	2.00	4.30	15.00	✓ 7.30
26	5	T04562-12010 W/SCREEN DAM KIT, <i>rec</i>	1.00	101.00	15.00	✓ 85.85
27	6	T08826-08682 SINGLE STEP PRIMER <i>rec</i>	1.00	173.44	15.00	✓ 147.42
28	7	T08826-08609 SUPER FAST URETHANE BLACK <i>rec</i>	2.00	90.08	15.00	✓ 153.14
29	8	L61611-33250 PANEL, QUARTER RH <i>rec</i>	1.00	1449.90	15.00	✓ 1232.41
30	9	L58747-33071 PROTECTOR, QUART <i>rec</i>	1.00	27.70	15.00	✓ 23.54
31	0	T08826-08115 PANEL BONDING AD <i>rec</i>	1.00	237.60	15.00	✓ 201.96
32	1	L75851-33912 MOULDING BODY <i>rec</i>	1.00	774.70	15.00	✓ 658.49
33	2	L75863-33030 PROTECTOR ROCKER <i>rec</i>	3.00	25.00	15.00	✓ 63.75
34	3	L75866-30030 ROCKER MLDG PROTECTOR 6 <i>rec</i>	2.00	9.60	15.00	✓ 16.32
35	4	L75867-30130 CLIP <i>rec</i>	9.00	9.10	15.00	✓ 69.57
36	5	L75867-33050 CLIP ROCKER PANEL <i>rec</i>	7.00	8.80	15.00	✓ 52.36

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 5,456.91	17,636.91
		Labour 12,180.00	GST 7.00%
		Materials 0.00	1,234.58
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 18,871.49

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 07/12/2017
TIME 08:10

VEHICLE NO E0900B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Atas Taufik
Final Bill

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MP-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail				Account No S1000004 / ICCUA1		Customer Detail		
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept				Document No 0		Mr Chee Siang Chye 85 Hillview Avenue #10-03 Singapore 669587 Mobile: 96190550		
				Document Date 08/02/2018				
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
13	BEYGB S1	AVV60R	08/01/2014	E0900B	50076	14740	640D/E0900B/051217	
Chassis No		Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHBW1GG502041971		2AR0975684	60	Wally Tan G H	06/12/2017	0.00	08/02/2018 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:A 80410564 QMY ACC DATE:05.12.17 TOW/DRIVE IN: EXCESS:\$1000/- DATE-IN:12.12.17 DATE SURVEY:08.12.17 NO OF REPAIR DAYS: BY:TAUFIKH (LKK) AUTHORIZED ON:11.12.17						80.00
2	B	BP-LAB TRANSFER R/R DOOR COMPONENT AND MECHANISM TO NEW DOOR SHELL. (NETT)			22			816.00
3	B	BP-LAB REMOVE/REPLACE RHS ROCKER MLDG. (NETT)			22			204.00
4	I	BP-WS REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR. (NETT)			22			816.00
5	B	BP-LAB CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)			22			204.00
6	B	BP-LAB REMOVE/REFIX REAR LUGGAGE COMPARTMENT INTERIOR TRIM GARNISH TO ASSIST REPAIR.			22			612.00
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature			Change Summary		Total	
		Please acknowledge receipt of vehicle			Parts Labour Materials Lubrication/Fluid Others		Less	
							Amount Due	

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 08/02/2018
TIME 16:26

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO E0900B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : NP-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 120462
Tel no.: 6631 1388

Account Detail				Account No S1000004 / ICCUA1		Customer Detail			
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept				Document No 0		Mr Chee Siang Chye 85 Hillview Avenue #10-03 Singapore 669587 Mobile: 96190550			
				Document Date 08/02/2018					
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
13	BEXGB	S1	AVV60R	08/01/2014	E0900B	50076	14740 640D/E0900B/051217		
Chassis No		Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHBW1GG502041971		2AR0975684	60	Wally Tan G H	06/12/2017	0.00	08/02/2018 18.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
7	B	BP-LAB REMOVE/REFIX INTERIOR UPHOLSTERY, ROOF LINING, REAR SPEAKER BOARD, TRIMMINGS, GARNISHES, FRONT AND REAR SEATS, SEAT BELTS, FLOOR CARPETS IN ORDER TO FACILITATE REPAIR. (NETT)				22			816.00
8	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN RHS DOOR PILLAR, RHS ROCKER PANEL, R/R WHEEL ARCH PANEL, R/R BODY PANEL, CUT AND WELD PANEL AND FIT NEW PARTS.				22			4080.00
9	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				50			2450.00
10	Z	BP-SLANT SUPPLY SEALANT (NETT)							100.00
11	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)				18			612.00
12	V	EXC Excess element of insurance repair to be paid by the insured party				88			-1000.00
13	1	L67003-33220 PANEL SUB-ASSY RR				1.00	1150.60	15.00	978.01
14	2	L75977-33030 STRIPE RR DOOR				1.00	36.90	15.00	31.36
15	3	L75987-33060 STRIPE RR DOOR				1.00	67.10	15.00	57.03
16	4	L67895-33030 WEATHERSTRIP RR				1.00	59.80	15.00	50.83
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.									
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total			
		Please acknowledge receipt of vehicle		Parts Labour Materials Lubrication/Fluid Others		Less			
						Amount Due			

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 08/02/2018
TIME 16:26PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO E0900B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : 196700000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	Account No S1000004 / ICCUA1	Customer Detail Mr Chee Siang Chye 85 Hillview Avenue #10-03 Singapore 669587 Mobile: 96190550
	Document No 0	
	Document Date 08/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BEXGB	S1	AVV60R	08/01/2014	E0900B	50076	14740 640D/E0900B/051217

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBWIGG502041971	2AR0975684	60	Wally Tan G H	06/12/2017	0.00	08/02/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
17	5	L67887-33040 WEATHERSTRIP RR	1.00	59.80	15.00	50.83
18	6	L67857-33040 PROTECTOR, RR DOOR	1.00	10.80	15.00	9.18
19	7	L75473-33020 PLATE, BODY SIDE RH	1.00	73.80	15.00	62.73
20	8	L75761-33070 MOULDING RR DOOR	1.00	95.30	15.00	81.00
21	9	L90269-04051 RIVET	7.00	1.20	15.00	7.14
22	0	L64801-33905 GLASS, BACK WINDOW	1.00	1571.60	15.00	1335.86
23	1	L75573-33080 MOULDING, BACK WINDOW	1.00	58.40	15.00	49.64
24	2	L56117-50140 DAM, WINDOW GLASS	1.00	27.90	15.00	23.71
25	3	L56115-30100 STOPPER, WINDSHIELD	2.00	4.40	15.00	7.48
26	4	T56116-22050 STOPPER, WINDSHIELD	2.00	4.30	15.00	7.30
27	5	T04562-12010 DAM KIT, WINDOW GLASS	1.00	101.00	15.00	85.85
28	6	T08826-08682 SINGLE STEP PRIMER	1.00	173.44	15.00	147.42
29	7	T08826-08609 SUPER FAST URETHANE BLACK	2.00	90.08	15.00	153.14
30	8	L61611-33250 PANEL, QUARTER RH	1.00	1449.90	15.00	1232.41
31	9	L58747-33071 PROTECTOR, QUARTER	1.00	27.70	15.00	23.54
32	0	T08826-08115 PANEL BONDING AD	1.00	237.60	15.00	201.96
33	1	L75851-33912 MOULDING BODY	1.00	774.70	15.00	658.49
34	2	L75863-33030 PROTECTOR ROCKER	3.00	25.00	15.00	63.75
35	3	L75866-30030 ROCKER MOULDING PROTECTOR	2.00	9.60	15.00	16.32
36	4	L75867-30130 CLIP	9.00	9.10	15.00	69.57
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature Please acknowledge receipt of vehicle	Change Summary Parts Labour Materials Lubrication/Fluid Others	Total
			Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 08/02/2018
TIME 16:26PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO E0900B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : 196700000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail				Account No S1000004 / ICCU1		Customer Detail			
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept				Document No 0		Mr Chee Siang Chye 85 Hillview Avenue #10-03 Singapore 669587 Mobile: 96190550			
				Document Date 08/02/2018					
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
13	BEUGB S1	AVV60R	08/01/2014	E0900B	50076	14740	64OD/E0900B/051217		
Chassis No		Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHBW1GG502041971		2AR0975684	60	Wally Tan G H	06/12/2017	0.00	08/02/2018 18.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
37	S	L75867-33050 CLIP, ROCKER PANEL				7.00	8.80	15.00	52.36
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.									
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total			
		Please acknowledge receipt of vehicle		Parts		15,246.91			
				Labour		1,067.28			
				Materials		0.00			
				Lubrication/Fluid		0.00			
				Others		0.00			
						Less			
						0.00			
						Amount Due			
						16,314.19			

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 08/02/2018
TIME 16:26PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO E0900B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2017		07 Dec 2017 15:27 Edit Adj Rpt	S\$16,246.91 Edit Estimates	S\$16,246.91 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	CHEE SIANG CHYE, ID: S1471129E, Tel: +6596190550, Email: ALFREDCHEE1003@GMAIL.COM								
Vehicle Reg. No.:	E900B	Date of Loss:	05/12/2017 14:00 - :59 [46 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 539920	Policy/Cover Note No.:	A80410564QMY (Comprehensive) Coverage: 10/08/2016 - 07/01/2018						
		Excess:	S\$1,000.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 06/01/2018]								
Driver/Custodian:	CHEE SIANG CHYE (56 / Male), NRIC: S1471129E, Tel: +6596190550								
Adj Asg. Remarks:	REVERT - OWNER WAITING 8/12/17 @ 10AM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (02/04/2018): Alert - Adj Mandate Approved (S\$16246.91) - E900B - Claim Handler: Eliza Ho Teng... - MSIG_SG (11/12/2017): Alert - Adj Mandate Approved (S\$14911.06) - E900B - Claim Handler: Eliza Ho Teng...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*E900B (539920)
OD
Dec 5 2017 2:00PM
[CHEE SIANG CHYE]
Borneo Motors (S) Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)		Thumbnail	Print
1	06/12/17 15:48	Accident Statement		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/12/17 09:59	Adjuster Immediate Advice		Load HTM	
2	28/03/18 08:38	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)		Thumbnail	Print
1	06/12/17 15:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	06/12/17 15:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	06/12/17 15:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	06/12/17 15:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	06/12/17 15:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	06/12/17 15:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	06/12/17 15:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	06/12/17 15:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/12/17 10:16	General View		Load JPG	☒
2	11/12/17 10:16	General View		Load JPG	☒
3	11/12/17 10:16	General View		Load JPG	☒
4	11/12/17 10:16	General View		Load JPG	☒
5	11/12/17 10:16	General View		Load JPG	☒
6	11/12/17 10:16	General View		Load JPG	☒
7	11/12/17 10:16	General View		Load JPG	☒
8	11/12/17 10:16	General View		Load JPG	☒
9	11/12/17 10:16	General View		Load JPG	☒
10	11/12/17 10:16	General View		Load JPG	☒
11	11/12/17 10:16	General View		Load JPG	☒
12	11/12/17 10:16	General View		Load JPG	☒
13	11/12/17 10:16	General View		Load JPG	☒
14	11/12/17 10:16	General View		Load JPG	☒
15	11/12/17 10:16	General View		Load JPG	☒
16	11/12/17 10:16	General View		Load JPG	☒
17	11/12/17 10:16	General View		Load JPG	☒
18	11/12/17 10:16	General View		Load JPG	☒
19	11/12/17 10:16	General View		Load JPG	☒
20	11/12/17 10:16	General View		Load JPG	☒
21	11/12/17 10:16	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
22	28/03/18 09:15	Reinspection Photo	 Load JPG	☒
23	28/03/18 09:15	Reinspection Photo	 Load JPG	☒
24	28/03/18 09:15	Reinspection Photo	 Load JPG	☒
25	28/03/18 09:15	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/12/17 10:50	BORNEO ESTIMATE	 Load PDF	
2	07/12/17 10:52	WALLY REQUEST FOR SURVEY	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 10:12	estimate	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	06/12/17 15:48	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	06/12/17 15:48	Accident Photo	 Load JPG	☒
2	06/12/17 15:48	Accident Photo	 Load JPG	☒
3	06/12/17 15:48	Accident Photo	 Load JPG	☒
4	06/12/17 15:48	Accident Photo	 Load JPG	☒
5	06/12/17 15:48	Accident Photo	 Load JPG	☒
6	06/12/17 15:48	Accident Photo	 Load JPG	☒
7	06/12/17 15:48	Accident Photo	 Load JPG	☒
8	06/12/17 15:48	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	06/12/17 14:18	Accident Sketch Plan	 Load JPG	☒
2	06/12/17 14:18	Accident Sketch Plan	 Load JPG	☒
3	06/12/17 14:18	Accident Sketch Plan	 Load JPG	☒
4	06/12/17 14:18	Identification Card	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17023291/T1TBQ2

Date: 05/04/2018

REFERENCE

Insured/Claimant:	CHEE SIANG CHYE	Policy No:	A80410564QMY	
Date of Loss:	05/12/2017	Nature of Claim:	OD	Claim No: 539920

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	E900B		Engine No:	2AR0975684
Make & Model:	LEXUS ES300H, 2.5 Executive (A)		Chassis No:	JTHBW1GG502041971
Reg. Date:	08/01/2014 (Man. Year: 2013)		Odometer:	49848 km
Colour:	Silver			
Engine Capacity:	2494 cc			
Market Value/New Car Price:	S\$118,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,556.91	5,536.91	20.00	0.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,080.00	10,710.00	1,370.00	11.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,636.91	16,246.91	1,390.00	7.88
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	16,636.91	15,246.91	1,390.00	8.35
+ GST 7.00/7.00% (S\$)	1,164.58	1,067.28	97.30	8.35
Nett Amount (S\$)	17,801.49	16,314.19	1,487.30	8.35

INSPECTION

Date of Assignment:	07/12/2017	
Date Inspected:	08/12/2017	Inspected At: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2018)
Parts: 143	LEXUS ES300H 2.5 Executive (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for E900B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*80.00 FS
2	1		*PANEL SUB-ASSY RR	Bent	978.01 FS	*978.01 FS
3	1		*STRIPE RR DOOR	Necessary	31.36 FS	*31.36 FS
4	1		*STRIPE RR DOOR	Necessary	57.03 FS	*57.03 FS
5	1		*WEATHERSTRIP RR	Necessary	50.83 FS	*50.83 FS
6	1		*WEATHERSTRIP RR	Necessary	50.83 FS	*50.83 FS
7	1		*PROTECTOR ,RR DOOR	Necessary	9.18 FS	*9.18 FS
8	1		*PLATE ,BODY SIDE RH	Necessary	62.73 FS	*62.73 FS
9	1		*MOULDING RR DOOR	Necessary	81.00 FS	*81.00 FS
10	7		*RIVET	Necessary	7.14 FS	*7.14 FS
11	1		*GLASS ,BACK WINDOW	Necessary	1,335.86 FS	*1,335.86 FS
12	1		*MOULDING ,BACK WINDOW	Necessary	49.64 FS	*49.64 FS
13	1		*DAM,WINDOW GLASS	Necessary	23.71 FS	*23.71 FS
14	2		*STOPPER ,WINDSHIELD	Necessary	7.48 FS	*7.48 FS
15	2		*STOPPER ,WINDSHIE	Necessary	7.30 FS	*7.30 FS
16	1		*W/SCREEN DAM KIT	Necessary	85.85 FS	*85.85 FS
17	1		*SINGLE STEP PRIMER	Necessary	147.42 FS	*147.42 FS
18	2		*SUPER FAST URETHANE BLACK	Necessary	153.14 FS	*153.14 FS
19	1		*PANEL ,QUARTER RH	Bent	1,232.41 FS	*1,232.41 FS
20	1		*PROTECTOR ,QUART	Necessary	23.54 FS	*23.54 FS
21	1		*PANEL BONDING AD	Necessary	201.96 FS	*201.96 FS
22	1		*MOULDING BODY	Distorted	658.49 FS	*658.49 FS
23	3		*PROTECTOR ROCKER	Necessary	63.75 FS	*63.75 FS
24	2		*ROCKER MLDG PROTECTOR 6	Necessary	16.32 FS	*16.32 FS
25	9		*CLIP	Necessary	69.57 FS	*69.57 FS
26	7		*CLIP ROCKER PANEL	Necessary	52.36 FS	*52.36 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,556.91	5,536.91
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER R/R DOOR COMPONENT AND MECHANISM TO NEW DOOR SHELL	New	816.00	816.00
2	REMOVE/REPLACE RHS ROCKER MLDG	New	204.00	204.00
3	REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR	New	816.00	816.00
4	CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE	New	204.00	204.00
5	REMOVE/REFIX REAR LUGGAGE COMPARTMENT INTERIOR TRIM GARNISH TO ASSIST REPAIR	New	816.00	612.00
6	REMOVE/REFIX INTERIOR UPHOLSTERY ,ROOF LINING ,REAR SPEAKER BOARD,TRIMMINGS ,GARNISHS,FRONT AND REAR SEATS ,SEAT BELTS ,FLOOR CARPETS IN ORDER T FACILITATE REPAIR	New	816.00	816.00
7	REMOVE ALL NECESSARY PARTS ,TO ENABLE REPAIRING AND STRAIGHTEN RHS DOOR PILLAR,RHS ROCKER PANEL,R/R WHEEL ARCH PANEL,R/R BODY PANEL,CUT AND WELD PANEL AND FIT NEW PARTS	New	4,896.00	4,080.00
8	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	2,800.00	2,450.00
9	SUPPLY SEALANT	New	100.00	100.00
10	TO RESET ECU AND REPROGRAMME	New	612.00	612.00
Gross Labour Cost (S\$)			12,080.00	10,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >