

INS. CASE OWNER:

CC 4/AXA1702 3322, K2p679

LKK:

IDAC:

Surveyor:

Lavin

DOI:

ASSIGNMENT

2/12/19

Date / Time:

7/12/19

Registered in Merimen:

9/12/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 521K

Name of Insured:

TRANS-4B SERVICES PIV

Insured Tel No.:

HP:

Excess Sec II :\$5

4500

D.O.A.:

02/12/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LEE SONH BEE

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

10467850

Policy No.:

VX/PL680520

Make / Model:

RENNULT

Place of Accident:

AIRPORT BOULEVARD 73 TRV1
AUEUE

OI GIA REPORT (YES / NO):

TP GIA REPORT (YES / NO)

Insured Liability:

%

Final ? Yes / No

SH 94336

INSRS:
WSP:
Tel:
Liability:
RMKS:WUE
W
(APC)INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

01/12/19

Sent By:

Lm

PENALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email

Call

PENAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

KNO or B 28, Ass. Lia:

Repair Cost:

SS

353.10

Loss of Rental (LOR):

SS

50.76

4

days)

\$12519

Loss of Use (LOU):

SS

20.00

50

x 4

days)

Loss of Income (LOI):

SS

20.00

50

x 4

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GRA/LTA Search

SS

Medical:

SS

Overseasment:

SS

(e.g. Tow/Independent)

Legal Cost

SS

Total:

SS

1052.86

Global Sum SS: 1050.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Period 1:

SS

1050.00

Name 1:

Comfortelgro Engineering Pte Ltd

Period 2: (Strike if N.A.)

SS

Name 2:

Period 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

COPY SENT

Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Van No: SH 49336 Yr Regn: 7 Mar 2012
 Type: M/Car / M/Cycle / Bus / Van / Lorry / T/G Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq CC
 Colour: Blue A/C Insured / Std / NI / NA
 Sp Reading: 88642 T/Ratio: Insured / Std / NI / NA

Eng No: _____

C/No: _____

Gen. Cond: Good / F/P / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / 1 A/Rim or

Tyre Size F: 195/65R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / NIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Nexen

Front	Rear
R/Bal: <u>2</u> mm	R/Bal: <u>2</u> mm
L/Bal: <u>2</u> mm	L/Bal: <u>2</u> mm
D.O.A: <u>2/12/12</u>	D.O.I: <u>7/12/12</u>
Survey held at: _____	<u>CHAE (1/2/12)</u>

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP # 330 CRod # 1396.32 8241.

Axa
 1/1

Date/Time File Pass to:

☐

: Prel. Report

/

☐

: Final Report

Date/Time File Return to:

/

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1.3 + 1.5 = 2.8

Phone:

Other:

Report Format:

Lump Sum / I.B./I.C.

Add Fee:

☐

Site Insp: 15

☐

Intervy: 5

☐

Tech Insp: 5

☐

Weekend: 5

TOTAL:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/AXA17023322/K1pb3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 07-12-2017



Code : AX/2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 5221K	Veh. Inspected	SH 9933G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/12/2017	Inspection Date	07/12/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.305094823

CUSTOMER
R/MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL (P) 65508755 (O)

REGN NO SH 9933G	MILEAGE
MAKE HYUNDAI	FUEL E 1/2 F
MODEL IONIQ	DATE/TIME IN 04.12.2017 13:35
YR OF MANU 17.03.2017	TARGET DATE
CHASSIS CODE RMHC851CVHU022745	COMPLETION DATE/TIME

DISCOUNT CARD NO.

JOB DESCRIPTION

Ident Date: 02.12.2017
NATURE: 3P 02.12.2017

S/NO LABOR CODE DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

Vehicle No.: SH 9933G
CHIANG @

Vehicle No.: SH 9933G

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE*

DATE 5/12/2017 10:46

MAKE :

MODEL : HYUNDAI IONIC

Page 1 of 1

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305094823
Date : 07/12/17

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM


To : LKK
Attn : KALVIN
Vehicle Reg No. : SH9933G 02/12/17


Fax :

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: AXA SHC5221K
- The finalized amount shall be:

(a) Spare Parts after List discount	
(b) Labour Charges	\$330.00
Total for Part-By-Part Repair Cost	\$330.00
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	
- Estimated normal period for repairs: 2 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
- Thank you for your assistance. We confirm the estimates and finalized amount.

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : KALVIN
Date : 18/12/17

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 07.12.2017
Time: 17:05:11
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305094823
REGN NO : SH 9933G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ
DATE OF REGN : 17.03.2017
DATE/TIME IN : 04.12.2017 13:35
ACCIDENT DATE : 02.12.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 20-05	REAR BUMPER MAT	50.00
0001 L	PANEL BEATING	100.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	180.00

SUB-TOTAL : 330.00

TOTAL : 330.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

REPAIR ESTIMATE*

DATE 5/12/2017 10:46

MODEL : HYUNDAI IONIC

Labour Charge

Panel Beating

Spray Painting Charge

Wiring Charge

Remove/Refix Reverse Sensor

TOTAL LABOUR

ESTIMATE TOTAL

K₉102 1616161

7/12/17 1015h

2 Py.

pp

P.P.
After Rejo photo

8/12

LINK Auto
the Reg

- To identify the most likely

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 19 January 2018 9:06 AM
To: 'williamtan@cdge.com.sg'; 'catherinekoh@cdge.com.sg'
Subject: <Request for Video Footage> Your Ref: T1217/ SH 9933G/ WT(st) *Our Ref: CC4/AXA17023322/K1pb3 [ACCIDENT INVOLVING SHC 5221K(AXA) & SH 9933G ON 02/12/2017]
Attachments: SHC 5221K.PDF

Your Ref: **T1217/ SH 9933G/ WT(st)**
Our Ref: CC4/AXA17023322/K1pb3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SHC 5221K(AXA) & SH 9933G ON 02/12/2017

We refer to the above matter.

Please be informed that liability is unclear as our insured driver reported that your client reversed and collided onto his taxi. Attached here with a copy of our insured driver accident report for your easy reference.

We would like to request a copy of video footage as stated in your client accident report for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Catherine Koh Mui Gek <catherinekoh@cdge.com.sg>
Sent: Tuesday, 30 January 2018 4:30 PM
To: Hsiao Tong (LKKAuto)
Subject: Re: <Request for Video Footage> Your Ref: T1217/ SH 9933G/ WT(st) *Our Ref: CC4/AXA17023322/K1pb3 [ACCIDENT INVOLVING SHC 5221K(AXA) & SH 9933G ON 02/12/2017] - (scene photo attached, will hand CD to Calvin)
Attachments: IMG_9175.JPG; IMG_9177.JPG

Dear Hsiao Tong

Attached scene photo for your reference. Due to size of video footage, will hand CD to Calvin. Kindly settle our PD claim as per BOLA S27.

Thank you.

Best Regards
Catherine Koh
Claims Department | ComfortDelgro Engineering Pte Ltd
Off : 62148733 | Fax : 62141843

From: "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com>
To: "williamtan@cdge.com.sg" <williamtan@cdge.com.sg>, "catherinekoh@cdge.com.sg" <catherinekoh@cdge.com.sg>
Date: 19/01/2018 09:06 AM
Subject: <Request for Video Footage> Your Ref: T1217/ SH 9933G/ WT(st) *Our Ref: CC4/AXA17023322/K1pb3 [ACCIDENT INVOLVING SHC 5221K(AXA) & SH 9933G ON 02/12/2017]

Your Ref: **T1217/ SH 9933G/ WT(st)**
Our Ref: CC4/AXA17023322/K1pb3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SHC 5221K(AXA) & SH 9933G ON 02/12/2017

We refer to the above matter.

Please be informed that liability is unclear as our insured driver reported that your client reversed and collided onto his taxi. Attached here with a copy of our insured driver accident report for your easy reference.

We would like to request a copy of video footage as stated in your client accident report for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[attachment "SHC 5221K.PDF" deleted by Catherine Koh Mui Gek/cdge/delgronotes]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

Hsiao Tong (LKKAUTO)

From: claims <claims@transcab.com.sg>
Sent: Thursday, 20 September 2018 5:16 PM
To: Hsiao Tong (LKKAUTO)
Cc: 'jasminetan'; zhewei.kek@transcab.com.sg; claims@transcab.com.sg
Subject: RE: ACCIDENT INVOLVING SHC 5221K [AAD1712-047] AND SH 9933G ALONG/AT AIRPORT BOULEVARD T3 TAXI QUEUE ON 02/12/2017

WITHOUT PREJUDICE

Dear Hsiao Tong

Sorry for the delay.

We regret to inform that we do not have the video footage for this case.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, 16 June, 2018 3:34 PM
To: claims@transcab.com.sg; 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; 'Zhe Wei' (zhewei.kek@transcab.com.sg) <zhewei.kek@transcab.com.sg>
Subject: RE: ACCIDENT INVOLVING SHC 5221K AND SH 9933G ALONG/AT AIRPORT BOULEVARD T3 TAXI QUEUE ON 02/12/2017

Hi,

We refer to the above matter.

Kindly advise if there is any video footage submitted by your client to support his version that third party reversed and collided onto his taxi.

Appreciate an early reply.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Thursday, 21 December 2017 12:14 PM

To: claims@transcab.com.sg

Cc: 'carrisalee@ava-ins.com' <carrisalee@ava-ins.com>; 'ireneng@ava-ins.com' <ireneng@ava-ins.com>; Foo, John (VWG Singapore) (John.Foo@vw.com.sg) <John.Foo@vw.com.sg>; 'icewong@ava-ins.com' <icewong@ava-ins.com>

Subject: ACCIDENT INVOLVING SHC 5221K AND SH 9933G ALONG/AT AIRPORT BOULEVARD T3 TAXI QUEUE ON 02/12/2017

21 DEC 2017

Transcab Taxi
Singapore

Dear Sir,

OUR REF : CC4/AXA17023322/K1pb3

YOUR REF : P1680520 (SHC 5221K)

ACCIDENT INVOLVING SHC 5221K AND SH 9933G ALONG/AT AIRPORT BOULEVARD T3 TAXI QUEUE ON 02/12/2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from ComfortDelgro Engineering Pte Ltd acting on behalf of the owner of SH 9933G against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

We also wish to advise that there is an excess of **\$S5,000.00** attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

As Insurers, AXA shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg / chewht@lkkauto.com or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

"Wishes you a Merry Christmas & Happy New Year 2018"

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Sent Message

This mail is associated with :

***SH9933G (C0467050)**
[SHC5221K]

TP

COMFORTDELGRO ENGINEERING
Dec 2 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]
ComfortDelGro Engineering Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 16/06/2018 15:38 PM.
To cynthia.loh@axa.com.sg
CC AXA_SG; chewht@lkkauto.com
Subject Re: <Seek Instruction> C0467050 / P1680520

Hi Cynthia,

We refer to the above matter.

We have submitted a copy of third party video footage to you via Accellion.

From third party video footage, it shows that third party was moving forward slowly and stopped. His taxi did not reverse as reported by OID.

In view of the above, kindly advise if we may proceed to settle the matter under BOLA S27 or else advise further instruction.

Thank you.

Hsiao Tong
DID: 6742 3197

Print Sent Message

This mail is associated with :

***SH9933G (C0467050)**
[SHC5221K]

TP
COMFORTDELGRO ENGINEERING
Dec 2 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]
ComfortDelGro Engineering Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 28/07/2018 11:42 AM.
To vale.oh@axa.com.sg
CC AXA_SG; chewht@lkkauto.com
Subject Re: <Seek Instruction> C0467050 / P1680520

Hi,

We refer to the above matter.

We have uploaded a copy of third party video footage in Merimen.

From third party video footage, it shows that third party was moving forward slowly and stopped. His taxi did not reverse as reported by OID.

In view of the above, kindly advise if we may proceed to settle the matter under BOLA S27 or else advise further instruction.

Thank you.

Hsiao Tong
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: cynthia.loh@axa.com.sg
CC: AXA_SG; chewht@lkkauto.com
Sent On: 07/07/2018 08:49 AM
Subject: Re: C0467050 / P1680520

Hi Cynthia,

We refer to our email dated 16/06/2018.

Kindly let us have your instruction.

Hsiao Tong

<-- Original Message -->

From: LKK_HQ
To: cynthia.loh@axa.com.sg
CC: AXA_SG; chewht@lkkauto.com
Sent On: 16/06/2018 03:38 PM
Subject: Re: C0467050 / P1680520

Hi Cynthia,

We refer to the above matter.

We have submitted a copy of third party video footage to you via Accellion.

From third party video footage, it shows that third party was moving forward slowly and stopped. His taxi did not reverse as reported by OID.

In view of the above, kindly advise if we may proceed to settle the matter under BOLA S27 or else advise further instruction.

Thank you.

Hsiao Tong
DID: 6742 3197

Hsiao Tong (LKKAUTO)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Saturday, 28 July 2018 3:00 PM
To: vale.oh@axa.com.sg
Cc: Hsiao Tong (LKKAUTO)
Subject: Re: <Seek Instruction> C0467050 / P1680520

This mail is associated with :

***SH9933G (C0467050)**

[SHC5221K]

TP

COMFORTDELGRO ENGINEERING

Dec 2 2017 12:00AM

[TRANS-CAB SERVICES PTE LTD]

ComfortDelGro Engineering Pte Ltd



AXA INSURANCE PTE LTD
8 Shenton Way, #24-01 AXA Tower
Singapore 068811
Customer Centre 24/7 Cc
☎ (SG) 6880 4888
☎ (SG) 6338 2522
🌐 www.axa.com.sg
GST Reg No.: 1000035128
Co. Reg No.: 1000035128

Hi

We can't see any accident impact from the video, please advise, thanks.

VO

<-- Original Message -->

From: LKK_HQ
To: vale.oh@axa.com.sg
CC: AXA_SG; chewht@lkkauto.com
Sent On: 28/07/2018 11:42 AM
Subject: Re: C0467050 / P1680520

Hi,

We refer to the above matter.

We have uploaded a copy of third party video footage in Merimen.

From third party video footage, it shows that third party was moving forward slowly and stopped. His taxi did not reverse as reported by OID.

In view of the above, kindly advise if we may proceed to settle the matter under BOLA S27 or else advise further instruction.

Thank you.

1/2 ADMITTED THAT THERE WAS A SLIGHT TOUCH BUT ATTRIBUTED IT TO T/P'S REVERSING. HE ATTEMPTED TO PUT THE BLAME TO T/P BY TWISTING THE FACT IF NOT FOR THE CC FOOTAGE. WE ARE OF THE OPINION THAT IT IS A WEAK CASE IN THE EVENT OF LITIGATION. SOMETIME. IT IS NOT POSSIBLE TO SINGLE OUT THE IMPACT BETWEEN VEHICLES BY VISION AS THE IMPACT IS SLIGHT. HOWEVER, THE REPAIR IS ONLY CONFINED TO REPAIR COST.

Hsiao Tong
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: cynthia.loh@axa.com.sg
CC: AXA_SG; chewht@lkkauto.com
Sent On: 07/07/2018 08:49 AM
Subject: Re: C0467050 / P1680520

Hi Cynthia,

We refer to our email dated 16/06/2018.

Kindly let us have your instruction.

Hsiao Tong

<-- Original Message -->

From: LKK_HQ
To: cynthia.loh@axa.com.sg
CC: AXA_SG; chewht@lkkauto.com
Sent On: 16/06/2018 03:38 PM
Subject: Re: C0467050 / P1680520

Hi Cynthia,

We refer to the above matter.

We have submitted a copy of third party video footage to you via Accellion.

From third party video footage, it shows that third party was moving forward slowly and stopped. His taxi did not reverse as reported by OID.

In view of the above, kindly advise if we may proceed to settle the matter under BOLA S27 or else advise further instruction.

Thank you.

Hsiao Tong
DID: 6742 3197

This is an auto-generated email. Do not reply to this email.

Sent by : Vale Oh (AXA Insurance Pte Ltd)

Print Received Message

This mail is associated with :

***SH9933G (C0467050)**
[SHC5221K]

TP
COMFORTDELGRO ENGINEERING
Dec 2 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]
ComfortDelGro Engineering Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 05/11/2018 09:29 AM.
To vale.oh@axa.com.sg; LKK_HQ
CC AXA_SG; chewht@lkkauto.com
Subject Re: <Seek Instruction> C0467050 / P1680520

Hi Hsiao Tong

Pls proceed, tks

VO

<-- Original Message -->

From: LKK_HQ
To: vale.oh@axa.com.sg
CC: AXA_SG; chewht@lkkauto.com
Sent On: 28/10/2018 10:11 AM
Subject: Re: C0467050 / P1680520

Hi Vale,

We have forwarded a copy of video footage to insured as per instruction. However there was no response from OI up-to-date.

Kindly let us have your instruction as third party is chasing for settlement.

Thank you.

Hsiao Tong

<-- Original Message -->

From: AXA_SG
To: vale.oh@axa.com.sg; LKK_HQ
CC: AXA_SG; chewht@lkkauto.com
Sent On: 25/09/2018 09:51 AM
Subject: Re: C0467050 / P1680520

Hi Hsiao Tong

Refer to your email below.

Please get back to Insured on the video footage, thanks

VO

<-- Original Message -->

From: LKK_HQ
To: vale.oh@axa.com.sg
CC: AXA_SG; chewht@lkkauto.com
Sent On: 21/09/2018 08:37 AM
Subject: Re: C0467050 / P1680520

Hi Vale,

We refer to your below email.

Sometime, it is not possible to single out the impact between vehicles by vision as the impact is very slight. Our insured driver reported that third party reversed and there was slight touch between both vehicles. From the video, third party taxi did not reverse.

There was no video/ evidences form our insured.

In view of the above, kindly let us have your instruction in order for us to proceed further.

Thank you.

Hsiao Tong
DID: 6742 3197

<-- Original Message -->

From: AXA_SG
To: vale.oh@axa.com.sg; LKK_HQ
CC: AXA_SG; chewht@lkkauto.com
Sent On: 28/07/2018 02:56 PM
Subject: Re: C0467050 / P1680520



AXA INSURANCE PTE LTD
8 Raffles Way, #04-01, AXA Tower
Singapore 109453
Customer Centre 480-101
TEL: 6860-6860
FAX: 6860-6822
www.axa.com.sg
MOT Reg No.: L290000120
Ins. Reg No.: L290000120

Hi

We can't see any accident impact from the video, please advise, thanks.

VO

<-- Original Message -->

From: LKK_HQ
To: vale.oh@axa.com.sg
CC: AXA_SG; chewht@lkkauto.com
Sent On: 28/07/2018 11:42 AM
Subject: Re: C0467050 / P1680520

Hi,

We refer to the above matter.

We have uploaded a copy of third party video footage in Merimen.

From third party video footage, it shows that third party was moving forward slowly and stopped. His taxi did not reverse as reported by OID.

In view of the above, kindly advise if we may proceed to settle the matter under BOLA S27 or else advise further instruction.

Thank you.

Hsiao Tong
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: cynthia.loh@axa.com.sg
CC: AXA_SG; chewht@lkkauto.com
Sent On: 07/07/2018 08:49 AM

Subject: Re: C0467050 / P1680520

Hi Cynthia,

We refer to our email dated 16/06/2018.

Kindly let us have your instruction.

Hsiao Tong

<-- Original Message -->

From: LKK_HQ

To: cynthia.loh@axa.com.sg

CC: AXA_SG; chewht@lkkauto.com

Sent On: 16/06/2018 03:38 PM

Subject: Re: C0467050 / P1680520

Hi Cynthia,

We refer to the above matter.

We have submitted a copy of third party video footage to you via Accellion.

From third party video footage, it shows that third party was moving forward slowly and stopped. His taxi did not reverse as reported by OID.

In view of the above, kindly advise if we may proceed to settle the matter under BOLA S27 or else advise further instruction.

Thank you.

Hsiao Tong

DID: 6742 3197

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 13 December 2018 3:34 PM
To: 'williamtan@cdge.com.sg'; 'catherinekoh@cdge.com.sg'
Subject: Your Ref: T1217/ SH 9933G/ WT(st) *Our Ref: CC4/AXA17023322/K1pb3
[ACCIDENT INVOLVING SHC 5221K(AXA) & SH 9933G ON 02/12/2017]

Your Ref: **T1217/ SH 9933G/ WT(st)** Without Prejudice
Our Ref: CC4/AXA17023322/K1pb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SHC 5221K(AXA) & SH 9933G ON 02/12/2017

We refer to the above matter.

We propose settlement at a global sum of \$960.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

18/12/18
\$1050 (all-in)
→ by agent

Hsiao Tong (LKKAUTO)

From: William Tan Thoo Seng <williamtan@cdge.com.sg>
Sent: Tuesday, 18 December 2018 10:22 AM
To: Hsiao Tong (LKKAUTO)
Cc: KKLau; Aileen Tan Lee Noi
Subject: Re: Your Ref: Your Ref: CC4/AXA17023322/K1pb3 [ACCIDENT INVOLVING SHC 5221K(AXA) & SH 9933G ON 02/12/2017]

Without Prejudice.

Dear Ms Hsiao Tong

Preceding email refers.

We spoke a moment ago.

As negotiated, we hereby confirm settlement at global sum of \$1,050.00.

Kindly forward your discharge voucher.

Thank you.

Best Regards

William Tan

Claims Department | ComfortDelgro Engineering Pte Ltd

Off : 62148737 | Fax : 62141843

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Thursday, 13 December 2018 3:34 PM
To: William Tan Thoo Seng; Catherine Koh Mui Gek
Subject: Your Ref: T1217/ SH 9933G/ WT(st) *Our Ref: CC4/AXA17023322/K1pb3 [ACCIDENT INVOLVING SHC 5221K(AXA) & SH 9933G ON 02/12/2017]

Your Ref: **T1217/ SH 9933G/ WT(st)** Without Prejudice
Our Ref: CC4/AXA17023322/K1pb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SHC 5221K(AXA) & SH 9933G ON 02/12/2017

We refer to the above matter.

We propose settlement at a global sum of \$960.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Thursday, 21 December, 2017 12:14 PM
To: claims@transcab.com.sg
Cc: 'carrisalee@ava-ins.com'; 'ireneng@ava-ins.com'; Foo, John (VWG Singapore) (John.Foo@vw.com.sg); 'icewong@ava-ins.com'
Subject: ACCIDENT INVOLVING SHC 5221K AND SH 9933G ALONG/AT AIRPORT BOULEVARD T3 TAXI QUEUE ON 02/12/2017

21 DEC 2017

Transcab Taxi
Singapore

Dear Sir,

OUR REF : CC4/AXA17023322/K1pb3

YOUR REF : P1680520 (SHC 5221K)

ACCIDENT INVOLVING SHC 5221K AND SH 9933G ALONG/AT AIRPORT BOULEVARD T3 TAXI QUEUE ON 02/12/2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from ComfortDelgro Engineering Pte Ltd acting on behalf of the owner of SH 9933G against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

We also wish to advise that there is an excess of **S\$5,000.00** attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

As Insurers, AXA shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg / chewht@lkkauto.com or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

"Wishes you a Merry Christmas & Happy New Year 2018"

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Our Ref : T1217/ SH 9933G /WT(st)

Your Ref :

Date : 19-Dec-17

AXA Insurance Pte Ltd
8 Shenton Way
#24-01, AXA Tower
Singapore 068811

Attn : Motor Claims Department

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 8280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 196053420

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609296

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

5.95 Yishun Industrial Park A
Singapore 768732

Dear Sir

ACCIDENT INVOLVING OUR TAXI SH 9933G YOUR INSURED SHC5221K
AND OTHER ON 02.12.17

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor vehicle No : **SH 9933G** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : **SHC5221K**
we are submitting these claim for your consideration on behalf of the claimants

TAXI OWNER'S CLAIM

1	Cost of Repair	\$	353.10
2	5 days Loss of Rental @ \$ 125.19 per day	\$	625.95
3	Survey Report Fees (Surveyed by M/s LKK)	\$	-
4	GIA / LTA Search Fee	\$	-
5	GIA / Police Report Fees	\$	-
6	Towing / Medical / Transporation Fees	\$	-
	Sub Total :	\$	979.05

HIRER'S CLAIM

7	<u>5</u>	days Loss of Income @	<u>\$ 80.00</u>	per days	<u>\$ 400.00</u>
Total Claims:					\$ 1,379.05

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photostat photographs _____ 8 _____ pcs
b) LTA search slip/s of : _____ - _____
c) GIA / Police report/s of : _____ SH 9933G _____
d) Letter of authority from owner / hirer / operator _____
(X) Photocopie/s of Accident Scene Photo/s () Traffic Compound () PIR
() Witness statement/s (x) Rental Rate letter (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

Deputy Manager

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO



Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 27 September 2018 11:24 AM
To: 'claims'
Cc: 'jasminetan'; zhewei.kek@transcab.com.sg
Subject: RE: ACCIDENT INVOLVING SHC 5221K [AAD1712-047] AND SH 9933G ALONG/AT AIRPORT BOULEVARD T3 TAXI QUEUE ON 02/12/2017
Attachments: SH9933G doa 021217_.mp4; IMG_9177.jpg; IMG_9175.jpg

Without Prejudice

Hi Wai Yin,

Thank you for your email.

As per AXA instruction, we attached here with a copy of third party video and scene photos for your easy reference. From third party video footage, it shows that third party was moving forward slowly and stopped. His taxi did not reverse as reported by our insured driver.

We are of the view that we would have to resolve the matter based on BOLA 27.

If you feel strongly against our settlement offer to the third party, kindly let us have them in writing within the next 7 days i.e. by **05/10/2018**, after we shall proceed with negotiation with Third Party claimant on the without prejudice basis and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claims <claims@transcab.com.sg>
Sent: Thursday, 20 September 2018 5:16 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: 'jasminetan' <jasminetan@transcab.com.sg>; zhewei.kek@transcab.com.sg; claims@transcab.com.sg
Subject: RE: ACCIDENT INVOLVING SHC 5221K [AAD1712-047] AND SH 9933G ALONG/AT AIRPORT BOULEVARD T3 TAXI QUEUE ON 02/12/2017

WITHOUT PREJUDICE

Dear Hsiao Tong

Sorry for the delay.

We regret to inform that we do not have the video footage for this case.

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Saturday, 16 June, 2018 3:34 PM

To: claims@transcab.com.sg; 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; 'Zhe Wei' (zhewei.kek@transcab.com.sg) <zhewei.kek@transcab.com.sg>

Subject: RE: ACCIDENT INVOLVING SHC 5221K AND SH 9933G ALONG/AT AIRPORT BOULEVARD T3 TAXI QUEUE ON 02/12/2017

Hi,

We refer to the above matter.

Kindly advise if there is any video footage submitted by your client to support his version that third party reversed and collided onto his taxi.

Appreciate an early reply.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Thursday, 21 December 2017 12:14 PM

To: claims@transcab.com.sg

Cc: 'carrisalee@ava-ins.com' <carrisalee@ava-ins.com>; 'ireneng@ava-ins.com' <ireneng@ava-ins.com>; Foo, John (VWG Singapore) (John.Foo@vw.com.sg) <John.Foo@vw.com.sg>; 'icewong@ava-ins.com' <icewong@ava-ins.com>

Subject: ACCIDENT INVOLVING SHC 5221K AND SH 9933G ALONG/AT AIRPORT BOULEVARD T3 TAXI QUEUE ON 02/12/2017

21 DEC 2017

Transcab Taxi
Singapore

Dear Sir,

OUR REF : CC4/AXA17023322/K1pb3

YOUR REF : P1680520 (SHC 5221K)

ACCIDENT INVOLVING SHC 5221K AND SH 9933G ALONG/AT AIRPORT BOULEVARD T3 TAXI QUEUE ON 02/12/2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from ComfortDelgro Engineering Pte Ltd acting on behalf of the owner of SH 9933G against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

We also wish to advise that there is an excess of **S\$5,000.00** attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

As Insurers, AXA shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg / chewht@lkkauto.com or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

"Wishes you a Merry Christmas & Happy New Year 2018"

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****I 40 SH9933G , SHC5221K
T 3 LINK SOUTH
(STAND TAXI)****ON 02-Dec-17 22:25**

I / We

KWAN WEI GUANG(Hirer) NRIC No.: **S8205083C**

and/or

(Relief) NRIC No.:

Taxi Number

SH9933G

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

04-Dec-2017

Name of Hirer

KWAN WEI GUANG

Hirer NRIC

S8205083C

Signature :



Address

**662 YISHUN AVENUE 4 #05-253
760662**

Contact No.

96993931



redefining / insurance

CLAIM REF : C0467050
INSURED : TRANS-CAB SERVICES PTE LTD

DISCHARGE VOUCHER

We, **ComfortDelgro Engineering Pte Ltd** confirm that by letter of authorisation dated 04/12/2017, we are authorised to and do hereby give this discharge for ourselves and on behalf of Comfort Transportation Pte Ltd and the Hirer Kwan Wei Guang of vehicle no. SH 9933G.

Now we **ComfortDelgro Engineering Pte Ltd** for ourselves and the said Hirer and the driver jointly and severally:-

- agree to accept the sum of Singapore Dollars **One Thousand Fifty** only (**S\$1,050.00**) in the aggregate in full and final settlement of all claims of whatever kind including damages for personal injuries and/or damage to property that all and any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no (SHC 5221K) arising out of an accident with (SH 9933G) on 02/12/2017.
- declare that **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of the Insured vehicle shall not be liable for any further claim(s) whatsoever or howsoever present or future that any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. SHC 5221K arising directly/indirectly as a consequence of the accident and hereby give our full and final discharge.
- We hereby declare that I/we am/are the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made in favour of **ComfortDelgro Engineering Pte Ltd** is made without any admission of liability whatsoever on the part of **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. SHC 5221K.

Dated this 26 day of December 2018

Signed by _____
(AUTHORISED SIGNATORY)

Company Stamp _____
COMFORTDELGRO ENGINEERING PTE LTD
89 LUNANG DRIVE
SINGAPORE 508883

Witness : _____

Name : _____

I/C No : _____

Address : _____

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

The contents of this document apply to vehicle damages only
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W

Page: 1

8010010

AXA INSURANCE PTE LTD

#24-01 8 SHKNTON WAY AXA TOWER
SINGAPORE SG 068811

CONTACT NO: 63387288

VEHICLE NO

SH 9933G

MAKE

HYUNDAI

MODEL

IONIQ

DATE OF REG

17.03.2017

(CHASSIS CODE

KMHC851CVHJ022745

INV. NO/DATE

91346792 18.12.2017

JOB NO.

305094823

CLOCKMETER READING

DATE/TIME IN

04.12.2017 13:35

Description : 3P 02.12.2017

S/No Part No.

Qty Unit Price %Disc Net

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0001	20-05	REAR BUMPER MAT	50.00	50.00
0002	I.	PANEL BEATING	100.00	100.00
0003	23-502	SPRAYPAINT ON AFFECTED AREA	180.00	180.00
SUB-TOTAL :				330.00

PLEASE NOTE: ALL INFORMATION HEREON IS FOR INFORMATION PURPOSES ONLY. IT IS NOT A CONTRACT. THE CONTRACT IS THE INVOICE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE.

PLEASE NOTE: ALL INFORMATION HEREON IS FOR INFORMATION PURPOSES ONLY. IT IS NOT A CONTRACT. THE CONTRACT IS THE INVOICE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE.

PLEASE NOTE: ALL INFORMATION HEREON IS FOR INFORMATION PURPOSES ONLY. IT IS NOT A CONTRACT. THE CONTRACT IS THE INVOICE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE.

PLEASE NOTE: ALL INFORMATION HEREON IS FOR INFORMATION PURPOSES ONLY. IT IS NOT A CONTRACT. THE CONTRACT IS THE INVOICE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE. THE INVOICE IS THE ONLY DOCUMENT THAT SHALL BE USED TO DETERMINE THE AMOUNT DUE.

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:

205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHO No.
8010010	91346792	353.10	

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W

Page: 2

8010010

AXA INSURANCE PTE LTD

#24-01 8 SHENTON WAY AXA TOWER
SINGAPORE SG 068811

CONTACT NO: 63387288

VEHICLE NO
SH 9933G

MAKE
HYUNDAI

MODEL
IONIQ

DATE OF REG
17.03.2017

CHASSIS CODE
KMHCB51CVHU022745

INV. NO/DATE
91346792 18.12.2017

JOB NO.
305094823

ODOMETER READING

DATE/TIME IN
04.12.2017 13:35

Items total		330.00
Add GST @	7.000 %	23.10
Invoice amount		353.10

Issued by : KATHERINETAN 18.12.2017 16:30:41
Repair type : CLASO/57/57
Payment type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010010	91346792	353.10	

Our Ref: CT17120111

Date: 18 December 2017



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 02/12/2017 @ 22:25 hrs
ALONG T3 LINK SOUTH TAXI STAND
INVOLVING SHC5221K

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH9933G** (the "Taxi"). The Taxi was hired to **KWAN WEI GUANG IC NO S8205083C** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$125.19** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Executive, Fleet Safety

This is a computer generated letter. No signature is required.

DATE	NAME OF DRIVER	MILEAGE READING					MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)		DATE	NAME OF DRIVER	MIL
		8	7	8	0	5		FROM	TO			
2/12/17	Mr	8	7	8	0	5	406					
3/12/17	Mr	8	8	2	1	1	408					
05/12/17	Student Rep						811 91 336	1335				
08/12/17							0.		1155			

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Dec 2017		07 Dec 2017 09:43 Edit Adj Rpt	S\$330.00 Edit Estimates	S\$330.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SH9933G	Date of Loss:	02/12/2017 00:00 - :59 [8 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0467050	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHC5221K	Policy No. (Claimant):	MCOM0015						
		Excess:	S\$5,000.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Vale Oh - 6880 4897]								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 18/12/2017]								
Driver/Custodian (Insured):	LEE SONG BEE (), NRIC: S1104638Z								
Adj Asg. Remarks:	TP IS ARC WORKSHOP.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (05/11/2018): Re: <Seek Instruction> C0467050 / P1680520 AXA_SG (25/09/2018): Re: <Seek Instruction> C0467050 / P1680520 AXA_SG (28/07/2018): Re: <Seek Instruction> C0467050 / P1680520 AXA_SG (07/12/2017): New TP Assignment - /P1680520 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SH9933G (C0467050)
[SHC5221K]
TP
COMFORT TRANSPORTATION PTE LTD
Dec 2 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/07/18 11:42	VIDEO FROM THIRD PARTY	Load MP4	
Letters/Correspondences				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Assessment Reports				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/12/17 19:10	Adjuster Immediate Advice	Load HTM	
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
2	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
3	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
4	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
5	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
6	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
7	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
8	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
9	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
10	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
11	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
12	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
13	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
14	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
15	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
16	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
17	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
18	18/12/17 16:40	General View	Load JPG	<input checked="" type="checkbox"/>
19	18/12/17 16:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	18/12/17 16:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	18/12/17 16:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	18/12/17 16:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
23	18/12/17 16:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
24	18/12/17 16:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	18/12/17 16:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation				
			1 per page	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail Print
1	06/12/17 16:57	EMAIL		Load PDF
2	06/12/17 16:57	img-Z05140508-0001		Load PDF
3	07/12/17 09:33	EMAIL		Load PDF
4	07/12/17 09:33	ESTIMATE & GIA REPORT		Load PDF
5	07/12/17 09:33	GIA REPORT OF SH9933G (TP)		Load PDF
6	07/12/17 09:33	GIA REPORT OF SHC5221K (INSD)		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	08/12/17 12:22	TP ESTIMATE- MARKED		Load PDF
2	31/01/18 13:40	Scene photos from TP		Load PDF
3	28/10/18 10:09	Email to OI dd 270918		Load PDF
4	14/01/19 09:32	WORKSHOP INVOICE		Load PDF
5	14/01/19 09:32	AUTHORISATION TO ACT FORM		Load PDF
6	14/01/19 09:32	DISCHARGE VOUCHER		Load PDF
7	14/01/19 09:32	RENTAL RECEIPT		Load PDF
8	14/01/19 09:32	RENTAL MILEAGE		Load PDF
9	14/01/19 09:32	LOD		Load PDF
10	14/01/19 09:32	LETTER TO OI		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHC5221K (Insd veh)	Model:	HYUNDAI IONIQ HYBRID 1.6
	SH9933G (TP veh)		GLS DCT (A)
Date of Accident:	02/12/2017		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	1,847.16
Final Repair Cost	:	\$	353.10
Loss of Token Sum	:	\$	200.00
Rental (if any)	:	\$	500.76
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	1,050.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	:	\$ 1,050.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

14 Jan
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17023322/K1PB3Q2

Date: 14/01/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No : SH9933G

Insured Vehicle No :

SHC5221K

Date of Loss: 02/12/2017

Nature of Claim:

TP

Claim No:

C0467050

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH9933G

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEGU327558

Reg. Date: 17/03/2017 (Man. Year: 2017)

Chassis No:

KMHC851CVHU022745

Colour: Blue

Odometer:

88642 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Nexen 7 mm

Rear Left Side:

Nexen 7 mm

Front Right Side: Nexen 7 mm

Rear Right Side:

Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,006.32	50.00	956.32	95.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	720.00	280.00	440.00	61.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,726.32	330.00	1,396.32	80.88
+ GST 7.00/7.00% (S\$)	120.84	23.10	97.74	80.88
Nett Amount (S\$)	1,847.16	353.10	1,494.06	80.88
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (S\$)		500.76		
Nett Liability (S\$)		1,053.86		
Global Sum Settlement (S\$)		1,050.00		

INSPECTION

Date of Assignment: 07/12/2017

Date Inspected: 07/12/2017 Inspected At:

 ComfortDelGro Engineering Pte Ltd
 (Loyang)
 59 Loyang Drive
 Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2019)
Parts: 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH9933G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (CONSISTENT)	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Serviceable	294.80 FL	*- FL
3	1		*REAR BUMPER CLIP (NPA) (CONSISTENT)	Not Necessary	0.00 FL	*- FL
4	2		*REAR BUMPER STAY LH/RH (CONSISTENT)	Serviceable	138.10 FL	*- FL
5	1		*REAR BUMPER UNDER COVER (CONSISTENT)	Serviceable	270.00 FL	*- FL
6	2		*REAR BUMPER BRACKET (LH/RH) (CONSISTENT)	Serviceable	33.10 FL	*- FL
7	1		*REAR BUMPER RUBBER MAT (CONSISTENT)	Necessary	50.00 FS	*50.00 FS
					Sub Total (\$\$)	1,245.40 50.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	239.08 0.00
					Total Parts (\$\$)	1,006.32 50.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	100.00
2	SPRAY PAINTING CHARGE	New	200.00	180.00
3	WIRING CHARGE	New	50.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	120.00	0.00
Gross Labour Cost (S\$)			720.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >