

ASS. REC. BY:

REF: CS/FCI(70)3339/Arbez

Special Instruction:

Surveyor: Adrian

**ASSIGNMENT (Office)**

From (Person):

CWS May Chua

of

FCI

Date/Time: 08-12-2017 842am

Estimated Cost:

Bill to:

OD ~~FCI~~ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 5187E

Insured:

SH 9150Z

at Workshop m/s

7b Motorsports

Tel:

90211096

of

62 &amp; 64 Kaki Bukit Ave 6 AAK @ KB

Policy No:

Claim No:

D17011294M9H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

06-12-2017

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

08122017 4:34am

Person Contacted:

Alywin

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate      |               |
|-----------|--------------------------------------|---------------|
|           | SLA 5187E - NA/CTU(TC)3127/r3        | Dir: 061217   |
|           | SH 9150Z - PCB/ALH12072792/1412105W2 | Dir: 22.11.17 |
|           |                                      |               |
|           | Sent poli thm email.                 |               |
|           | Confirm L/S \$7200, 6 days           |               |
|           | Red: 817.111.04, 70%                 |               |

REF: RCL

## ASSIGNMENT

From: \_\_\_\_\_ Date: **08/12/2017**

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No: **SLQ 5187E**

at Workshop no: **96 motorsports**

of: **62 & 64 Kaki Bukit Ave 6**

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAO Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS Wpr \_\_\_\_\_

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **SLQ 5187E** (Pr Regn) **2017 July**

Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or \_\_\_\_\_

Make: **Honda Vezel** cc **1496**

Colour: **Brown** A/C Insured / Std / NI / NA

Sp. Reading: **28044** T. Radio Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C No: **RU11207224**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ in order / Jammed / Leaked / Burnt or

Brake: ☒ in order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: **215/60R16**

R: **215/60R16**

BS / ☒ SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal: **06** mm R/Bal: **06** mm

L/Bal: **06** mm L/Bal: **06** mm

D.O.A: \_\_\_\_\_ D.O.I: **08/12/17**

Survey held at: **96 motorsports**

Des. of Damages: Fnt / Rear / O/S ☒ N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

TP 1st Cap

Front Bumper NH due to accident.

RECEIVED 10/12/17

Date/Time File Pass to? ☐ : Preli. Report

typist

☒ : Final Report

Date/Time File Return to?

Days Of Repair: **6**Resurvey No. of Trip: **-**

Survey Fee

Transportation

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Report Format: **TP**Lump Sum: **7200**Add Fee: ☐ Site Insp \$☐ Inten \$☐ Test \$☐ Clean up \$

14x15 = 210

130+210  
50

41

471



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023339/Arb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 08-12-2017



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | SH 9150Z       | Veh. Inspected | SLQ 5187E  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | D17011294MFSH  | Excess (\$)    | 0.00       |
| Assign From  | CWS (MAY CHUA) | Assign Date    | 08/12/2017 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |                                                                                     |                 |            |
|----------------|-------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 06/12/2017                                                                          | Inspection Date | 08/12/2017 |
| Survey held at | 96 MOTORSPORTS PTE LTD<br>62/64 KAKI BUKIT AVENUE 6<br>SINGAPORE 417893<br>ARK @ KB |                 |            |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

|                    |                                                     |                               |
|--------------------|-----------------------------------------------------|-------------------------------|
| Date               | 07-12-2017                                          | Our Ref No. D17011294MFSH     |
| Accident Date      | 06-12-2017                                          | Claim Type. Third Party       |
| Insured Vehicle    | SH9150Z                                             | Third Party Vehicle. SLQ5187E |
| Survey Location    | 62 & 64 Kaki Bukit Avenue 6 ARK@KB Singapore 417893 |                               |
| Contact Person.    | ALYWIN SOH                                          |                               |
| Contact No.        | 67026996/ 90211096                                  | Fax No. 63846996              |
| Survey Type        | WITHOUT PREJUDICE:                                  |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                        |                               |
| Contact Person     | NA                                                  | Fax No. 68416315              |
| Contact Number.    | NA                                                  |                               |

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

|                   |                        |                         |
|-------------------|------------------------|-------------------------|
| Cc : Workshop     | 96 MOTORSPORTS PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | VISION LAW LLC         | TP Solicitor Fax No. NA |
| Officer Incharge  | MAY CHUA               |                         |

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231570)



PRI Documents



Close



## PRI Header Details

|                          |                                                         |                                              |                                                                                                                                                           |                                 |         |
|--------------------------|---------------------------------------------------------|----------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|---------|
| <b>Claim No</b>          | D17011294MFSH                                           | <b>Policy No</b>                             | D-15072701MFSH                                                                                                                                            | <b>Claimant S.No &amp; Name</b> | 1 & VIS |
| <b>Workshop Name</b>     | 96 MOTORSPORTS PTE LTD<br>(Contact Person : ALYWIN SOH) | <b>Survey Location &amp; Contact Details</b> | 62 & 64 Kaki Bukit Avenue 6 ARK@KB Singapore<br><b>Mobile:</b> 90211096 , <b>Phone:</b> 67026996 , <b>Fax:</b><br><b>EmailId:</b> JACTAN@VISIONLAWLLC.COM |                                 |         |
| <b>Our Surveyor</b>      | LKK AUTO CONSULTANTS PTE LTD                            | <b>Instructions To Surveyor</b>              | WITHOUT PREJUDICE:                                                                                                                                        |                                 |         |
| <b>Insured Name</b>      | COMFORT TRANSPORTATION PTE LTD                          | <b>Insured Vehicle No</b>                    | SH9150Z                                                                                                                                                   | <b>TP Vehicle No</b>            | SLQ518  |
| <b>PRI Recieved Date</b> | 07-12-2017 05:08:45 PM                                  | <b>Surveyor Appointed Date</b>               | 08-12-2017 08:42:28 AM                                                                                                                                    | <b>Surveyor Accept Date</b>     | 08-12-  |

## Survey Report Upload

|                                    |  |                             |            |                                |  |
|------------------------------------|--|-----------------------------|------------|--------------------------------|--|
| <b>Surveyor Inspection Date *:</b> |  | <b>Surveyor Report Date</b> | 08-12-2017 | <b>Upload Survey Report *:</b> |  |
|------------------------------------|--|-----------------------------|------------|--------------------------------|--|

## Vehicle Particulars

|                  |                      |                       |                       |                |                      |
|------------------|----------------------|-----------------------|-----------------------|----------------|----------------------|
| <b>Make</b>      | Please Select Make ▼ | <b>Model</b>          | Please Select Model ▼ | <b>Year</b>    | Select               |
| <b>Chasis No</b> | <input type="text"/> | <b>Engine No</b>      | <input type="text"/>  | <b>Mileage</b> | <input type="text"/> |
| <b>Color</b>     | <input type="text"/> | <b>Cubic Capacity</b> | <input type="text"/>  |                |                      |

## Multiple Documents Upload

|                                           |               |
|-------------------------------------------|---------------|
| <a href="#">Upload Multiple Documents</a> |               |
| <b>File Name</b>                          | <b>Action</b> |

## Surveyor Job Remarks



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D17011294MFSH

Our Ref: CS/FCI17023339/Arb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 5187E.**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08/12/2017 at the premises of M/s 96 MOTORSPORTS PTE LTD and have the following to report:-

|                          |                   |
|--------------------------|-------------------|
| Workshop Estimate Amount | : S\$ 24,311.04 . |
| Revised Estimate Amount  | : S\$ 9,002.56 .  |
| "Check" Items Amount     | : S\$ .           |
| Market Value             | : S\$ - .         |
| LTA Reimbursement Value  | : S\$ - .         |
| Nett Value               | : S\$ - .         |

**Description of Damage:**

The vehicle sustained damages  
at n/s body. The undercarriage affected  
due to collision.



Yours faithfully  
ADRIAN  
Automotive Assessor

## Janice Lee (LKKAUTO)

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Monday, March 19, 2018 12:43 PM  
**To:** 'Claim Workflow System'  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D17011294MFSH/1  
**Attachments:** SLQ 5187E.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for **SLQ 5187E**.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Admin-D (LKKAUTO)

**Sent:** Friday, December 08, 2017 9:37 AM

**To:** 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>

**Cc:** MAYCHUA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>

**Subject:** RE: SURVEY ASSESSMENT - D17011294MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]

**Sent:** Friday, 8 December, 2017 8:42 AM

**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [MAYCHUA@FIRST-INSURANCE.COM.SG](mailto:MAYCHUA@FIRST-INSURANCE.COM.SG)

**Subject:** PRI: SURVEY ASSESSMENT - D17011294MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business  
Owner ID: 7904X

### Vehicle Details

Vehicle No.: SLQ5187E  
Vehicle to be Exported: No  
Intended De-registration Date: 19 Mar 2018  
Vehicle Make: HONDA  
Vehicle Model: VEZEL 1.5X CVT  
Primary Colour: Brown  
Manufacturing Year: 2016  
Engine No.: L15B4407228  
Chassis No.: RU11207224  
Maximum Power Output: 96.0 kW (128 bhp)  
Open Market Value: \$19,945.00  
Original Registration Date: 13 Jul 2017  
First Registration Date: 13 Jul 2017  
Transfer Count: 0  
Actual ARF Paid: \$9,945.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 12 Jul 2027  
PARF Rebate Amount: \$7,458.00

### Intended COE Rebate Details

COE Expiry Date: 12 Jul 2027  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$42,801.00  
COE Rebate Amount: \$39,859.00  
**Total Rebate Amount: \$47,317.00**

The information contained herein is correct as at 19 Mar 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                              |
|----------------------------|------------------------------|
| Date Of Report             | 06/12/2017 11:57             |
| Date Of Accident           | 06/12/2017 09:05             |
| Exact Location Of Accident | KALLANG WAY TWDS ALJUNIED RD |
| Country/State of Loss      | SINGAPORE                    |

### DETAILS OF OWN VEHICLE

|                             |                          |
|-----------------------------|--------------------------|
| Vehicle Registration Number | SLQ5187E                 |
| <b>Insured/Policyholder</b> |                          |
| Name Of Registered Owner    | KL TRANSPORT SERVICES    |
| Co Reg No                   | 53337904X                |
| Email Address               | ADMIN1@96MOTORSPORTS.COM |
| Mobile Phone No             |                          |
| Alternative Phone No        | OFFICE-82828393          |

### Vehicle Particulars

|                                                                    |       |
|--------------------------------------------------------------------|-------|
| Manufacturer                                                       | HONDA |
| Model                                                              | VEZEL |
| Exact Purpose for which vehicle was being used at time of accident | WORK  |

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

### Insurance Company

|                           |                                               |
|---------------------------|-----------------------------------------------|
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE                                 |
| Fleet Policy              | NO                                            |
| Policy Number             | DMNCSN1748721700                              |
| Cover Note Number         |                                               |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | LEE CHOON ENG         |
| NRIC No              | S1634581D             |
| Date Of Birth        | 04/12/1964            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 19/06/1987            |
| Driving Experience   | 30 YEARS AND 5 MONTHS |
| Gender               | MALE                  |
| Mobile Number        |                       |
| Fax Number           |                       |
| Contact Number       |                       |
| EMail Address        | NOEMAIL               |

|                                                     |                                       |
|-----------------------------------------------------|---------------------------------------|
| Address                                             | BLK 113 POTONG PASIR AVE 1<br>#13-846 |
| Postcode                                            | 350113                                |
| Was driver an employee of the Insured's Company     | NO                                    |
| If No, Relationship of the Driver with the Insured  | OTHER - HIRER                         |
| Vehicle Registration Number of Driver's Own Vehicle | -                                     |
|                                                     | -                                     |
|                                                     | -                                     |
| Insurance Company of Driver's Own Vehicle           | -                                     |
|                                                     | -                                     |
|                                                     | -                                     |

#### General Information of the Accident

|                    |                               |
|--------------------|-------------------------------|
| Type Of Accident   | COLLISION - CHANGE/CROSS LANE |
| Weather Conditions | CLEAR                         |
| Road Surface       | DRY                           |

#### Other Information

|                                                                                             |     |
|---------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in this accident?                                          | NO  |
| Was any body injured in the Accident?                                                       | NO  |
| Was any other material or property damaged?                                                 | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)                                                     | 1   |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

#### Attachment(s)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |         |
|-------------------------------------|---------|
| Vehicle Registration Number         | SH9150Z |
| Vehicle Make/Model/Colour           |         |
| Details Of Properties               |         |
| Name of Driver                      |         |
| NRIC/Passport Number                |         |
| Contact Number                      |         |
| Address                             |         |
| Postcode                            |         |
| Insurance Company Name              |         |
| Nature Of Damage                    |         |
| No. Of Passenger (Including Driver) |         |

#### Details of Witness

|               |  |
|---------------|--|
| Name          |  |
| Phone Number  |  |
| Email Address |  |

### SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.




6/2/17

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

 06/12/17  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/IN No.:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A was travelling along Kallang Way lane 1 and vehicle B was trying to make a right turn from lane 2 and hit into my left front portion of my vehicle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NIC/PIN No.:

CPA Form 10-12/13/14/15/16/17/18/19/20/21/22/23/24/25/26/27/28/29/30/31/32/33/34/35/36/37/38/39/40/41/42/43/44/45/46/47/48/49/50/51/52/53/54/55/56/57/58/59/60/61/62/63/64/65/66/67/68/69/70/71/72/73/74/75/76/77/78/79/80/81/82/83/84/85/86/87/88/89/90/91/92/93/94/95/96/97/98/99/100/101/102/103/104/105/106/107/108/109/110/111/112/113/114/115/116/117/118/119/120/121/122/123/124/125/126/127/128/129/130/131/132/133/134/135/136/137/138/139/140/141/142/143/144/145/146/147/148/149/150/151/152/153/154/155/156/157/158/159/160/161/162/163/164/165/166/167/168/169/170/171/172/173/174/175/176/177/178/179/180/181/182/183/184/185/186/187/188/189/190/191/192/193/194/195/196/197/198/199/200/201/202/203/204/205/206/207/208/209/210/211/212/213/214/215/216/217/218/219/220/221/222/223/224/225/226/227/228/229/230/231/232/233/234/235/236/237/238/239/240/241/242/243/244/245/246/247/248/249/250/251/252/253/254/255/256/257/258/259/260/261/262/263/264/265/266/267/268/269/270/271/272/273/274/275/276/277/278/279/280/281/282/283/284/285/286/287/288/289/290/291/292/293/294/295/296/297/298/299/300/301/302/303/304/305/306/307/308/309/310/311/312/313/314/315/316/317/318/319/320/321/322/323/324/325/326/327/328/329/330/331/332/333/334/335/336/337/338/339/340/341/342/343/344/345/346/347/348/349/350/351/352/353/354/355/356/357/358/359/360/361/362/363/364/365/366/367/368/369/370/371/372/373/374/375/376/377/378/379/380/381/382/383/384/385/386/387/388/389/390/391/392/393/394/395/396/397/398/399/400/401/402/403/404/405/406/407/408/409/410/411/412/413/414/415/416/417/418/419/420/421/422/423/424/425/426/427/428/429/430/431/432/433/434/435/436/437/438/439/440/441/442/443/444/445/446/447/448/449/450/451/452/453/454/455/456/457/458/459/460/461/462/463/464/465/466/467/468/469/470/471/472/473/474/475/476/477/478/479/480/481/482/483/484/485/486/487/488/489/490/491/492/493/494/495/496/497/498/499/500/501/502/503/504/505/506/507/508/509/510/511/512/513/514/515/516/517/518/519/520/521/522/523/524/525/526/527/528/529/530/531/532/533/534/535/536/537/538/539/540/541/542/543/544/545/546/547/548/549/550/551/552/553/554/555/556/557/558/559/560/561/562/563/564/565/566/567/568/569/570/571/572/573/574/575/576/577/578/579/580/581/582/583/584/585/586/587/588/589/590/591/592/593/594/595/596/597/598/599/600/601/602/603/604/605/606/607/608/609/610/611/612/613/614/615/616/617/618/619/620/621/622/623/624/625/626/627/628/629/630/631/632/633/634/635/636/637/638/639/640/641/642/643/644/645/646/647/648/649/650/651/652/653/654/655/656/657/658/659/660/661/662/663/664/665/666/667/668/669/670/671/672/673/674/675/676/677/678/679/680/681/682/683/684/685/686/687/688/689/690/691/692/693/694/695/696/697/698/699/700/701/702/703/704/705/706/707/708/709/710/711/712/713/714/715/716/717/718/719/720/721/722/723/724/725/726/727/728/729/730/731/732/733/734/735/736/737/738/739/740/741/742/743/744/745/746/747/748/749/750/751/752/753/754/755/756/757/758/759/760/761/762/763/764/765/766/767/768/769/770/771/772/773/774/775/776/777/778/779/780/781/782/783/784/785/786/787/788/789/790/791/792/793/794/795/796/797/798/799/800/801/802/803/804/805/806/807/808/809/810/811/812/813/814/815/816/817/818/819/820/821/822/823/824/825/826/827/828/829/830/831/832/833/834/835/836/837/838/839/840/841/842/843/844/845/846/847/848/849/850/851/852/853/854/855/856/857/858/859/860/861/862/863/864/865/866/867/868/869/870/871/872/873/874/875/876/877/878/879/880/881/882/883/884/885/886/887/888/889/890/891/892/893/894/895/896/897/898/899/900/901/902/903/904/905/906/907/908/909/910/911/912/913/914/915/916/917/918/919/920/921/922/923/924/925/926/927/928/929/930/931/932/933/934/935/936/937/938/939/940/941/942/943/944/945/946/947/948/949/950/951/952/953/954/955/956/957/958/959/960/961/962/963/964/965/966/967/968/969/970/971/972/973/974/975/976/977/978/979/980/981/982/983/984/985/986/987/988/989/990/991/992/993/994/995/996/997/998/999/1000/1001/1002/1003/1004/1005/1006/1007/1008/1009/1010/1011/1012/1013/1014/1015/1016/1017/1018/1019/1020/1021/1022/1023/1024/1025/1026/1027/1028/1029/1030/1031/1032/1033/1034/1035/1036/1037/1038/1039/1040/1041/1042/1043/1044/1045/1046/1047/1048/1049/1050/1051/1052/1053/1054/1055/1056/1057/1058/1059/1060/1061/1062/1063/1064/1065/1066/1067/1068/1069/1070/1071/1072/1073/1074/1075/1076/1077/1078/1079/1080/1081/1082/1083/1084/1085/1086/1087/1088/1089/1090/1091/1092/1093/1094/1095/1096/1097/1098/1099/1100/1101/1102/1103/1104/1105/1106/1107/1108/1109/1110/1111/1112/1113/1114/1115/1116/1117/1118/1119/1120/1121/1122/1123/1124/1125/1126/1127/1128/1129/1130/1131/1132/1133/1134/1135/1136/1137/1138/1139/1140/1141/1142/1143/1144/1145/1146/1147/1148/1149/1150/1151/1152/1153/1154/1155/1156/1157/1158/1159/1160/1161/1162/1163/1164/1165/1166/1167/1168/1169/1170/1171/1172/1173/1174/1175/1176/1177/1178/1179/1180/1181/1182/1183/1184/1185/1186/1187/1188/1189/1190/1191/1192/1193/1194/1195/1196/1197/1198/1199/1200/1201/1202/1203/1204/1205/1206/1207/1208/1209/1210/1211/1212/1213/1214/1215/1216/1217/1218/1219/1220/1221/1222/1223/1224/1225/1226/1227/1228/1229/1230/1231/1232/1233/1234/1235/1236/1237/1238/1239/1240/1241/1242/1243/1244/1245/1246/1247/1248/1249/1250/1251/1252/1253/1254/1255/1256/1257/1258/1259/1260/1261/1262/1263/1264/1265/1266/1267/1268/1269/1270/1271/1272/1273/1274/1275/1276/1277/1278/1279/1280/1281/1282/1283/1284/1285/1286/1287/1288/1289/1290/1291/1292/1293/1294/1295/1296/1297/1298/1299/1300/1301/1302/1303/1304/1305/1306/1307/1308/1309/1310/1311/1312/1313/1314/1315/1316/1317/1318/1319/1320/1321/1322/1323/1324/1325/1326/1327/1328/1329/1330/1331/1332/1333/1334/1335/1336/1337/1338/1339/1340/1341/1342/1343/1344/1345/1346/1347/1348/1349/1350/1351/1352/1353/1354/1355/1356/1357/1358/1359/1360/1361/1362/1363/1364/1365/1366/1367/1368/1369/1370/1371/1372/1373/1374/1375/1376/1377/1378/1379/1380/1381/1382/1383/1384/1385/1386/1387/1388/1389/1390/1391/1392/1393/1394/1395/1396/1397/1398/1399/1400/1401/1402/1403/1404/1405/1406/1407/1408/1409/1410/1411/1412/1413/1414/1415/1416/1417/1418/1419/1420/1421/1422/1423/1424/1425/1426/1427/1428/1429/1430/1431/1432/1433/1434/1435/1436/1437/1438/1439/1440/1441/1442/1443/1444/1445/1446/1447/1448/1449/1450/1451/1452/1453/1454/1455/1456/1457/1458/1459/1460/1461/1462/1463/1464/1465/1466/1467/1468/1469/1470/1471/1472/1473/1474/1475/1476/1477/1478/1479/1480/1481/1482/1483/1484/1485/1486/1487/1488/1489/1490/1491/1492/1493/1494/1495/1496/1497/1498/1499/1500/1501/1502/1503/1504/1505/1506/1507/1508/1509/1510/1511/1512/1513/1514/1515/1516/1517/1518/1519/1520/1521/1522/1523/1524/1525/1526/1527/1528/1529/1530/1531/1532/1533/1534/1535/1536/1537/1538/1539/1540/1541/1542/1543/1544/1545/1546/1547/1548/1549/1550/1551/1552/1553/1554/1555/1556/1557/1558/1559/1560/1561/1562/1563/1564/1565/1566/1567/1568/1569/1570/1571/1572/1573/1574/1575/1576/1577/1578/1579/1580/1581/1582/1583/1584/1585/1586/1587/1588/1589/1590/1591/1592/1593/1594/1595/1596/1597/1598/1599/1600/1601/1602/1603/1604/1605/1606/1607/1608/1609/1610/1611/1612/1613/1614/1615/1616/1617/1618/1619/1620/1621/1622/1623/1624/1625/1626/1627/1628/1629/1630/1631/1632/1633/1634/1635/1636/1637/1638/1639/1640/1641/1642/1643/1644/1645/1646/1647/1648/1649/1650/1651/1652/1653/1654/1655/1656/1657/1658/1659/1660/1661/1662/1663/1664/1665/1666/1667/1668/1669/1670/1671/1672/1673/1674/1675/1676/1677/1678/1679/1680/1681/1682/1683/1684/1685/1686/1687/1688/1689/1690/1691/1692/1693/1694/1695/1696/1697/1698/1699/1700/1701/1702/1703/1704/1705/1706/1707/1708/1709/1710/1711/1712/1713/1714/1715/1716/1717/1718/1719/1720/1721/1722/1723/1724/1725/1726/1727/1728/1729/1730/1731/1732/1733/1734/1735/1736/1737/1738/1739/1740/1741/1742/1743/1744/1745/1746/1747/1748/1749/1750/1751/1752/1753/1754/1755/1756/1757/1758/1759/1760/1761/1762/1763/1764/1765/1766/1767/1768/1769/1770/1771/1772/1773/1774/1775/1776/1777/1778/1779/1780/1781/1782/1783/1784/1785/1786/1787/1788/1789/1790/1791/1792/1793/1794/1795/1796/1797/1798/1799/1800/1801/1802/1803/1804/1805/1806/1807/1808/1809/1810/1811/1812/1813/1814/1815/1816/1817/1818/1819/1820/1821/1822/1823/1824/1825/1826/1827/1828/1829/1830/1831/1832/1833/1834/1835/1836/1837/1838/1839/1840/1841/1842/1843/1844/1845/1846/1847/1848/1849/1850/1851/1852/1853/1854/1855/1856/1857/1858/1859/1860/1861/1862/1863/1864/1865/1866/1867/1868/1869/1870/1871/1872/1873/1874/1875/1876/1877/1878/1879/1880/1881/1882/1883/1884/1885/1886/1887/1888/1889/1890/1891/1892/1893/1894/1895/1896/1897/1898/1899/1900/1901/1902/1903/1904/1905/1906/1907/1908/1909/1910/1911/1912/1913/1914/1915/1916/1917/1918/1919/1920/1921/1922/1923/1924/1925/1926/1927/1928/1929/1930/1931/1932/1933/1934/1935/1936/1937/1938/1939/1940/1941/1942/1943/1944/1945/1946/1947/1948/1949/1950/1951/1952/1953/1954/1955/1956/1957/1958/1959/1960/1961/1962/1963/1964/1965/1966/1967/1968/1969/1970/1971/1972/1973/1974/1975/1976/1977/1978/1979/1980/1981/1982/1983/1984/1985/1986/1987/1988/1989/1990/1991/1992/1993/1994/1995/1996/1997/1998/1999/2000/2001/2002/2003/2004/2005/2006/2007/2008/2009/2010/2011/2012/2013/2014/2015/2016/2017/2018/2019/2020/2021/2022/2023/2024/2025/2026/2027/2028/2029/2030/2031/2032/2033/2034/2035/2036/2037/2038/2039/2040/2041/2042/2043/2044/2045/2046/2047/2048/2049/2050/2051/2052/2053/2054/2055/2056/2057/2058/2059/2060/2061/2062/2063/2064/2065/2066/2067/2068/2069/2070/2071/2072/2073/2074/2075/2076/2077/2078/2079/2080/2081/2082/2083/2084/2085/2086/2087/2088/2089/2090/2091/2092/2093/2094/2095/2096/2097/2098/2099/2100/2101/2102/2103/2104/2105/2106/2107/2108/2109/2110/2111/2112/2113/2114/2115/2116/2117/2118/2119/2120/2121/2122/2123/2124/2125/2126/2127/2128/2129/2130/2131/2132/2133/2134/2135/2136/2137/2138/2139/2140/2141/2142/2143/2144/2145/2146/2147/2148/2149/2150/2151/2152/2153/2154/2155/2156/2157/2158/2159/2160/2161/2162/2163/2164/2165/2166/2167/2168/2169/2170/2171/2172/2173/2174/2175/2176/2177/2178/2179/2180/2181/2182/2183/2184/2185/2186/2187/2188/2189/2190/2191/2192/2193/2194/2195/2196/2197/2198/2199/2200/2201/2202/2203/2204/2205/2206/2207/2208/2209/2210/2211/2212/2213/2214/2215/2216/2217/2218/2219/2220/2221/2222/2223/2224/2225/2226/2227/2228/2229/2230/2231/2232/2233/2234/2235/2236/2237/2238/2239/2240/2241/2242/2243/2244/2245/2246/2247/2248/2249/2250/2251/2252/2253/2254/2255/2256/2257/2258/2259/2260/2261/2262/2263/2264/2265/2266/2267/2268/2269/2270/2271/2272/2273/2274/2275/2276/2277/2278/2279/2280/2281/2282/2283/2284/2285/2286/2287/2288/2289/2290/2291/2292/2293/2294/2295/2296/2297/2298/2299/2300/2301/2302/2303/2304/2305/2306/2307/2308/2309/2310/2311/2312/2313/2314/2315/2316/2317/2318/2319/2320/2321/2322/2323/2324/2325/2326/2327/2328/2329/2330/2331/2332/2333/2334/2335/2336/2337/2338/2339/2340/2341/2342/2343/2344/2345/2346/2347/2348/2349/2350/2351/2352/2353/2354/2355/2356/2357/2358/2359/2360/2361/2362/2363/2364/2365/2366/2367/2368/2369/2370/2371/2372/2373/2374/2375/2376/2377/2378/2379/2380/2381/2382/2383/2384/2385/2386/2387/2388/2389/2390/2391/2392/2393/2394/2395/2396/2397/2398/2399/2400/2401/2402/2403/2404/2405/2406/2407/2408/2409/2410/2411/2412/2413/2414/2415/2416/2417/2418/2419/2420/2421/2422/2423/2424/2425/2426/2427/2428/2429/2430/2431/2432/2433/2434/2435/2436/2437/2438/2439/2440/2441/2442/2443/2444/2445/2446/2447/2448/2449/2450/2451/2452/2453/2454/2455/2456/2457/2458/2459/2460/2461/2462/2463/2464/2465/2466/2467/2468/2469/2470/2471/2472/2473/2474/2475/2476/2477/2478/2479/2480/2481/2482/2483/2484/2485/2486/2487/2488/2489/2490/2491/2492/2493/2494/2495/2496/2497/2498/2499/2500/2501/2502/2503/2504/2505/2506/2507/2508/2509/2510/2511/2512/2513/2514/2515/2516/2517/2518/2519/2520/2521/2522/2523/2524/2525/2526/2527/2528/2529/2530/2531/2532/2533/2534/2535/2536/2537/2538/2539/2540/2541/2542/2543/2544/2545/2546/2547/2548/2549/2550/2551/2552/2553/2554/2555/2556/2557/2558/2559/2560/2561/2562/2563/2564/2565/2

# 96 motorsports PTE LTD

62 & 64 Kaki Bukit Ave 6, (S) 417893, Ark@KB

Tel: 6702 6996

Fax: 6384 6996

Email: admin@96motorsports.com

Vehicle number: SLQ5187E

Vehicle Made & Model: HONDA VEZEL

TP 1st Cap Service.

| Qty | List Items                                      | Amount \$                 |
|-----|-------------------------------------------------|---------------------------|
| 1   | Front bumper <i>Repair</i>                      | 881.90 *                  |
| 1   | Front bumper side retainer - LH <i>3 new</i>    | 48.60 *                   |
| 10  | Front bumper clips @ 4.50                       | 45.00 *                   |
| 1   | Front fender - LH <i>Painted</i>                | 680.90 ✓                  |
| 1   | Front fender wheel arch garnish <i>Rehomed.</i> | 311.80 ✓                  |
| 1   | Front fender inner shield - LH <i>3 new</i>     | 212.60 *                  |
| 15  | Front fender inner shield clips @ 4.50          | 67.50 *                   |
| 1   | Front door - LH <i>Distorted</i>                | <del>1,257.60</del> 1,042 |
| 1   | Front door side mirror <i>new</i>               | 680.90 *                  |
| 1   | Front door glass outer moulding <i>new</i>      | 120.20 *                  |
| 1   | Front door glass run channel <i>new</i>         | 155.60 *                  |
| 1   | Front door outer handle <i>new</i>              | 180.60 *                  |
| 1   | Front door inner lock <i>2nd</i>                | 481.60 ✓                  |
| 1   | Front door inner board <i>3 new</i>             | 781.60 *                  |
| 1   | Front door insulation                           | 120.30 *                  |
| 1   | Front door glass regulator assy <i>2nd</i>      | <del>489.50</del> 358     |
| 1   | Front door checker <i>new</i>                   | 89.60 *                   |
| 2   | Front door hinges @ 85.60 <i>new</i>            | 171.20 *                  |
| 1   | Front door w/strip <i>2 new</i>                 | 181.20 ✓                  |
| 1   | Front door lower seal                           | 122.60 ✓                  |
| 1   | Front door edge seal                            | 141.20 ✓                  |
| 1   | Front shock absorber - LH <i>Best</i>           | 445.20 ✓                  |
| 1   | Front shock absorber top mount <i>new</i>       | 181.90 *                  |
| 1   | Front lower arm <i>Best</i>                     | 415.60 ✓                  |
| 1   | Front knuckle arm <i>Best</i>                   | <del>580.30</del> 490.40  |
| 1   | Front wheel hub <i>2nd</i>                      | 241.80 ✓                  |
| 1   | Front wheel bearing <i>new</i>                  | 130.60 ✓                  |
| 1   | Front anti roll bar <i>3 new</i>                | 312.2 *                   |
| 1   | Front anti roll bar link                        | 89.90 *                   |
| 1   | Front drive shaft - LH                          | 1,365.00 *                |
| 1   | Front steering rack assy                        | 1,635.60 *                |
| 1   | Side sill panel <i>Repair</i>                   | 645.00 *                  |

Vehicle number: SLQ5187E

Vehicle Made & Model: HONDA VEZEL

|                   |                                |          |                     |        |
|-------------------|--------------------------------|----------|---------------------|--------|
| 1                 | Side sill panel skirt          | veh d.   | 689.60              | ✓      |
| 1                 | Rear door - LH                 | Sealed   | <del>1,257.60</del> | ✓ 1025 |
| 1                 | Rear door sticker tape         | me       | 89.60               | ✓      |
| 1                 | Rear door glass outer moulding | 2 per me | 126.20              | ✓      |
| 1                 | Rear door glass run channel    |          | 155.60              | ✓      |
| 1                 | Rear door outer handle         | }        | 141.50              | ✓      |
| 1                 | Rear door inner lock           |          | 465.50              | ✓      |
| 1                 | Rear door inner board          |          | 691.90              | ✓      |
| 1                 | Rear door insulation           |          | 120.30              | ✓      |
| 1                 | Rear door glass regulator      |          | 481.60              | ✓      |
| 1                 | Rear door checker              |          | 89.60               | ✓      |
| 1                 | Rear door w/strip              | 2 per    | 141.20              | ✓      |
| 1                 | Rear door edge seal            |          | 121.30              | ✓      |
| 1                 | Rear door lower seal           |          | 89.90               | ✓      |
| 1                 | Rear fender - LH               | 4 per me | 981.60              | ✓      |
| 1                 | Rear fender wheel arch garnish | 6 per    | 241.20              | ✓      |
| 1                 | Rear fender inner shield       | }        | 146.50              | ✓      |
| 1                 | Rear shock absorber - LH       |          | 281.60              | ✓      |
| 1                 | Rear axle beam                 |          | 1,895.20            | ✓      |
| 1                 | Rear wheel hub with bearing    | 4 per me | 541.20              | ✓      |
| <b>Sub-total</b>  |                                |          | <u>22,013.80</u>    |        |
| <b>Less 20%</b>   |                                |          | <u>4,402.76</u>     |        |
| <b>Total List</b> |                                |          | <b>17,611.04</b>    |        |

7443.70  
5952.56

Vehicle number: SLQ5187E

Vehicle Made & Model: HONDA VEZEL

**Special Net Items**

|                    |                            |            |                              |
|--------------------|----------------------------|------------|------------------------------|
| 1                  | Front wheel sport rim - LH | <i>lit</i> | <del>550.00</del> <i>450</i> |
| 1                  | Front tyre                 | <i>XL</i>  | 380.00 X                     |
| 1 set              | Front door black tape - LH | <i>new</i> | <del>120.00</del> <i>60</i>  |
| 1 set              | Rear door black tape - LH  |            | <del>120.00</del> <i>60</i>  |
| 1                  | Rear wheel sport rim - LH  | <i>lit</i> | <del>550.00</del> <i>400</i> |
| 1                  | Rear tyre                  | <i>XL</i>  | 380.00 X                     |
| 1 set              | F/R door sun visor         | <i>new</i> | <del>450.00</del> <i>100</i> |
| Total Special Nett |                            |            | <u>2,550.00</u>              |

**Labour Charges**

|                                                          |                                |
|----------------------------------------------------------|--------------------------------|
| To remove, refix front & rear undercarriage              | <del>600.00</del> <i>220</i>   |
| To check wheel alignment                                 | <del>120.00</del> <i>80</i>    |
| To check front electrical wiring                         | <del>50.00</del> <i>30</i>     |
| To re-seal anti-rust                                     | <del>180.00</del> <i>50</i>    |
| To respray painting & etc                                | <del>1,600.00</del> <i>900</i> |
| Panel beating, cut, weld, remove & replacing above parts | <del>1,600.00</del> <i>700</i> |
| Total Labour                                             | <u>4,150.00</u>                |

**ESTIMATE PARTS & LABOUR GRAND TOTAL \$**

**24,311.04**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To inspect damaged parts during assembly
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

total 9002.56  
h/s: 7.2K  
06 Dimp

7.2K



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023339/Arbe2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-03-2018



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | SH 9150Z       | Veh. Inspected | SLQ 5187E  |
| Policy No.   | D-15072701MFSH | Coverage (\$)  | 0.00       |
| Claim No.    | D17011294MFSH  | Excess (\$)    | 0.00       |
| Assign From  | MAY CHUA       | Assign Date    | 08/12/2017 |

### 2. Vehicle Particulars & Condition

|              |             |              |                    |
|--------------|-------------|--------------|--------------------|
| Make & Model | HONDA VEZEL | c.c          | 1496               |
| Engine No.   | HIDDEN      | Year of Reg. | 2017               |
| Chassis No.  | RU11207224  | Colour       | BROWN              |
| Odometer     | 28044       | Steering     | IN ORDER           |
| Brakes       | IN ORDER    | Modification | STANDARD ALLOY RIM |
| General      | GOOD        |              |                    |

### 3. Conditions of Tyres

|                | Size       | Make   | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm    |
| L/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm    |
| R/H Rear Tyre  | 215/60 R16 | DUNLOP | 6 mm    |
| L/H Rear Tyre  | 215/60 R16 | DUNLOP | 6 mm    |

### 4. Description of Damages

|                                                                                                  |
|--------------------------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE PORTION.<br>DAMAGES SEE DETAILS. |
|--------------------------------------------------------------------------------------------------|

### 5. General Information

|                |                                                                                     |                 |            |
|----------------|-------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 06/12/2017                                                                          | Inspection Date | 08/12/2017 |
| Survey held at | 96 MOTORSPORTS PTE LTD<br>62/64 KAKI BUKIT AVENUE 6<br>SINGAPORE 417893<br>ARK @ KB |                 |            |

### 5a. Remarks

|                                                                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 6 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 5187E

| Qty | Description of Parts                    | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>             |                      |                           |                   |
| 1   | FRONT BUMPER                            | TO REPAIR SEE LABOUR | 881.90                    | -                 |
| 1   | FRONT BUMPER SIDE RETAINER - LH         | NOT NECESSARY        | 48.60                     | -                 |
| 10  | FRONT BUMPER CLIPS @\$4.50              | NOT NECESSARY        | 45.00                     | -                 |
| 1   | FRONT FENDER - LH                       | DENTED               | 680.90                    | 680.90            |
| 1   | FRONT FENDER WHEEL ARCH GARNISH         | DEFORMED             | 311.80                    | 311.80            |
| 1   | FRONT FENDER INNER SHIELD - LH          | NOT NECESSARY        | 212.60                    | -                 |
| 15  | FRONT FENDER INNER SHIELD CLIPS @\$4.50 | NOT NECESSARY        | 67.50                     | -                 |
| 1   | FRONT DOOR - LH                         | DISTORTED            | 1,257.60                  | 1,042.00          |
| 1   | FRONT DOOR SIDE MIRROR                  | NOT NECESSARY        | 680.90                    | -                 |
| 1   | FRONT DOOR GLASS OUTER MOULDING         | NOT NECESSARY        | 120.20                    | -                 |
| 1   | FRONT DOOR GLASS RUN CHANNEL            | NOT NECESSARY        | 155.60                    | -                 |
| 1   | FRONT DOOR OUTER HANDLE                 | NOT NECESSARY        | 180.60                    | -                 |
| 1   | FRONT DOOR INNER LOCK                   | DAMAGED              | 481.60                    | 481.60            |
| 1   | FRONT DOOR INNER BOARD                  | NOT NECESSARY        | 781.60                    | -                 |
| 1   | FRONT DOOR INSULATION                   | NOT NECESSARY        | 120.30                    | -                 |
| 1   | FRONT DOOR GLASS REGULATOR ASSY         | DAMAGED              | 489.50                    | 358.00            |
| 1   | FRONT DOOR CHECKER                      | NOT NECESSARY        | 89.60                     | -                 |
| 2   | FRONT DOOR HINGES @\$85.60              | NOT NECESSARY        | 171.20                    | -                 |
| 1   | FRONT DOOR W/STRIP                      | NECESSARY            | 181.20                    | 181.20            |
| 1   | FRONT DOOR LOWER SEAL                   | NECESSARY            | 122.60                    | 122.60            |
| 1   | FRONT DOOR EDGE SEAL                    | NECESSARY            | 141.20                    | 141.20            |
| 1   | FRONT SHOCK ABSORBER - LH               | BENT                 | 445.20                    | 445.20            |
| 1   | FRONT SHOCK ABSORBER TOP MOUNT          | NOT NECESSARY        | 181.90                    | -                 |
| 1   | FRONT LOWER ARM                         | BENT                 | 415.60                    | 415.60            |
| 1   | FRONT KNUCKLE ARM                       | BENT                 | 580.30                    | 490.40            |
| 1   | FRONT WHEEL HUB                         | DAMAGED              | 241.80                    | 241.80            |
| 1   | FRONT WHEEL BEARING                     | NECESSARY            | 130.60                    | 130.60            |
| 1   | FRONT ANTI ROLL BAR                     | NOT NECESSARY        | 312.20                    | -                 |
| 1   | FRONT ANTI ROLL BAR LINK                | NOT NECESSARY        | 89.90                     | -                 |
| 1   | FRONT DRIVE SHAFT - LH                  | NOT NECESSARY        | 1,365.00                  | -                 |

Report Ref No. CS/FCI17023339/Arbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                | Condition            | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|-------------------------------------|----------------------|----------------------------|-------------------|
| 1   | FRONT STEERING RACK ASSY            | NOT NECESSARY        | 1,635.60                   | -                 |
| 1   | SIDE SILL PANEL                     | TO REPAIR SEE LABOUR | 645.00                     | -                 |
| 1   | SIDE SILL PANEL SKIRT               | DEFORMED             | 689.60                     | 689.60            |
| 1   | REAR DOOR - LH                      | DENTED               | 1,257.60                   | 1,025.00          |
| 1   | REAR DOOR STICKER TAPE              | NECESSARY            | 89.60                      | 89.60             |
| 1   | REAR DOOR GLASS OUTER MOULDING      | NOT NECESSARY        | 126.20                     | -                 |
| 1   | REAR DOOR GLASS RUN CHANNEL         | NOT NECESSARY        | 155.60                     | -                 |
| 1   | REAR DOOR OUTER HANDLE              | NOT NECESSARY        | 141.50                     | -                 |
| 1   | REAR DOOR INNER LOCK                | NOT NECESSARY        | 465.50                     | -                 |
| 1   | REAR DOOR INNER BOARD               | NOT NECESSARY        | 691.90                     | -                 |
| 1   | REAR DOOR INSULATION                | NOT NECESSARY        | 120.30                     | -                 |
| 1   | REAR DOOR GLASS REGULATOR           | NOT NECESSARY        | 481.60                     | -                 |
| 1   | REAR DOOR CHECKER                   | NOT NECESSARY        | 89.60                      | -                 |
| 1   | REAR DOOR W/STRIP                   | NECESSARY            | 141.20                     | 141.20            |
| 1   | REAR DOOR EDGE SEAL                 | NECESSARY            | 121.30                     | 121.30            |
| 1   | REAR DOOR LOWER SEAL                | NECESSARY            | 89.90                      | 89.90             |
| 1   | REAR FENDER - LH                    | NOT NECESSARY        | 981.60                     | -                 |
| 1   | REAR FENDER WHEEL ARCH GARNISH      | CUT                  | 241.20                     | 241.20            |
| 1   | REAR FENDER INNER SHIELD            | NOT NECESSARY        | 146.50                     | -                 |
| 1   | REAR SHOCK ABSORBER - LH            | NOT NECESSARY        | 281.60                     | -                 |
| 1   | REAR AXLE BEAM                      | NOT NECESSARY        | 1,895.20                   | -                 |
| 1   | REAR WHEEL HUB WITH BEARING         | NOT NECESSARY        | 541.20                     | -                 |
|     | LESS 20% DISCOUNT                   |                      | -4,402.76                  | -1,488.14         |
|     |                                     |                      | 17,611.04                  | 5,952.56          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>    |                      |                            |                   |
| 1   | FRONT WHEEL SPORT RIM - LH (SN)     | CUT                  | 550.00                     | 450.00            |
| 1   | FRONT TYRE (SN)                     | NOT NECESSARY        | 380.00                     | -                 |
| 1   | SET FRONT DOOR BLACK TAPE - LH (SN) | NECESSARY            | 120.00                     | 60.00             |
| 1   | SET REAR DOOR BLACK TAPE - LH (SN)  | NECESSARY            | 120.00                     | 60.00             |
| 1   | REAR WHEEL SPORT RIM - LH (SN)      | CUT                  | 550.00                     | 400.00            |
| 1   | REAR TYRE (SN)                      | NOT NECESSARY        | 380.00                     | -                 |

Report Ref No. CS/FCI17023339/Arbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                  | Description of Parts                                                                                                   | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
| 1                                                                    | SET F/R DOOR SUN VISOR (SN)                                                                                            | NECESSARY | 450.00                    | 100.00            |
|                                                                      |                                                                                                                        |           | 2,550.00                  | 1,070.00          |
|                                                                      | <b>LABOUR</b>                                                                                                          |           |                           |                   |
|                                                                      | TO REMOVE, REFIX FRONT & REAR UNDERCARRIAGE.                                                                           |           | 600.00                    | 220.00            |
|                                                                      | TO CHECK WHEEL ALIGNMENT.                                                                                              |           | 120.00                    | 80.00             |
|                                                                      | TO CHECK FRONT ELECTRICAL WIRING.                                                                                      |           | 50.00                     | 30.00             |
|                                                                      | TO RE-SEAL ANTI-RUST.                                                                                                  |           | 180.00                    | 50.00             |
|                                                                      | TO RESPRAY PAINTING & ETC.                                                                                             |           | 1,600.00                  | 900.00            |
|                                                                      | PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND SIDE SILL PANEL. |           | 1,600.00                  | 700.00            |
|                                                                      |                                                                                                                        |           | 4,150.00                  | 1,980.00          |
| GRAND TOTAL                                                          |                                                                                                                        |           | 24,311.04                 | 9,002.56          |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |                                                                                                                        |           |                           | 7,200.00          |

Report Ref No. CS/FCI17023339/Arbe2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.