

ASS. EC. BY:

REF: CS/MS(17023348 / Ktb

Special Instructions:

Surveyor:

ASSIGNMENT (Office)

Meliman

From (Person): Irene Tan

of

MSL

Date/Time: 07-12-2017 5:13pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GW 3031L

Insured:

SJX 2395C

at Workshop m/s

Accord Auto

Tel:

64819517

of

Blk 10 AMK Ind Park 2A #03-11

Policy No:

1000103060

Claim No:

213136

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05-12-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time: 08-12-2017 9:31am

Person Contacted:

Jessa

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GW 3031L - X

SJX 2395C - NA / MS(17023348) / 24

Dof. 031217

11/1 11 Lp 8295d enrol &amp; confirm (Red: 5735.90 : 667.)

REF: MSIG

## ASSIGNMENT

From: \_\_\_\_\_ Date: 18/11/2017

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GW 3031L

at Workshop m/s Accord Auto

of 10 AMK Ind. Park 2A #03-11

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: @ 25%

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (wp)

10/20

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GW 3031L Yr Regn: 10 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota / Hiace c.c. 2496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 27313P T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTF14502P 100030185

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15X8

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Matti

Front

Rear

R/Bal. 9 mm

R/Bal. 6 mm

L/Bal. 9 mm

L/Bal. 6 mm

D.O.A. 5/12/17

D.O.I. 18/12/17

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/12 File sent to Carpenter

RECEIVED 17 JAN 2018

Date/Time: File Pass to?

☐

Preli. Report

1) H/Typist

☐

Final Report

Date/Time: File Return to?

2) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

S + PS: \$

Photos

Others

Report Format: TP

Lump Sum / I.B.I: (\$ 2950)-

200

10

210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17023348/Ktb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 08-12-2017



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 2395C	Veh. Inspected	GW 3031L
Policy No.	1000103060	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	07/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	05/12/2017	Inspection Date	18/12/2017
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	06 Dec 2017		07 Dec 2017 17:13 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
<b>Insured:</b>	HENG SOON WAH, ID: S1362550F								
<b>Main Claimant:</b>	X-COOL AIRCONDITIONING & ELECTRICAL PTE LTD, Co. Reg. No.: 200506544C								
<b>Vehicle Reg. No.:</b>	GW3031L	<b>Date of Loss:</b>	05/12/2017 13:00 - :59						
<b>Claim Type:</b>	TP	<b>Policy/Cover Note No.:</b>	1000103060 (Comprehensive) Coverage: 26/11/2017 - 25/11/2018						
<b>Vehicle Reg. No. (Insured):</b>	SJX2395C	<b>Policy No. (Claimant):</b>							
	<b>Excess:</b>								
<b>Repairer:</b>	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140								
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/12/2017]								
<b>Driver/Custodian (Insured):</b>	NG ZAI JIN ( / Male), NRIC: S1198792C								
<b>Adj. Asg. Remarks:</b>	Please assign to Kenneth Kong								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# Survey Department Check List (Case Handler)

Reference No. : CS/MBE/F1023348/ktb  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (Catherine)** : Case handler to make sure all Information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

## Surveyor (Kenneth)

: Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By: Denise 17/11/2018  
Case Handler Date

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.	GW3031L
Vehicle Type	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	TOYOTA
Vehicle Model	HIACE MANUAL
Chassis No.	JTFHS02P100030185
Propellant	Diesel
Engine No.	2KD1367417
Engine Capacity	2494 cc
Maximum Power Output	-
Maximum Laden Weight	2800 kg
Unladen Weight	1740 kg
Year Of Manufacture	2005
Original Registration Date	28 Oct 2005
Lifespan Expiry Date	27 Oct 2025
COE Category	C - Goods Vehicle & Bus
PQP Paid	\$23,992.00
COE Expiry Date	27 Oct 2020
Road Tax Expiry Date	27 Apr 2018
Inspection Due Date	27 Apr 2018
Intended Transfer Date	05 Dec 2017
CO2 Emission	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	11.00	-	11.00
<b>Total Amount Payable</b>			<b>11.00</b>

### Message

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	06/12/2017 15:18
Date Of Accident	05/12/2017 13:30
Exact Location Of Accident	COMMONWEALTH AVE WEST
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GW3031L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	X-COOL AIRCONDITIONING & ELECTRICAL PTE LTD
Co Reg No	200506544C
Email Address	ADMIN@XCOOL.COM.SG
Mobile Phone No	(LOCAL) +65-90622563
Alternative Phone No	OFFICE-90622563
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	HIACE MANUAL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	A28629985MKC
Cover Note Number	
<b>Driver</b>	
Name of Driver	LEE CHEE HOE
Passport No/FIN	G7932545M
Date Of Birth	12/09/1987
Occupation	OUTDOOR
Date Of Driving Pass	28/04/2010
Driving Experience	7 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94275017
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	90 JELICOE ROAD #16-30
Postcode	208749
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN. WILL REPAIR & CLAIM AT ACCORD AUTO SERVICES PTE LTD.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX2395C
Vehicle Make/Model/Colour	TOYOTA / CAMRY /BLACK /GREY
Details Of Properties	
Name of Driver	NG ZAN JIN
NRIC/Passport Number	S1198792C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJN9382X
Vehicle Make/Model/Colour	HYUNDAI / AVANTE / GREY



**Details Of Properties**

Name of Driver	NONIS MACNEU MARTIN
NRIC/Passport Number	S6918657B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**Details of Witness**

Name	
Phone Number	
Email Address	

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number	SLH6877M
Vehicle Make/Model/Colour	TOYOTA / WISH / WHITE
Details Of Properties	
Name of Driver	KAMARUDIN BIN OSMAN
NRIC/Passport Number	S1528626A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**Details of Witness**

Name	
Phone Number	
Email Address	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**X-Cool Airconditioning & Electrical Pte Ltd**  
90 Jellicoe Road #16-30 Singapore 208749  
Tel: 6858 2877 Email: admin@xcool.com.sg  
Co. Reg. No. 200506544C


Policyholder's Signature:  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature:  
Name:  
NRIC/TIN No:

### Sketch Plan #2

SKETCH PLAN Vehicle A: GW3031 L Vehicle B: SJX 2395C Vehicle C: SJN 9382X  
Vehicle D: SLH 6877M



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date of Accident: 05/12/2017 Time of Accident: 1:30pm

On the date and time above, I was travelling along Commonwealth Ave West. Traffic light was red so I stopped my vehicle. After few minutes, suddenly I felt an impact from rear portion. I alight and check on my vehicle and found out there were other 3 vehicles involved this accident.

My prefer workshop: Accord Auto Services Pte Ltd

X-Cool Airconditioning & Electrical Pte Ltd  
90 Jellicoe Road, #10-30 Singapore 208749  
Tel: 6858 2877 Email: [admin@xccool.com.sg](mailto:admin@xccool.com.sg)  
Co. Reg. No. 200506544C

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Yan Jey  
NRIC/FIN No.: \_\_\_\_\_

# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

## ESTIMATE

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way,

#21-01 SGC Centre 2,

Singapore 068807

Attn: Motor Claims Department

Date :

06/12/2017

Vehicle No :

GW3031L

Veh Make/Model :

Toyota Hiace Manual

YOM :

2005

Chassis No :

JTFHS02P100030185

Date of Accident :

05/12/2017

No	Qty	Description	Amount \$
<b>List Items:-</b>			
1	1	Tailgate	\$ 1,950.00
2	1	Tailgate outer garnish	\$ 129.20
3	1	Tailgate number plate lamp	\$ 171.80
4	2	Tailgate hinge	\$ 131.40
5	1	Tailgate lock	\$ 264.70
6	2	Tailgate damper	\$ 299.50
7	1	Tailgate weatherstrip	\$ 391.70
8	1	Tailgate inner trim board	\$ 469.70
9	1	Tailgate windscreen	\$ 1,251.70
10	1	Tail lamp LH	\$ 338.50
11	1	Tail lamp lower panel LH	\$ 525.90
12	1	Rear bumper	\$ 492.10
13	2	Rear bumper side retainer	\$ 112.60
14	10	Rear bumper clips	\$ 52.00
15	1	End panel	\$ 325.40
16	1	End panel top garnish	\$ 238.20
17	1	Spare tyre carrier	\$ 256.80
<b>Total - List Item</b>			<b>\$ 7,401.20</b>
<b>Less 25%</b>			<b>\$ 1,850.30</b>
<b>Total</b>			<b>\$ 5,550.90</b>
<b>Special Nett Items:-</b>			
1	1	Rear number plate	\$ 35.00
2	1 Set	Rear reverse sensor	\$ 380.00
3	1	"70Km/h" sticker	\$ 10.00
4	1	Tail gate windscreen gum	\$ 80.00
<b>Total - SN Item</b>			<b>\$ 505.00</b>
<b>Balance b/f</b>			<b>\$ 6,055.90</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: [claims@mycarworkshop.com.sg](mailto:claims@mycarworkshop.com.sg)

### ESTIMATE

Attn: Motor Claims Department

Date : 06/12/2017  
Vehicle No : GW3031L  
Veh Make/Model : Toyota Hiace Manual  
YOM : 2005  
Chassis No : JTFHS02P100030185  
Date of Accident : 05/12/2017

[illegible]

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023348/KTBN2

Date: 18/01/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1000103060
Claimant Vehicle No :	GW3031L	Insured Vehicle No :	SJX2395C
Date of Loss:	05/12/2017	Nature of Claim:	TP
		Claim No:	213136

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	GW3031L	Engine No:	2KD1367417
Make & Model:	TOYOTA HIACE, 2.5 (M)	Chassis No:	JTFHS02P100030185
Reg. Date:	28/10/2005 (Man. Year: 2005)	Odometer:	273139 km
Colour:	Silver		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Maxxis 9 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 9 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,055.90	2,364.62	3,691.28	60.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	1,370.00	1,360.00	49.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,785.90</b>	<b>3,734.62</b>	<b>5,051.28</b>	<b>57.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,950.00</b>		
(S\$)	8,785.90	2,950.00	5,835.90	66.42
<b>+ GST 7.00/7.00% (S\$)</b>	<b>615.01</b>	<b>206.50</b>	<b>408.51</b>	<b>66.42</b>
<b>Nett Amount (S\$)</b>	<b>9,400.91</b>	<b>3,156.50</b>	<b>6,244.41</b>	<b>66.42</b>

## INSPECTION

Date of Assignment:	07/12/2017	
Date Inspected:	18/12/2017 Inspected At:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 18 Jan 2018)	
<b>Parts:</b>	N/A	TOYOTA HIACE 2.5 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GW3031L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,950.00 FL	*1,950.00 FL
2	1		*TAILGATE OUTER GARNISH	Serviceable	129.20 FL	*- FL
3	1		*TAILGATE NUMBER PLATE LAMP	Serviceable	171.80 FL	*- FL
4	2		*TAILGATE HINGE	Repair	131.40 FL	*- FL
5	1		*TAILGATE LOCK	Repair	264.70 FL	*- FL
6	2		*TAILGATE DAMPER	Serviceable	299.50 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Serviceable	391.70 FL	*- FL
8	1		*TAILGATE INNER TRIM BOARD	Serviceable	469.70 FL	*- FL
9	1		*TAILGATE WINDSCREEN	Serviceable	1,251.70 FL	*- FL
10	1		*TAIL LAMP LH	Serviceable	338.50 FL	*- FL
11	1		*TAIL LAMP LOWER PANEL LH	Serviceable	525.90 FL	*- FL
12	1		*REAR BUMPER	Buckled	492.10 FL	*492.10 FL
13	2		*REAR BUMPER SIDE RETAINER	Serviceable	112.60 FL	*- FL
14	10		*REAR BUMPER CLIPS	Necessary	52.00 FL	*52.00 FL
15	1		*END PANEL	Bent	325.40 FL	*325.40 FL
16	1		*END PANEL TOP GARNISH	No such part	238.20 FL	*- FL
17	1		*SPARE TYRE CARRIER	Repair	256.80 FL	*- FL
18	1		*REAR NUMBER PLATE	Serviceable	35.00 FS	*- FS
19	1		*SET REAR REVERSE SENSOR	Cracked	380.00 FS	*200.00 FS
20	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
21	1		*TAIL GATE WINDSCREEN GUM	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,906.20</b>	<b>3,069.50</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,850.30</b>	<b>704.88</b>
<b>Total Parts (\$\$)</b>	<b>6,055.90</b>	<b>2,364.62</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	900.00	500.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,100.00	600.00
3	TO APPLY ANTI RUST TREATMENT	New	180.00	60.00
4	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	20.00
5	TO REMOVE AND REPLACE REVERSE SENSOR	New	120.00	50.00
6	TO REMOVE AND REPLACE TAILGATE WINDSCREEN GLASS	New	150.00	120.00
7	TO ADJUST EXHAUST SILENCER SYSTEM	New	100.00	-
8	TO CHECK AND TEST TAILGATE WATER LEAKING	New	80.00	20.00
Gross Labour Cost (S\$)			2,730.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >