

A: REC. BY:

REF: CS/EQTU7023349 / Gmbk

Special Instruction:

Survivor:

GR

ASSIGNMENT (Office)

merimen

From (Person):

Bazlin Ahmad

of

EQ2

Date/Time:

07/12/2017 5:10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 6919R

Insured:

at Workshop m/s

Auto N Cars

Tel:

6555 2909

of

Blk 1 Kaki Bukit Ave 1

01-04

Policy No:

DMPPHQ17 - 003107

Claim No:

DM17H002748

Sum Insured:

Excess:

\$ 550.00

Make of Veh:

(Client's Record)

D.O.A.

25.11.2017

CA / REV / REP. / REV 24 HRS

12.12.2017 @ 3pm owner waiting

H.O.D. Endorsement:

Date/Time:

08/12/2017 9:27am

Person Contacted:

Darla

Vehicle IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|--|
| | SKQ 6919R - CC4 / AXA 15016924 / Rwb3q2 |
| | DOA: 01-10-15 |
| 13/12/17 | Revert by merimen |
| 14/12/17 | Rece approved from Bazlin Ahmad by merimen |
| 14/12/17 | Informed Darla c/a on LS repair ex \$ 550 by email |
| | No after paint photos |

11.12.17

DL

11/7/18

Surrogate

Merimen

XHE

REF: EQ2

6848B

ASSIGNMENT

From: _____ Date: 12/12/2017

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKQ 6919R

at Workshop m/s: Auto Ni Cars

of: Bkt 1 Kaki Bukit Ave 6 #01-04

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$ 550.00

(Client's Record)

Make of Veh: _____

(Policy Condition) 3pm owner waiting

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$98K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SKQ 6919R Yr Regn: 27 Jul 2012

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Range Rover Evoque

Make: Land Rover C.O. 1999

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 155045 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SALVA 2AGSCH689140

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size: F: 235/60 R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 12-12-17

Survey held at w/s 3pm

Des. of Damages: ☒ Front / ☒ Rear / O/S / ☒ N/S / U/C / Rooftop or

and

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|---|
| 10/7/18 | LS \$ 11,000 confirmed by email (Recd 9570-64, 46B) |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to? _____

2) 11/7 - typist

Report Format: merimen

Lump Sum / I.B.I: (\$ 11,000/2)

Days Of Repair: 6

Resurvey No. of Trip: -

Survey Fee: 300

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S - RS (\$ _____)

☐ : Interview (\$ _____) ☐ : Photos

☐ : Tech. Invs (\$ _____) ☐ : Others

☐ : Weekend (\$ _____)

TOTAL: _____

Survey Department Check List (Case Handler)

Reference No.: CS/ESI 17023349 QVB
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

1) Office Assign Form

| | | Y-Date | N-Date | Y-Date | N-Date |
|---|---------------------------------------|--------|--------|--------|--------|
| C | Reference No. | ✓ | | | |
| C | Customer Code | | | | |
| N | Assign From | | | | |
| C | Assign Date | ✓ | | | |
| C | Veh No (Inspected) | ✓ | | | |
| C | Veh No (Insured) | | | | |
| C | D.O.A | ✓ | | | |
| C | Policy No | ✓ | | | |
| C | Claim No | ✓ | | | |
| C | Insurance Authorisation (CA /REV/REP) | ✓ | | | |
| C | Report Type | ✓ | | | |
| C | Weekend Charges | | | | |
| N | Survey held at/Repairer | ✓ | | | |
| C | Excess | ✓ | | | |

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

| | | | | | |
|---|-------------------------|---|--|--|--|
| C | Vehicle No | ✓ | | | |
| C | Regn Month/Year | ✓ | | | |
| N | Vehicle Type | ✓ | | | |
| N | Make & Model | ✓ | | | |
| C | Engine Capacity. (C.C) | ✓ | | | |
| N | Colour | ✓ | | | |
| C | Odometer. (Sp. Reading) | ✓ | | | |
| C | Chassis No | ✓ | | | |
| N | General Condition | ✓ | | | |
| N | Steering | ✓ | | | |
| N | Brake | ✓ | | | |
| N | Modification (Modi) | ✓ | | | |
| C | Tyre Size | ✓ | | | |
| N | Tyre Make | ✓ | | | |
| C | Tyre Balance | ✓ | | | |
| C | Date of Inspection | ✓ | | | |
| N | Survey held | ✓ | | | |
| N | Des.of Damages | ✓ | | | |

(2) System - (Views/Merimen)

| | | | | | |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ | | | |
|---|--------------------------------------|---|--|--|--|

(3) Workshop Estimate/Assignment Form

| | | | | | |
|---|---|---|--|--|--|
| N | ALL Parts condition | ✓ | | | |
| C | Market Value for OD cases | ✓ | | | |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) | | | | |
| C | Days of repair | ✓ | | | |
| C | Finalised Amount | ✓ | | | |
| C | Re-inspection Cases to Finalize within 5 Days | | | | |

(4) System - (Views/Merimen)

| | | | | | |
|---|-------------------------|--|--|--|--|
| C | Resurvey photo Uploaded | | | | |
|---|-------------------------|--|--|--|--|

Check By:

VERON

11/5/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|--------------------------|---|
| EQ INSURANCE COMPANY LTD | | Ref : CS/EQI17023349/Gvb | |
| 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110 | | Date : 08-12-2017 |  |
| | | Code : EQI | |
| 1. Policy Particulars :- OWN DAMAGE | | | |
| Insured Veh. | | Veh. Inspected | SKQ 6919R |
| Policy No. | DMPPHQ17-003107 | Coverage (\$) | 0.00 |
| Claim No. | DM17HO02748 | Excess (\$) | 550.00 |
| Assign From | MERIMEN (BAZLIN AHMAD) | Assign Date | 07/12/2017 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 25/11/2017 | Inspection Date | |
| Survey held at | AUTO N CARS SERVICES PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883. | | |
| 5a. Remarks | | | |
| A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. | | | |

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|--------------------------------------|--------------------------------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 06 Dec 2017 15:15 Sendback Est | 06 Dec 2017 15:33 S\$20,570.64 | 07 Dec 2017 17:10 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | |
|----------------------------------|---|-------------------------------|---------------------------------|-----------------------------------|--------------------------|
| CLAIM SUBFOLDER DETAILS | | | | | |
| Insured: | CHAN POI HONG, ID: S7476848B, Tel: +6598424643, Email: NOEMAIL | | | | |
| Vehicle Reg. No.: | SKQ6919R | Date of Loss: | 25/11/2017 22:00 - :59 | | |
| Claim Type: | OD / DM17HO02748 | Policy/Cover Note No.: | DMPPHQ17-003107 (Comprehensive) | | |
| | | Excess: | S\$550.00 | | |
| Repairer: | Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6555 2909 | | | | |
| Handling Insurer: | EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Bazlin Ahmad] | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/12/2017] | | | | |
| Driver/Custodian: | CHAN POI HONG (43 / Male), NRIC: S7476848B, Tel: +6598424643 | | | | |
| Adj Asg. Remarks: | EXCESS \$1,100 @ 50% DISCOUNT. | | | | |
| ASSOCIATED MAIL RECEIVED | | | | | |
| | | | View All | Compose Case Mail | |
| There are no mail for this case. | | | | | |
| ALL ASSOCIATED TASKS | | | | | |
| | | View All | Search Tasks | Create New Task | Complete |
| Due Date | Priority | Type | Task Group | Subject | Handler |
| | | | | Assigned By | Completed On |
| | | | | Created On | Done? |
| No results. | | | | | |

View Received Message

This mail is associated with :

SKQ6919R (DM17H002748)

OD

Nov 25 2017 10:00PM

[CHAN POI HONG]

Auto N Cars Services Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From EQ Insurance Company Ltd (HQ) (EQI_HQ), sent on 14/12/2017 11:45 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$18625.64) - SKQ6919R - Claim Handler: Bazlin Ahmad

Approved:18625.64.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 14 December, 2017 12:30 PM
To: Darla Balingit; SUR
Subject: SKQ 6919R-DOA: 25/11/2017 (EQ OD)

Dear Darla,

As instructed by our client **EQI** , please proceed to repair the insured vehicle **SKQ 6919R on Lump Sum Basis (Excess \$550/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>
Sent: Thursday, 14 December, 2017 11:44 AM
To: Veron Chen (LKKAUTO)
Subject: RE: DM17HO02748 SKQ6919R-DOA: 25/11/2017

Dear Veron

Done.

Thank You.

Regards,

Lynn Ahmad

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, December 14, 2017 10:31 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>; Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: SKQ 6919R-DOA: 25/11/2017 (EQ REF: DM17HO02748)

Dear Wei Yin/Janet,

We refer to the mentioned vehicle.

Kindly assist for mandate approval in merimen.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Bazlin Ahmad

Date: 13 Dec 2017

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-------------------|
| Vehicle No | : SKQ6919R | Accident Date | : 25/11/2017 |
| Make | : LAND ROVER RANGE ROVER EVOQUE | Policy No. | : DMPPHQ17-003107 |
| Assignment Date | : 07/12/2017 | Excess | : S\$550.00 |
| Date of Inspection | : 12/12/2017 | Est. Duration of Repair | : 6.00 |
| Inspection At | : AUTO N CARS SERVICES PTE LTD (HQ) BLK 1 KAKI BUKIT AVE 6 #01-04, AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and n/s body and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 20,570.64 |
| Revised Amount | :S\$ | 14,525.89 |
| Check Items (Estimated) | :S\$ | 4,099.75 |
| Total | :S\$ | 18,625.64 |

Lump Sum Repair :S\$

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 98,000.00 |
| COE / PARF Rebate | :S\$ | 78,419.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 19,581.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|---------------------------------------|
| Owner ID Type | Singapore NRIC |
| Owner ID | 6848B |
| Vehicle Details | |
| Vehicle No. | SKQ6919R |
| Vehicle to be Exported | No |
| Intended De-registration Date | 13 Dec 2017 |
| Vehicle Make | LAND ROVER |
| Vehicle Model | RANGE ROVER EVOQUE 2.0 AT ABS 4WD HID |
| Primary Colour | Black |
| Manufacturing Year | 2012 |
| Engine No. | 280512181500204PT |
| Chassis No. | SALVA2AG5CH689140 |
| Maximum Power Output | 177.0 kW (237 bhp) |
| Open Market Value | \$52,320.00 |
| Original Registration Date | 27 Jul 2012 |
| First Registration Date | 27 Jul 2012 |
| Transfer Count | 1 |
| Actual ARF Paid | \$52,320.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility | Yes |
| PARF Eligibility Expiry Date | 26 Jul 2022 |
| PARF Rebate Amount | \$36,624.00 |
| Intended COE Rebate Details | |
| COE Expiry Date | 26 Jul 2022 |
| COE Category | E - Open Category |
| COE Period(Years) | 10 |
| QP Paid | \$92,700.00 |
| COE Rebate Amount | \$41,795.00 |
| Total Rebate Amount | \$78,419.00 |

The information contained herein is correct as at 13 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-------------------------------------|
| Date Of Report | 05/12/2017 11:06 |
| Date Of Accident | 25/11/2017 22:00 |
| Exact Location Of Accident | ALONG JALAN KOTA TINGGI - PENDERANG |
| Country/State of Loss | MALAYSIA/JOHOR DARUL TAKZIM |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKQ6919R |
| Insured/Policyholder | |
| Name Of Registered Owner | CHAN POI HONG |
| NRIC No | S7476848B |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-98424643 |
| Alternative Phone No | OFFICE-98424643 |

Vehicle Particulars

| | |
|--|--------------------------------|
| Manufacturer | LAND ROVER |
| Model | RANGE ROVER-3.0 D TDV6 TSS (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES |
| If No, Please state action to be taken | |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------|
| Name of Insurance Company | EQ INSURANCE COMPANY LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMPPHQ17-003107 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | CHAN POI HONG |
| NRIC No | S7476848B |
| Date Of Birth | 13/02/1974 |
| Occupation | INDOOR |
| Date Of Driving Pass | 08/08/2000 |
| Driving Experience | 17 YEARS AND 3 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-98424643 |
| Fax Number | |
| Contact Number | OFFICE-98424643 |
| Email Address | NOEMAIL |

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



A 2KQ 6919 R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

near

The accident happened on 25/11/2017 at 10pm along Jalan Kota Tinggi - Pengerang. Vehicle A was driving straight when suddenly there was a road construction barricade. As there was no warning and no lights, vehicle A veered to the right in an attempt to avoid the barricade. The front and left side of the vehicle is damaged.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





Co. Reg: 200922097K GST Reg.No: 200922097K

Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883

• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date: 6/12/2017

Total Pages : 1

TO:

EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110

Our Customer : CHAN POI HONG

Vehicle No : SKQ6919R

Model : RANGE ROVER-3.0 D TDV6 TSS

Manufacture Year : \$ 2,012.00

Date of Accident : 5/12/2017

Total Estimate Repair Days : \$ 10.00

Attn : Motor Claims Department

Fax : \$ 62,243,903.00

Re: Repair Estimate For Own Damage Claim Against Policy : DMPPHQ17-003107

| No. | Item Descriptions | Qty | Unit Price | Amount | Remarks From Surveyor |
|-----------|--|-----|------------|--------------------|-----------------------|
| A. | Spare Parts | | | | |
| \$ 1.00 | Front no plate / <i>mis</i> | 1 | \$50.00 | \$50.00 | |
| \$ 2.00 | Front bumper / <i>re</i> 1800 | 1 | \$1,950.00 | \$1,950.00 | |
| \$ 3.00 | Front no plate base / <i>mis</i> | 1 | \$98.00 | \$98.00 | |
| \$ 4.00 | Front bumper retainer / <i>re</i> | 2 | \$80.00 | \$160.00 | |
| \$ 5.00 | Front bumper clip / <i>re</i> | 14 | \$2.80 | \$39.20 | |
| \$ 6.00 | Front bumper lower grille / <i>re</i> <i>CHA</i> | 1 | \$392.00 | \$392.00 | |
| \$ 7.00 | Front bumper ctr lw top garnish / <i>cut</i> | 1 | \$135.00 | \$135.00 | |
| \$ 8.00 | Front bumper ctr lw bottom garnish / <i>cut</i> | 1 | \$358.00 | \$358.00 | |
| \$ 9.00 | Front bumper impact garnish / <i>NN</i> | 1 | \$295.00 | \$295.00 | |
| \$10.00 | Front bumper parking sensor ctr / <i>mis</i> | 2 | \$320.00 | \$640.00 | |
| \$11.00 | Front bumper parking sensor LH / <i>DM</i> | 1 | \$320.00 | \$320.00 | |
| \$12.00 | LH headlamp / <i>NN</i> | 1 | \$2,580.00 | \$2,580.00 | |
| \$13.00 | LHF fog lamp / <i>mis</i> | 1 | \$480.00 | \$480.00 | |
| \$14.00 | LHF fog lamp cover top(big) / <i>mis</i> | 1 | \$105.00 | \$105.00 | |
| \$15.00 | LHF fog lamp cover bottom / <i>mis</i> | 1 | \$65.00 | \$65.00 | |
| \$16.00 | LHF foglamp base / <i>NN</i> | 1 | \$135.00 | \$135.00 | |
| \$17.00 | Front bumper ctr top retainer / <i>NN</i> | 1 | \$92.00 | \$92.00 | |
| \$18.00 | Front bonnet RANGE ROVER emblem / <i>re</i> | 1 | \$150.00 | \$150.00 | |
| \$19.00 | Front grille assmeby / <i>re</i> | 1 | \$398.00 | \$398.00 | |
| \$20.00 | Front ctr support panel garnish / <i>NN</i> | 1 | \$598.00 | \$598.00 | |
| \$21.00 | LHF fender protector / <i>mis</i> | 1 | \$285.00 | \$285.00 | |
| \$22.00 | LHF fender protector clip / <i>re</i> | 10 | \$2.80 | \$28.00 | |
| \$23.00 | LHF fender splash shield / <i>re</i> | 1 | \$250.00 | \$250.00 | |
| \$24.00 | LHF fender splash shield clip / <i>re</i> | 16 | \$2.80 | \$44.80 | |
| \$25.00 | LHF fender / <i>repair</i> | 1 | \$680.00 | \$680.00 | |
| \$26.00 | RHF fender splash shield / <i>re</i> | 1 | \$250.00 | \$250.00 | |
| \$27.00 | RHF fender splash shield clip / <i>re</i> | 16 | \$2.80 | \$44.80 | |
| \$28.00 | LHF door assembly / <i>re</i> | 1 | \$1,980.00 | \$1,980.00 | |
| \$29.00 | LHF door lower protector / <i>cut</i> | 1 | \$310.00 | \$310.00 | |
| \$30.00 | LHF door lower protector clip / <i>re</i> | 12 | \$2.80 | \$33.60 | |
| \$31.00 | LHF door lower protector moulding / <i>cut</i> | 1 | \$180.00 | \$180.00 | |
| \$32.00 | Rear bumper / <i>re</i> 1680 | 1 | \$1,580.00 | \$1,580.00 | |
| \$33.00 | Rear bumper retainer / <i>re</i> | 2 | \$95.00 | \$190.00 | |
| \$34.00 | Rear bumper LH outer garnish / <i>cut</i> | 1 | \$280.00 | \$280.00 | |
| \$35.00 | Rear bumper clip / <i>re</i> | 10 | \$2.80 | \$28.00 | |
| \$36.00 | LHR fender splash shield / <i>re</i> | 1 | \$250.00 | \$250.00 | |
| \$37.00 | LHR fender splash shield clip / <i>re</i> | 14 | \$2.80 | \$39.20 | |
| \$38.00 | Coolant / <i>NN</i> | 1 | \$20.00 | \$20.00 | |
| | Total | | | \$15,513.60 | |
| | Cost Plus 15% | | | \$2,327.04 | |
| | Sub Total 1 | | | \$17,840.64 | |
| | Total for Parts | | | \$17,840.64 | |
| C. | Labour | | | | |

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 10 July 2018 2:28 PM
To: 'Jing Tong Choo'
Subject: RE: SKQ 6919R-DOA: 25/11/2017 (EQ OD)

Dear Jaden,

Please forward us after paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jing Tong Choo [mailto:jtchoo@autoncars.com.sg]
Sent: Tuesday, 10 July 2018 2:13 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: SKQ 6919R-DOA: 25/11/2017 (EQ OD)

Hi Veron,

We confirm repair at \$11K @ 6 days.

--

Best regards,



Jaden Choo

Autobay @ Kaki Bukit Ave 6

#01-04 Area 'A' S(417883)

Contact No: 6555 2909 / 81881361

Web: www.autoncars.com.sg

Email: JTchoo@autoncars.com.sg

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 6 July 2018 12:07 PM
To: 'Darla Balingit'
Subject: RE: SKQ 6919R-DOA: 25/11/2017 (EQ OD)

Dear Darla,

Any update?

Offer Lump Sum \$11,000 before excess \$550 @ 6 working days

Kindly confirmed and forward us after paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 6 June 2018 4:38 PM
To: 'Darla Balingit' <darla@autoncars.com.sg>
Subject: RE: SKQ 6919R-DOA: 25/11/2017 (EQ OD)

Dear Darla,

Offer Lump Sum \$11,000 before excess \$550 @ 6 working days

Kindly confirmed and forward us after paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 14 December 2017 12:30 PM
To: Darla Balingit <darla@autoncars.com.sg>; SUR <sur@lkkauto.com>
Subject: SKQ 6919R-DOA: 25/11/2017 (EQ OD)

Dear Darla,

As instructed by our client **EQI** , please proceed to repair the insured vehicle **SKQ 6919R on Lump Sum Basis (Excess \$550/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|--|---|--|---|---|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 06 Dec 2017 15:15 Sendback Est | 06 Dec 2017 15:33 S\$20,570.64 | 07 Dec 2017 17:10 Edit Adj Rpt | S\$11,000.00 Edit Estimates | S\$11,000.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|---|------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | | | | | | | | |
| Insured: CHAN POI HONG , ID: S7476848B, Tel: +6598424643, Email: NOEMAIL | | | | | | | | | |
| Vehicle Reg. No.: SKQ6919R | | Date of Loss: 25/11/2017 22:00 - :59 [63 Months and 29 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: OD / DM17H002748 | | Policy/Cover Note No.: DMPPHQ17-003107 (Comprehensive) | | | | | | | |
| | | Excess: S\$550.00 | | | | | | | |
| Repairer: Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6555 2909 | | | | | | | | | |
| Handling Insurer: EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Bazlin Ahmad] | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 18/12/2017] | | | | | | | | | |
| Driver/Custodian: CHAN POI HONG (43 / Male), NRIC: S7476848B, Tel: +6598424643 | | | | | | | | | |
| Adj Asg. Remarks: EXCESS \$1,100 @ 50% DISCOUNT. | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> EQI_HQ (14/12/2017): Alert - Adj Mandate Approved (S\$18625.64) - SKQ6919R - Claim Handler: Bazlin Ahm... | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

SKQ6919R (DM17H002748)

















































OD


Nov 25 2017 10:00PM

[CHAN POI HONG]


Auto N Cars Services Pte Ltd



| | | |
|---|-----------------|---|
| Upload Documents Upload Photos Compose New Letter | | View View in Browser |
| Assessment Reports | | 1 per page <input type="checkbox"/> <input checked="" type="checkbox"/> |
| No | Finalized On | Auto N Cars Services Pte Ltd (HQ) |
| 1 | 06/12/17 15:33 | Repairer Estimates |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) |
| 1 | 13/12/17 14:15 | Adjuster Immediate Advice |
| Photos/Images | | 3 per page <input type="checkbox"/> <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |
| 1 | 13/12/17 10:59 | General View |
| 2 | 13/12/17 10:59 | General View |
| 3 | 13/12/17 10:59 | General View |
| 4 | 13/12/17 10:59 | General View |
| 5 | 13/12/17 10:59 | General View |
| 6 | 13/12/17 10:59 | General View |
| 7 | 13/12/17 10:59 | General View |
| 8 | 13/12/17 10:59 | General View |
| 9 | 13/12/17 10:59 | General View |
| 10 | 13/12/17 10:59 | General View |
| 11 | 13/12/17 10:59 | General View |
| 12 | 13/12/17 10:59 | General View |
| 13 | 13/12/17 10:59 | General View |
| 14 | 13/12/17 10:59 | General View |
| 15 | 13/12/17 10:59 | General View |
| 16 | 13/12/17 10:59 | General View |
| 17 | 13/12/17 10:59 | General View |
| 18 | 13/12/17 10:59 | General View |
| 19 | 13/12/17 10:59 | General View |
| 20 | 13/12/17 10:59 | General View |
| 21 | 13/12/17 10:59 | General View |
| 22 | 13/12/17 10:59 | General View |
| 23 | 13/12/17 10:59 | General View |
| 24 | 13/12/17 10:59 | General View |
| 25 | 13/12/17 10:59 | General View |
| 26 | 13/12/17 10:59 | General View |
| 27 | 13/12/17 10:59 | General View |
| 28 | 13/12/17 10:59 | General View |
| 29 | 13/12/17 10:59 | General View |
| 30 | 13/12/17 10:59 | General View |
| 31 | 13/12/17 10:59 | General View |
| 32 | 13/12/17 10:59 | General View |
| 33 | 13/12/17 10:59 | General View |
| 34 | 13/12/17 10:59 | General View |


| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | Auto N Cars Services Pte Ltd (HQ) | Thumbnail | Print |
| | | |  | <input checked="" type="checkbox"/> |
| 35 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | Auto N Cars Services Pte Ltd (HQ) | Thumbnail | Print |
| 84 | 13/12/17 10:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |

Linked Accident Report Documents

| Assessment Reports | | | View | View in Browser |
|--------------------|----------------|-----------------------------------|--|-----------------|
| No | Finalized On | Auto N Cars Services Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 05/12/17 11:32 | Accident Statement |  Load HTM | |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | Auto N Cars Services Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 05/12/17 11:31 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | Auto N Cars Services Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 05/12/17 11:31 | Sketch Plan |  Load TIF | |
| 2 | 05/12/17 11:31 | Sketch Plan #2 |  Load TIF | |
| 3 | 05/12/17 11:31 | IC & DL |  Load TIF | |

Documents Checklist

| | | | |
|--|-------|------|-------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQI17023349/GVBE2

Date: 17/07/2018

REFERENCE

Insured/Claimant: CHAN POI HONG Policy No: DMPPHQ17-003107
Date of Loss: 25/11/2017 Nature of Claim: OD Claim No: DM17HO02748

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ6919R**
Make & Model: LAND ROVER RANGE ROVER EVOQUE, 2.0 ABS 4WD HID SR (A) Engine No: 280512181500204PT
Reg. Date: 27/07/2012 (Man. Year: 2012) Chassis No: SALVA2AG5CH689140
Colour: Black Odometer: 155045 km
Engine Capacity: 1999 cc
Market Value/New Car Price: S\$98,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|------------------|------------------|--------------|
| Parts | 17,840.64 | 12,763.39 | 5,077.25 | 28.46 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,730.00 | 1,590.00 | 1,140.00 | 41.76 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 20,570.64 | 14,353.39 | 6,217.25 | 30.22 |
| Approved Total (Overridden) (S\$) | | 11,000.00 | | |
| - Excess (S\$) | 0.00 | 550.00 | -550.00 | |
| (S\$) | 20,570.64 | 10,450.00 | 10,120.64 | 49.20 |
| + GST 7.00/7.00% (S\$) | 1,439.94 | 731.50 | 708.44 | 49.20 |
| Nett Amount (S\$) | 22,010.58 | 11,181.50 | 10,829.08 | 49.20 |

INSPECTION

Date of Assignment: 07/12/2017 Present Location: Auto N Cars Services Pte Ltd (HQ)
Date Inspected: 12/12/2017 Inspected At: Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jul 2018)

Parts: M1-SUV LAND ROVER RANGE ROVER EVOQUE 2.0 ABS 4WD HID SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKQ6919R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|---------------|------------|-------------|
| 1 | 1 | | *Front no plate | Missing | 50.00 F | *50.00 F |
| 2 | 1 | | *Front bumper | Deformed | 1,950.00 F | *1,800.00 F |
| 3 | 1 | | *Front no plate base | Missing | 98.00 F | *98.00 F |
| 4 | 2 | | *Front bumper retainer | Necessary | 160.00 F | *160.00 F |
| 5 | 14 | | *Front bumper clip | Necessary | 39.20 F | *39.20 F |
| 6 | 1 | | *Front bumper lower grille | Cracked | 392.00 F | *392.00 F |
| 7 | 1 | | *Front bumper ctr lw top garnish | Cut | 135.00 F | *135.00 F |
| 8 | 1 | | *Front bumper ctr lw bottom garnish | Cut | 358.00 F | *358.00 F |
| 9 | 1 | | *Front bumper impact garnish | Not Necessary | 295.00 F | *- F |
| 10 | 2 | | *Front bumper parking sensor ctr | Missing | 640.00 F | *640.00 F |
| 11 | 1 | | *Front bumper parking sensor LH | Damaged | 320.00 F | *320.00 F |
| 12 | 1 | | *LH headlamp | Not Necessary | 2,580.00 F | *- F |
| 13 | 1 | | *LHF fog lamp | Missing | 480.00 F | *480.00 F |
| 14 | 1 | | *LHF fog lamp cover top(big) | Missing | 105.00 F | *105.00 F |
| 15 | 1 | | *LHF fog lamp cover bottom | Missing | 65.00 F | *65.00 F |
| 16 | 1 | | *LHF foglamp base | Missing | 135.00 F | *135.00 F |
| 17 | 1 | | *Front bumper ctr top retainer | Not Necessary | 92.00 F | *- F |
| 18 | 1 | | *Front bonnet RANGE ROVER emblem | Necessary | 150.00 F | *150.00 F |
| 19 | 1 | | *Front grille assmebly | Broken | 398.00 F | *398.00 F |
| 20 | 1 | | *Front ctr support panel garnish | Not Necessary | 598.00 F | *- F |
| 21 | 1 | | *LHF fender protector | Missing | 285.00 F | *285.00 F |
| 22 | 10 | | *LHF fender protector clip | Necessary | 28.00 F | *28.00 F |
| 23 | 1 | | *LHF fender splash shield | Deformed | 250.00 F | *250.00 F |
| 24 | 16 | | *LHF fender splash shield clip | Necessary | 44.80 F | *44.80 F |
| 25 | 1 | | *LHF fender | Repair | 680.00 F | *- F |
| 26 | 1 | | *RHF fender splash shield | Torn | 250.00 F | *250.00 F |
| 27 | 16 | | *RHF fender splash shield clip | Necessary | 44.80 F | *44.80 F |
| 28 | 1 | | *LHF door assembly | Bent | 1,980.00 F | *1,980.00 F |
| 29 | 1 | | *LHF door lower protector | Cut | 310.00 F | *310.00 F |
| 30 | 12 | | *LHF door lower protector clip | Necessary | 33.60 F | *33.60 F |
| 31 | 1 | | *LHF door lower protector moulding | Cut | 180.00 F | *180.00 F |
| 32 | 1 | | *Rear bumper | Deformed | 1,580.00 F | *1,580.00 F |
| 33 | 2 | | *Rear bumper retainer | Necessary | 190.00 F | *190.00 F |
| 34 | 1 | | *Rear bumper LH outer garnish | Cut | 280.00 F | *280.00 F |
| 35 | 10 | | *Rear bumper clip | Necessary | 28.00 F | *28.00 F |
| 36 | 1 | | *LHR fender splash shield | Deformed | 250.00 F | *250.00 F |
| 37 | 14 | | *LHR fender splash shield clip | Necessary | 39.20 F | *39.20 F |
| 38 | 1 | | *Coolant | Not Necessary | 20.00 F | *- F |

F=Franchise part.

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------|--|------------|-----------|
| | | | | Sub Total (S\$) | 15,513.60 | 11,098.60 |
| | | | | + Margin on L,N Items 15.00/15.00% (S\$) | 2,327.04 | 1,664.79 |
| | | | | Total Parts (S\$) | 17,840.64 | 12,763.39 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | To knock and straighten the necessary portion, cut & weld damaged panel, adjust and re-align the same | New | 1,300.00 | 600.00 |
| 2 | To putty and spray paint frt bonnet, frt supt panel, frt bumper, frt bumper lower extension, LHF fender, LHF door, LHR door, LHR fender, rear bumper | New | 1,000.00 | 900.00 |
| 3 | To remove and renew radiator assembly and air-con condenser. Vacuum and charge up gas | New | 150.00 | 0.00 |
| 4 | To transfer LHF door rubber beading, LH door glass, run channel, door lock mechanism, door trim board, power winder regulator, motor assy & wire harness | New | 200.00 | 60.00 |
| 5 | To check wiring and all lighting & ctr locking system | New | 80.00 | 30.00 |
| Gross Labour Cost (\$\$) | | | 2,730.00 | 1,590.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >