

REF:

REF: CS/CT1A03361/Gvb02

Special Instructions:

Survivor

60

**ASSIGNMENT (Office)**

From (Person):

Management

Jowyn Tay

of

CU

Date/Time:

08/22/17 2:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFR 6979X

Insured:

SLA 683(7)

at Workshop m/s

Ngalak mutur

Tel:

9850 2153

of

10 Kaki Bukit Rd 2 #03-36

Policy No:

DM PCSN 3034521701

Claim No:

SNMIF 00696200

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 05.12.2017

CA / REV / REP. / REV 24 HRS (W)

H.O.D. Endorsement:

Date/Time:

0812207 223pm

Person Contacted:

Mr. Kwan

Vehicle (IN/OUT)


Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	STR 1.979X - x
	3LA 6834 - x

REF: **CTL**  
**merimen**

**ASSIGNMENT**

(2019)

From: \_\_\_\_\_ Date: **08/12/2017**  
Estimated Cost: \_\_\_\_\_  
OD / **(P)** WS / TP RES / OD RES / EVA / INV / MV  
To inspect vehicle No: **SFR 6979X**  
at Workshop no: **Ngiak motor**  
of: **10 Kaki Bukit Rd 2 #03-36**  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: **Mr. Kwan - 9850 2253**  
  
(Policy Condition)  
Remark: **The veh had commenced its repair at the time of inspection.**  
  
Bal. or Market Value: **\$16500.**  
IDAO Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
Est. Repairs: **7** days Res: Yes or No  
Lum Sum: **20** % 3 Val: Yes or No  
  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: **SFR 6979X** Yr Reg: **02 Feb 2005**  
Type: **(C)** M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: **Hyundai Getz** cc: **1599**  
Colour: **Black** A/C: \_\_\_\_\_ Insured / Std / NI / NA  
Sp. Reading: **175916** T. Radio: Insured / Std / NI / NA  
Eng No: \_\_\_\_\_  
C No: **KMH1BU51BR-5U334443**  
Gen. Cond: **(C)** Good / Fair / Poor / Burnt  
Steering: **(C)** In order / Jammed / Leaked / Burnt or  
Brake: **(C)** In order / Jammed / Leaked / Burnt or  
Mod: **(C)** Nil / S/Rim / STD Air / Rim or  
Tyre Size: F: **195/50 R15**  
R: **11**  
BS / DUN / EXNOVA / GY / FS / LIZA / **(C)** MIG / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R. Bal. **6** mm R. Bal. **6** mm  
L. Bal. **6** mm L. Bal. **6** mm  
D.O.A. \_\_\_\_\_ D.O.I. **08-12-17**  
Survey held at: **w/s** **5:30pm**  
Des. of Damages: Frt / **(C)** Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision

Date: \_\_\_\_\_ Time: \_\_\_\_\_ Action / Instruction: **(LS) 08/12 Finalized \$2800 with kwan. (Red 7337.60, 7312)**

RECEIVED 11 FEB 2018  
RECEIVED 6 FEB 2018

Date/Time File Passed: ☐ Preli. Report  
☐ Final Report

Days Of Repair: **7**  
Resurvey No. of Trip: **1**

Date/Time File Return to: **11/12 - typist**  
Report Format: **merimen**  
Lump Sum - L.B.H: **2800/2**

Add Fee: ☐ Site Insp: \$  
☐ Inter. Insp: \$  
☐ Tech. Insp: \$  
☐ Rec. Insp: \$

Survey Fee: **220**  
Transportation: \_\_\_\_\_  
Photos: \_\_\_\_\_  
Other: \_\_\_\_\_  
**220**

## Survey Department Check List (Case Handler)

Reference No.: **CS/CTI/7023361/6vb**  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

### (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

### (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp. Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des. of Damages	✓			

### (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

### (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

### (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: **VERON** **11/12/17**  
 Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17023361/Gvb

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 08-12-2017



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 683G	Veh. Inspected	SFR 6979X
Policy No.	DMPCSN3034521701	Coverage (\$)	0.00
Claim No.	SNM17D06962C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	08/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	05/12/2017	Inspection Date	08/12/2017
Survey held at	NGIAK MOTOR WORKS NO. 10 KAKI BUKIT ROAD 2 FIRST EAST CENTRE #03-36 SINGAPORE 417868		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Dec 2017		08 Dec 2017 14:06 <a href="#">Assign</a>				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
<b>Insured:</b>	CLEMENT TAN KENG MIANG, ID: S7022078D								
<b>Main Claimant:</b>	CHANSUP KOW @ CHAN SIONG KEE, ID: S0342469C								
<b>Vehicle Reg. No.:</b>	SFR6979X	<b>Date of Loss:</b>	05/12/2017 14:00 - :59						
<b>Claim Type:</b>	TP / SNM17D06962C02	<b>Policy/Cover Note No.:</b>	DMPCSN3034521701 (Comprehensive) Coverage: 13/08/2017 - 12/08/2018						
<b>Vehicle Reg. No. (Insured):</b>	SLA683G	<b>Policy No. (Claimant):</b>	GA0096865/1						
		<b>Excess:</b>	S\$0.00						
<b>Repairer:</b>	Ngiak Motor Works (HQ) 6 Ghim Moh Road, #10-194, 270006 Ghim Moh - Tel: 98502253								
<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
<b>Claimant's Insurer:</b>	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/12/2017]								
<b>Adj Asg. Remarks:</b>	1) REQUESTED SURVEYOR: KENNETH 2) PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	2469C

### Vehicle Details

Vehicle No.	SFR6979X
Vehicle to be Exported	No
Intended De-registration Date	11 Dec 2017
Vehicle Make	HYUNDAI
Vehicle Model	GETZ1.65DR A
Primary Colour	Black
Manufacturing Year	2004
Engine No.	G4ED4009176
Chassis No.	KMHBUS1BR5U334443
Maximum Power Output	77.0 kW (103 bhp)
Open Market Value	\$11,050.00
Original Registration Date	02 Feb 2005
First Registration Date	02 Feb 2005
Transfer Count	2
Actual ARF Paid	\$12,155.00

### Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

### Intended COE Rebate Details

COE Expiry Date	31 Dec 2019
COE Category	E - Open Category
COE Period(Years)	5
PQP Paid	\$32,292.00
COE Rebate Amount	\$13,264.00
<b>Total Rebate Amount</b>	<b>\$13,264.00</b>

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Dec 2017

## ► Hyundai Getz Used Vehicle List (11 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
<b>Hyundai Getz 1.4A 5DR (COE till \$21,800 03/2021)</b>		\$6,760 /yr	03-Mar-2006	1,399 cc	138,496 km	William Lee Car Aircon Engineering	<b>Available</b>

Hyundai Getz One Of The Most Affordable Hatchback In The Market. Powered By A 1.4L DOHC Engine Producing A Power Of 93Bhp. Affordable And Easy Maintain.Low Depreciation And Low Monthly. Call Now For V...

Office No. - 63821006

Calvin - 97363232 | Ben - 98274488 | Terence - 94507536 | Keith - 98290368

<b>Hyundai Getz 1.4A 5DR</b>	<b>\$16,800</b>	\$7,560 /yr	11-Aug-2009	1,399 cc	138,400 km	Cycle & Carriage.Fulco Motor Dealer	<b>Available</b>
------------------------------	-----------------	-------------	-------------	----------	------------	-------------------------------------	------------------

1 Owner With Decent Mileage, Most Affordable And Value Hatch You Can Get In The Market. Call Now To View!

Office No. - 67468117

Lionel Chee - 96520717 | Alan Ng - 96710232

<b>Hyundai Getz 1.4A 5DR (OPC)</b>	<b>\$6,888</b>	\$5,570 /yr	15-Jul-2008	1,399 cc	101,000 km	V-Kar Traders Pte Ltd	<b>Available</b>
------------------------------------	----------------	-------------	-------------	----------	------------	-----------------------	------------------

1 Owner. Seldom Used. PARF At 10 Years Is \$3500.

Office No. - 67197301

Rendous - 85223383 | Ray - 96367367 | Ash - 97545294

<b>Hyundai Getz 1.4A 5DR</b>	<b>\$11,800</b>	\$8,620 /yr	27-Nov-2008	1,399 cc	60,120 km		<b>Available</b>
------------------------------	-----------------	-------------	-------------	----------	-----------	--	------------------

Car In Good Condition, Road Tax Just Renewed On 26/10/17, Low Mileage As Previously Is OPC, Just Convert On This Month, Interest Please Call For Test Drive.

Office No. - -

Lynn - 87814811

<b>Hyundai Getz 1.4A 5DR (COE till \$23,000 07/2021)</b>		\$6,430 /yr	10-Jul-2006	1,399 cc	110,000 km		<b>Available</b>
--	--	-------------	-------------	----------	------------	--	------------------

Wear And Tear Done Up (Did Major Servicing, Change Water Pump And Timing Belt, Engine Mounting, Total Flush Of AT Liquid, Etc) And Good To Go For Rest Of COE Lifespan. Low Mileage As Previously Was We...

Office No. - -

Ethan - 98397791

<b>Hyundai Getz 1.4A 5DR (COE till \$24,800 06/2021)</b>		\$6,980 /yr	30-Jun-2006	1,399 cc	90,000 km	Presto Expat Motoring Services Pte Ltd	<b>Available</b>
--	--	-------------	-------------	----------	-----------	--	------------------

The Hyundai Getz, One Of The Most Affordable Hatchback In The Market. Sufficiently Powered By A 1.4L DOHC Engine. Super Reliable, Affordable And Easy Maintenance Ride To Own. This Unit Is Well Maintai...

Office No. - 67327737

Gary - 85117182 | Lionel - 85117181

<b>Hyundai Getz 1.1M 5DR (COE till \$18,800 02/2021)</b>		\$5,940 /yr	09-Feb-2006	1,086 cc	147,000 km		<b>Available</b>
--	--	-------------	-------------	----------	------------	--	------------------

Changed Many Parts When Bought Over From 1st Owner Two Years Ago. Engine Mounting, Alternator, Timing Belt, Stabilizer Links, Water Pump, Rear Shock Absorbers, Fan Belt, Drive Shaft, Thermostat, Spark...

Office No. - -

Mr Neo - 96527812

<b>Hyundai Getz 1.1M 5DR</b>	<b>\$5,800</b>	-	25-Feb-2008	1,086 cc	-	Zenith Motoring	<b>Available</b>
------------------------------	----------------	---	-------------	----------	---	-----------------	------------------

Office No. - 64403350

Daniel - 96922249 | Shawn - 97713161

<b>Hyundai Getz 1.1M 5DR</b>	<b>\$6,500</b>	-	08-Mar-2008	1,086 cc	87,778 km	1 Genesis Pte Ltd	<b>Available</b>
------------------------------	----------------	---	-------------	----------	-----------	-------------------	------------------

Very Well Maintained And Able To Do Uber Grab.

Office No. - -

Nicholas Ng - 88696755 | Justine - 98166222

<b>Hyundai Getz 1.1M 5DR (OPC) (COE till 11/2021)</b>	<b>\$22,000</b>	\$5,550 /yr	28-Nov-2006	1,086 cc	150,000 km		<b>Available</b>
---	-----------------	-------------	-------------	----------	------------	--	------------------

Well Maintained By Garage R, No Repair Needed, Very Smooth Engine, Cool Air-Conditioning System, New Tyres, Accident Free.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/12/2017 13:31
Date Of Accident	05/12/2017 14:40
Exact Location Of Accident	ECP ( AFTER MARINE PARADE ROAD )
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFR6979X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHANSUP KOW @ CHAN SIONG KEE
NRIC No	S0342469C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96654977
Alternative Phone No	OTHERS-96654977

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	GETZ-1.6 5DR (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA0096865/1
Cover Note Number	

### Driver

Name of Driver	CHANSUP KOW @ CHAN SIONG KEE
NRIC No	S0342469C
Date Of Birth	18/11/1937
Occupation	INDOOR
Date Of Driving Pass	15/06/1960
Driving Experience	57 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96654977
Fax Number	
Contact Number	OTHERS-96654977
Email Address	NOEMAIL



Address BLK 5000A MARINE PARADE ROAD # 10-03  
SINGAPORE  
Postcode 449284  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -  
-

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Was any body injured in the Accident? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s)  
soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 3

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACH STATEMENT RECORDED BY JIA MIN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 67415336

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLA683G  
Vehicle Make/Model/Colour  
Details Of Properties  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### Details of Witness

Name  
Phone Number  
Email Address

### Sketch Plan

## REFERENCES

## IMPORTANT NOTICE

© 2004 Blackwell Publishing Ltd, *Journal of Internal Medicine* 255: 103–112

© 2007 The Authors  
Journal compilation © 2007 Blackwell Publishing Ltd

[illegible]

### Sketch Plan #2

### SKETCH PLAN

Vehicle No. \_\_\_\_\_

[illegible]

1000

**Figure 1** *Flowchart of the study*

6-A

### TEST RIDE CIRCUMSTANCES OF THE ACCIDENT

## DECLARATION

1. *Staphylococcus aureus* (10<sup>8</sup> CFU/ml) was inoculated into 100 ml of sterile distilled water. The suspension was stirred for 1 h at 37°C and then centrifuged at 1000g for 5 min. The supernatant was removed and the pellet was resuspended in 100 ml of sterile distilled water. This process was repeated three times. The final suspension was adjusted to a concentration of 10<sup>8</sup> CFU/ml.

$\frac{1}{2} \left( \frac{1}{2} + \frac{1}{2} \right) = \frac{1}{2}$

[illegible]

*Journal of Management Education* 30(6)

[illegible]

• • •

1. *Staphylococcus aureus* 2. *Staphylococcus epidermidis*

1. *Phragmites australis* (Cav.) Trin. ex Steud.

6/1/17  
139/104

# NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 6th Dec 2017

Quotation: SFR 6979 X Hyundai Getz

	\$\$\$
1 Pc. Rear lid / BT	856.10 /
1 Pc. Rear lid lock X	110.70 X
1 Pc. Rear lid 'HYUNDAI' logo X	38.40 X
1 Pc. Rear lid 'HYUNDAI' plate /	30.60 /
1 Pc. Rear lid 'Getz' plate /	28.30 /
1 Pc. Rear lid 'GLS' plate /	25.10 /
1 Pc. Rear lid rubber / TN	138.80 /
1 Pc. Rear bumper / Re	478.30 330.9
1 Pc. Rear bumper reinforcement ? / CRA	386.10 155.2
1 Pc. Rear bumper centre protector / GR	239.50 132
1 Set Rear bumper clips & rivets /	50.00 /
2 Pcs Rear bumper side retainer /	66.00 /
2 Pcs Rear lamp assy. / CRA @ \$269.20	538.40 /
2 Pcs Rear lamp inner seal @ \$23.50 X NN	47.00 X
2 Pcs Rear lamp lower panel @ \$95.00 / Re	190.00 /
1 Pc. Rear end panel ? / BUL	485.90 341.3
1 Pc. Spare tyre compartment X Repair.	678.50 X
1 Pc. Rear end panel inner trim / Re	124.30 67.3
2 Pcs Rear fender inner plastic cover @ \$257.60	515.20 257.6
1 Set Plastic cover clips / MC	38.00 /
1 Pc. Rear exhaust silencer box X Repair.	421.90 X
1 Pc. Tool Tray / Re	114.80 /
1 Pc. Spare tyre top cover / TN	226.00 /
	C / fd 5,834.50
2 Pcs Rear lid side catch / CRA	68.00 /

# NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

3659

20%: 2927.2

S\$

b/fd

5,834.50

Less 20%

1,166.90

4,667.60

## Netts Items

1 Pc. Rear lid windscreen sealant / MLC	150.00	50
1 Pc. Spare tyre compartment sealant X NN	100.00	X
1 Pc. Rear end panel sealant / MLC	100.00	40
1 Set Reverse sensor X NN	250.00	X
		90.

## Labour charges:-

① To check wiring	30	50.00
② To do computerised wheel alignment	X	120.00 NN
③ To remove & transfer rear lid windscreen	100	200.00
④ To remove & transfer rear lid inner items	60	100.00
⑤ To renew rear exhaust silencer box	60	80.00
⑥ To install reverse sensor	40	90.00
⑦ Rustproofing	60	200.00
⑧ To remove & refix cushion, side cover, mats & upholstery.	60	280.00
⑨ To remove & refix fuel tank	X	200.00
⑩ To remove & refix rear suspension	X	250.00
⑪ Panel beating	800	1,600.00
⑫ Spray painting	900	1,600.00

Total

10,037.60 2/10

Ans Qiang - 82880282

Unpsum repair.

After repair.

08/12/17 5:30pm

7Days.

5127.2

10092.72

20%: 2800

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Dec 2017		08 Dec 2017 14:06 <a href="#">Edit Adj Rpt</a>	<b>S\$2,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]	
Insured:	CLEMENT TAN KENG MIANG, ID: S7022078D		
Main Claimant:	CHANSUP KOW @ CHAN SIONG KEE, ID: S0342469C		
Vehicle Reg. No.:	SFR6979X	Date of Loss:	05/12/2017 14:00 - :59
Claim Type:	TP / SNM17D06962C02	Policy/Cover Note No.:	DMPCSN3034521701 (Comprehensive) Coverage: 13/08/2017 - 12/08/2018
Vehicle Reg. No. (Insured):	SLA683G	Policy No. (Claimant):	GA0096865/1
		Excess:	S\$0.00
Repairer:	Ngiak Motor Works (HQ) 6 Ghim Moh Road, #10-194, 270006 Ghim Moh - Tel: 98502253		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/12/2017]		
Adj Asg. Remarks:	1) REQUESTED SURVEYOR: KENNETH 2) PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS.		




































ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

**\*SFR6979X (SNM17D06962C02)**  
**[SLA683G]**  
**TP**  
**CHANSUP KOW @ CHAN SIONG KEE**  
**Dec 5 2017 2:00PM**  
**[CLEMENT TAN KENG MIANG]**  
**Ngiak Motor Works**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View In Browser</a>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
2	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
20	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
21	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
22	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
23	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
24	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
25	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
26	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
27	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
28	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
29	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
30	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
31	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
33	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/12/17 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>

36	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
54	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
55	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
56	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
57	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
58	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
59	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
60	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
61	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
62	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
63	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
64	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
65	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
66	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
67	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
68	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
69	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
70	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
71	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
72	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
73	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
74	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
75	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
76	11/12/17 10:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
77	11/12/17 12:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
78	11/12/17 12:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
79	11/12/17 12:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
80	11/12/17 12:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
81	15/12/17 09:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
82	15/12/17 09:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
83	15/12/17 09:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>



No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	08/12/17 14:07	E-filed GIA report	1	Load PDF	

## Linked Accident Report Documents

				<b>View</b>	<b>View In Browser</b> ▼
<b>Assessment Reports</b>				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	06/12/17 13:44	Accident Statement	1	Load HTM	
<b>Photos/ Images</b>				3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	06/12/17 13:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	06/12/17 13:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	06/12/17 13:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	06/12/17 13:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	06/12/17 13:42	Sketch Plan	1	Load JPG	<input checked="" type="checkbox"/>
2	06/12/17 13:42	Sketch Plan #2	1	Load JPG	<input checked="" type="checkbox"/>
3	06/12/17 13:43	DRIVER NRIC	1	Load TIF	
4	06/12/17 13:43	CI	1	Load TIF	
5	06/12/17 13:43	DRIVING LICENCE ( PROOF BY TRAFFIC POLICE )	1	Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT17023361/GVBE2

Date: 15/01/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3034521701

Claimant Vehicle  
No : SFR6979XInsured Vehicle  
No : SLA683G

Date of Loss: 05/12/2017

Nature of Claim: TP

Claim  
No: SNM17D06962C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFR6979X

Make &amp; Model: HYUNDAI GETZ, 1.6 5DR (A)

Engine No: G4ED4009176

Reg. Date: 02/02/2005 (Man. Year: 2004)

Chassis No: KMHBU51BR5U334443

Colour: Black

Odometer: 175916 km

Engine Capacity: 1599 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/50 R15

Rear Tyre Size: 195/50 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,322.72	3,017.52	2,305.20	43.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,770.00	2,110.00	2,660.00	55.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,092.72</b>	<b>5,127.52</b>	<b>4,965.20</b>	<b>49.20</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,800.00</b>		
<b>Nett Amount (\$\$)</b>	<b>10,092.72</b>	<b>2,800.00</b>	<b>7,292.72</b>	<b>72.26</b>

## INSPECTION

Date of Assignment: 08/12/2017

Date Inspected: 08/12/2017 Inspected At:

Ngiak Motor Works (HQ)  
NO. 10 KAKI BUKIT ROAD 2  
FIRST EAST CENTRE #03-36  
SINGAPORE 417868

Estimated Period of Repair: 7.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2018)
<b>Parts:</b> 144	HYUNDAI GETZ 1.6 5DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SFR6979X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR LID	Bent	856.10 FL	*856.10 FL
2	1	*REAR LID LOCK	Not Necessary	110.70 FL	*- FL
3	1	*REAR LID HYUNDAI LOGO	Not Necessary	38.90 FL	*- FL
4	1	*REAR LID HYUNDAI PLATE	Necessary	30.60 FL	*30.60 FL
5	1	*REAR LID GETZ PLATE	Necessary	28.30 FL	*28.30 FL
6	1	*REAR LID GLS PLATE	Necessary	25.10 FL	*25.10 FL
7	1	*REAR LID RUBBER	Torn	138.80 FL	*138.80 FL
8	1	*REAR BUMPER	Deformed	475.30 FL	*330.90 FL
9	1	*REAR BUMPER REINFORCEMENT	Cracked	386.10 FL	*155.20 FL
10	1	*REAR BUMPER CENTRE PROTECTOR	Scratched	239.50 FL	*132.00 FL
11	1	*SET REAR BUMPER CLIPS & RIVETS	Necessary	50.00 FL	*50.00 FL
12	2	*REAR BUMPER SIDE RETAINER	Necessary	66.00 FL	*66.00 FL
13	2	*REAR LAMP ASSY	Cracked	538.40 FL	*538.40 FL
14	2	*REAR LAMP INNER SEAL	Not Necessary	47.00 FL	*- FL
15	2	*REAR LAMP LOWER PANEL	Deformed	190.00 FL	*190.00 FL
16	1	*REAR END PANEL	Buckled	485.90 FL	*341.30 FL
17	1	*SPARE TYRE COMPARTMENT	Repair	678.50 FL	*- FL
18	1	*REAR END PANEL INNER TRIM	Deformed	129.30 FL	*67.30 FL
19	1	*REAR FENDER INNER PLASTIC COVER	N/S Not Necessary/O/S Cracked	515.20 FL	*257.60 FL
20	1	*SET PLASTIC COVER CLIPS	Necessary	38.00 FL	*38.00 FL
21	1	*REAR EXHAUST SILENCER BOX	Repair	421.90 FL	*- FL
22	1	*TOOL TRAY	Deformed	119.80 FL	*119.80 FL
23	1	*SPARE TYRE TOP COVER	Torn	226.00 FL	*226.00 FL
24	2	*REAR LID SIDE CATCH	Cracked	68.00 FL	*68.00 FL
25	1	*REAR LID WINDSCREEN SEALANT	Necessary	150.00 FS	*50.00 FS
26	1	*SPARE TYRE COMPARTMENT SEALANT	Not Necessary	100.00 FS	*- FS
27	1	*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
28	1	*SET REVERSE SENSOR	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,503.40</b>	<b>3,749.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,180.68</b>	<b>731.88</b>
<b>Total Parts (\$\$)</b>	<b>5,322.72</b>	<b>3,017.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DO COMPUTERISED WHEEL ALIGNMENT	New	120.00	0.00
3	TO REMOVE & TRANSFER REAR LID WINDSCREEN	New	200.00	100.00
4	TO REMOVE & TRANSFER REAR LID INNER ITEMS	New	100.00	60.00
5	TO RENEW REAR EXHAUST SILENCER BOX	New	80.00	60.00
6	TO INSTALL REVERSE SENSOR	New	90.00	40.00
7	RUSTPROOFING	New	200.00	60.00
8	TO REMOVE & REFIT CUSHION, SIDE COVER, MATS & UPHOLSTERY	New	280.00	60.00
9	TO REMOVE & REFIT FUEL TANK	New	200.00	0.00
10	TO REMOVE & REFIX REAR SUSPENSION	New	250.00	0.00
11	PANEL BEATING	New	1,600.00	800.00
12	SPRAY PAINTING	New	1,600.00	900.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,770.00</b>	<b>2,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >