

|                                                                        |                                                                                                                                        |                 |                    |                                                                                     |
|------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-----------------|--------------------|-------------------------------------------------------------------------------------|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023384/K1qbn2      |                                                                                                                                        |                 |                    |                                                                                     |
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556 |                                                                                                                                        |                 | Date: 28-12-2017   |  |
|                                                                        |                                                                                                                                        |                 | Code: INC4         |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                      |                                                                                                                                        |                 |                    |                                                                                     |
| Insured Veh.                                                           | SLJ 9582H                                                                                                                              | Veh. Inspected  | SHC 7093A          |                                                                                     |
| Policy No.                                                             | 5090674093                                                                                                                             | Coverage (\$)   | 0.00               |                                                                                     |
| Claim No.                                                              | MT/0972761-002                                                                                                                         | Excess (\$)     | 0.00               |                                                                                     |
| Assign From                                                            |                                                                                                                                        | Assign Date     | 08/12/2017         |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                          |                                                                                                                                        |                 |                    |                                                                                     |
| Make & Model                                                           | HYUNDAI I40                                                                                                                            | c.c             | 1685               |                                                                                     |
| Engine No.                                                             | HIDDEN                                                                                                                                 | Year of Reg.    | 2016               |                                                                                     |
| Chassis No.                                                            | KMHLB41UMGU088857                                                                                                                      | Colour          | YELLOW             |                                                                                     |
| Odometer                                                               | 241252                                                                                                                                 | Steering        | IN ORDER           |                                                                                     |
| Brakes                                                                 | IN ORDER                                                                                                                               | Modification    | STANDARD ALLOY RIM |                                                                                     |
| General                                                                | FAIR                                                                                                                                   |                 |                    |                                                                                     |
| <b>3. Conditions of Tyres</b>                                          |                                                                                                                                        |                 |                    |                                                                                     |
|                                                                        | Size                                                                                                                                   | Make            | Balance            |                                                                                     |
| R/H Front Tyre                                                         | 205/60 R16                                                                                                                             | TRIANGLE        | 7 mm               |                                                                                     |
| L/H Front Tyre                                                         | 205/60 R16                                                                                                                             | TRIANGLE        | 7 mm               |                                                                                     |
| R/H Rear Tyre                                                          | 205/60 R16                                                                                                                             | TRIANGLE        | 7 mm               |                                                                                     |
| L/H Rear Tyre                                                          | 205/60 R16                                                                                                                             | TRIANGLE        | 7 mm               |                                                                                     |
| <b>4. Description of Damages</b>                                       |                                                                                                                                        |                 |                    |                                                                                     |
|                                                                        | THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                        |                 |                    |                                                                                     |
| <b>5. General Information</b>                                          |                                                                                                                                        |                 |                    |                                                                                     |
| Accident Date                                                          | 06/12/2017                                                                                                                             | Inspection Date | 08/12/2017         |                                                                                     |
| Survey held at                                                         | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969                                                               |                 |                    |                                                                                     |
| <b>5a. Remarks</b>                                                     |                                                                                                                                        |                 |                    |                                                                                     |
|                                                                        | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                 |                    |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                     |                                                                                                                                        |                 |                    |                                                                                     |
|                                                                        | ESTIMATED NORMAL PERIOD FOR REPAIR: <b>3 Working Days</b>                                                                              |                 |                    |                                                                                     |