

INASS

INS. CASE OWNER:

Prig

CC 3/1117023411 1 R1 eaz

LKK:

IDAC

Surveyor:

Rahul

DOI:

ASSIGNMENT

9/1/18

Date / Time:

11/12/17

Registered in Merimen:

11/12/17

Pre-assign / CCU / FTE



Insured Vehicle No. : SHA 53856

Name of Insured : CTPL

Insured Tel No. : HP:

Excess Sec II : SS D.O.A. : 08/12/17

Is driver the owner? (YES ☒ NO ☐ Nature of Accident :

If NO, Driver Name / Age : HO WENG HONG

Driver Tel No. : (VA ☒ YES / NO ☐

Claim No. : M217120351

Policy No. : MLOM0015

Make / Model : HYUNDAI SONATA - 2.0 (A)

Place of Accident : KEPPEL ROAD X CANTONMENT LINK

OI GIA REPORT ☒ YES / NO ☐ ; TP GIA REPORT ☒ YES / NO ☐

Insured Liability : % Final ? Yes / No

SJN 6005E

INSRS:  
WSP: Performance (Alkandak)  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/Time		STAGE	DATE / PIC
	SJN 6005E - NSA/MCG/190/15030/Y D.O.A. 01/07/15	Non-Reporting ltr (1st)	
	SHA 53856 - CCA/1117023411/11/12/17 D.O.A. 25/11/17	Non-Reporting ltr (2nd)	
12/12/17 (Ashe)		Non-Reporting ltr (Final)	
		Notification ltr (if non-pickup)	
13/12/17	SEEK MANDATE FOR LIABILITY.	Call OI:	
		After call ltr to OI:	
14/12/17	MANDATE APPROVE LIABILITY.	Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	<input type="checkbox"/>
14/12/17	EMAIL WSP LIABILITY CASE.	After call ltr to OI:	<input type="checkbox"/>
		Authorization To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice	<input type="checkbox"/>
		LTA / GIA :	<input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

<b>PRELIMINARY ADVICE</b> Date/Time: - Sent By: -		Confirm by: VBS	
<b>FINALIZATION</b> Date/Time: 9/3/18 Confirm with: CAROLINE		Confirm by: VBS	
Repair Cost: PP \$53,062.40	( 3 days) Reduction: 54 %	Email <input checked="" type="checkbox"/>	Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b> Date/Time: 23/4/18 Confirm with: CAROLINE		Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Final Liability: % 100	(Agreed / Assessed) BOLA S/N No.: 27	If NO or B 28, Ass. Lia:	
Repair Cost: 4/15 \$53,716.77	DID REPE ENORD TP		
Loss of Rental (LOR): 4/15 \$5 274.10	( 3 days) x 970		
Loss of Use (LOU): \$5 -	(5 x days)		
Loss of Income (LOI): \$5 -	(5 x days)		
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search: \$5 -			
Medical: \$5 -			
Disbursement: \$5 -	(e.g. Tow/ Independent)	1) Claim status: <input checked="" type="checkbox"/> Normal/Reject/Private Settle	
Legal Cost: \$5 -		2) Report Format: TP	
Total: \$53,501.47	Global Sum \$5:	3) Survey fee: \$320 + H20	
<b>FINAL PAYMENT</b> Date/Time: 23/4/18 Confirm with: CAROLINE		Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Payee 1: \$53,501.47	Name 1: PERFORMANCE MOTORS LIMITED		
Payee 2: (Strike if N.A.) \$5	Name 2:		
Payee 3: (Strike if N.A.) \$5	Name 3:		

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: **3JN 6005E**  
 at Workshop m/s: **PERFORMANCE**  
 of: \_\_\_\_\_  
 Insured: **III / TP**  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition) **ctm**  
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **3** days Res: Yes or No  
 Lump Sum: **-** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **3JN 6005E** Yr Regn: **2016 NOV**  
 Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: **P.M.W 2160 GRM TOURER cc K496**  
 Colour: **WHITE** A/O: Insured / Std / NI / NA  
 Sp.Reading: **27493** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **WBA 2E 320705B45516**  
 Gen. Cond: Good / **Fair** / Poor / Burnt  
 Steering: **Worder** / Jammed / Leaked / Burnt or  
 Brake: **Worder** / Jammed / Leaked / Burnt or  
 Mod: **Nil** / SRim / STD A/Rim or  
 Tyre Size: F: **205/55R17**  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: **6** mm R/Bal: **6** mm  
 L/Bal: **6** mm L/Bal: **6** mm  
 D.O.A: **08/12/17** D.O.I: **09/01/18**  
 Survey held at: **PERFORMANCE**  
 Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	P/P: 3,062.40 (RCD: 3,588.05 54%)

Date/Time: File Pass to? ☐ : Prel. Report

Date/Time: File Return to? ☐ : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transaction: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Insp (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Photo: \_\_\_\_\_

Other: \_\_\_\_\_

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III17023411/R1ea3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 11-12-2017		
		Code : III2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 5385G	Veh. Inspected	SJN 6005E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	08/12/2017	Inspection Date	09/01/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401339W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 43190100 (Sales & Admin)  
43190111 (AfterSales)  
Fax. 44747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438188  
Tel. 43190888 (AfterSales)  
Fax. 43449773

311, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 43190528 (AfterSales)  
43190533/330 (Motorrad)  
Fax. 44796601 (AfterSales)  
44796624 (Motorrad)



9/1/2017  
Sunny & repair

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

09 DEC 2017

Estimate No. : b1 45108  
Date Estimated : 09/12/2017  
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -  
Chua Kai Meng (Cai Kaiming)  
8 Bedok Reservoir View  
#11-20

Singapore 479235

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN6005E	5B45516	30/11/2016	216d G TOURER	0

### DESCRIPTION

Replace rear bumper and remove attachment etc include knock on accident dent

850 1,700.00

Spray painting rear bumper

934 1,038.00

To replace rear PDC sensor wire harness including reset and checks for proper function.

X 266.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

40 150.00

Total Labour 1: 3,331.00

### DESCRIPTION

RR BUMPER LH SIDE GUIDE  
RR BUMPER RH SIDE GUIDE  
REAR BUMPER CARRIER  
RR BUMPER LH INNER SIDE GUIDE  
RR BUMPER RH INNER SIDE GUIDE  
REAR BUMPER TRIM STRIP (CHROM)  
LEFT PROTECT  
RIGHT PROTEC  
REAR BUMPER PANEL PRIMED (LINES PDC  
SET MOUNTS PDC SENSOR REAR  
REAR BUMPER TOWING FLAP EYE PRIMED  
DECOUPING RING PDC TORQUE CONVERTER  
ULTRASONIC SENSOR ALPINWEISS (U300)

QTY	PRIC
1	58.55
1	58.55
1	413.45
1	64.30
1	64.30
1	105.65
1	2.05
1	2.05
1	942.75
1	62.50
1	27.10
4	4.95
4	374.60

VALUE
58.55
58.55
413.45
64.30
64.30
105.65
2.05
2.05
942.75
62.50
27.10
19.80
1,498.40

Total Parts : 3,319.45

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel: 63190888 (AfterSales)  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 45108  
Date Estimated : 09/12/2017  
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN6005E	5B45516	30/11/2016	216d G TOURER	0

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer: Third Party / Uninsured Insurance Settlement

Regn No:                                          

Date/Time: 09/01/18 09:10                     

Surveyor: Rafael                     

Survey No: 90010068                                                               

Authorised Date:                      Time:                     

RESURVEY PARTS PHOTO BY SURVEYOR: Yes / No                      PM: Yes / No                     

Surveyor's E-mail:                     

No. of Working Days Recommend 3 days

Resurvey by paint

Labour 1	:	3,331.00
Parts	:	3,319.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	465.53
Grand Total	:	7,115.98

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



## FINAL REPORT

Estimate No. : b1 45108  
Date Estimated : 09/12/2017  
Prepared By : Chua Kee Sin

Page No. :

**REPAIR FOR -**  
Chua Kai Meng (Cai Kaiming)  
8 Bedok Reservoir View  
#11-20

**- ACCOUNT - 219**  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

Singapore 479235

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJN6005E	5B45516	30/11/2016	216d G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM STRIP (CHROM)	105.65	1.00		105.65
REAR BUMPER PANEL PRIMED (LINES PDC)	942.75	1.00		942.75

### # SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,048.40
Total Labour & Parts :	3,062.40
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,062.40
GST @7%:	214.37
Grand Total :	3,276.77

## Asher Sng (LKKAUTO)

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Thursday, 14 December, 2017 8:55 AM  
**To:** PBSP  
**Cc:** Vic (LKKAUTO); Admin A; assignments  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT - SJN6005E & SHA5385G (III) ON 08.12.2017 \*\*\*  
LKK REF - CC3/III17023411/ea3

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Monday, 11 December, 2017 9:15 AM  
**To:** PBSP <pml-pbsp@simedarby.com.sg>  
**Cc:** Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT - SJN6005E & SHA5385G (III) ON 08.12.2017 \*\*\* LKK REF - CC3/III17023411/ea3

Dear Caroline,

We refer to the above matter.

Please be informed that we are currently **pending for our insured's GIA report**.

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

***Meanwhile, please arrange appointment for survey.***

***To check availability of the case handler, you may contact the undersigned.***

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP [<mailto:pml-pbsp@sime-darby.com.sg>]

**Sent:** Saturday, 9 December, 2017 11:43 AM

**To:** CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** REQ FOR DIRECT SETTLEMENT - SJN6005E & SHA5385G (III) ON 08.12.2017

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

“This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”



## Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	11 Dec 2017 09:13	Clim Veh Model Changed	(204327) BMW 216D 1.5 D Gran Tourer (F46) (A).		[A] Hiew May Fung
2	11 Dec 2017 09:13	Clim Created	Reg No: SJN6005E, Acct Date: 2017/12/08. Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: AXA Insurance Pte Ltd (HQ), Workshop: Performance Motors Limited (Alexandra)		[A] Hiew May Fung
3	11 Dec 2017 09:13	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] Hiew May Fung
4	11 Dec 2017 09:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/20		[A] Hiew May Fung
5	11 Dec 2017 09:13	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[A] Hiew May Fung
6	11 Dec 2017 09:14	Label Added	(30653):Direct Settlement.		[A] Hiew May Fung
7	11 Dec 2017 09:14	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH		[A] Hiew May Fung
8	12 Dec 2017 11:40	Clim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD. Claimant's ID: -> 19930382 1R.		[A] Hiew May Fung
9	13 Dec 2017 10:22	Adj Mandate Request	Cur.Req:0.00:PODS: LIABILITY: 100% REMARK: B:27 OID REAR ENDED TP		[A] Asher Sng Rong Yi
10	13 Dec 2017 10:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/20		[I] Priya
11	13 Dec 2017 10:52	Adj Mandate Set	Approved:0.00.		[I] Priya
12	11 Jan 2018 11:51	Adj Adjuster Assigned	MOHD TAUFIKH BIN HAMID -> MOHD RASUL		[A] Hiew May Fung
13	11 Jan 2018 11:55	Adj Rpt Initiated			[A] Hiew May Fung
14	11 Jan 2018 11:55	Clim Details Notified			[A] Hiew May Fung
15	19 Apr 2018 14:22	Adj Mandate Request	Cur.Req:3501.47:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST : \$3,276.77 + (b) LOR w/GST : \$224.70 (3days x \$70) Total: a+b = \$3,501.47 VEH MODEL: BMW 216D 14 96cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.		[A] Asher Sng Rong Yi

Date From Date To Audit Type None Go

### ACTIVITY

[22/01/2018 09:53] HOW MEI KWAN:  
PENDING FINALIZE

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1692000	11/01/2018	Motor	LKK Auto	LKK Auto	SJN6005E		10.70

**AXA INSURANCE PTE LTD**

8 Shenton Way, #24-01  
 AXA Tower, Singapore 068811  
 Customer Service Centre #B1-01  
 Tel: 6338 7288 Fax: 6338 2522  
 Website: www.axa.com.sg  
 GST Registration Number: 199903512M

**Original**Agent Code: **13854**

Policy No. (if any):

**New Business**

SmartDrive Quote Ref:

**MOTOR COVER NOTE**No. **CN817210**

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) - Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby **HELD COVERED** under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

**SCHEDULE**

THE COMPANY	AXA INSURANCE PTE LTD
INSURED	CHUA KAI MENG (CAI KAIMING)
MAKE AND DESCRIPTION OF VEHICLE	BMW 216D GRAN TOURER LED NAV 7 SEATER
VEHICLE REGISTRATION NO.	SJN6005E
YEAR OF MANUFACTURE	2016
ENGINE NO.	30459707B37C15A
CHASSIS NO.	WBA2E320705B45516
ENGINE CAPACITY/TONNAGE	1496
COVER TYPE	COMPREHENSIVE
HIRE PURCHASE	MAYBANK
VALUE (S\$)	AS PER MARKET VALUE
PERIOD OF INSURANCE	FROM: <b>16/03/2017</b> TO: <b>29/05/2018</b>
EXCESS (S\$)	300
AXA PREMIUM WORKSHOP?	NO



I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).

**AXA INSURANCE PTE LTD**

Issued by

SIME DARBY  
SINGAPORE LIMITED

on

15/03/2017 5:37pm

Authorised Signature

**Note :** This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.

• Premium for time on risk will be charged subject to minimum of S\$53.50 (inclusive of GST), if the policy is cancelled after the inception date.

• An administrative fee of S\$26.75 (inclusive of GST) will be charged;

• Cover note issued and cancelled before inception.

• Retaining the old registration number for a new vehicle insuring with AXA.

**PREMIUM WARRANTY**For Individual Customers:

Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.

For Non-Individual Customers:

Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days on inception / renewal / endorsement. For all other cases, the premium in full should be paid before inception.

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7902907F



CHUA KAI MENG  
(CAI KAIMING)

蔡开明

CHINESE

Date of Birth

30-01-1979

Sex

M

Country of Birth

SINGAPORE

S7902907F

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S7902907F

Name

CHUA KAI MENG  
(CAI KAIMING)

Birth Date 30 Jan 1979

Issue Date 01 Sep 2003



LICENCE No. S7902907F



Date of Birth

18-02-2009

BLK 6 BEDOK RESERVOIR VIEW #11-20  
SINGAPORE 479235

NRIC No. S7902907F

Date: 21/04/2013

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of  
which unladen does not exceed 3500 kilograms

28 Oct 1999

NP 426A



## Print Received Message

This mail is associated with :

**\*SJN6005E (MCT17120351)**

**[SHA5385G]**

TP

CHUA KAI MENG

Dec 8 2017 5:00PM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 20/04/2018 10:49 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$3501.47) - SJN6005E - Claim Handler: Priya

Approved:3501.47.



(A)

India Int'l Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711  
Attention: Motor Claims

**"Without Prejudice"**

Your Ref:  
Our Ref:  
Date:  
Subject:

23 March 2018

**ACCIDENT INVOLVING VEHICLES SJN6005E & SHA5385G ON 08.12.2017**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	3276.77
Car rental	:	S\$	224.70
Total	:	S\$	3501.47

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill
3. Copy of Certificate of Insurance & Rental Invoice & Rental Agreement
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation

Performance Motors  
Limited  
1900-Call-BMW  
(1800-2255-268)

www.pml.com.sg

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel AfterSales:  
6319 0111  
Fax 6474 7770

215 Alexandra Road  
#01-01  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel AfterSales:  
6319 0527  
Fax 6479 6824

380  
Kemping Arang Rd  
East Coast Centre  
Singapore 439180  
Tel AfterSales:  
6319 0888  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No:  
197401558W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

  
Teng Wai Khan  
Customer Service Manager, Body & Paint

LETTER OF AUTHORISATION

ACCIDENT INVOLVING SJN 6005E & SHA 53856 ON 8/12/2017

I, Chua Kai Meng owner of Vehicle Registration No. SJN 6005E  
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and  
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all  
documents whatsoever in relation to this matter and to accept and receive any payment due  
to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation  
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if  
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement  
amount in respect of such claim shall constitute the full discharge of my claim in respect of  
such loss and damage.

Signed by:



Name: Chua Kai Meng  
NRIC No.: S7902917

(Date) 9/12/17

In the presence of:



Name:

(Date)

NRIC No.:

  
09/12/2017  
@ 1054hs



INDIA  
INTERNATIONAL  
INSURANCE  
PTE LTD  
Serving the English-Speaking World

INDIA INTERNATIONAL INSURANCE PTE LTD

Reg. No. 19074772E (and Reg. No. M2-047488-01)  
411 Cecil Street, #03-005 (above 2) The Arcade, Singapore 069711  
Tel: +65 (0) 63475100 Fax: +65 (0) 63475102  
E-mail: info@iia.com.sg Website: www.iia.com.sg

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MC17120351  
Claimant Ref: SM 605E

We/I, PERFORMANCE MOTORS LIMITED ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 3,276.77 (repair cost), S\$ 334.70 (loss of rental), S\$ - (search fee), vehicle no. SM 605E that was damaged pursuant to the accident which occurred on 08.12.17 (date) at KEPPEL ROAD (DIPLORE CANTONMENT JMT) (location) involving vehicle no. SM 505G (insured vehicle). This is pursuant to the inspection conducted on 09.01.18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Chua Kai Meng ("the third party claimant") of vehicle no. SM 505G to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SM 605E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 3,501.47 to PERFORMANCE MOTORS LIMITED

Dated this 25 day of 4 20 18

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Wong Yit Loong  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Signed by the workshop (with chop)

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



MKB

Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-05 SINGAPORE 408933

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796634 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : <b>B1 1235421</b>	Page No. : <b>1 of 2</b>
Date IN : <b>09/01/2018</b>	Invoice Number : <b>1942886 / WSB</b>
Cust. Svc. Advisor: <b>Chua Kee Sin</b>	Invoice Date : <b>12/03/2018</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

### - CUSTOMER INFORMATION -

Mr Chua Kai Meng (Cai Kaiming)  
8 Bedok Reservoir View  
#11-20

Singapore 479235

### - INVOICE TO - 219

India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO. <b>SJN6005E</b>	CHASSIS NO. <b>5B45516</b>	REGN. DATE <b>30/11/2016</b>	MODEL <b>216D G TOURER</b>	MILEAGE <b>27493</b>
------------------------------	-------------------------------	---------------------------------	-------------------------------	-------------------------

### ----- LABOUR 1 -----

To replace rear bumper and trim strip including to remove and install body parts in order to carry out painting job.	850.00
To respray rear bumper.	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR, DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 8.12.2017. 3RD PARTY CAR : SHA5385G.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO CONSULTANTS PTE LTD ON 9.1.2018 AT 10.10 AM.	
AUTHORISED REPAIR BY MS ASHER SNG FROM LKK ON 14.12.2017 VIA E-MAIL.	
PROPOSE CAR RENTAL = \$224.70. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00

Total Labour 1: **2,014.00**

### ----- PARTS -----

	Qty	Retail Price	NETT
REAR BUMPER PANEL PRIMED (LINES PDC	1	942.75	942.75
REAR BUMPER TRIM STRIP (CHROM)	1	105.65	105.65
Total Parts :			<b>1,048.40</b>



H Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

289, Kampong Arang Road  
East Coast Centre  
Singapore 438189  
Tel. 63190888 (AfterSales)  
Fax. 63448773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190822 (AfterSales)  
63190531/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1235421	Page No. : 2 of 2
Date IN : 09/01/2018	Invoice Number : 1942886 / WSB
Cust. Svc. Advisor: Chua Kee Sin	Invoice Date : 12/03/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Labour Charges : 1,934.00	Total Labour & Parts Charges : S\$ 3,062.40
Parts Charges : 1,048.40	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 80.00	Invoice Total Amount Exclude GST : S\$ 3,062.40
	GST @ 7% : S\$ 214.37
	Invoice Total Amount Include GST : S\$ 3,276.77
Computer generated invoice. No signature is required.	
Amount Payable Include GST : S\$ 3,276.77	

All amounts are in Singapore Dollars.  
Work was carried out subject to the Company's Terms and Conditions of Service.  
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.  
For credit purchases, interest @1% per month will be debited on overdue amounts.





## TAX INVOICE

Invoice No. 55 - 510464  
Page 1 of 1

MR CHUA KAI MENG

BLK 8 BEDOK RESERVOIR VIEW #11-20  
479235 SINGAPORE

SIME DARBY SERVICES PTE LTD

Thrifty International Licensee

305 Alexandra Road, #03-01

Vantage Automotive Centre, Singapore 159942

p (65) 6447 3388 f (65) 6345 7247

Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

INVOICE DATE : 11-JAN 2018

R.A. No. 55004451 / Muhammad Lukman bin Mohamed Sidek

TITLE	: MR	KILOMETER OUT/IN	: 798 / 995
AUTHORIZED DRIVER	: CHUA KAI MENG	KILOMETER DRIVEN	: 197
NRIC/PASSPORT NO.	: S7902907F	PETROL LEVEL OUT/IN	: FULL / FULL
MAKE & MODEL	: FORD FOCUS 4DR TITANIUM 1.0	DATE & TIME OUT	: 09-JAN 2018 10:15
CAR REGISTRATION NO.	: SLV15038 / UNIT #: 0003078	DATE & TIME IN	: 11-JAN 2018 17:20
CAR GROUP GIVEN	: G	CHECK IN LOCATION	: SHORT TERM-HQ (SIN55)-THRIFTY
CAR GROUP CHARGED	: F	NO. OF DAY(S) CHARGED	: 2 DAY(S) 8 HOUR(S)

DESCRIPTION	UNIT PRICE (SGD)	UNIT	AMOUNT BEFORE GST (SGD)	GST @ 7%	AMOUNT (SGD)
-------------	------------------	------	-------------------------	----------	--------------

## INSURANCE CLAIMS RATES 2017

3 DAY(S) @ \$70.00 / DAY

210.00

14.70

224.70

## SUB-TOTAL

210.00

14.70

224.70

REMARKS: BMW OWNER: SJN6005E  
PML CSA: CHUA (CLAIMS)

TOTAL (SGD) :

210.00

14.70

224.70

\* ITEMS NOT SUBJECT TO GST

MC XXXXXXXXXXXXX6464

-224.70

BALANCE DUE

0.00

## NOTE:

I / WE HEREBY AGREE TO THE TERMS AND CONDITIONS AND BE HELD LIABLE FOR ALL AMOUNT DUE UNDER THIS AGREEMENT; ALL TRAFFIC FINES INCLUDING ADMIN FEES INCURRED DURING PERIOD OF HIRE; ANY COSTS INCURRED BY SIME DARBY SERVICES PTE LTD FOR MY FAILURE TO REPORT ANY ACCIDENT WITHIN 24 HOURS. FINAL CHARGES IS SUBJECT TO FULL INSPECTION OF THE VEHICLE BY A COMPANY REPRESENTATIVE.

HIRER'S AND/OR ADDITIONAL DRIVER'S SIGNATURE

Printed on 11-Jan-2018

17:21

Entered by Muhammad Lukman bin Mohamed

**SIME DARBY SERVICES PTE LTD**

Thrifty International Licensee

305 Alexandra Road, #03-01

Vantage Automotive Centre, Singapore 159942

p (65) 6447.3388 f (65) 6345.7247

Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

**TO BE PAID BY**

PAYMENT : MC - XXXXXXXXXXXXXXX6464

**HIRER'S DETAILS**

TITLE : MR  
 NAME : CHUA KAI MENG  
 ADDRESS : BLK 8 BEDOK RESERVOIR VIEW  
 #11-20  
 479235  
 SINGAPORE

NRIC/PASSPORT NO. : S7902907F ISSUE : 18/02/2009  
 ISSUED BY : SINGAPORE  
 LICENSE : S7902907F EXPIRY : 30/12/2999  
 ISSUED BY : SINGAPORE  
 NATIONALITY : SINGAPOREAN D.O.B. : 30/01/1979  
 FREQUENT FLYER NO. :  
 LOCAL CONTACT : 9761 6400  
 HOTEL :  
 COMPANY'S DETAILS  
 NAME :  
 ADDRESS :

RENTAL AGREEMENT NUMBER : 55004451

RENTAL LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY

**CHECKOUT**

UNIT # / REGN NO. : 00003078 / SLV1503B  
 MAKE & MODEL : FORD FOCUS 4DR TITANIUM 1.0  
 CAR GROUP GIVEN : G CHARGE: F  
 KILOMETER OUT : 798  
 PETROL LEVEL OUT : FULL  
 DATE & TIME OUT : 09/01/2018 10:15  
 EST.DUE DATE & TIME IN : 12/01/2018 10:15  
 CHECKIN LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY

**RENTAL RATES**

AS: INSURANCE CLAIMS RATES 2017

DAILY @ S\$ 70.00

EXTRA DAY @ S\$ 70.00

EXTRA HOUR @ S\$ 14.00

**FOR RATES TO APPLY**

MINIMUM 24 HOURS. CAR MUST BE RETURNED TO RENTING LOCATION  
 ON THE DUE DATE

**INSURANCE**

BY INITIALS, THE HIRER

INCLUSIVE LDW

NON-WAIVERABLE DAMAGE EXCESS: S\$ 1,500.00 (SIN USE)

DECLINES PAI @ S\$ 5.00 PER DAY

DECLINES WSC @ S\$ 5.00 PER DAY

THIS CAR IS FOR SINGAPORE USE ONLY. THERE IS NO INSURANCE  
 COVERAGE FOR USE OUTSIDE SINGAPORE

**OTHER CHARGES**

FUEL SERVICES @ S\$2.70 / LITRE

**IMPORTANT NOTICE**

- Hirer is liable for all traffic fines including admin fees that are issued by Singapore or Malaysia authorities for a grace period of 12 months from the date of car return.
- A security deposit depending on the respective car group rented will be withheld on the Hirer's credit card.
- Any accident has to be reported within the next working day to Sime Darby Services Pte Ltd. In the event of failure to report, hirer shall be liable for any costs incurred by Sime Darby Services Pte Ltd or claims made by the other party.
- Smoking, durians and pets are not allowed in the vehicle. An additional 3 day's rental would be imposed if smoking and durian smell/pet's fur is detected upon car return.
- Hirer must inform Sime Darby Services Pte Ltd in advance for vehicle drop-off in Thrifty Malaysia renting location. A one-way rental fee and Malaysia surcharge are applicable as stated in our One Way Rental policy.
- Hirer is responsible for any missing items/car accessories or loss of keys will be charged accordingly.
- The excess do not cover i) Car accessories ii) Loss of key iii) Vandalism iv) Alcohol/intoxicants/drugs.
- Vehicles are prohibited to be driven into Thailand.

The vehicle is rented subject to all terms and conditions on this page and on the reverse side whether printed or handwritten. Hirer represents that they have read, understand and agree with the conditions of the rental agreement. The hirer authorises all amounts due under the rental agreement to be charged to the hirer's credit card shown on this form.

x   
 Hirer

x \_\_\_\_\_  
 Additional Driver

ADDITIONAL DRIVERS:

**REMARKS**

BMW OWNER: SJN6005E  
 PML CSA: CHUA (CLAIMS)

**HI RESERVATION**

RES. ID#  
 Muhammad Lukman bin Mohamed Sir

TACO#:  
 REF SRC: INSCLAIMS

Printed on 09-Jan-2018 10:14  
 Entered by: Muhammad Lukman bin Mohamed

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017 <a href="#">Edit Reg</a>		09 Jan 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,062.40</b> <a href="#">Edit Estimates</a>	<b>S\$3,062.40</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	CHUA KAI MENG, ID: S7902907F								
Vehicle Reg. No.:	SJN6005E	Date of Loss:	08/12/2017 17:00 - :59 [12 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT17120351	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHAS385G	Policy No. (Claimant):	CN817210						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 20/12/2017]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (20/04/2018): Alert - Adj Mandate Approved (S\$3501.47) - SJN6005E - Claim Handler: Priya</li> <li>III_SG (13/12/2017): Alert - Adj Mandate Approved (S\$0.00) - SJN6005E - Claim Handler: Priya</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJN6005E (MCT17120351)  
[SHA5385G]  
TP  
CHUA KAI MENG  
Dec 8 2017 5:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Performance Motors Limited

Upload Documents			Upload Photos		Compose New Letter		View <span>View in Browser</span>	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
2	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
3	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
4	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
5	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
6	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
7	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
8	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
9	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
10	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
11	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
12	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
13	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
14	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
15	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
16	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
17	09/03/18 15:58	General View		Load JPG	<input checked="" type="checkbox"/>			
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	11/12/17 09:14	TP GIA REPORT 1		Load PDF				
2	11/12/17 09:14	TP GIA REPORT 2		Load PDF				
3	11/12/17 09:14	TP ESTIMATE		Load PDF				
4	11/01/18 11:59	TP ESTIMATE- MARKED		Load PDF				
5	11/04/18 17:06	WORKSHOP INVOICE		Load PDF				
6	11/04/18 17:06	RENTAL RECEIPT		Load PDF				
7	11/04/18 17:06	LOD		Load PDF				
8	27/04/18 09:59	DISCHARGE VOUCHER		Load PDF				
9	27/04/18 09:59	AUTHORISATION TO ACT FORM		Load PDF				
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print			
1	12/12/17 08:52	Singapore Accident Statement		Load PDF				

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III17023411/R1EA3Q2

Date: 27/04/2018

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
**Claimant Vehicle No :** SJN6005E **Insured Vehicle No :** SHA5385G  
 Date of Loss: 08/12/2017 Nature of Claim: TP Claim No: MCT17120351

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJN6005E**  
 Make & Model: BMW 216D, 1.5 D Gran Tourer (F46) (A) Engine No: 30459707B37C15A  
 Reg. Date: 30/11/2016 (Man. Year: 2016) Chassis No: WBA2E320705B45516  
 Colour: White Odometer: 27493 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,469.45	1,128.40	2,341.05	67.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,181.00	1,934.00	1,247.00	39.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,650.45</b>	<b>3,062.40</b>	<b>3,588.05</b>	<b>53.95</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>465.53</b>	<b>214.37</b>	<b>251.16</b>	<b>53.95</b>
<b>Nett Amount (S\$)</b>	<b>7,115.98</b>	<b>3,276.77</b>	<b>3,839.21</b>	<b>53.95</b>
<b>+ Car Rental (3.0 x S\$70.00/day + 7.00% GST) (S\$)</b>		<b>224.70</b>		
<b>Nett Liability (S\$)</b>		<b>3,501.47</b>		

## INSPECTION

Date of Assignment: 09/01/2018  
 Date Inspected: 09/01/2018 Inspected At: Performance Motors Limited (Alexandra)  
 303 Alexandra Road, Sime Darby  
 Performance Centre  
 Singapore 159941  
 Estimated Period of Repair: 3.0 days

---

**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2018)
<b>Parts:</b>	M1-MPV	BMW 216D 1.5 D Gran Tourer (F46) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJN6005E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	58.55 FS	*- FS
3	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	58.55 FS	*- FS
4	1		*REAR BUMPER CARRIER	Not Necessary	413.45 FS	*- FS
5	1		*RR BUMPER LH INNER SIDE GUIDE	Not Necessary	64.30 FS	*- FS
6	1		*RR BUMPER RH INNER SIDE GUIDE	Not Necessary	64.30 FS	*- FS
7	1		*REAR BUMPER TRIM STRIP (CHROM)	Cut	105.65 FS	*105.65 FS
8	1		*LEFT PROTECT	Not Necessary	2.05 FS	*- FS
9	1		*RIGHT PROTEC	Not Necessary	2.05 FS	*- FS
10	1		*REAR BUMPER PANEL PRIMED (LINES PDC)	Deformed	942.75 FS	*942.75 FS
11	1		*SET MOUNT S PDC SENSOR REAR	Not Necessary	62.50 FS	*- FS
12	1		*REAR BUMPER TOWING FLAP EYE PRIMED	Not Necessary	27.10 FS	*- FS
13	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	19.80 FS	*- FS
14	4		*ULTRASONIC SENSOR ALPINWEISS (U300)	Not Necessary	1,498.40 FS	*- FS

F=Franchise part, S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>3,469.45</b>	<b>1,128.40</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	1,700.00	850.00
2	SPRAY PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO REPLACE REAR PDC SENSOR WIRE HARNESS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION	New	266.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			<b>3,181.00</b>	<b>1,934.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >