

IMS CASE OWNER:

Rasheed

CC6 / AIG17023413

Uua3/

LEK:

IDAC:

ASSIGNMENT

Surveyor:

MARCUS

DOI:

11/12/17

Date / Time:

11/12/17

Registered in Merimen:

11/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLM 9621M

Claim No.:

1825434679.59

Name of Insured:

ONG BENH CHOO

Policy No.:

2100507379

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

01/12/17

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGY 3244D



INSRS:

WSP: Jm Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

13/12/17 (THURSDAY)

SGY 3244D - NA/ECI14008777/61

SLM 9621M - X

OI NR - SEND FIRST LETTER TO OI.

OID coming out from parking lot and collided onto TP vehicle.

RECEIVED 04 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

28/6/18

Confirm with: Jouis

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 23

If NO or B 28, Ass. Lia:

Repair Cost:

SS

1819.00

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

150.00 (\$ 50 x 3 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

1969.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1969.00

Name 1:

JIN AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

SINGAPORE

REF:

A191

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SA1/32X41
 at Workshop m/s J.1.1.1. 9.15
 of _____
 Insured: SLM962/M
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 G/A / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

0300C
 Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SA1/32X41 Yr Regn: 9.07
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (9)
 Make: Toyota Sienna C.C. 1496
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 102072 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: NCP815037242
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Harder / Jammed / Leaked / Burnt or
 Brake: Harder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/65R14
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN

Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 11/12/17 D.O.I. 11/12/17
 Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 23-9-20221742/08

11/12/17 conf. card h/s #1700 with Jones.

(Red: \$1177.40 / 41.1%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format:

Lump Sum / I.B.I. (\$) _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Insp (\$ _____)

☐

: Weekend (\$ _____)

) \$ + RE \$ _____

) Photo

) Other

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17023413/Uua3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 11-12-2017	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLM 9621M	Veh. Inspected	SGY 3244D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/12/2017	Inspection Date	11/12/2017
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	0300C
Vehicle Details	
Vehicle No.	SGY3244D
Vehicle to be Exported	No
Intended De-registration Date	11 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	SIENTA 1.5 A
Primary Colour	Grey
Manufacturing Year	2007
Engine No.	1NZC691110
Chassis No.	NCP815037242
Maximum Power Output	81.0 kW (108 bhp)
Open Market Value	\$16,621.00
Original Registration Date	24 Sep 2007
First Registration Date	24 Sep 2007
Transfer Count	2
Actual ARF Paid	\$18,284.00
Intended PARF Rebate Details	
PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	23 Sep 2022
COE Category	A - Car (1600cc & below)
COE Period(Years)	5
PQP Paid	\$22,041.00
COE Rebate Amount	\$21,085.00
Total Rebate Amount	\$21,085.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Dec 2017

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

5/12/2017

not Authorized
11/12/17
Tehnght. Atkinson -
2/s \$1700/-
3 day.

M/S AIG

ESTIMATE REPAIR COST FOR SGY3244D TOYOTA SIENTA CHASSIS : NCP81-5037242

S/N	QTY	DESCRIPTION
1	1 PC	FRONT BUMPER
2	1 PC	FRONT BUMPER CLIPS
3	1 PC	FRONT BUMPER LH SIDE RETAINER
4	1 PC	FRONT LH FENDER
5	1 PC	FRONT LH HEADLAMP

D.S	\$	1,280.50	—
her	\$	30.00	—
sub	\$	68.10	—
n	\$	708.90	x
scr/cr	\$	515.70	—
	\$	2,603.20	1894.3
LESS 25%	\$	(650.80)	1420.72
	\$	1,952.40	
	\$	450.00	400
	\$	450.00	300
	\$	25.00	✓
	\$	2,877.40	
			2145.72

6	SPRAY PAINTING
7	LABOUR CHARGE
8	WIRING CHECK

LKK & W Consultant's hence notify
the Repairer of the following:

- To resurvey within 48hrs after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Business Registration No:200704370C

Date : 17/04/2018

Your ref:SLM9621M (AIG Insured)

C/O LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Park
(S) 408933

Dear Sir/Madam

Accident involving vehicle SGY3244D & SLM9621M ON 01/12/18

We are instructed by the owner SGY3244D to write ,negotiate and settle claim on her behalf for the above mentioned accident. we are now seeking the total amount of claim as follow:

Repair cost	S\$1819.00(with gst)
Loss of used	180.00

TOTAL S\$ 1998.00

We shall appreciate if you could kindly consider our claim at your earliest convenience and kindly let us have your acknowledgement of receipt of this letter within 14days of your receipt of this letter.

Yours faithfully



Louis Seow (Email: louis@jinauto.com.sg)





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG17023413/Uua3

06 FEBRUARY 2018

ONG BENG CHOO
100 KASAI ROAD
SINGAPORE 808340

Dear Sir/Madam,

ACCIDENT INVOLVING SLM 9621M & SGY 3244D ON 01/12/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

LETTER OF AUTHORISATION

To: Jin Auto Services Pte Ltd

Dear Sir

ACCIDENT INVOLVING SGY3244D & SLM9621M ON 1/12/2017.

I/We, the owner of Vehicle Registration Number SGY3244D hereby authorise you to repair my/our vehicle repair, submit and settle my/our claim for cost of repair and/or uninsured losses arising from the above accident .

I/We further confirm that the acceptance by M/s Jin Auto Services Pte Ltd of the settlement amount in respect of such claim shall constitute the full discharge of my/our claim in respect of such loss and damage.

Signed by :



Name : NOORAHEZAN BINTE SARIP
NRIC NO: S7610300C

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **JIN AUTO SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$ 1,819.00** (Repair Cost), **S\$ 150.00** (Loss of ~~Rental~~/Use), **S\$ —** (Disbursement) for vehicle no. **SGY 3244D** that was damaged pursuant to the accident which occurred on **01/12/2017** (date) along **JALAN KAYU** (location) involving vehicle no/s **SLM 9621M**. This is pursuant to the inspection conducted on **11/12/2017** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **NOORAHEZAN BINTE SARIP** ("the third party claimant") of vehicle no. **SGY 3244D** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SGY 3244D** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 04 (day) of July (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

JIN AUTO SERVICES PTE LTD

Blk 14 #01- 410/412 Defu Lane 10 Singapore 539195

Tel: 6289 8126 (24 hrs) Fax: 6287 0590

Email: jin@jinauto.com.sg

Company Reg. No: 200704370C GST Reg. No: 200704370C

TAX INVOICE

M/s

ALH. ASIA PACIFIC INSURANCE PTE LTD

Invoice No: 15891

Vehicle No: SEA 3244D

Date: 20/4/18.

[illegible]

N.B No responsibility will be accepted for any loss or damage to any Vehicles or parts left in this workshop for any reason whatsoever.

E. & O. E.

ADD GST	\$ 119.00
---------	-----------

TOTAL	\$1819.40
-------	-----------



JIN AUTO SERVICES PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2017 Edit Reg		11 Dec 2017 00:00 Edit Adj Rpt	\$51,700.00 Edit Estimates	\$51,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

ONG BENG CHOO, ID: S0140134C

Main Claimant:

NOORAHEZAN BINTE SARIP, ID: S7610300C

Vehicle Reg. No.:

SGY3244D

Date of Loss:

01/12/2017 20:00 - :59
[122 Months and 7 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 1835434679SG

Policy/Cover Note No.:

2100507329 (Comprehensive)
Coverage: 19/04/2017 - 18/04/2018

Vehicle Reg. No. (Insured):

SLM9621M

Policy No. (Claimant):

5094256975

Excess:

Repairer:

Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, S39195 Defu Lane - Tel: 6289 8126

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767]
Rashidah.Mohamedrasheed@aig.com

Claimant's Insurer:

NTUC Income Insurance Co-operative Ltd (HQ) - Tel:

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/12/2017]

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (12/12/2017): NO OI GIA REPORT
- AIG_SG (12/12/2017): TP GIA REPORT

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGY3244D (1835434679SG)
[SLM9621M]
TP
NOORAHEZAN BINTE SARIP
Dec 1 2017 8:00PM
[ONG BENG CHOO]
Jin Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1	Edit			
Assessment Reports															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail	Print			
1	24/01/18 14:47	Accident Statement From: OD - Reg. No: SLM9621M, Claimant: ONG BENG CHOO												1	Load HTM			
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print			
1	11/12/17 13:35	Odometer Reading												1	Load JPG	<input checked="" type="checkbox"/>		
2	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
3	11/12/17 13:35	Chassis Number												1	Load JPG	<input checked="" type="checkbox"/>		
4	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
5	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
6	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
7	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
8	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
9	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
10	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
11	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
12	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
13	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
14	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
15	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
16	11/12/17 13:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
17	11/12/17 13:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
18	11/12/17 13:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
19	11/12/17 13:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
20	11/12/17 13:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
21	11/12/17 13:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
22	11/12/17 13:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
23	11/12/17 13:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
24	11/12/17 13:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
25	11/12/17 13:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
26	11/12/17 13:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
27	08/03/18 08:32	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>		
28	08/03/18 08:32	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>		
29	08/03/18 08:32	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/12/17 09:16	TP GIA REPORT	 Load PDF	
2	13/12/17 09:16	TP ESTIMATE- MARKED	 Load PDF	
3	13/12/17 09:16	SLM 9621M - NON REPORTING LETTER	 Load PDF	
4	05/07/18 11:03	WORKSHOP INVOICE	 Load PDF	
5	05/07/18 11:03	AUTHORISATION TO ACT FORM	 Load PDF	
6	05/07/18 11:03	Release Voucher	 Load PDF	
7	05/07/18 11:03	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^v

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLM9621M (Insd veh)	Model:	TOYOTA SIENTA 1.5 (A)
	SGY3244D (TP veh)		
Date of Accident:	01/12/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	3,078.82
Final Repair Cost	:	\$	1,819.00
Loss of Use	:	\$	150.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,969.00

3.00 days at \$50.00 per day
days

Is Third Party Workshop GIA Registered?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u> :	Agreed Liability ____ 100 ____ (%)		
B) For <u>GIA Registered Workshop</u> :	BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Jin Auto Services Pte Ltd	:	\$ 1,969.00
2)		:	\$ 0

JOANNE LEE KHANG MIN

05 Jul

2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17023413/UUA3Q2

Date: 05/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100507329
Claimant Vehicle No : SGY3244D **Insured Vehicle No :** SLM9621M
 Date of Loss: 01/12/2017 Nature of Claim: TP Claim No: 1835434679SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY3244D**
 Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 1NZC691110
 Reg. Date: 24/09/2007 (Man. Year: 2007) Chassis No: NCP815037242
 Colour: Grey Odometer: 102072 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R14 Rear Tyre Size: 185/65 R14
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,952.40	1,420.72	531.68	27.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	925.00	725.00	200.00	21.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,877.40	2,145.72	731.68	25.43
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	2,877.40	1,700.00	1,177.40	40.92
+ GST 7.00/7.00% (S\$)	201.42	119.00	82.42	40.92
Nett Amount (S\$)	3,078.82	1,819.00	1,259.82	40.92
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
Nett Liability (S\$)		1,969.00		

INSPECTION

Date of Assignment: 11/12/2017
 Date Inspected: 11/12/2017 Inspected At: Jin Auto Services Pte Ltd (Defu)
 Blk 14 Defu Lane 10, #01-410/412
 Singapore 539195
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,280.50 FL	*1,280.50 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*FRONT BUMPER LH SIDE RETAINER	Bent	68.10 FL	*68.10 FL
4	1		*FRONT LH FENDER	Repair	708.90 FL	*- FL
5	1		*FRONT LH HEADLAMP	Scratched / Cracked	515.70 FL	*515.70 FL
Sub Total (S\$)					2,603.20	1,894.30
- List Item Discount on L Items 25.00/25.00% (S\$)					650.80	473.58
Total Parts (S\$)					1,952.40	1,420.72

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	450.00	400.00
2	LABOUR CHARGE	New	450.00	300.00
3	WIRING CHECK	New	25.00	25.00
Gross Labour Cost (\$\$)			925.00	725.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >