MBM217163540 / Borneo Motors (S) Pte Ltd - Pandan ENTRY DATE & TIME: 12/12/2017 16:08

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 12/12/2017 16:21

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policyliability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

aforesaid.					
	ACCIDENT STATEMENT				
Date Of Report	12/12/2017 16:08				
Date Of Accident	08/12/2017 17:15 438B ALEXANDRA ROAD SINGAPORE				
Exact Location Of Accident					
Country/State of Loss					
	DETAILS OF OWN VEHICLE				
Vehicle Registration Number	GBE5672C				
Insured/Policyholder					
Name Of Registered Owner	WYNNCORP ENGINEERING & CONSTRUCTION PTE LTD				
Co Reg No	200710978H				
Email Address	WCE@WYNNCORP.COM.SG				
Mobile Phone No					
Alternative Phone No	Office-63670702				
Vehicle Particulars					
Manufacturer	TOYOTA				
Model	DYNA 150-2.0 YY211 (M)				
Exact Purpose for which vehicle was being used at time of accident					
Are you claiming under your own insurance policy for repair to your vehicle?	NO				
If No, Please state action to be taken	REPORTING ONLY				
Vehicle Category	COMMERCIAL VEHICLE				
Insurance Company					
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.				
Type Of Coverage	COMPREHENSIVE				
Fleet Policy	NO				
Policy Number	2100448105				
Cover Note Number					
D					

Driver

Name of Driver HENG HIANG YEE

NRIC No F7297902T

Date Of Birth 16/12/1972

Occupation OUTDOOR

Date Of Driving Pass 16/09/2017

Driving Experience 0 YEAR AND 2 MONTH

Gender MALE

Mobile Number (LOCAL) +65-96532385

Fax Number

Contact Number

EMail Address KENNY@WYNNCORP.COM.SG

Address 190 WOODLANDS INDUSTRIAL PARK E5 #04-13 757516

Was driver an employee of the Insured's Company
If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident?

Was any body injured in the Accident?

NO

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLN2102K
Vehicle Make/Model/Colour MAZDA

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Accident Sketch Plan



SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurence Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

	& Time	Personnel
Sketch Plan		

I was being in the formy for my colleague to return from lente, when he get into the 1s my. I cheeked my Girls and Dack minor and there was no vehille behind the long, I engage the reverse gear as the larry was in the read in pointion. I turned the storing wheel anti-clockwise pointion and cheeked my left side minory for any vehicle and there was no vehicle. Then I proceed to reverse the larry. Suddenly I heard a knock and realised the right corner of the long collect with a passenger car which has stop stationary behild the long. To my knowledge, there wasn't and vehicle behind the long. We both necess the dange and it was found the passenger vehicle SLN 2102 k has a dent in his reat left door. My lorry only has slight paint dange.	Describe Circumstances of the Accident
referre from Poite, when he get into the 10 ray. I checked my Rides and back minor and there was no vehicle behind the 10 ray, I engage the reverse gear as the larry was in the nead in position. I turned the Receive wheel anti- clockwise position and checked my left side minor for any vehicle and there was no vehicle then I proceed to reverse the larry - Suddenly I heard a knock and realised the right corner of the lorry collied with a passenger car which has stop stationary behind the lorry. To my knowledge, there wasn't and vehicle behind the lorry. We both occess the damage and it was found the passenger vehicle SLN 2102 k has a dent in his rear left door.	I was waiting in the long for my colleague to
was no vehille behind the lorry, I engage the reverse gear as the lorry was in the nead in position. I turned the ateoring wheel anti clockwise position and checked my left side miner for any vehicle and there was no vehicle then I proceed to reverse the lorry. Suddenly I heard a knock and realised the right corner of the lorry collied with a passenger car which has stop stationary behind the lorry. To my knowledge, there wasn't and vehicle behind the lorry. We both occess the damage and it was found the passenger vehicle SLN 2102 k has a dent in his rear left door.	return from lente, when he got into the lorny.
was no vehille behind the lorry, I engage the reverse gear as the lorry was in the nead in position. I turned the extering wheel anti clockwise position and checked my left side miner for any vehicle and there was no vehicle then I proceed to reverse the lorry. Suddenly I heard a knock and realised the right corner of the lorry collied with a passenger car which has stop stationary behind the lorry. To my knowledge, there wasn't and vehicle behind the lorry. We both occess the damage and it was found the passenger vehicle SLN 2102 k has a dent in his rear left door.	I checked my Sides and back minor and there
and vehicle behind the lorry. We both once ess the damage and it was found the passenger vehicle SLN 2102 K has a dent in his rear left door.	was no vehicle behind the lorny, I engage the
and vehicle behind the lorry. We both once ess the damage and it was found the passenger vehicle SLN 2102 K has a dent in his rear left door.	reverse gear as the larry was in the nead
and vehicle behind the lorry. We both once ess the damage and it was found the passenger vehicle SLN 2102 K has a dent in his rear left door.	in position. I turned the steering wheel anti
and vehicle behind the lorry. We both once ess the damage and it was found the passenger vehicle SLN 2102 K has a dent in his rear left door.	clackwise position and checked my left side miner
and vehicle behind the lorry. We both once ess the damage and it was found the passenger vehicle SLN 2102 K has a dent in his rear left door.	for any vehicle and there was no vehicle. then I proceed to
and vehicle behind the lorry. We both once ess the damage and it was found the passenger vehicle SLN 2102 K has a dent in his rear left door.	reverse the larry - Suddenly I heard a knock and realised
and vehicle behind the lorry. We both once ess the damage and it was found the passenger vehicle SLN 2102 K has a dent in his rear left door.	the right corner of the long collied with
and vehicle behind the lorry. We both once ess the damage and it was found the passenger vehicle SLN 2102 K has a dent in his rear left door.	or passenger cut which has stop stationary
we both occess the damage and it was found the passenger vehicle SLN 2102 K has a dent in his rear left door.	Charles for collection to the dead to be a finished
the passenger vehicle SLN 2102 K has a dent in his rear left door.	and vehicle behind the lorry.
the passenger vehicle SLN 2102 K has a dent in his rear left door.	
	We both once ess the damage and it was dound
	the passenger vehicle SLN 2102 K has a dent
My lorry only has slight paint dangge.	in his rear lest door.
My lorry only has slight paint clangle.	
	My lorry only has Blight paint claimage,

Declaration

p. .

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (# driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel





CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

TOYOTA COMMERCIAL AUTO PROTECTOR

CERTIFICATE,NO. 2100448105-01000

OWN DAMAGE EXCESS \$\$800.00. (1) WINDSCREEN EXCESS S\$100.00

SUM INSURED Market Value INSURING WITH COE/PARF Yes

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT

4) DATE OF EXPIRY OF INSURANCE

Wynncorp Engineering & Construction

Pte Ltd 19 Jan 2017

GBE5672C

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person provided he is in the Insured's employ and is driving on their order or with their permission. A Young and/or Inexperienced Driver Excess ("YIDR") of \$53,000.00, in additional to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said. Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enectment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

1) Use in connection with the insured's business.
2) Use for the carriage of passengers [other than for hire or reward] in connection with the insured's business.
3) Use for social, domestic or pleasure purposes.
The policy does not cover: a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing.
b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicles.

APPROVED REPORTING CENTRES / TOYOTA AUTHORISED WORKSHOPS

APPROVED REPORTING CENTRES / TOYOTA AUTHORISED WORKSHOPS

1. Bornec Moltes (S) Pie Ltd - 2 Pandan Crescent (Tel: 5631 1188)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddeil Rd (Tel: 53837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 55684501)

4. Ethor - 30 Busik Batck Cres (Tel: 563777777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 52780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 57479500) 7. Lal Huet (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Move Automotive - 1008 Busik Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 57415336)

10. SME Motor - 1 Kaki Busik Ave 6 Bik D (Tel: 67476106)

LOSS OF USE Not included

* NAMED DRIVER NA

HIRE PURCHASE COMPANY HONG LEONG FINANCE LTD JEMPLOYER'S LOAN
"Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malsysia)-

Issued in Singapore 14 Dec 2016

INCHCAPE AUTO TOYOTA-LK1CYL 33 LENG KEE ROAD SINGAPORE 159102

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

ORIGINAL

IASHRO.











WynnCorp Engineering & Construction Pte Ltd 190, Woodlands Industrial Park E5, #04-13, Woodlands BizHub, Singapore 757516 Tel: #65 6367 0702, #65 6367 0703. Fax: #65 6367 0713 Email: wce@wynncorp.com.sg

biZSAFE,

Letter of Authorization

GST / Co. Reg. no. 200710978H

I	Chiew Henr	y (Mana	aging Director)	S7571590J		(NRIC) hereby authorise
Heng	Hiang Yee	(Name)	F7297902T	(NRIC/FIN)	to settle all the	ne related	matter with reference to
compa	any vehicle T	oyota Dyn	a (GBE5672C	On behalf	of Wynncorp	Engineer	ing & Construction Pte Ltd.

Mr Chiew Henry Managing Director

Date: 12/12/2017
















Accident Scene Photo



Accident Scene Photo



Accident Scene Photo

