

ASS. REC. BY:

REF: CS3/C7117023429/W/bed Special Instruction:

range & days

Surveyor: Wilson.

ASSIGNMENT (Office)

From (Person):

Joel Fon

of

C71

Date/Time: 08/12/2017 5:06pm

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JRE 8188

Insured:

GBE 459K

at Workshop m/s

N-51 Automotive

Tel:

68420051

of

81k 2 Kaki Bukit Ave 2 #01-17

Policy No:

DMCVSN3063121700

Claim No:

SNM1700689202/9

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30.11.2017

CA / REV / REP. / REV 24 HRS 'wp'

12.12.2017

H.O.D. Endorsement:

Date/Time: 11.12.2017 10:58am

Person Contacted:

Elynn

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	JRE 8188 - X
	GBE 459K - X
	Dismantle Part: 13.12.2017

PRS

REF:

CTL

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. JRE 8188

at Workshop no. NSI

or No. 2 Kale. Rukst Age 2 #01-18

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

G/A PR Seen:

Consistent? : Yes or No

Est. Repairs. 4 days Res. : Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction:

Veh No.

JRE 8188

Yr Regn

2015 Nov 30

Type: M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Pick-up.

Make

Ford Ranger-XLT 2198

Colour

Dark Grey AD Insured / Std / NI / NA

Sp. Reading

84953 T Radio: Insured / Std / NI / NA

Eng No.

C.No.

MNBL MFF 80GW 482 850

Gen. Cond.

Good / Fair / Poor / Burnt

Steering

Inorder / Jammed / Leaked / Burnt or

Brake

Inorder / Jammed / Leaked / Burnt or

Modi.

M/T S/Rim STD A/Rim or

Tyre Size

F:

265 / 70 R16

R:

265 / 70 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R.Bal

4

mm

R.Bal

4

mm

L.Bal

4

mm

L.Bal

4

mm

D.O.A

30/11/2017

D.O.I

12/12/2017 @

Survey held at

Above 2.42 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Right Frt.

The U/C / Chassis frame / Body Structure affected due to collision

Range

#3900 - \$4900

4 Days Repair

RECEIVED 16 APR 2018

Date/Time File Pass to:

☐

Preli. Report

Days Of Repair:

4

1

☐

Final Report

Resurvey No. of Trip:

1

Survey Fee

Date/Time File Return to:

2

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Invs \$

☐

Weekend \$

Report Format: PRE.

Lump Sum / I.B.I: \$

Transporter

\$ - \$5

Phone

Other

Total

150
150



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS3/CTI17023429/Wb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 11-12-2017	
			Code : CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBE 459K	Veh. Inspected	JRE 8188	
Policy No.	DMCVSN3063121700	Coverage (\$)	0.00	
Claim No.	SNM17D06892C02/9	Excess (\$)	0.00	
Assign From	MERIMEN (JOEL GOH)	Assign Date	08/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/11/2017	Inspection Date	12/01/2018	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Dec 2017		08 Dec 2017 17:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	WING KHIONG HARDWARE & MACHINERY, Co. Reg. No.: 0								
Main Claimant:	HONG XI RUI								
Vehicle Reg. No.:	JRE8188	Date of Loss:	30/11/2017 16:00 - :59						
Claim Type:	TP / SNM17D06892C02/9	Policy/Cover Note No.:	DMCVSN3063121700 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBE459K	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/12/2017]								
Adj Asg. Remarks:	NO ESTIMATES ASSIGNED FOR WP PRS								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Survey Department Check List (Case Handler)

Reference No.:

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

--	--

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN: **JRE8188**

No. Siri B **9146150**
ZJPTXKZT

Name Pemunya
Bendeftar

HONG XI RUI

950601086233
[MAL]

Alamat

NO 5-01 JALAN API-API 5 TAMAN MEGAH RIA
81750 MASA1 JOHOR

No. Enjin **P4AT2087319**
No. Casis **MNBLMFF80GW482850**
Buatan **FORD**
Nama Model **RANGER 2.2L XLT 4WD AT**
Keupayaan Enjin **2198 S.P**
Bahan Bakar **ENJIN DIESEL HIJAU**
Warna **KELABU**
Kelas Kegunaan **PSDN-JIP/VAN/BAS/KVN IND**
Jenis Badan **PICK-UP**
Tahun Dibuat **2015**
Tarikh Pendaftaran **30/11/2015**
Status Pemunya **PERSENDIRIAN**
Muatan Tempāt **5**
Duduk **5**
Kadar Lesen **6 bulan**
Kenderaan Motor **RM299.20** **12 bulan**
RM598.40

B.D.M/B.G.K
B.T.T.
Berat Kerb
B.T.M.
B.G.1
B.G.2
B.G.3
B.G.4
B.G.5
B.G.6
B.G.7
B.G.8
B.G.9
B.G.10
B.G.11
B.G.12

Tandatangan Pemunya Bendeftar

Perakuan Pendaftaran ini dikeluarkan
oleh Pengarah JPJ Negeri **JPJ NEGERI JOHOR**

KENDERAAN IMPORT BARU

UNTUK KEGUNAAN PEJABAT

HAK MILIK DITUNTUT OLEH: PUBLIC BANK BERHAD NO SIRI: H05/533389/15

NOTA PENTING

1. Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengarah Jabatan Pengangkutan Jalan (JPJ).
2. Gerek butiran-butiran kenderaan di muka ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
3. Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membaruh lesen 60 hari sebelum tempohnya tamat.
4. Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengarah JPJ sekiranya kenderaan anda tidak berlesen.

5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
6. Pemunya bendeftar kenderaan adalah bertanggungjawab di atas semua urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
7. Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.



SINGAPORE POLICE FORCE



T/20171130/2120

1 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20171130/2120

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/11/2017 17:41	Vide Report No.:	Station Diary No.: 121
--	------------------	---------------------------

Informant's Particulars

Name of Informant: HONG PET POH			Address: 5-01 JALAN API-API 5 TAMAN MEGAH RIA 81750 MASAI JOHOR		
ID Type / ID No.: NEW MALAYSIAN IC / 600617015755			Contact No.: Home/Office: Mobile: 87816751		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 57	Date of Birth: 17/06/1960	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: SUPERVISOR			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 30/11/2017 16:00	Type of Location: T-Junction
Location: Along Road 1 ANG MO KIO INDUSTRIAL PARK 2 BLK 5022 ANG MO KIO INDUSTRIAL PARK 2				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE459K	Lorry					0
JRE8188	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20171130/2120

2 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20171130/2120

CONTINUATION OF REPORT

Driver			
Name	Mark Kok Yuen	ID No.	S1317790B
Related Vehicle	GBE459K (Lorry)	Contact No.	97564616
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	HONG PET POH	ID No.	600617015755
Related Vehicle	JRE8188 (Car)	Contact No.	87816751
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 30/11/2017 at about 1600hrs, I was travelling my black car bearing plate number JRE8188 (FORD) at Ang Mo Kio Industrial Park 2 near to Blk 5022 Ang Mo Kio Industrial Park 2.

While I was travelling wanting to make a right turn, a silver lorry bearing plate number GBE459K (Nissan) in the parking lot 322 reverse and hit onto me (Parking head in). My right front of my car was dented in.

No one was injured at the point of time. The driver particulars are Mark Kok Yuen S1317790B, h/p: 97564616.



**SINGAPORE
POLICE FORCE**



T/20171130/2120

3 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20171130/2120

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt TAN JINNG YI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 YEO KIA HUAT

Contact No.: 65476325

Signature Of Informant:

Date/Time:

30/11/2017 17:41

Classification Of Case:

SN 085

Authentication Stamp

NP168



Signature:

Singapore Police Force

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Dec 2017		08 Dec 2017 17:06 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: WING KHIONG HARDWARE & MACHINERY , Co. Reg. No.: 0									
Main Claimant: HONG XI RUI									
Vehicle Reg. No.: JRE8188		Date of Loss: 30/11/2017 16:00 - :59 [24 Months From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM17D06892C02/9		Policy/Cover Note No.: DMCVSN3063121700 (Comprehensive)							
Vehicle Reg. No. (Insured): GBE459K		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 19/12/2017]									
Adj Asg. Remarks: NO ESTIMATES ASSIGNED FOR WP PRS									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JRE8188 (SNM17D06892C02/9)
[GBE459K]
TP
HONG XI RUI
Nov 30 2017 4:00PM
[WING KHIONG HARDWARE & MACHINERY]
N-51 Automotive Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	01/12/17 17:33	Accident Statement		Load HTM	

Photos/Images

3 per page

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	01/12/17 17:33	Accident Photo [Linked Accident Report Documents]		Load JPG	
2	01/12/17 17:33	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	01/12/17 17:33	Accident Photo [Linked Accident Report Documents]		Load JPG	
4	01/12/17 17:33	CHASSIS NUMBER [Linked Accident Report Documents]		Load JPG	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/04/18 10:17	LKK SURVEYOR PHOTO 1		Load PDF	
2	16/04/18 10:17	LKK SURVEYOR PHOTO 2		Load PDF	

Documentation

1 per page

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	01/12/17 14:59	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	01/12/17 15:00	INSURANCE CERTIFICATE [Linked Accident Report Documents]		Load TIF	
3	01/12/17 15:00	DRIVER NRIC & DRIVING LICENCE [Linked Accident Report Documents]		Load TIF	
4	01/12/17 15:00	POLICE REPORT [Linked Accident Report Documents]		Load TIF	

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	08/12/17 17:06	OI GIA REPORT		Load PDF	

Linked Accident Report Documents

View

View in Browser

Assessment Reports										1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print
1	01/12/17 17:33	Accident Statement							1	Load HTM	

Photos/Images										3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print
1	01/12/17 17:33	Accident Photo							1	Load JPG	☒
2	01/12/17 17:33	Accident Photo							1	Load JPG	☒
3	01/12/17 17:33	Accident Photo							1	Load JPG	☒
4	01/12/17 17:33	CHASSIS NUMBER							1	Load JPG	☒

Documentation										1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print

Assessment Reports			1 per page	☐	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	01/12/17 14:59	Sketch Plan		Load TIF	
2	01/12/17 15:00	INSURANCE CERTIFICATE		Load TIF	
3	01/12/17 15:00	DRIVER NRIC & DRIVING LICENCE		Load TIF	
4	01/12/17 15:00	POLICE REPORT		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT117023429/WBE2

Date: 18/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3063121700

Claimant Vehicle
No: JRE8188Insured Vehicle
No: GBE459K

Date of Loss: 30/11/2017

Nature of Claim: TP

Claim
No: SNM17D06892C02/9

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JRE8188

Make & Model: FORD RANGER, 2.5 D 4X4M (M)

Engine No: P4AT2087319

Reg. Date: 30/11/2015 (Man. Year: 2015)

Chassis No: MNBLMFF80GW482850

Colour: Dark Grey

Odometer: 84953 km

Engine Capacity: 2198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/70 R16

Rear Tyre Size: 265/70 R16

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm

Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/12/2017

Date Inspected: 12/12/2017 Inspected At:

N-51 Automotive Pte Ltd (HQ)
2 KAKI BUKIT AVE 2
#01-17 KAKI BUKIT AUTOHUB
SINGAPORE 417921

Estimated Period of Repair: 4.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,900.00 - \$4,900.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Apr 2018)	
Parts:	N/A	FORD RANGER 2.5 D 4X4M (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JRE8188)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >