

*Arg Asia-CP/P*  
*LKK - Kalvin*

*TS*

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305095841  
REGN NO : SHA4361G  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 19.05.2016  
DATE/TIME IN : 08.12.2017 07:40  
ACCIDENT DATE : 08.12.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT			
0001	04-01-0103-0579-G	BUMPER REAR	1	603.60	20.00	482.88	X repair
0002	04-01-0103-0738-G	BUMPER LOWER REAR	1	225.00	20.00	180.00	X
0003	04-01-0101-0111-G	BUMPER CLIPS	10 L	22.00	20.00	17.60	X
0004	09-01-9999-0068-A	REVERSE SENSOR	1	135.70	<del>200</del>	135.70	X
				SUB-TOTAL :		816.18	

JOB NATURE

0000 L	PANEL BEATING	280.00	<del>100</del>			
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00	<del>180</del>			
0002 L	R/I REVERSE SENSOR	120.00	X			
				SUB-TOTAL :		600.00

TOTAL : 1,416.18

MVA NAME & SIGNATURE  
DATE :

*LMF*

SURVEYOR NAME & SIGNATURE  
DATE :

*Kalvin LKK*  
*8/12/17 1100 hrs*  
*2 Days*  
*PIP*  
*After Repair photo*

AUTHORISED : YES / NO

AKA

the Rep... notify

- To resurvey : ...
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_