

ASS. REC. BY:

REF: CS/MSH17023458/Gtber Special Instruction:

ASSIGNMENT (Office)

From (Person): Clara Miah of MSH Date/Time: 11.12.2017 2:34pm

Estimated Cost: _____ Bill to: _____

① TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SFA 1001P Insured: _____at Workshop m/s Borneo Motor Tel: 9847 6209of 17 Ubi Rd 4Policy No: 8039 14940MY Claim No: 540137Sum Insured: _____ Excess: \$ 1500.00Make of Veh: _____ D.O.A. 05.12.2017
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 11.12.2017 2:40pm Person Contacted: Sam Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>any aggravated damages</u>
	<u>STN 1001P - X</u>
<u>12/12-</u>	<u>Report via merimen</u>
<u>13/12@ 13:29</u>	<u>inform by Chen How authorize repair. Excess \$1500-</u>
<u>13/12@ 1:47pm</u>	<u>inform Sam authorize repair. max \$18K.</u>
<u>14/12</u>	<u>Seek Supplementary X final approval.</u>
<u>17/12</u>	<u>approve Supplementary.</u>

REF:

REF:

MS16

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop via Borneo Motors

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

\$1500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	
N/S	O/S

Bal. or Market Value:

\$93k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / FR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res:

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA / ☒ REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Yeh No:

STA 1001P

Yr Regn:

23 DEC 2013

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Toyota 86

CC

1998

Colour

white

A/C

Insured / Std / NI / NA

Sp. Reading

24324

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No

JF1ZN6K72EG 018621

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A.

D.O.A.

11-12-17

Survey held at

w/s

5:30pm

Des. of Damages ☒ Frt / Rear / O/S / N/S / U/C / Rooftop orThe ☒ Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Final figure @ \$15934.33 cred: 10538.54 ; 39%

RECEIVED 25 SEP 2018

Date/Time. File Pass to?

☐

: Prel. Report

Date/Time. File Return to?

☒

: Final Report

Date/Time. File Return to?

2)

Report Format :

OP

Lump Sum / I.B.I. (\$) 15934.33

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee

Transportation

1 \$ + RS 31

Photo

Diary

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

300

10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17023458/Gtb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 11-12-2017		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SFA 1001P	
Policy No.	80391494QMY	Coverage (\$)	0.00	
Claim No.	540137	Excess (\$)	1,500.00	
Assign From	MERIMEN (CLARA MILAH)	Assign Date	11/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/12/2017	Inspection Date	11/12/2017	
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inv Rpt/Est	Status
Main	08 Dec 2017		11 Dec 2017 14:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LEE CHOON SING, ID: S13983723, Tel: +6597549721									
Vehicle Reg. No.: SFA1001P		Date of Loss: 05/12/2017 20:00 - :59							
Claim Type: OD / 540137		Policy/Cover Note No.: 80391494QMY (Comprehensive) Coverage: 23/12/2016 - 22/12/2017							
		Excess: S\$1,500.00							
Repairer: Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road #, 408611 Ubi - Tel: 6631 1868									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/12/2017]									
Driver/Custodian: DUAN ZIYAN (33 / Female), NRIC: S84610731, Tel: +6584082322									
Adj Asg. Remarks: Please check for any aggravated damages. Please revert. Thanks.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 13 December, 2017 1:50 PM
To: 'SanJoi.Sam@borneomotors.com.sg'
Cc: SUR
Subject: SFA 1001P / MSIG / OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SFA 1001P (Excess \$1500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SFA1001P (540137)**

OD

Dec 5 2017 8:00PM

[LEE CHOON SING]

Borneo Motors (S) Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_5G), sent on 13/12/2017 13:29 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9573.00) - SFA1001P - Claim Handler: Clara Miah Yeo

Approved:9573.00;Cost of Repair: cap at \$18000.00

DOCUMENTS SUMMARY

There are no documents.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	08 Dec 2017 13:37	Clim Veh Model Changed	[204323] TOYOTA 86 2.0 (A);	[I] Clara Milah Yeo
2	08 Dec 2017 13:37	Clim Created	Reg No: SFA1001P. Policy No: 80391494QMY, Acct Date: 2017/12/05. Claim Type: O D. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Borneo Motors (S) Pte Ltd (Ubl). Ins.Status => Incoming Claim. Created from SAS:MBM217161337	[I] Clara Milah Yeo
3	08 Dec 2017 14:13	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please check for any aggra vated damages. Please revert. Thanks.	[I] Clara Milah Yeo
4	08 Dec 2017 14:13	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/09	[I] Clara Milah Yeo
5	08 Dec 2017 14:13	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Clara Milah Yeo
6	11 Dec 2017 09:58	Assignment 1st Accessed		[A] Ho Pei Fang
7	11 Dec 2017 14:33	Adj Assignment Cancelled		[I] Eliza Ho Teng Boon
8	11 Dec 2017 14:33	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Eliza Ho Teng Boon
9	11 Dec 2017 14:34	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please check for any aggravated damages. Please revert. Thanks.	[I] Eliza Ho Teng Boon
10	11 Dec 2017 14:34	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/12	[I] Eliza Ho Teng Boon
11	11 Dec 2017 14:34	Adj Mandate Set	Approved:25000.00,Reinsp:Adj decides.	[I] Eliza Ho Teng Boon
12	11 Dec 2017 14:36	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
13	11 Dec 2017 15:47	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] CATHERINE CHONG KAI LING
14	12 Dec 2017 11:35	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
15	12 Dec 2017 17:26	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/10	[A] DENISE TAY KWEE CHENG
16	12 Dec 2017 17:26	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/10	[A] DENISE TAY KWEE CHENG
17	12 Dec 2017 17:34	Adj Mandate Request	Cur.Req:18024.67;DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
18	13 Dec 2017 13:29	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/10. Mandate Remarks: Cost of Repair: cap at \$18000.00	[I] NG CHEN HOW
19	13 Dec 2017 13:29	Adj Mandate Set	Approved:9573.00:Cost of Repair: cap at \$18000.00	[I] NG CHEN HOW
20	14 Sep 2018 14:14	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/10	[A] DENISE TAY KWEE CHENG
21	14 Sep 2018 14:15	Adj Mandate Request	Cur.Req:15934.83;DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
22	17 Sep 2018 11:16	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/10. Mandate Remarks: Cost of Repair: cap at \$18000.00	[I] NG CHEN HOW
23	17 Sep 2018 11:16	Adj Mandate Set	Approved:15934.83:Cost of Repair: cap at \$18000.00	[I] NG CHEN HOW

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1664861	12/12/2017 11:35	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFA1001P		10.70
1682234	08/12/2017 13:40	Motor	MSIG Insurance (Singapore) Pte. Ltd.	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	SFA1001P	540137	XX.XX

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 14 Sep 2018

Preliminary Advice

Vehicle No	: SFA1001P	Accident Date	: 05/12/2017
Make	: TOYOTA 86	Policy No.	: 80391494QMY
Assignment Date	: 11/12/2017	Excess	: S\$1,500.00
Date of Inspection	: 11/12/2017	Est. Duration of Repair	: 10.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (UBI) 17 UBI ROAD 4 SINGAPORE 408611		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident. The undercarriage affected due to collision

Repairer's Estimate (Gross)	:S\$	26,473.37	inclusive supplementary 4,145.91
Revised Amount	:S\$	15,934.83	inclusive supplementary 4,145.91
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	15,934.83	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	93,000.00
COE / PARF Rebate	:S\$	73,126.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,874.00

Remarks

- (x) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
Attn: Motor Claims Dept

S1000004 /ICCUA1

39006158

Mr Lee Choon Sing
164 Joo Chiat Road

Singapore 427438

Mobile: 97549721

13 BKE7 S1 ZN6 23/12/2013 SFA1001P 24329 15660 70D/SFA1001P/05121'

JF12N6K72EG018621 FA20H837848 60 Sam San Joi 07/12/2017 15.30 05/01/2018 8.19

9	TSU003-01303	FRAME SD FF SUB CRPL	/BT	1.00	158.00	15.00	134.30
0	TSU003-00355	ARM ASSY, FR LWR LH	/BT	1.00	840.20	15.00	714.17
1	TSU003-00372	ABSORBER ASSY, FR LH	/BT	1.00	394.30	15.00	335.15
2	TSU003-00394	LINK ASSY, STABILIZER	/BT	1.00	102.00	15.00	86.70
3	TSU003-00780	KNUCKLE, STEERING LH	/BT	1.00	696.80	15.00	592.28
4	TSU003-00782	HUB SUB-ASSY, FR	/BT	1.00	506.50	15.00	430.52
1	TSU003-01537	DISC WHEEL AL 17	/BT	1.00	73.80	15.00	62.73
2	TSU003-01538	PLATE, FR BUMPER	/BT	1.00	1674.30	15.00	1423.15
3	TSU003-04308	PLATE, FR BUMPER	/BT	1.00	22.10	15.00	18.78
4	TSU003-01511	COVER BMR LWR F	/BT	1.00	22.10	15.00	18.78
5	TSU003-01500	STAY, FR BUMPER	/BT	1.00	77.50	15.00	65.87
6	TSU003-02985	BRKT CTR LWR F	/BT	1.00	22.50	15.00	19.12
7	TSU003-02698	CLIP 2PIECE D6	/BT	1.00	119.20	15.00	101.32
8	TSU003-01221	JAR ASSY, W/SHIELD	/BT	2.00	2.50	15.00	4.24
		PLATE, RADIATOR	/BT	1.00	126.40	15.00	107.44
			/CRA	1.00	36.90	15.00	31.36

4,145.91

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

13/02/2018
13:16

SFA1001P

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 12 Dec 2017

Preliminary Advice

Vehicle No	: SFA1001P	Accident Date	: 05/12/2017
Make	: TOYOTA 86	Policy No.	: 80391494QMY
Assignment Date	: 11/12/2017	Excess	: S\$1,500.00
Date of Inspection	: 11/12/2017	Est. Duration of Repair	: 10.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (UBI) 17 UBI ROAD 4 SINGAPORE 408611		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	22,327.46
Revised Amount	:S\$	9,573.00
Check Items (Estimated)	:S\$	8,451.67
Total	:S\$	18,024.67

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	93,000.00
COE / PARF Rebate	:S\$	73,126.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,874.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 12 Dec 2017

Preliminary Advice

Vehicle No	: SFA1001P	Accident Date	: 05/12/2017
Make	: TOYOTA 86	Policy No.	: 80391494QMY
Assignment Date	: 11/12/2017	Excess	: S\$1,500.00
Date of Inspection	: 11/12/2017	Est. Duration of Repair	: 10.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (UBI) 17 UBI ROAD 4 SINGAPORE 408611		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	22,327.46	
Revised Amount	:S\$	9,543.00	9543
Check Items (Estimated)	:S\$	8,451.67	
Total	:S\$	17,994.67	18,024.67
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	93,000.00
COE / PARF Rebate	:S\$	73,126.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,874.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	8372J
Vehicle Details	
Vehicle No.	SFA1001P
Vehicle to be Exported	No
Intended De-registration Date	12 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	TOYOTA 86 HIGH GRADE AUTO
Primary Colour	White
Manufacturing Year	2013
Engine No.	FA20H837848
Chassis No.	JF1ZN6K72EG018621
Maximum Power Output	147.0 kW (197 bhp)
Open Market Value	\$31,104.00
Original Registration Date	23 Dec 2013
First Registration Date	23 Dec 2013
Transfer Count	0
Actual ARF Paid	\$35,546.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	22 Dec 2023
PARF Rebate Amount	\$26,659.00
Intended COE Rebate Details	
COE Expiry Date	22 Dec 2023
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$77,100.00
COE Rebate Amount	\$46,467.00
Total Rebate Amount	\$73,126.00

The information contained herein is correct as at 12 Dec 2017

OK

Items Search for an item, user or group



bankbazaar.sg



Save more on dining nights

This December, get S\$100 CapitaVouchers upon credit card approval*

APPLY NOW

< Cars for Sale (/categories/cars-32/cars-for-sale-1173/)



Toyota 86 2.0 Auto S

Used

matchingcars (/matchingcars/)

S\$86,888

Singapore

Buy now

Chat with Seller (/login/?next=/inbox/new/134689161/)

♥ 93

Share This With Friends

Twitter

G+

Peak%2520Car%3A%2520NoRebate%2520Info%3ACOE%2520Expiry%3A%252016%2520Jun%25202020OMV%3A%2520S%2429%2C504ARF%3A%2520S%2433%2C306QP%2520Paid%2520(COE)%3A%25

Description

Comments (0)

Depreciation: S\$12,493.11

Original Registration Date: 11 Jun 2013

Vehicle Info:

Age: 4 years 5 months
Mileage: 78,844km
Engine Capacity: 1998cc
Max Power Output: 197bhp
Propellant: Petrol
Off-Peak Car: No

Rebate Info:

COE Expiry: 10 Jun 2023
OMV: S\$29,504
ARF: S\$33,306
QP Paid (COE): S\$61,700

Road Tax: S\$1,210

Road Tax Expiry: 10 Dec 2017

Loan Estimation:

Based on MAS Guidelines of min 30% downpayment.
Industry Interest Rate: 2.98%
Max Loan Term: 67 months
Min Downpayment: S\$26,066.40
Est Monthly Instalment: S\$1,058.83
These values are estimated for you as a buyer service. Please check with the seller for actual terms.

Description:

Condition Good. Call us today to Arrange Viewing. Cheapest in town

Features:

Powered by 2L 4 Cylinder DOHC Boxer Engine Producing 197bhp, 205NM of Torque, Traction Control, Twin Exhaust.

Accessories:

Fabric Body Hugging Sports Seats Nice Trimmings. Lightweight Alloy Rims with Original TRD Bodykit, Retractable Side Mirror, VSC Sport Mode, USB, AUX.

Sales Contact:

Roger Loh
tel:88086789

Fida -

tel:90733877

Listed on Oct 25, 2017

MEET THE SELLER

Matching Cars Services



0 0 0 0

(/matchingcars/)

Drive away a **brand new car** from monthly rates at **\$1,200** onwards!

Rock-bottom
monthly
repayments



OTHERS ALSO VIEWED

BMW Z4 Coupe 3.0si Auto
S\$6,500

 chaiglapautotrading
4 days ago
(/chaiglapautotrading/)

38 ❤️

Subaru WRX 2.5 Manual STI
S\$13,300

 alvios
11 days ago
(/alvios/)

108 ❤️

MOTOR ACCIDENT REPORT

Date Of Report: 7/12/17 Time: 1150 Date Of Accident: 5/12/17 Time: 8pm
 Exact Location Of Accident: Bedok South Road
 Country/State of Loss: Singapore ☐ / Wilayah Persekutuan ☐ / Selangor ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /
 Johor ☐ / Perak ☐ / Kedah ☐ / Kelantan ☐ / Terengganu ☐ / Pulau Pinang ☐ / Perlis ☐ / Thailand ☐

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SFA1001P Co. Reg. No./for Co. Vehicle/NRIC/PP/FIN No: 5139P3725
 Name Of Registered Owner: Lee Chan Sing
 Mobile Number: 97549721 Alternative No: _____ Email Address: _____

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: P6
 Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify): _____
 Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐
 Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: MSIA
 Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
 Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: _____

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: Juan Zi Yan NRIC/Passport/FIN No: S84610731
 Date Of Birth: 09/07/1984 Occupation: Indoor ☒ Outdoor ☐
 Date Of Driving Pass: 11 Oct 2013 Gender: Male ☐ Female ☒
 Mobile Number: 84082322 Fax No: _____ Alternative No: _____
 Address: 71 Limau Garden, Singapore 467931 Postal Code: _____
 Email Address: Aliedzy@gmail.com
 Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured: Spouse
 Vehicle Registration Number of Driver's Own Vehicle (if applicable): _____
 Insurance Company of Driver's Own Vehicle (if applicable): _____

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: MCA Accident
 Weather Conditions: Clear ☒ Raining ☐ Others ☐ (if others, please state condition): _____
 Road Surface: Wet ☐ Dry ☒ Others ☐ (if others, please state condition): _____
 Was any body injured in the Accident? No ☒ Yes ☐ No. of Passengers (incl driver in your vehicle): _____
 Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: _____ Vehicle type: _____
 Was any other material or property (e.g. other vehicle) damaged? No ☒ Yes ☐
 Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☒ Yes ☐
 Was the accident reported to the police? No ☒ Yes ☐ (if yes, please state which Police Station): _____
 Was notice of intended Prosecution given? No ☒ Yes ☐ (if yes, please state against whom): _____
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☐ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: _____ Vehicle Make/Model/Colour: _____
 Details Of Properties Damage In Accident: _____
 Name of Driver: _____
 NRIC/Passport/FIN Number: _____ Contact Number: _____
 Address: _____ Postal Code: _____
 Insurance Company Name: _____
 Nature Of Damage: _____ No. Of Passenger (Including Driver): _____

DETAILS OF ACCIDENT INDEPENDANT WITNESS

Name: _____ Name: _____
 Phone Number: _____ Phone Number: _____
 Email Address: _____ Email Address: _____

DETAILS OF INJURED PERSON 1 (Please fill Annex A if more person injured)

Name: _____ Approximate Age: _____
 Address: _____ Postal Code: _____
 Injuries Sustained: _____ Injured person in which vehicle: _____
 Were seat belt worn? No ☐ Yes ☐ Were injured conveyed to hospital by ambulance? No ☐ Yes ☐

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/12/2017 15:25
Date Of Accident	05/12/2017 20:00
Exact Location Of Accident	BEDOK SOUTH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFA1001P
Insured/Policyholder	
Name Of Registered Owner	LEE CHOON SING
NRIC No	S1398372J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97549721
Alternative Phone No	OFFICE-97549721

Vehicle Particulars

Manufacturer	TOYOTA
Model	86-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	DUAN ZIYAN
NRIC No	S8461073I
Date Of Birth	09/07/1984
Occupation	INDOOR
Date Of Driving Pass	11/10/2013
Driving Experience	4 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-84082322
Fax Number	
Contact Number	
Email Address	ALICEDZY@GMAIL.COM

Address	71 LIMAU GARDEN
Postcode	467931
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



This image shows a full page of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page, leaving small margins at the top and bottom. There is no handwriting or other markings on the paper.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature (If driver is not you, please print name of driver)
& Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre Personnel	
---	--

Describe Circumstances of the Accident

Night-time road condition is dark so accidentally hit
on the kerb.
left side tyre grazed on the side kerb.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Identification Card



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S84610731

Name

DUAN ZIYAN

段自艳

Race

CHINESE

Date of birth

09-07-1984

Country/Place of birth

CHINA

Sex

F



Address

71 LIMAU GARDEN
SINGAPORE 467931

Nationality

CHINESE

Date of issue

02-04-2014

Ident. No. S84610731



9326461



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of the driver; and other motor vehicles $\leq 2500\text{kg}$ 11 Oct 2013

NP 428A



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1398372J



LEE CHOON SING
李俊成

CHINESE
Date of Birth: 10-11-1959
Sex: M
Country of Birth: SINGAPORE




164 JOO CHAT ROAD
SINGAPORE 427438
NAME: S1398372J



Handwritten: S1398372J

Handwritten: 02-02-1994

Handwritten: 1849458

Handwritten: 17.12.1994

Handwritten: 17.12.1994

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S1398372J**

LEE CHOON SING

Birth Date **18 Nov 1959**
 Expiry Date **20 Oct 2003**




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

Class 3 Motor Cars and Motor Tractors the weight of which (including does not exceed 2500 kilograms)

PASS DATE **21 Nov 1977**

Licence No. **S1398372J**



NP 420A

PRICELIST

SUVs & SPORTS



RAV4

4-door SUV

2.0i Elegance

2.0i Premium

CASH PRICE,
EX-FACTORY13,499,000
NOM. (including 10% GST)13,499,000
Subsidized (incl. 10% GST)

FORTUNER

Rating 10.8/10 7 Seater

2.7

20,000

180,000

194,000



TOYOTA 86

2-door 2-seater

R Auto

S Manual

GS Auto

GS Auto - 17" rim

GS Manual

-

160,000

170,000

-

160,000

170,000

-

174,000

178,000

-

175,000

180,000

-

172,000

175,000

RECOMMENDATIONS

Consult our sales engineers for full details.

Upgrade your 86 to:

TRD Aero Kit @ \$7,000

TRD Sports Kit @ \$15,000

TRD Performance Kit @ \$30,000

DRIVE IT YOUR WAY™. WE INVITE YOU TO CHOOSE YOUR UNIQUE TEST DRIVE EXPERIENCE TODAY!

TEST & DRIVE

- 1. Drive your way with a 10-minute test drive at any Toyota World.
- 2. Reserve a 10-minute test drive at any Toyota World by calling 1800 100 1000 or visiting www.toyota.com.sg.
- 3. Reserve a 10-minute test drive at any Toyota World by calling 1800 100 1000 or visiting www.toyota.com.sg.
- 4. Reserve a 10-minute test drive at any Toyota World by calling 1800 100 1000 or visiting www.toyota.com.sg.
- 5. Reserve a 10-minute test drive at any Toyota World by calling 1800 100 1000 or visiting www.toyota.com.sg.
- 6. Reserve a 10-minute test drive at any Toyota World by calling 1800 100 1000 or visiting www.toyota.com.sg.
- 7. Reserve a 10-minute test drive at any Toyota World by calling 1800 100 1000 or visiting www.toyota.com.sg.

10

MINUTES

5

MINUTES

TOYOTA

WORLD

DRIVE

YOUR WAY

	LABOUR	PARTS
30	135.6	820.33
	339	45.22
	339	1423.15
	3051	8.9
	1112	121.04
	508.5	398.65
	266	45.9
	5751.1	865.98
		62.73
		3791.9

total revise
9543 9573

CHECK ITEM

1356	335.15
	714.17
	10.45
	592.28
	430.52
	12.58
	346.97
	86.7
	881.11
	33.15
	33.15
	13.94
	31.36
	896.41
	8.84
	10.45
	2349.91
	20.91 total check item
	13.94 8451.67 /
	12.24
	12.24
	51.68
	9.43
	167.19
	10.45
	10.45
	7095.67

Check + Revise
17994.67



Reg No : 196700086Z
 ST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
 www.toyotasingapore.com.sg
 17 Ubi Road 4
 Singapore 408611
 Tel no.: 631 1188

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUAI	Mr. Lee Chuan Sing 194 "150" Christ Road Singapore 427438 Mobile: 97549721
	Document No 0	
	Document Date 2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BKE7	SI	23/12/2013	SFA1001P	20636	15660	70D/SFA1001P/05121

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JF12N6K72E3018621	FA20H837848	60	Sam San Jol	07/12/2017 13.30	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUNDRIES OD CLAIM				30.00
		POLICY NO.: ACC DATE:05/12/2017				
		DRIVE IN:07/12/2017 EXCESS:\$1500				
		DATE-IN:06/12/2017 DATE SURVEY:				
		NO OF REPAIR DAYS:				
		BY: AUTHORIZED ON:				
2	S	BP-SUBLET REPLACE FRT BOTH SPORT RIM & CONDUCT WHE				1356 271.20
		EL BALANCE				
3	B	BP-MECH CONDUCT FULL WHEEL ALIGNMENT				339.00
4	S	BP-SUBLET REMOVE & INSTALL AIRCON CONDENSER ASSY A				339.00
		ND CHARGE UP GAS				
5	S	BP-SUBLET REPLACE & INSTALL FRT SUSPENSION SYSTEM				(1017) ? 1356.00
		ASSY				
6	S	BP-SUBLET REPLACE FRT BUMPER, AIRCON CONDENSER, RADI				3051 4068.00
		ATOR, ETC STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED A				
		REAS				
7	S	BP-SUBLET RESPRAY JOB ON FRT & LH SIDE ACCIDENT AF				1112 2224.00
		FECTED ARE				
8	B	BP-MECH RESET ECU AND REPROGRAMME - repair.				NN X 508.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

KK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation

TO SECURITY GUARD Third party survey is on a "Without Prejudice" basis 07/12/2017

PLEASE ALLOW THE UNDERMENTIONED DATE 16:16

VEHICLE TO LEAVE THE COMPANY PREMISES. No illegal modification(s) is allowed TIME

Signature: Insurance Company

VEHICLE NO SFA1001P

CUSTOMER Signature: SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Not Authorized
 Excess \$1500

10 Days.

before paint photos.
 resurvey check items.

GucQir
 82880282

11/12/17



Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasg.com.sg
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1198

o Reg No : 196700086Z
IST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004/ICCUA1	Mr. Lee Choon Sing 164 Joo Chiat Road Singapore 427438 Mobile: 97549721
	Document No 0	
	Document Date 07/12/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BKE7	S1	23/12/2013	SFA1001P	20636	15660	70D/SFA1001P/05121

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JF1ZN6K72EG018621	FA20H837848	60	Sam San Jui	07/12/2017 13:00	--/--/----	0:00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	8	BP-SUBLET REPLACE FRT LH & RH TYRE MICHELIN (215/45/R17)	1	PC 1380	3%	760.00
10	1	TSU003-01482 BUMPER PUNCHING F	1.00	965.10	15.00	820.33
11	2	TSU003-01534 SEALING BMPR	1.00	53.20	15.00	45.22
12	3	TSU003-00757 DISC WHEEL AL 17	1.00	1674.30	15.00	2846.30
13	4	TSU003-02793 BOLT FLG M6X16	5.00	2.10	15.00	8.90
14	5	TSU003-00371 STRUT COMPL F	1.00	394.30	15.00	335.15
15	6	TSU003-00354 ARM ASSY F	1.00	840.20	15.00	714.17
16	7	TSU003-00359 PLATE ARM F	1.00	12.30	15.00	10.45
17	8	TSU003-07497 HOUSING F	1.00	696.80	15.00	592.28
18	9	TSU003-00782 HUB UNIT COMPL F	1.00	506.50	15.00	430.52
19	0	TSU003-04597 RPR KIT TIE ROD	1.00	14.80	15.00	12.58
20	1	TSU003-00391 STABILIZER F	1.00	408.20	15.00	346.97
21	2	TSU003-00394 STABILIZER LK F	1.00	102.00	15.00	86.70
22	3	TSU003-00348 CROSS MBR COMPL F	1.00	1036.60	15.00	881.11
23	4	TSU003-07500 SUB FRM COMPL LH	1.00	142.40	15.00	121.04
24	5	TSU003-07499 SUB FRM COMPL RH	1.00	142.40	15.00	121.04
25	6	TSU003-01383 UNDER COVER F AL	1.00	469.00	15.00	398.65
26	7	TSU003-01385 UNDER COVER F SD LH	1.00	39.00	15.00	33.15
27	8	TSU003-06141 UNDER COVER F SD RH	1.00	39.00	15.00	33.15

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3566707

O SECURITY GUARD

DATE 07/12/2017
TIME 16:16

3566707

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SFA1001P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motor



Reg No : 196700086Z
 ST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Lee Chuan Sing 164 Joo Chiat Road Singapore 427438 Mobile: 97549721
	Document No 0	
	Document Date 07/12/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BRE7	S1	23/12/2013	SFA1001P	20636	15660	70D/SFA1001P/US121

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JF12N6K72EG018621	FA20H837848	60	Sam San Jai	07/12/2017 13.00	/	/ 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
28	9	TSU003-02984 CLIP BMRP X MC. X NN	10.00	5.40	15.00	45.90
29	0	TSU003-01386 UNDER COVER F SDRH X	1.00	16.40	15.00	13.94
30	1	TSU003-01364 RAD PNL COMPL RPR	1.00	1018.80	15.00	865.98
31	2	TSU003-01221 PLATE AIR INTAKE X	1.00	36.90	15.00	31.36
32	3	TSU003-02116 CONDENSER ASSY X R/BT	1.00	1054.60	15.00	896.41
33	4	TSU003-02117 BRKT LH X NN	1.00	10.40	15.00	8.84
34	5	TSU003-02118 BRKT RH X NN	1.00	12.30	15.00	10.45
35	6	TSU003-01172 RADIATOR ASSY X R/BR	1.00	2764.60	15.00	2349.91
36	7	TSU003-01192 PACKING RAD UPR X	1.00	24.60	15.00	20.91
37	8	TSU003-01194 PACKING RAD LWR X	1.00	16.40	15.00	13.94
38	9	TSU003-01193 PACKING RAD SD LH X NN.	1.00	14.40	15.00	12.24
39	0	TSU003-01195 PACKING RAD SD RH X	1.00	14.40	15.00	12.24
40	1	TSU003-01189 HOSE RAD OUT X	1.00	60.80	15.00	51.68
41	2	TSU003-02996 CLAMP HOSE D38.5 X	1.00	11.10	15.00	9.43
42	3	TSU003-01175 SHROUD X	1.00	196.70	15.00	167.19
43	4	TSU003-01177 BRKT RAD UPR X	1.00	12.30	15.00	10.45
44	5	TSU003-01176 BRKT RAD UPR X	1.00	12.30	15.00	10.45
45	6	S08889-80102 COOLANT, ALLC&S X MC.	1.00	73.80	15.00	62.73

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

20956.13

For on behalf of Borneo Motors	Customer's Signature	Change Summary	Total GST 7.00%
	Please acknowledge receipt of vehicle	Parts 12,431.76	1,562.92
		Labour 877.50	0.00
		Materials 9,018.20	
		Lubrication/Fluid 0.00	
		Others 0.00	
			Amount Due 23,890.38

PLEASE TEAR ALONG PERFORATED LINE

3566708

O SECURITY GUARD

3566708

LEASE ALLOW THE UNDERMENTIONED
 EHICLE TO LEAVE THE COMPANY PREMISES.

DATE 07/12/2017
 TIME 16:16

VEHICLE NO SFA1001P

:CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motor

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
Attn: Motor Claims Dept

S1000004 /ICCUA1

39006158

13/02/2018

Mr Lee Choon Sing
164 Joo Chiat Road

Singapore 427438

Mobile: 97549721

13 BRE7 S1 ZN6 23/12/2013 SFA1001P 24329 15660 70D/SFA1001P/05121

JF1ZN6K72EG018621 FA20H837848 60 Sam San Joi 07/12/2017 15.30 05/01/2018 8.19

1	Z	BP-SUNDRY	SUNDRIES	OD CLAIM		30.00
		POLICY NO.: ACC DATE:05/12/2017				
		DRIVE IN:07/12/2017 EXCESS:\$1500				
		DATE-IN:06/12/2017 DATE SURVEY:11/12/2017				
		NO OF REPAIR DAYS:10 DAYS				
		BY:GUO QIANG(LKK) AUTHORISED ON:13/12/2017				
2	S	BP-SUBLET	REPLACE FRT BOTH SPORT RIM & CONDUCT WHE	C25		135.60
		EL BALANCIP0:6001				
3	B	BP-MECH	CONDUCT FULL WHEEL ALIGNMENT	*		339.00
4	S	BP-SUBLET	REMOVE & INSTALL AIRCON CONDENSER ASSY A	A45		339.00
		ND CHARGE UP GAS				
5	S	BP-SUBLET	REPLACE & INSTALL FRT SUSPENSION SYSTEM	A45		1017.00
		ASSY				
6	S	BP-SUBLET	REPLACE FRT BUMPER,AIRCON CONDENSER,RADI	A45		3051.00
		ATOR,ETCSTRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED A				
		REAS				
7	S	BP-SUBLET	RESPRAY JOB ON FRT & LH SIDE ACCIDENT AF	A45		1112.00
		FECTED ARE				
8	V	EXC	Excess element of insurance repair to be	88		-1500.00
		paidby the insured party				

13/02/2018

13:16

SFA1001P

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
Attn: Motor Claims Dept

S1000004 /ICCUA1

39006158

13/02/2018

Mr Lee Choon Sing
164 Joo Chiat Road

Singapore 427438

Mobile: 97549721

13 BKE7 S1 ZN6 23/12/2013 SFA1001P 24329 15660 70D/SFA1001P/05121

JF12N6K72EG018621 FA20H837848 60 Sam San Joi 07/12/2017 15.30 05/01/2018 8.19

9	B	BP-LAB 7)	REPLACE FRT LH TYRE - MICHELIN(215/45/R1	*				266.00
10	1	TSU003-01482	COVER,FR BUMPER		1.00	965.10	15.00	820.33
11	2	TSU003-01534	SEALING BMPR		1.00	53.20	15.00	45.22
12	3	TSU003-02793	BOLT FLG M6X16		1.00	2.10	15.00	1.79
13	4	TSU003-07500	SUB FRM COMPL LH		1.00	142.40	15.00	121.04
14	5	TSU003-01383	COVER,ENGINE UNDER		1.00	469.00	15.00	398.65
15	6	TSU003-01364	SUPPORT,RADIATOR		1.00	1018.80	15.00	865.98
16	7	TSU003-02116	CONDENSER ASSY		1.00	1054.60	15.00	896.41
17	8	TSU003-01172	RADIATOR ASSY		1.00	2764.60	15.00	2349.91
18	9	S08889-80102	COOLANT,SLLC&&&		1.00	73.80	15.00	62.73
19	0	TSU003-00757	DISC WHEEL AL 17		1.00	1674.30	15.00	1423.15
20	1	TSU003-01537	PLATE,FR BUMPER		1.00	22.10	15.00	18.78
21	2	TSU003-01538	PLATE,FR BUMPER		1.00	22.10	15.00	18.78
22	3	TSU003-04308	COVER BMPR LWR F		1.00	77.50	15.00	65.87
23	4	TSU003-01511	STAY,FR BUMPER		1.00	22.50	15.00	19.12
24	5	TSU003-01500	BRKT CTR LWR F		1.00	119.20	15.00	101.32
25	6	TSU003-02985	CLIP 2PIECE D6		2.00	2.50	15.00	4.24
26	7	TSU003-02698	JAR ASSY,W/SHIELD		1.00	126.40	15.00	107.44
27	8	TSU003-01221	PLATE,RADIATOR		1.00	36.90	15.00	31.36

13/02/2018
13:16

SFA1001P

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
Attn: Motor Claims Dept

S1000004 /ICCUA1

39006158

13/02/2018

Mr Lee Choon Sing
164 Joo Chiat Road

Singapore 427438

Mobile: 97549721

13 BKE7 S1 ZN6 23/12/2013 SFA1001P 24329 15660 70D/SFA1001P/05121

JF12N6K72EG018621 FA20H837B48 60 Sam San Joi 07/12/2017 15.30 05/01/2018 8.19

28 9	TSU003-01303	FRAME SD FF SUB CRPL	1.00	158.00	15.00	134.30
29 0	TSU003-00355	ARM ASSY, FR LWR LH	1.00	840.20	15.00	714.17
30 1	TSU003-00372	ABSORBER ASSY, FR LH	1.00	394.30	15.00	335.15
31 2	TSU003-00394	LINK ASSY, STABILIZER	1.00	102.00	15.00	86.70
32 3	TSU003-00780	KNUCKLE, STEERING LH	1.00	696.80	15.00	592.28
33 4	TSU003-00782	HUB SUB-ASSY, FR	1.00	506.50	15.00	430.52

photo { *BT* } *BT.*

COPY DOCUMENT

		14,434.83
9,645.23	GST 7.00%	1,010.44
635.00		0.00
5,654.60		
0.00		
0.00		15,445.27

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

13/02/2018
13:16

SFA1001P

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Dec 2017		11 Dec 2017 14:34 Edit Adj Rpt	S\$15,934.83 Edit Estimates	S\$15,934.83 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LEE CHOON SING , ID: S1398372J, Tel: +6597549721									
Vehicle Reg. No.: SFA1001P		Date of Loss: 05/12/2017 20:00 - :59 [47 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 540137		Policy/Cover Note No.: 80391494QMY (Comprehensive) Coverage: 23/12/2016 - 22/12/2017							
		Excess: S\$1,500.00							
Repairer: Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road 4, 408611 Ubi - Tel: 6631 1858									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/01/2018]									
Driver/Custodian: DUAN ZIYAN (33 / Female), NRIC: S8461073I, Tel: +6584082322									
Adj Asg. Remarks: Please check for any aggravated damages. Please revert. Thanks.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (17/09/2018): Alert - Adj Mandate Approved (S\$15934.83) - SFA1001P - Claim Handler: Clara Mila... - MSIG_SG (13/12/2017): Alert - Adj Mandate Approved (S\$9573.00) - SFA1001P - Claim Handler: Clara Milah...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFA1001P (540137)
OD
Dec 5 2017 8:00PM
[LEE CHOON SING]
Borneo Motors (S) Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)								Thumbnail	Print
1	07/12/17 15:34	Accident Statement								Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	12/12/17 17:26	Adjuster Immediate Advice								Load HTM	
2	14/09/18 14:14	Adjuster Immediate Advice								Load HTM	
									3 per page		☒
Photos/Images											
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	12/12/17 17:27	General View								Load JPG	☒
2	12/12/17 17:27	General View								Load JPG	☒
3	12/12/17 17:27	General View								Load JPG	☒
4	12/12/17 17:27	General View								Load JPG	☒
5	12/12/17 17:27	General View								Load JPG	☒
6	12/12/17 17:27	General View								Load JPG	☒
7	12/12/17 17:27	General View								Load JPG	☒
8	12/12/17 17:27	General View								Load JPG	☒
9	12/12/17 17:27	General View								Load JPG	☒
10	12/12/17 17:27	General View								Load JPG	☒
11	12/12/17 17:27	General View								Load JPG	☒
12	12/12/17 17:27	General View								Load JPG	☒
13	12/12/17 17:27	General View								Load JPG	☒
14	12/12/17 17:27	General View								Load JPG	☒
15	12/12/17 17:27	General View								Load JPG	☒
16	12/12/17 17:27	General View								Load JPG	☒
17	12/12/17 17:27	General View								Load JPG	☒
18	12/12/17 17:27	General View								Load JPG	☒
19	12/12/17 17:27	General View								Load JPG	☒
20	12/12/17 17:27	General View								Load JPG	☒
21	12/12/17 17:27	General View								Load JPG	☒
22	12/12/17 17:27	General View								Load JPG	☒
23	12/12/17 17:27	General View								Load JPG	☒
24	12/12/17 17:27	General View								Load JPG	☒
25	12/12/17 17:27	General View								Load JPG	☒
26	12/12/17 17:27	General View								Load JPG	☒
27	12/12/17 17:27	General View								Load JPG	☒
28	12/12/17 17:27	General View								Load JPG	☒
29	12/12/17 17:27	General View								Load JPG	☒
30	12/12/17 17:27	General View								Load JPG	☒
31	12/12/17 17:27	General View								Load JPG	☒
32	12/12/17 17:27	General View								Load JPG	☒
33	12/12/17 17:27	General View								Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
				☒
34	12/12/17 17:27	General View	 Load JPG	☒
35	12/12/17 17:27	General View	 Load JPG	☒
36	12/12/17 17:27	General View	 Load JPG	☒
37	12/12/17 17:27	General View	 Load JPG	☒
38	12/12/17 17:27	General View	 Load JPG	☒
39	12/12/17 17:27	General View	 Load JPG	☒
40	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
41	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
42	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
43	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
44	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
45	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
46	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
47	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
48	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
49	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
50	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
51	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
52	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
53	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
54	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
55	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
56	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
57	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
58	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
59	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
60	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
61	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
62	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
63	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
64	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
65	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
66	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
67	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
68	14/09/18 14:09	Reinspection Photo	 Load JPG	☒
69	14/09/18 14:10	Reinspection Photo	 Load JPG	☒
70	14/09/18 14:10	Reinspection Photo	 Load JPG	☒
71	14/09/18 14:10	Reinspection Photo	 Load JPG	☒
72	14/09/18 14:10	Reinspection Photo	 Load JPG	☒
73	14/09/18 14:10	Reinspection Photo	 Load JPG	☒
74	14/09/18 14:10	Reinspection Photo	 Load JPG	☒
75	14/09/18 14:10	Reinspection Photo	 Load JPG	☒
76	14/09/18 14:10	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/12/17 14:12	Repair Estimate	 Load PDF	
2	07/05/18 12:16	Request signed DV from w/shop	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 17:27	ESTIMATE	 Load PDF	

Assessment Reports				1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)		Thumbnail	Print
2	14/09/18 14:07	ESTIMATE	1	Load PDF	
3	14/09/18 14:08	SUPPLEMENTARY	1	Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)		Thumbnail	Print
1	07/12/17 15:34	Accident Statement	1	Load HTM	

Photos/Images				3 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)		Thumbnail	Print
1	07/12/17 15:31	Accident Photo	1	Load JPG	☒
2	07/12/17 15:31	Accident Photo	1	Load JPG	☒
3	07/12/17 15:31	Accident Photo	1	Load JPG	☒
4	07/12/17 15:31	Accident Photo	1	Load JPG	☒
5	07/12/17 15:31	Accident Photo	1	Load JPG	☒
6	07/12/17 15:31	Accident Photo	1	Load JPG	☒
7	07/12/17 15:31	Accident Photo	1	Load JPG	☒
8	07/12/17 15:31	Accident Photo	1	Load JPG	☒
9	07/12/17 15:31	Accident Photo	1	Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)		Thumbnail	Print
1	07/12/17 15:31	Accident Sketch Plan	1	Load JPG	☒
2	07/12/17 15:31	Identification Card	1	Load JPG	☒
3	07/12/17 15:31	Identification Card	1	Load JPG	☒
4	07/12/17 15:31	Identification Card	1	Load JPG	☒
5	07/12/17 15:31	Identification Card	1	Load JPG	☒
6	07/12/17 15:31	Accident Sketch Plan	1	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17023458/GTBE2

Date: 25/09/2018

REFERENCE

Insured/Claimant:	LEE CHOON SING	Policy No:	80391494QMY	Claim No:	540137
Date of Loss:	05/12/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFA1001P	Engine No:	FA20H837848
Make & Model:	TOYOTA 86, 2.0 (A)	Chassis No:	JF1ZN6K72EG018621
Reg. Date:	23/12/2013 (Man. Year: 2013)	Odometer:	24324 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$93,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,850.43	9,941.23	5,909.20	37.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,105.70	5,993.60	3,112.10	34.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,956.13	15,934.83	9,021.30	36.15
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	23,456.13	14,434.83	9,021.30	38.46
+ GST 7.00/7.00% (S\$)	1,641.93	1,010.44	631.49	38.46
Nett Amount (S\$)	25,098.06	15,445.27	9,652.79	38.46

INSPECTION

Date of Assignment:	11/12/2017		
Date Inspected:	11/12/2017	Inspected At:	Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road 4 Singapore 408611
Estimated Period of Repair:	10.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2018)
Parts:	M1-COUPE	TOYOTA 86 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFA1001P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH & RH TYRE - MICHELIN (215/45/ R17) (\$380) (30%) (2PCS)	Scratched - 1pc only	760.00 FS	*266.00 FS
2	1		*BUMPER PUNCHING F	Cut	820.33 FS	*820.33 FS
3	1		*SEALING BMPR	Necessary	45.22 FS	*45.22 FS
4	1		*DISC WHEEL AL 17 (2PCS)	Cut-1pc only	2,846.30 FS	*1,423.15 FS
5	1		*BOLT FLG M6X16 (5PCS)	Necessary	8.90 FS	*1.78 FS
6	1		*STRUT COMPL F LH	Not Necessary	335.15 FS	*- FS
7	1		*ARM ASSY F LH	Not Necessary	714.17 FS	*- FS
8	1		*PLATE ARM F	Not Necessary	10.45 FS	*- FS
9	1		*HOUSING F LH	Not Necessary	592.28 FS	*- FS
10	1		*HUB UNIT COMPL F	Not Necessary	430.52 FS	*- FS
11	1		*RPR KIT TIE ROD	Not Necessary	12.58 FS	*- FS
12	1		*STABILIZER F	Not Necessary	346.97 FS	*- FS
13	1		*STABILIZER LK F	Not Necessary	86.70 FS	*- FS
14	1		*CROSS MBR COMPL F	Not Necessary	881.11 FS	*- FS
15	1		*SUB FRM COMPL LH	Bent	121.04 FS	*121.04 FS
16	1		*SUB FRM COMPL RH	Not Necessary	121.04 FS	*- FS
17	1		*UNDER COVER F AL	Deformed	398.65 FS	*398.65 FS
18	1		*UNDER COVER F SD LH	Not Necessary	33.15 FS	*- FS
19	1		*UNDER COVER F SD RH	Not Necessary	33.15 FS	*- FS
20	10		*CLIP BMPR	Not Necessary	45.90 FS	*- FS
21	1		*UNDER COVER F SDRRH	Not Necessary	13.94 FS	*- FS
22	1		*RAD PNL COMPL RPR	Bent	865.98 FS	*865.98 FS
23	1		*PLATE AIR INTAKE	Deformed	31.36 FS	*31.36 FS
24	1		*CONDENSER ASSY	Bent	896.41 FS	*896.41 FS
25	1		*BRKT LH	Not Necessary	8.84 FS	*- FS
26	1		*BRKT RH	Not Necessary	10.45 FS	*- FS
27	1		*RADIATOR ASSY	Broken	2,349.91 FS	*2,349.91 FS
28	1		*PACKING RAD UPR	Not Necessary	20.91 FS	*- FS
29	1		*PACKING RAD LWR	Not Necessary	13.94 FS	*- FS
30	1		*PACKING RAD SD LH	Not Necessary	12.24 FS	*- FS
31	1		*PACKING RAD SD RH	Not Necessary	12.24 FS	*- FS
32	1		*HOSE RAD OUT	Not Necessary	51.68 FS	*- FS
33	1		*CLAMP HOSE D38.5	Not Necessary	9.43 FS	*- FS
34	1		*SHROUD	Not Necessary	167.19 FS	*- FS
35	1		*BRKT RAD UPR	Not Necessary	10.45 FS	*- FS
36	1		*BRKT RAD UPR	Not Necessary	10.45 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*COOLANT , SLLC &&&	Necessary	62.73 FS	*62.73 FS
38	1		*PLATE, FR BUMPER	Necessary	18.78 FS	*18.78 FS
39	1		*PLATE, FR BUMPER	Necessary	18.78 FS	*18.78 FS
40	1		*COVER BMPR LWR F	Cracked	65.87 FS	*65.87 FS
41	1		*STAY, FR BUMPER	Necessary	19.12 FS	*19.12 FS
42	1		*BRKT CTR LWR F	Cracked	101.32 FS	*101.32 FS
43	2		*CLIP 2PIECE D6	Necessary	4.24 FS	*4.24 FS
44	1		*JAR ASSY, W/SHIELD	Deformed	107.44 FS	*107.44 FS
45	1		*FRAME SD FF SUB CRPL	Bent	134.30 FS	*134.30 FS
46	1		*ARM ASSY, FR LWR LH	Bent	714.17 FS	*714.17 FS
47	1		*ABSORBER ASSY, FR LH	Bent	335.15 FS	*335.15 FS
48	1		*LINK ASSY, STABILIZER	Bent	86.70 FS	*86.70 FS
49	1		*KNUCKLE, STEERING LH	Bent	592.28 FS	*592.28 FS
50	1		*HUB SUB-ASSY, FR	Bent	430.52 FS	*430.52 FS
51	1		*SUNDRY	Necessary	30.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					15,850.43	9,941.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE FRT BOTH SPORT RIM & CONDUCT WHEEL BALANCE	New	271.20	135.60
2	CONDUCT FULL WELL ALIGNMENT	New	339.00	339.00
3	REMOVE & INSTALL AIRCON CONDENSER ASSY AND CHARGE UP GAS	New	339.00	339.00
4	REPLACE & INSTALL FRT SUSPENSION SYSTEM ASSY	New	1,356.00	1,017.00
5	REPLACE FRT BUMPER, AIRCON CONDENSER, RADIATOR, ETC STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS	New	4,068.00	3,051.00
6	RESPRAY JOB ON FRT & LH SIDE ACCIDENT AFFECTED ARE	New	2,224.00	1,112.00
7	RESET ECU AND PROGRAMME	New	508.50	0.00
Gross Labour Cost (S\$)			9,105.70	5,993.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >