

ASS. REC. BY:

REF:

C8/CTU7023466/Kgbez

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTU

Date/Time:

11-12-2017 9:05am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 1516T

Insured:

SGT 9160M

at Workshop m/s

Motor Image

Tel:

6703 8104

of

19 Lorong 8 Taa Puyoh

Policy No:

DMPR SN3035971707

Claim No:

SNM17D 06067C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29-11-2017

CA / REV / REP. / REV 24 HRS 'OS'

H.O.D. Endorsement:

Date/Time:

29-11-2017 11:04am

Person Contacted:

Sayed

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 1516T - X
	SGT 9160M - X
12/12	83848.68 Confirmed by email (Red 8 384.88, 9%)

ASS. REC. BY:

REF:

CT21

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: 6 Consistent?: Yes or NoEst. Repairs: 04 days Res. Yes or NoLum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24-HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: \_\_\_\_\_

Colour: \_\_\_\_\_

Sp. Reading: \_\_\_\_\_

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / R/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R/Bal: \_\_\_\_\_

L/Bal: \_\_\_\_\_

D.O.A. \_\_\_\_\_

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/12/17 File pass to Corbin

List 1

12/2/2018

Date/Time, File Pass to?

☐

Prel. Report

☐

Final Report

Date/Time, File Return to?

3)

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS \$

Photos

Others

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$

MER-TP

3848.08

220

220



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17023466/Kqb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 11-12-2017	
		Code : CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJT 9160M	Veh. Inspected	SLG 1516T
Policy No.	DMPCSN3035971707	Coverage (\$)	0.00
Claim No.	SNM17D06067C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	11/12/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	29/11/2017	Inspection Date	11/12/2017
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Reference No. : CS/CTI/7073466/K96  
Policy Type: OD / (TP) / TP RES / TL / EVA

SLG 15167

**Typist**

**(1) Office Assign Form**

C	Reference No.
C	Customer Code
N	Assign From
C	Assign Date
C	Veh No (Inspected)
C	Veh No (Insured)
C	D.O.A
C	Policy No
C	Claim No
C	Insurance Authorisation (CA /REV/REP)
C	Report Type
C	Weekend Charges
N	Survey held at/Repairer
C	Excess

[illegible]

### (1) Assignment Form

- |   |                        |
|---|------------------------|
| C | Vehicle No             |
| C | Regn Month/Year        |
| N | Vehicle Type           |
| N | Make & Model           |
| C | Engine Capacity. (C.C) |
| N | Colour                 |
| C | Odometer. (Sp.Reading) |
| C | Chassis No             |
| N | General Condition      |
| N | Steering               |
| N | Brake                  |
| N | Modification (Modi)    |
| C | Tyre Size              |
| N | Tyre Make              |
| C | Tyre Balance           |
| C | Date of Inspection     |
| N | Survey held            |
| N | Des.of Damages         |

[illegible]

### C Damaged Vehicle Photographs Uploaded

--	--	--	--

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓	
✓	
✓	

C Resurvey photo Uploaded

--	--	--	--

	12/8/18
---	---------

Date \_\_\_\_\_

21/05/2014

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Los Auth'd	Status
Main	11 Dec 2017		11 Dec 2017 09:05				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
<b>Insured:</b>	MOHAMED ALI BIN OTHMAN, ID: S2003964G								
<b>Main Claimant:</b>	HEE CHEE MENG, ID: S6803888Z								
<b>Vehicle Reg. No.:</b>	SLG1516T	<b>Date of Loss:</b>	29/11/2017 14:00 - :59						
<b>Claim Type:</b>	TP / SNM17D06067C02	<b>Policy/Cover Note No.:</b>	DMPCSN3035971707 (Comprehensive) Coverage: 09/11/2017 - 08/11/2018						
<b>Vehicle Reg. No. (Insured):</b>	SJT9160M	<b>Policy No. (Claimant):</b>	2100483084						
		<b>Excess:</b>	S\$0.00						
<b>Repairer:</b>	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038104								
<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
<b>Claimant's Insurer:</b>	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/12/2017]								
<b>Adj Asg. Remarks:</b>	PLEASE PROCEED TO SURVEY AND ARRANGE FOR DIRECT SETTLEMENT.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All Search Tasks Create New Task Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/11/2017 01:42
Date Of Accident	29/11/2017 14:15
Exact Location Of Accident	C T HUB CARPARK LEVEL 2
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG1516T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HEE CHEE MENG
NRIC No	S6803888Z
Email Address	ELBETHEL@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-97323735
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 I-L (SJ) (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100483084
Cover Note Number	

### Driver

Name of Driver	LOW SIAM HONG
NRIC No	S6833883B
Date Of Birth	11/09/1968
Occupation	INDOOR
Date Of Driving Pass	01/11/1993
Driving Experience	24 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER ATTACHED STATEMENT

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJT9160M  
 Vehicle Make/Model/Colour TOYOTA VIOS SILVER  
 Details Of Properties FRONT RH SIDE  
 Name of Driver SITI NORHADIJAH BTE MOHD ALI  
 NRIC/Passport Number S8814734J  
 Contact Number 93213125

Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

#### Details of Witness


Name  
 Phone Number  
 Email Address


## Accident Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

#### Sketch Plan





## Individual Statement

**Describe Circumstances of the Accident**

On 29 Nov 2017 at 2:45 pm I was driving at CT Hub Car Park level 2 (2, Kallang Avenue Singapore 339401) at the exit going down to level 1.

The Exit is 2-way and car B (SITABOM) was coming up to level 2. Coming to the turn, I slowed down and eventually stopped at the turn as the oncoming car B had come too close for me to negotiate the turn. So I looked for the driver of car B to stop. However the driver failed to stop on the brake. According to the driver she apologized for the accident and explained that her slippery shoes had missed the brake pad and hence the car continued to move forward and then hit the right front door of my car.

### Declaration

**We declare the foregoing particulars are true in every respect**

Policyholder Signature / Date & Time

4/17/2017  
4/17/2017  
Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : TOA PAYOH  
CONTACT NO : 64730333  
REFERENCE : INS/IC/CHI/0515/2017  
DATE : 09-DEC-2017

CHINA TAIPING INSURANCE (SINGAPORE)PTE LTD  
3 ANSON ROAD  
#15-00 SPRINGLEAF TOWER  
SINGAPORE S(079909)  
TEL : 6389 6111  
FAX : 6222 1033

OWNER'S NAME : HEE CHEE MENG  
ADDRESS : APT BLK 236A SERANGOON AVENUE 2  
#05-147  
S(551236)  
TELEPHONE NO : 81257333

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100483084  
VEHICLE NO : SLG1516T  
MODEL CODE : SJ5DK7C  
MODEL/YEAR : FORESTER 2.0I-L AWD CVT  
ENGINE NO : FB20Y380782  
CHASSIS NO : JF1SJ5KC5GG076302  
MILEAGE : 1 KM  
DATE IN : 09/12/2017  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : SAYEDINAH ALI\*\*  
ACCIDENT DATE : 29/11/2017

Print Date : 09/12/2017  
Print Time : 11:53:17

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLG1516T  
-----

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE/REPAIR FRT RH DOOR &RR RH DOOR	1120.00	840
2	ZZ/002	RESPRAY FRT RH DOOR & RR RH DOOR	840.00	✓
3	ZZ/003	SUNDRIES	100.00	30
TOTAL LABOUR CHARGES			2060.00	

MOICRIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLG1516T

-----

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT
1	PNL COMPL DR F RH	60009SG0429P	B <sub>1</sub> 720.00	✓	
2	PNL COMPL DR RRH	60409SG0019P	B <sub>1</sub> 1368.00	✓	
3	WSTR OUT DR F RH	61280SG020	Sm 100.80	X	
4	WSTR OUT DR R RH	62280SG020	Sm 100.80	X	
5	TAPE DR SASH F F RH	90422SG000	Sm 5.40	—	
6	TAPE DR SASH F M RH	90422SG020	Sm 18.00	—	
7	TAPE DR SASH F R RH	90422SG040	Sm 18.00	—	
8	TAPE DR SASH R F RH	90422SG060	Sm 18.00	—	
9	TAPE DR SASH R M RH	90422SG080	Sm 10.80	—	
10	TAPE DR SASH R R RH	90422SG100	Sm 14.40	—	
11	GARNISH AY DR F RH	SG121/120 91112SG122	Sm 198.00	X	
12	GARNISH AY DR R RH (SG140/141)	91112SG142	Sm 144.00	X	
SUB TOTAL			2716.20	0.00	0.00
LESS DISCOUNT ( NETT-20 %)			543.24	0.00	0.00
GRAND TOTAL			2172.96	0.00	0.00
OVERALL TOTAL			2172.96		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255 \*

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLG1516T

TOTAL LABOUR CHARGES 2060.00

TOTAL SPARE PARTS CHARGES 2172.96

GRAND TOTAL 4232.96 \* 4632.96

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :  
SURVEYED DATE :  
AUTHORIZED DATE :  
EXCESS CLAUSE : 0.00  
LIABILITY : 0.00  
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Not Authorized  
1.13.1  
Resurvey B4 paint  
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : TOA PAYOH  
CONTACT NO : 64730333  
REFERENCE : INS/IC/CHI/0515/2017  
DATE : 09-DEC-2017

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
3 ANSON ROAD  
#15-00 SPRINGLEAF TOWER  
SINGAPORE S(079909)  
TEL : 6389 6111  
FAX : 6222 1033

OWNER'S NAME : HEE CHEE MENG  
ADDRESS : APT BLK 236A SERANGOON AVENUE 2  
#05-147  
S(551236)  
TELEPHONE NO : 81257333

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100483084  
VEHICLE NO : SLG1516T  
MODEL CODE : SJ5DK7C  
MODEL/YEAR : FORESTER 2.0I-L AWD CVT  
ENGINE NO : FB20Y380782  
CHASSIS NO : JF1SJ5KC5GG076302  
MILEAGE : 33350 KM  
DATE IN : 09/12/2017  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : SAYEDINAH ALI\*\*  
ACCIDENT DATE : 29/11/2017

Print Date : 06/02/2018  
Print Time : 17:03:28

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 6, TOA PAYOH  
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLG1516T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE/REPAIR FRT RH DOOR & RR RH DOOR	1120.00	840.00 ✓
2	ZZ/002	RESPRAY FRT RH DOOR & RR RH DOOR	840.00	840.00 ✓
3	ZZ/003	SUNDRIES	100.00	30.00
4	ZZ/004	TRANSFER 2X DOOR MECHANISM TO FACILITIES REPAIR (Supp).	400.00	400.00 ✓
TOTAL LABOUR CHARGES			2460.00	2110.00

MOTORIMAGE ENTERPRISES PTE. LTD.  
 19 LORONG 8, TOA PAYOH  
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLG1516T

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT
					S/LIST REMARKS
1	PNL COMPL DR F RH	60009SG0429P	720.00		OK
2	PNL COMPL DR RRH	60409SG0019P	1368.00		OK
3	WSTR OUT DR F RH	61280SG020	100.80		X
4	WSTR OUT DR R RH	62280SG020	100.80		X
5	TAPE DR SASH F F RH	90422SG000	5.40		OK
6	TAPE DR SASH F M RH	90422SG020	18.00		OK
7	TAPE DR SASH F R RH	90422SG040	18.00		OK
8	TAPE DR SASH R F RH	90422SG060	18.00		OK
9	TAPE DR SASH R M RH	90422SG080	10.80		OK
10	TAPE DR SASH R R RH	90422SG100	14.40		OK
11	GARNISH AY DR F RH	SG121/120 91112SG122	198.00		X
12	GARNISH AY DR R RH (SG140/141)	91112SG142	144.00		X
SUB TOTAL			2172.60	0.00	0.00
LESS DISCOUNT ( NETT-20 % )			434.52	0.00	0.00
GRAND TOTAL			1738.08	0.00	0.00
OVERALL TOTAL			1738.08		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED



MOTORIMAGE ENTERPRISES PTE. LTD.  
49 LORONG 8, TOA PAYOH  
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLG1516T

NETT ITEM 2172.60  
LESS 20 % -434.52  
NETT AMOUNT 1738.08

LIST ITEM 0.00  
LESS 50 % 0.00  
LIST AMOUNT 0.00

SPECIAL NETT AMOUNT 0.00

S/LIST ITEM 0.00  
LESS 30 % 0.00  
S/LIST AMOUNT 0.00

TOTAL LABOUR CHARGES 2110.00  
TOTAL SPARE PARTS CHARGES 1738.08

TOTAL CHARGES 3848.08  
ADD 7 % GST 269.37

GRAND TOTAL 4117.45

✓ ok



**Motor Image Enterprises Pte Ltd**  
19 Lorong 8 Toa Payoh Singapore 319255  
T (65) 6417 0333 F (65) 6252 5655  
W www.motorimage.net  
Co Reg No: 198702032R

# DISCHARGE VOUCHER

Name of Insured: HEE CHEE MENG

Address of Insured: BLK 236A SERANGGOON AVE 2 #05-147 S(551236)

Name of Repairs: MOTOR IMAGE ENTERPRISES PTE LTD / WORKSHOP

Address of Repairs: NO. 19 LORONG 8 TOA PAYOH SINGAPORE 319225

Place of Accident: CT HUB CAR PARK LEVEL 2

Date of Accident: 29/11/2017 Vehicle No: SLG1516T

Policy No: 2100483084-01 Claim No: \_\_\_\_\_

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of CHINA TAIPING INS settling the repair costs stated above with the said repairers, I/We hereby release and discharge the said insurers from all further obligations and liabilities under the aforesaid policy in respect on and accident involving my/our said motor vehicle on or about the abovementioned date and place.

I/We agree that by virtue of such payment, all my/our rights and remedies in respect of the damages to the said Motor Vehicle are subrogated to the said Insurers in accordance with the laws governing such matters.

I/We hereby grant the said insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefore.  
I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their parts they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:

Company's Chop & Signature

INSURED:

S6803888Z

IC No. & Signature/Company's Chop

SAYEDINAH ALI

Name

HEE CHEE MENG

Name

15/12/2017

Date

15/12/2017

Date

**MotorImage**

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2017		11 Dec 2017 09:05 <a href="#">Edit Adj Rpt</a>	<b>S\$3,848.08</b> <a href="#">Edit Estimates</a>	<b>S\$3,848.08</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]		
Insured:	MOHAMED ALI BIN OTHMAN, ID: S2003964G					
Main Claimant:	HEE CHEE MENG, ID: S6803888Z					
Vehicle Reg. No.:	SLG1516T	Date of Loss:	29/11/2017 14:00 - :59			
Claim Type:	TP / SNM17D06067C02	Policy/Cover Note No.:	DMPCSN3035971707 (Comprehensive) Coverage: 09/11/2017 - 08/11/2018			
Vehicle Reg. No. (Insured):	SJT9160M	Policy No. (Claimant):	2100483084			
		Excess:	S\$0.00			
Repairer:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038104					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]					
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/12/2017]					
Adj Asg. Remarks:	PLEASE PROCEED TO SURBEY AND ARRANGE FOR DIRECT SETTLEMENT.					

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>																				
<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th><th>Priority</th><th>Type</th><th>Task Group</th><th>Subject</th><th>Handler</th><th>Assigned By</th><th>Completed On</th><th>Created On</th><th>Done?</th></tr> </thead> <tbody> <tr> <td colspan="10">No results.</td></tr> </tbody> </table>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.													
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								



























## Claim Documents

\*SLG1516T (SNM17D06067C02)  
[SJT9160M]  
TP  
HEE CHEE MENG  
Nov 29 2017 2:00PM  
[MOHAMED ALI BIN OTHMAN]  
Motor Image Enterprises Pte Ltd











[Upload Documents](#) | 
 [Upload Photos](#) | 
 [Compose New Letter](#)

View [View in Browser ▼](#)

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	30/11/17 01:55	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	30/11/17 01:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	30/11/17 01:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	30/11/17 01:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	30/11/17 01:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	30/11/17 01:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	30/11/17 01:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	30/11/17 01:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/18 12:03	General View	 Load JPG	<input checked="" type="checkbox"/>
2	12/02/18 12:03	General View	 Load JPG	<input checked="" type="checkbox"/>
3	12/02/18 12:03	General View	 Load JPG	<input checked="" type="checkbox"/>
4	12/02/18 12:03	General View	 Load JPG	<input checked="" type="checkbox"/>
5	12/02/18 12:03	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/02/18 12:03	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/02/18 12:03	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/02/18 12:03	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/02/18 12:03	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/02/18 12:03	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
11	12/02/18 12:03	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/12/17 09:01	Quotation/Replacement/Repair invoice	 Load PDF	
2	11/12/17 09:01	E-filed GIA report	 Load PDF	
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	30/11/17 01:53	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	30/11/17 01:53	Individual Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/02/18 16:56	Discharge Voucher	 Load PDF	

## Linked Accident Report Documents

View [View In Browser ▾](#)

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	30/11/17 01:55	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	30/11/17 01:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	30/11/17 01:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	30/11/17 01:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	30/11/17 01:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	30/11/17 01:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	30/11/17 01:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	30/11/17 01:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	30/11/17 01:53	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	30/11/17 01:53	Individual Statement	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CT117023466/KQBE2**Date:** 21/02/2018**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3035971707	
Claimant Vehicle No :	SLG1516T	Insured Vehicle No :	SJT9160M	
Date of Loss:	29/11/2017	Nature of Claim:	TP	Claim No: SNM17D06067C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLG1516T</b>	Engine No:	FB20Y380782
Make & Model:	SUBARU FORESTER, 2.0 i-L (SJ) (A)	Chassis No:	JF1SJ5KC5GG076302
Reg. Date:	22/09/2016 (Man. Year: 2016)	Odometer:	33349 km
Colour:	Metallic Pearl White		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,272.96	1,768.08	504.88	22.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	2,080.00	280.00	11.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,632.96</b>	<b>3,848.08</b>	<b>784.88</b>	<b>16.94</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>324.31</b>	<b>269.37</b>	<b>54.94</b>	<b>16.94</b>
<b>Nett Amount (S\$)</b>	<b>4,957.27</b>	<b>4,117.45</b>	<b>839.82</b>	<b>16.94</b>

**INSPECTION**

Date of Assignment:	11/12/2017	
Date Inspected:	11/12/2017	Inspected At: Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh Singapore 319255
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 14 Feb 2018)

**Parts:** M1-SUV      SUBARU FORESTER 2.0 i-L (SJ) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLG1516T)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*PNL COMPL DR F RH	Bent	720.00 FN	*720.00 FN
3	1		*PNL COMPL DR RRH	Bent	1,368.00 FN	*1,368.00 FN
4	1		*WSTR OUT DR F RH	Serviceable	100.80 FN	*- FN
5	1		*WSTR OUT DR R RH	Serviceable	100.80 FN	*- FN
6	1		*TAPE DR SASH F F RH	Necessary	5.40 FN	*5.40 FN
7	1		*TAPE DR SASH F M RH	Necessary	18.00 FN	*18.00 FN
8	1		*TAPE FR SASH F R RH	Necessary	18.00 FN	*18.00 FN
9	1		*TAPE DR SASH R F RH	Necessary	18.00 FN	*18.00 FN
10	1		*TAPE DR SASH R M RH	Necessary	10.80 FN	*10.80 FN
11	1		*TAPE DR SASH R R RH	Necessary	14.40 FN	*14.40 FN
12	1		*GARNISH AY DR F RH	Serviceable	198.00 FN	*- FN
13	1		*GARNISH AY DR R RH	Serviceable	144.00 FN	*- FN

F=Franchise part, S=SpcNett, N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,816.20</b>	<b>2,202.60</b>
<b>- Nett Item Discount on N Items 20.00/20.00% (\$\$)</b>	<b>543.24</b>	<b>434.52</b>
<b>Total Parts (\$\$)</b>	<b>2,272.96</b>	<b>1,768.08</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE / REPAIR FRT RH DOOR & RR RH DOOR	New	1,120.00	840.00
2	RESPRAY FRT RH DOOR & RR RH DOOR	New	840.00	840.00
3	TRANSFER 2X DOOR MECHANISM TO FACILITATE REPAIR	New	400.00	400.00
Gross Labour Cost (\$\$)			2,360.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >