

22/09/2002

SS. REC. BY:

REF:

183/LPC17023473/Wq6<sup>52</sup>

Special Instruction:

Surveyor: Wilson

ASSIGNMENT (Office)

From (Person): Gerald Pon

of

IPC

Date/Time: 11-12-2017 11:23am

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JRU 1702

Insured:

SKN 2816X

at Workshop m/s

Asia Motorsport

Tel:

67453811

of

568 beylang Road

Policy No:

Claim No:

17/17/17 / VP05 / 020265

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05.12.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

11/12/17 11:32am

Person Contacted:

Mr. Loo

Vehicle: ~~IN~~ OUT

Date/Time	Action/Instruction ( X ) Estimate
	JRU 1702 - X
	SKN 2816X - X
13/12/17@ 10:33am	Gerald informed that the insured had transfer the ownership of vehicle SKN 2816X on 10/10/17.
18/12/17	Submit PRS.


## REF:

### ASSIGNMENT

Date \_\_\_\_\_  
 Estimated Cost \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect vehicle No. 3RU 1702  
 at Worksite No. Asia Motor Sports  
S68, Gaylang Rd.  
 Date \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claim No. \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess \_\_\_\_\_  
 (Client's Record)  
 Make of Veh \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Book or Market Value

IDAC Accident Report	Consistent? Yes or No
----------------------	-----------------------

Q1	Q2	Q3	Q4	Q5	Q6	Q7	Q8	Q9	Q10	Q11	Q12	Q13	Q14	Q15	Q16	Q17	Q18	Q19	Q20	Q21	Q22	Q23	Q24	Q25	Q26	Q27	Q28	Q29	Q30	Q31	Q32	Q33	Q34	Q35	Q36	Q37	Q38	Q39	Q40	Q41	Q42	Q43	Q44	Q45	Q46	Q47	Q48	Q49	Q50	Q51	Q52	Q53	Q54	Q55	Q56	Q57	Q58	Q59	Q60	Q61	Q62	Q63	Q64	Q65	Q66	Q67	Q68	Q69	Q70	Q71	Q72	Q73	Q74	Q75	Q76	Q77	Q78	Q79	Q80	Q81	Q82	Q83	Q84	Q85	Q86	Q87	Q88	Q89	Q90	Q91	Q92	Q93	Q94	Q95	Q96	Q97	Q98	Q99	Q100
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100

Est. Repairs	Days	Res	Yes or No
--------------	------	-----	-----------

Sum	Sum	95	3 Val	Yes or No
-----	-----	----	-------	-----------

CA / REV / REP / 24HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Date	Time	Action	Instruction
------	------	--------	-------------

Van No. JRU 1702      110  
Type M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make  
Color Black - Yellow      Insured / Std / Nil / NA  
Se. Reading 28734      \* Se. Insured / Std / Nil / NA  
Eng. No.  
City  
Gen. Cond. Good / Fair / Poor / Burnt  
Steering Inorder / Jammed / Leaked / Burnt or  
Brake Inorder / Jammed / Leaked / Burnt or  
Mod. Nil / S/Rim / STD A/Rim or  
Tyre Size F: 2.25-17  
R: 80/90-17

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO of *Keen*

$$\frac{1}{2} \quad \frac{1}{3}$$

DOA 2011/12/25

Survey held at: As Above. 2-02pm

Des of Damages (Frt) / Rear / O/S (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 10 DEC 2017

18/12 1998 ☐ : Prelim. Report  
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip

Survey Fee

\*  $\frac{1}{2} \times \frac{1}{2} = \frac{1}{4}$

Add Fee:	<input type="text"/>	Site Insp	\$
	<input type="text"/>	Interview	\$
	<input type="text"/>	Test Insp	\$
	<input type="text"/>	Travel	\$

Report Format: *PKS*

Lump Sum / I.B. 1.5

# Survey Department Check List (Case Handler)

Reference No.: 183/LPC17023473/1096  
Policy Type: OD / TP / TP RES / TL / EVA

JRU 1702

Case Handler

Typist

**Admin** ( Cather ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor** ( Wilson ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

18/12/17



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC17023473/Wqb

300 BEACH ROAD

#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 11-12-2017

Code : LPC2



## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKN 2816X	Veh. Inspected	JRU 1702
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17/VP05/020265	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	11/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	05/12/2017	Inspection Date	11/12/2017
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

**Catherine Chong (LKK Auto)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Monday, 11 December, 2017 11:23 AM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** PRE-REPAIR SURVEY OF JRU1702  
**Attachments:** 11122017105702.pdf

Our Ref : 17/17/17/VP05/020265

Dear Catherine,

Kindly see attached and proceed accordingly.

For your information, our insured has yet to lodge a report.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

**ASIA MOTORSPORTS SOLUTION PTE LTD**

Specialise in sales of new &amp; reconditioned bikes

Co. Reg. No: 200507766N

No. 568, Geylang Road Singapore 389514 Tel: +65 6745 3811 Fax: +65 6746 5110 Website: www.asiamotorsports.com.sg

Your Ref: 17/17/17/VP05/020265

Our Ref: JRU 1702

11 December 2017

Lonpac Insurance Bhd  
100 Beach Road  
#19-00 Shaw Tower  
Singapore 189702

Attn: Claims Department

Dear Sir/Mdm,



**PROPERTY CLAIM  
(WITHOUT PREJUDICE  
TO: Any Personal Injury  
Claims)**

**ACCIDENT INVOLVING JRU 1702 & SKN 2816 X ON 5 DECEMBER 2017 - CALL FOR PRE-REPAIR INSPECTION**

Thank you so much for your reply dated 11 December 2017. Unfortunately, we are unable to reach a compromise on the appointment of a Single Joint Expert. As such, we will be appointing one motor surveyor from our proposed list to conduct the survey on our client's damaged vehicle.

We are also sending out this letter as a call for pre-repair inspection to your kind office.

As we/our client are unable to wait indefinitely, kindly note that if we do not hear from you by **13 December 2017 (Wednesday), 1030H**, we will proceed with the necessary repair on our client's damaged vehicle.

Our address is 568, Geylang Road Singapore 389514.

Thank you and we hope to hear from you soonest.

Regards,  
Asia Motorsports Solution Pte Ltd  
568 Geylang Road  
Singapore 389514

6745 3811  
6746 5110 (fax)  
asiamotorsports@hotmail.com

---

For Internal Reference

Sent on: 11/12/2017, 1025H

## Shiau Chan (LKKAuto)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Wednesday, 13 December, 2017 10:33 AM  
**To:** 'GERALD POH WEE BIN'; SUR  
**Cc:** assignments  
**Subject:** FW: PRE-REPAIR SURVEY OF JRU1702  
**Attachments:** 12122017143726.pdf

Dear Mr Gerald,

Thank you for your email.

Dear Shiau Chan,

**FYNA. Our Ref: CS3/LPC17023473/Wqb**

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]  
**Sent:** Tuesday, 12 December, 2017 2:42 PM  
**To:** Catherine Chong (LKK Auto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>  
**Subject:** RE: PRE-REPAIR SURVEY OF JRU1702

Dear Catherine,

Please see attached and close your file.

Is there any survey fee incurred ?

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]  
**Sent:** Monday, 11 December, 2017 11:34 AM  
**To:** GERALD POH WEE BIN; [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** MT\_Claim\_SG; [sur@lkkauto.com](mailto:sur@lkkauto.com)  
**Subject:** RE: PRE-REPAIR SURVEY OF JRU1702

Dear Mr Gerald,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

**Sent:** Monday, 11 December, 2017 11:23 AM

**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

**Subject:** PRE-REPAIR SURVEY OF JRU1702

Our Ref : 17/17/17/VP05/020265

Dear Catherine,

Kindly see attached and proceed accordingly.

For your information, our insured has yet to lodge a report.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

10 Sin Ming Drive Singapore 575701  
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

Our ref: 1010170501N001891190

10 Oct 2017

JOHARI BIN CARY  
APT BLK 531 CHOA CHU KANG STREET 51  
#03-319  
SINGAPORE 680531



Dear MR JOHARI BIN CARY

**NOTIFICATION ON TRANSFER OF OWNERSHIP FOR VEHICLE NO. SKN2816X**

We are pleased to inform you that your application to transfer ownership of the above-mentioned vehicle has been approved. You are no longer the registered owner of the vehicle with effect from 10 Oct 2017. The details are as follows:

Vehicle No.	: SKN2816X
Application Date	: 10 Oct 2017
Effective Transfer of Ownership Date	: 10 Oct 2017
Vehicle Make	: HONDA
Vehicle Model	: FREED 1.5G A
Chassis No./Trailer Chassis No.	: GB31030546 / -
Engine No./Motor No.	: L15A2330912 / -

2. Please contact our customer service officers at tel: 1800-CALL LTA (1800-2255 582) should you require further assistance.
3. Thank you.

Yours sincerely

NG LAY CHOO (MS)  
DEPUTY DIRECTOR, VRL SERVICE OPERATIONS  
VEHICLE SERVICES GROUP  
LAND TRANSPORT AUTHORITY

(This is a computer-generated notice that requires no signature.)

From 15 February 2017, you do not need to display road tax disc on the windscreen of your vehicle. LTA has stopped issuing physical road tax discs as part of our efforts to streamline our processes. Please ensure that your original motor insurance certificate is readily available in your vehicle at all times. If you are driving into Malaysia, you are advised to carry printed proof of the validity of your road tax in your vehicle.

10 Sin Ming Drive Singapore 575701  
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

06 Oct 2017



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

<b>PRE-REPAIR INSPECTION REPORT</b>			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC17023473/Wqbs2 Date: 21-12-2017 Code: LPC2	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SKN 2816X	Veh. Inspected	JRU 1702
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17/VP05/020265	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	11/12/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	110
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	YELLOW
Odometer	28734 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	2.25-17	KENDA	2 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	KENDA	3 mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.			
<b>5. General Information</b>			
Accident Date	05/12/2017	Inspect Date / Time	11/12/2017 ( 02:02 PM )
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC17023473/Wqbs2

Inspected By



WILSON TEO CHENG MING

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.