

27/03/2002

SS. REC. BY:

REF: CS/MS617023477/Kvb2 Special Instruction:

SURVEYOR: Kenneth ASSIGNMENT (Office)

From (Person): Katherine Wong of MS47 Date/Time: 11.12.2017 2.11 pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGH 3448Y Insured: SJV 4853U

at Workshop m/s MBM Wheelpower Tel: 9328 8668

of 160 Sin ming Drive #06-02

Policy No: A38984372 MCX Claim No: 539601

Sum Insured: Excess:

Make of Veh: D.O.A. 04/22017

(Client's Record) 12.12.2017

CA / REV / REP. / REV 24 HRS Wp H.O.D. Endorsement:

Date/Time: 11.12.2017 2.13pm Person Contacted: Danny Vehicle IN / OUT

| Date/Time | Action/Instruction ( ✓ ) Estimate                    |
|-----------|--|
|           | SGH 3448Y - X  |
|           | SJV 4853U - red / alt 11023825 / Gsr / DCA: 18-11-11 |
| 13/12/17  | Send preli revised by merimen                        |
| 12/1      | 21 Lys 8 2650r Cufm (Red 1277.75, 30%)               |

SINCE

merimen

## ASSIGNMENT

From: \_\_\_\_\_ Date: 12.12.2017

Estimated Cost: \_\_\_\_\_

OD / P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGH 3448Y

at Workshop m/s: MRM Wheelpower

of: 160 Sin Mng Dye #06-02

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)


Make of Veh: \_\_\_\_\_

Darryl

Manning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Wpr

Date: 5/21

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SGH 3448Y Yr Regn: 06 06

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Car C.C. 1584Colour: 2. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 406058 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JMYSTCS3A6U 009P37

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 4/12/17

Rear

R/Bal. 5 mm

L/Bal. 5 mm

D.O.I. 12/12/17

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rec. N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/12 File pass to Catherine

RECEIVED 12 JAN 2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

2) 12/1 - typist

Report Format: merimen

Lump Sum / I.B.I: \$ 2650/-

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp. (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + PS \$

) Photos

) Others

TOTAL

200

10

210

# Survey Department Check List (Case Handler)

Reference No.: CS MSG 17023477 Kvb  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin ( ): Case handler to make sure all information created by the assignment team are ACCURATE.

## (1) Office Assign Form

|   |                                       | Y-Date | N-Date | Y-Date | N-Date |
|---|---------------------------------------|--------|--------|--------|--------|
| C | Reference No.                         | ✓      |        |        |        |
| C | Customer Code                         |        |        |        |        |
| N | Assign From                           |        |        |        |        |
| C | Assign Date                           | ✓      |        |        |        |
| C | Veh No (Inspected)                    | ✓      |        |        |        |
| C | Veh No (Insured)                      | ✓      |        |        |        |
| C | D.O.A                                 | ✓      |        |        |        |
| C | Policy No                             | ✓      |        |        |        |
| C | Claim No                              | ✓      |        |        |        |
| C | Insurance Authorisation (CA /REV/REP) |        |        |        |        |
| C | Report Type                           | ✓      |        |        |        |
| C | Weekend Charges                       |        |        |        |        |
| N | Survey held at/Repairer               | ✓      |        |        |        |
| C | Excess                                |        |        |        |        |

Surveyor ( ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

|   |                        |   |  |  |  |
|---|------------------------|---|--|--|--|
| C | Vehicle No             | ✓ |  |  |  |
| C | Regn Month/Year        | ✓ |  |  |  |
| N | Vehicle Type           | ✓ |  |  |  |
| N | Make & Model           | ✓ |  |  |  |
| C | Engine Capacity. (C.C) | ✓ |  |  |  |
| N | Colour                 | ✓ |  |  |  |
| C | Odometer. (Sp.Reading) | ✓ |  |  |  |
| C | Chassis No             | ✓ |  |  |  |
| N | General Condition      | ✓ |  |  |  |
| N | Steering               | ✓ |  |  |  |
| N | Brake                  | ✓ |  |  |  |
| N | Modification (Modi)    | ✓ |  |  |  |
| C | Tyre Size              | ✓ |  |  |  |
| N | Tyre Make              | ✓ |  |  |  |
| C | Tyre Balance           | ✓ |  |  |  |
| C | Date of Inspection     | ✓ |  |  |  |
| N | Survey held            | ✓ |  |  |  |
| N | Des.of Damages         | ✓ |  |  |  |

## (2) System - (Views/Merimen)

|   |                                      |   |  |  |  |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ |  |  |  |
|---|--------------------------------------|---|--|--|--|

## (3) Workshop Estimate/Assignment Form

|   |   |   |  |  |  |
|---|---|---|--|--|--|
| N | ALL Parts condition                           | ✓ |  |  |  |
| C | Market Value for OD cases                     |   |  |  |  |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) |   |  |  |  |
| C | Days of repair                                | ✓ |  |  |  |
| C | Finalised Amount                              | ✓ |  |  |  |
| C | Re-inspection Cases to Finalize within 5 Days |   |  |  |  |

## (4) System - (Views/Merimen)

|   |                         |   |  |  |  |
|---|-------------------------|---|--|--|--|
| C | Resurvey photo Uploaded | ✓ |  |  |  |
|---|-------------------------|---|--|--|--|

Check By:

VERON

12/1/18

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |                           |                          |            |  |
|--|---------------------------|--------------------------|------------|--|
| MSIG INSURANCE (SINGAPORE) PTE LTD   |                           | Ref : CS/MSG17023477/Kvb |            |  |
| 16 RAFFLES QUAY<br>#24-01 HONG LEONG BLDG SINGAPORE 048581   |                           | Date : 11-12-2017        |            |  |
|  |                           | Code : MSG               |            |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |                           |                          |            |  |
| Insured Veh.   | SJV 4853U                 | Veh. Inspected           | SGH 3448Y  |  |
| Policy No.   | A28984372MCX              | Coverage (\$)            | 0.00       |  |
| Claim No.  | 539601                    | Excess (\$)              | 0.00       |  |
| Assign From  | MERIMEN (KATHERINE WONG)  | Assign Date              | 11/12/2017 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |                           |                          |            |  |
| Make & Model   |                           | c.c                      | 0          |  |
| Engine No.   | HIDDEN                    | Year of Reg.             |            |  |
| Chassis No.  |                           | Colour                   |            |  |
| Odometer   | -                         | Steering                 |            |  |
| Brakes   |                           | Modification             |            |  |
| General  |                           |                          |            |  |
| <b>3. Conditions of Tyres</b>  |                           |                          |            |  |
|  | Size                      | Make                     | Balance    |  |
| R/H Front Tyre   |                           |                          | mm         |  |
| L/H Front Tyre   |                           |                          | mm         |  |
| R/H Rear Tyre  |                           |                          | mm         |  |
| L/H Rear Tyre  |                           |                          | mm         |  |
| <b>4. Description of Damages</b>   |                           |                          |            |  |
|  |                           |                          |            |  |
| <b>5. General Information</b>  |                           |                          |            |  |
| Accident Date  | 04/12/2017                | Inspection Date          | 12/12/2017 |  |
| Survey held at   | 160 SIN MING DRIVE #06-02 |                          |            |  |
| Repairer   | MBM WHEELPOWER PTE LTD    |                          |            |  |
| <b>5a. Remarks</b>   |                           |                          |            |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                           |                          |            |  |

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status   |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 05 Dec 2017 |               | 11 Dec 2017<br>14:11<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

| Main                             | Reference   | Claim Details  | Documents   | Show All |         |             |              |            |       |
|----------------------------------|---|--|---|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>   |   | <b>[Created by insurer]</b>  |   |          |         |             |              |            |       |
| Insured:                         | DHIVYAM WEDDING, Co. Reg. No.: 53351215L  |  |   |          |         |             |              |            |       |
| Main Claimant:                   | GOVINDARAJU RAJENTHIRAN, ID: S0104301C  |  |   |          |         |             |              |            |       |
| Vehicle Reg. No.:                | SGH3448Y  | Date of Loss:  | 04/12/2017 19:00 - :59  |          |         |             |              |            |       |
| Claim Type:                      | TP / 539601   | Policy/Cover Note No.:   | A28984372MCX (Comprehensive)<br>Coverage: 04/07/2017 - 26/07/2018 |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):      | SJV4853U  | Policy No. (Claimant):   |   |          |         |             |              |            |       |
|                                  | Excess:   |  |   |          |         |             |              |            |       |
| Repairer:                        | MBM Wheelpower Pte Ltd (HQ) 160 SIN MING DRIVE #06-02, SIN MING AUTOCITY, 575722 Sin Ming - Tel: 6262 8888            |  |   |          |         |             |              |            |       |
| Handling Insurer:                | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544] |  |   |          |         |             |              |            |       |
| Adjuster:                        | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/12/2017]                                    |  |   |          |         |             |              |            |       |
| Driver/Custodian (Insured):      | NALANGILI S/O APANA (), NRIC: S8311256E, Tel: +6591066401   |  |   |          |         |             |              |            |       |
| Adj Asg. Remarks:                | Car is in, survey by today. Thank You.  |  |   |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b>  |   | <a href="#">View All</a> <a href="#">Compose Case Mail</a>   |   |          |         |             |              |            |       |
| There are no mail for this case. |   |  |   |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b>      |   | <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> |   |          |         |             |              |            |       |
| Due Date                         | Priority  | Type   | Task Group  | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                      |   |  |   |          |         |             |              |            |       |

**LKK Auto Consultants Pte Ltd** (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

|  |   |
|--|---|
| To: MSIG Insurance (Singapore) Pte. Ltd.<br>4 Shenton Way<br>#21-01 SGX Centre 2<br>Singapore 068807 | From: LKK Auto Consultants Pte Ltd<br>51 Ubi Ave 1 #01-25<br>Paya Ubi Industrial Park<br>Singapore 408933 |
| Attn: Katherine Wong Chew Shong  | Date: 13 Dec 2017   |

**Preliminary Advice**

|                    |   |                         |              |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SJV4853U  | Accident Date           | : 04/12/2017 |
| TP Vehicle No      | : SGH3448Y  | Assignment Date         | : 11/12/2017 |
| Make               | : MITSUBISHI LANCER   | Est. Duration of Repair | : 5.00       |
| Date of Inspection | : 12/12/2017  |                         |              |
| Inspection At      | : MBM WHEELPOWER PTE LTD (HQ)<br>160 SIN MING DRIVE #06-02, SIN MING AUTOCITY<br>SINGAPORE 575722 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

|                                 |      |          |
|---------------------------------|------|----------|
| Repairer's Estimate (Gross)     | :S\$ | 3,927.75 |
| Revised Amount                  | :S\$ | 3,342.75 |
| Check Items (Estimated)         | :S\$ | 425.00   |
| Total                           | :S\$ | 3,767.75 |
| Lump Sum Repair                 | :S\$ |          |
| <b>Total Loss Consideration</b> |      |          |
| New for Old Value               | :S\$ |          |
| Pre-Accident Value              | :S\$ |          |
| COE / PARF Rebate               | :S\$ |          |
| Salvage Value                   | :S\$ |          |
| Margin for Repair               | :S\$ |          |

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Enquire PARF/COE Rebate for Registered Vehicle

|   |                          |
|---|--------------------------|
| <b>Vehicle Owner Particulars</b>  |                          |
| Owner ID Type   | Singapore NRIC           |
| Owner ID  | 4301C                    |
| <b>Vehicle Details</b>  |                          |
| Vehicle No.   | SGH3448Y                 |
| Vehicle to be Exported  | No                       |
| Intended De-registration Date   | 13 Dec 2017              |
| Vehicle Make  | MITSUBISHI               |
| Vehicle Model   | LANCER 1.6 A             |
| Primary Colour  | Silver                   |
| Manufacturing Year  | 2006                     |
| Engine No.  | 4G18HJ0925               |
| Chassis No.   | JMYSTCS3A6U009937        |
| Maximum Power Output  | 79.0 kW (105 bhp)        |
| Open Market Value   | \$12,603.00              |
| Original Registration Date  | 08 Jun 2006              |
| First Registration Date   | 08 Jun 2006              |
| Transfer Count  | 0                        |
| Actual ARF Paid   | \$13,864.00              |
| <b>Intended PARF Rebate Details</b>   |                          |
| PARF Eligibility  | Forfeited                |
| PARF Eligibility Expiry Date  | -                        |
| PARF Rebate Amount  | \$0.00                   |
| <b>Intended COE Rebate Details</b>  |                          |
| COE Expiry Date   | 31 May 2021              |
| COE Category  | A - Car (1600cc & below) |
| COE Period(Years)   | 5                        |
| PQP Paid  | \$22,789.00              |
| COE Rebate Amount   | \$15,793.00              |
| <b>Total Rebate Amount</b>  | <b>\$15,793.00</b>       |
| <b>Message</b>  |                          |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                          |

The information contained herein is correct as at 13 Dec 2017



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM



## Enquire Transfer Fee

| Vehicle Details  |                            |                     |                           |
|--|----------------------------|---------------------|---------------------------|
| Vehicle No.  | SGH3448Y                   |                     |                           |
| Vehicle Type   | P10 - Passenger Motor Car  |                     |                           |
| Vehicle Attachment 1   | No Attachment              |                     |                           |
| Vehicle Scheme   | Normal                     |                     |                           |
| Vehicle Make   | MITSUBISHI                 |                     |                           |
| Vehicle Model  | LANCER 1.6 A               |                     |                           |
| Chassis No.  | JMYSTCS3A6U009937          |                     |                           |
| Propellant   | Petrol                     |                     |                           |
| Engine No.   | 4G18HJ0925                 |                     |                           |
| Engine Capacity  | 1584 cc                    |                     |                           |
| Maximum Power Output   | 79.0 kW ( 105 bhp )        |                     |                           |
| Maximum Laden Weight   | 1600 kg                    |                     |                           |
| Unladen Weight   | 1162 kg                    |                     |                           |
| Year Of Manufacture  | 2006                       |                     |                           |
| Original Registration Date   | 08 Jun 2006                |                     |                           |
| Lifespan Expiry Date   | -                          |                     |                           |
| COE Category   | A - Car (1600cc & below)   |                     |                           |
| PQP Paid   | \$22,789.00                |                     |                           |
| COE Expiry Date  | 31 May 2021                |                     |                           |
| Road Tax Expiry Date   | 07 Jun 2018                |                     |                           |
| Inspection Due Date  | 07 Jun 2018                |                     |                           |
| Intended Transfer Date   | 20 Dec 2017                |                     |                           |
| CO2 Emission   | -                          |                     |                           |
| Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use <a href="#">Enquire Road Tax Payable</a> for fee(s) payable.        |                            |                     |                           |
| Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred. |                            |                     |                           |
| Amount Payable   |                            |                     |                           |
|  | Amount Before GST<br>(S\$) | GST Amount<br>(S\$) | Amount After GST<br>(S\$) |
| Transfer Fee   | 25.00                      | -                   | 25.00                     |
| <b>Total Amount Payable</b>  |                            |                     | <b>25.00</b>              |
| Message  |                            |                     |                           |

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                |
|----------------------------|--------------------------------|
| Date Of Report             | 05/12/2017 12:37               |
| Date Of Accident           | 04/12/2017 18:30               |
| Exact Location Of Accident | JUNCTION OF TOA PAYOH LORONG 6 |
| Country/State of Loss      | SINGAPORE                      |

### DETAILS OF OWN VEHICLE

|                             |                              |
|-----------------------------|------------------------------|
| Vehicle Registration Number | SGH3448Y                     |
| <b>Insured/Policyholder</b> |                              |
| Name Of Registered Owner    | GOVINDARAJU RAJENTHIRAN      |
| NRIC No                     | S0104301C                    |
| Email Address               | RAJEN.GOVINDARAJU@WBL.COM.SG |
| Mobile Phone No             | (LOCAL) +65-92471615         |
| Alternative Phone No        | OFFICE-92471615              |

### Vehicle Particulars

|  |              |
|--|--------------|
| Manufacturer   | MITSUBISHI   |
| Model  | LANCER 1.6 A |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE      |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO           |
| If No, Please state action to be taken                                       | THIRD PARTY  |
| Vehicle Category   | PRIVATE CAR  |

### Insurance Company

|                           |               |
|---------------------------|---------------|
| Name of Insurance Company | AVIVA LTD     |
| Type Of Coverage          | COMPREHENSIVE |
| Fleet Policy              | NO            |
| Policy Number             | 10027218      |
| Cover Note Number         |               |

### Driver

|                      |                              |
|----------------------|------------------------------|
| Name of Driver       | GOVINDARAJU RAJENTHIRAN      |
| NRIC No              | S0104301C                    |
| Date Of Birth        | 08/05/1954                   |
| Occupation           | INDOOR                       |
| Date Of Driving Pass | 07/11/1995                   |
| Driving Experience   | 22 YEARS AND 0 MONTHS        |
| Gender               | MALE                         |
| Mobile Number        | (LOCAL) +65-92471615         |
| Fax Number           |                              |
| Contact Number       | OFFICE-92471615              |
| Email Address        | RAJEN.GOVINDARAJU@WBL.COM.SG |

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

ON THE DATE AND TIME MENTIONED, I WAS MAKING A RIGHT TURN AT THE SAID MENTIONED LOCATION WHEN MY VEHICLE WAS HIT FROM THE REAR BY VEHICLE B. NO BODY WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

#### Attachment(s)


Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV4853U  
 Vehicle Make/Model/Colour KIA/CERATO FORTE 1.6SX AT ABS D/AB 2WD 4DR/SILVER  
 Details Of Properties  
 Name of Driver UNKNOWN DRIVER  
 NRIC/Passport Number  
 Contact Number UNKNOWN  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

#### Details of Witness

Name  
 Phone Number  
 Email Address



ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED, I WAS MAKING A RIGHT TURN AT THE SAID MENTIONED LOCATION WHEN MY VEHICLE WAS HIT FROM THE REAR BY VEHICLE B. NO BODY WAS INJURED.

STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

5 December 2017 at 10:20 AM

Date/Time:

5 December 2017 at 10:21 AM

# MBM WHEELPOWER PTE LTD

Your Ref: SJV4853U

Our Ref: SGH3448Y

mbm wheelpower

To: MSIG Insurance (Singapore) Pte Ltd  
No. 16, Raffles Quay  
CC #24-01, Hong Leong Building  
Singapore 048581

Email

Fax

Date: 6/12/2017  
From: Danny  
Fax: 62509015  
Contact: 93288668  
Make / Model: MITSUBISHI LANCER 1.6A  
Chassis No.: JMYSTCS3A6U009937  
Engine No.: 4G15HJ0925  
Year of Make: 2006  
Accident Date: 4 December 2017

ESTIMATE FOR VEHICLE NO.: SGH3448Y

## DESCRIPTION

REAR BUMPER  
REAR BUMPER CLIPS  
BOOTLID  
BOOTLID EMBLEM "LANCER"  
REAR LH TAIL LAMP  
END PANEL

| QTY                      | List Price  |
|--------------------------|-------------|
| 1                        | \$ 800.00 ✓ |
| 10                       | \$ 50.00 ✓  |
| 1                        | \$ 750.00 ✓ |
| 2                        | \$ 35.00 ✓  |
| 1                        | \$ 500.00 ✓ |
| 1                        | \$ 580.00 ✓ |
| Total: \$ 2,715.00       |             |
| LESS 15% \$ (407.25)     |             |
| Parts Total: \$ 2,307.75 |             |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t 62828888 f 64529823

Company Registration Number : 200204110W

**SPECIAL NETT**

REAR BUMPER SENSORS

2

\$ *Shot 200sn* 300.00**LABOUR**TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO  
KNCK-OUT, STRAIGHTEN, ON THE AFFECTED AREAS

\$ 600.00 ✓

TO REMOVE &amp; REPLACE BUMPER SENSORS

\$ 40.00 ✓

TO CHECK &amp; RECONNECT ALL NECESSARY WIRING

\$ *201* 80.00

TO SPRAY PAINTING ON THE AFFECTED AREA

\$ 600.00 ✓

Total: \$ 3,927.75

7% GST: \$ 274.94

**Grand Total: \$ 4,202.69**

Please survey the vehicle at :-  
160 SIN MING DRIVE,  
#06-09 SIN MING AUTOCITY,  
SINGAPORE 575722

(Kindly contact Danny @ 93288668)

**Mbm wheelpower pte ltd**  
160 SIN MING DRIVE  
#06-02  
SIN MING AUTOCITY  
t 62828888 f 64529823

Company Registration Number : 200204110W

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023477/KVBN2

Date: 15/01/2018

## REFERENCE

|                       |                                      |                      |              |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | A28984372MCX |
| Claimant Vehicle No : | SGH3448Y                             | Insured Vehicle No : | SJV4853U     |
| Date of Loss:         | 04/12/2017                           | Nature of Claim:     | TP           |
|                       |                                      | Claim No:            | 539601       |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SGH3448Y                     | Engine No:  | 4G18HJ0925        |
| Make & Model:               | MITSUBISHI LANCER, 1.6 (A)   | Chassis No: | JMYSTCS3A6U009937 |
| Reg. Date:                  | 08/06/2006 (Man. Year: 2006) | Odometer:   | 406058 km         |
| Colour:                     | Metallic Silver              |             |                   |
| Engine Capacity:            | 1584 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/60R15     | Rear Tyre Size:  | 195/60R15     |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 5 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                    | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts                             | 2,607.75   | 2,082.75   | 525.00     | 20.13  |
| Miscellaneous Items               | 0.00       | 0.00       | 0.00       |        |
| Labour                            | 1,320.00   | 1,260.00   | 60.00      | 4.55   |
| Paintwork Labour                  | 0.00       | 0.00       | 0.00       |        |
| Towing                            | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 3,927.75   | 3,342.75   | 585.00     | 14.89  |
| Approved Total (Overridden) (S\$) |            | 2,650.00   |            |        |
| (S\$)                             | 3,927.75   | 2,650.00   | 1,277.75   | 32.53  |
| + GST 7.00/7.00% (S\$)            | 274.94     | 185.50     | 89.44      | 32.53  |
| Nett Amount (S\$)                 | 4,202.69   | 2,835.50   | 1,367.19   | 32.53  |

## INSPECTION

|                     |                          |  |
|---------------------|--------------------------|--|
| Date of Assignment: | 11/12/2017               |  |
| Date Inspected:     | 12/12/2017 Inspected At: | MBM Wheelpower Pte Ltd (HQ)<br>160 SIN MING DRIVE #06-02, SIN<br>MING AUTOCITY<br>Singapore 575722 |

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

### Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 15 Jan 2018)  |
| <b>Parts:</b> 143  | mitsubishi LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)  |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SGH3448Y) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No.   | Qty | Part No. | Particulars            | Condition   | Repairer's | Amount     |
|---|-----|----------|------------------------|-------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER           | Bent        | 800.00 FL  | *800.00 FL |
| 2   | 10  |          | *REAR BUMPER CLIPS     | Necessary   | 50.00 FL   | *50.00 FL  |
| 3   | 1   |          | *BOOTLID               | Bent        | 750.00 FL  | *750.00 FL |
| 4   | 2   |          | *BOOTLID EMBLEM LANCER | Necessary   | 35.00 FL   | *35.00 FL  |
| 5   | 1   |          | *REAR LH TAIL LAMP     | Serviceable | 500.00 FL  | *- FL      |
| 6   | 1   |          | *END PANEL             | Bent        | 580.00 FL  | *580.00 FL |
| 7   | 2   |          | *REAR BUMPER SENSORS   | Shorted     | 300.00 FS  | *200.00 FS |
| F=Franchise part. S=SpcNett. L=ListItemDisc.        |     |          |                        |             |            |            |
| Sub Total (\$\$)                                    |     |          |                        |             | 3,015.00   | 2,415.00   |
| - List Item Discount on L Items 15.00/15.00% (\$\$) |     |          |                        |             | 407.25     | 332.25     |
| Total Parts (\$\$)                                  |     |          |                        |             | 2,607.75   | 2,082.75   |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars   | Lab.Type | Repairer's | Amount   |
|-------------------------|---|----------|------------|----------|
| <u>Labour Items</u>     |   |          |            |          |
| 1                       | TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS.INCLUDING TO KNOCK-OUT,STRAIGHTEN ON THE AFFECTED AREAS | New      | 600.00     | 600.00   |
| 2                       | TO REMOVE & REPLACE BUMPER SENSORS  | New      | 40.00      | 40.00    |
| 3                       | TO CHECK & RECONNECT ALL NECESSARY WIRING   | New      | 80.00      | 20.00    |
| 4                       | TO SPRAY PAINTING ON THE AFFECTED AREA  | New      | 600.00     | 600.00   |
| Gross Labour Cost (S\$) |   |          | 1,320.00   | 1,260.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >