Surveyor Rasal | REF: AXA | 23257 / Rua3 - (4) 1302A

ASSIGNMENT

From: | Date: 18012018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKF 6853D

at Workshop m/s Wearnes

of 249 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Mandy

(Policy Condition) 1pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKF 6853D Yr Regn: 2012 / Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLVO V60T4 1.6A c.c 1596

Colour BLACK A/C: Insured / Std / NI / NA

Sp.Reading 143464 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: YV1FW485BC1066966

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50 ZR17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	01/12/17	D.O.I.	18/01/18

Survey held at WEARNES

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) S + RS SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

TOTAL