

ASS. REC. BY:

REF: CS/CTI17023532/49617

Special Instructions:

SINGAPORE
Menmen 1 Marcus

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI

Date/Time: 11/12/17 @ 5:47 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJC 8142 L

Insured:

at Workshop m/s

Specialists Motor

Tel:

6747 2112

of

Blk 3018A Ubi Rd 7 # 01-24/25/26, 408711

Policy No:

DM PCSN 90.36151707

Claim No:

SNM17D07025 C01

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/12/17

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:18am @ 12/12/17

Person Contacted:

Irene

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

11/12/17 @

SJC 8142 L - X

5:51pm revert to Chong

13/12 @ 17:42

authorise repair by Alfred Toh

14/12 @ 17:42

inform Irene authorise repair confirm \$1600 4s

Surveyor: marcus

REF:

C71/

CS/CT47023337/Urb

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJC8142L
at Workshop m/s spubut.
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: NIL
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$8500
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: ✓ Consistent?: Yes or No
Est. Repairs: 6 days Res.: Yes or No
Lump Sum: 20 % 3 Val.: Yes or No

REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJC8142L Yr Reg: 28/208
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or (A)
Make: Nissan Sunny c.c. 1597
Colour: white AC: Insured / Std / NI / NA
Sp. Reading: 128499 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JN1CFAN1620111260
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil S/Rim / STD A/Rim or
Tyre Size: F: 185/65R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Falken

Front 6 mm Rear 6 mm
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 9/12/17 D.O.I. 12/12/17
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time : _____ Action / Instruction

asky 1800 274 6833 2nd body.11/11 confirmed 2/5 \$1600 with MR NH.
(car # 4634.82, 74%)

RECEIVED: 8 JAN 2018

Date/Time. File Pass to?

☐

Preli. Report

1) 10/1 MPT

☐

Final Report

Date/Time. File Return to?

2) _____

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

) S+RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.T. (\$)

MR NH1600

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

TOTAL

220

220




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17023532/Uqb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 12-12-2017		
		Code : CTI		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SJC 8142L	
Policy No.	DMPCSN9036151707	Coverage (\$)	0.00	
Claim No.	SNM17D07025C01	Excess (\$)	0.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	12/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/12/2017	Inspection Date	12/12/2017	
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No: CS/CT/17073537/1645
 Policy Type: OD / TP / TP RES / TL / EVA

STC 8142L

Case Handler

Typist

Admin (Cathy): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		

Surveyor (Mawa): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

<input checked="" type="checkbox"/>	
-------------------------------------	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

<input checked="" type="checkbox"/>	
-------------------------------------	--

Check By:

[Signature] 10/1/18
 Case Handler Date

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case No.	Submitted	Est. Submission	Adj Assigned	Adj Rpt	Est. Completed	Final Adj.
Main	11 Dec 2017 Sendback Est	11 Dec 2017 15:19 S\$6,192.82	11 Dec 2017 17:47 Assign			
						New Assignment Cancel Case

Reference	Reference	Claim Details	Documents	Show All
-----------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	XU HONGWEI , ID: S7078433E, Tel: +6591167940		
Vehicle Reg. No.:	SJC8142L	Date of Loss:	09/12/2017 22:00 - :59
Claim Type:	OD / SNM17D07025C01	Policy/Cover Note No.:	DMPCSN9036151707 (Comprehensive) Coverage: 01/03/2017 - 28/02/2018
		Excess:	S\$0.00
Repairer:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26, 408711 Ubi - Tel: 6747 2112		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/12/2017]		
Driver/Custodian:	XU HONGWEI (47 / Male) , NRIC: S7078433E, Tel: +6591167940		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Work Date	Priority	Type	Task Name	Subject	Task No.	Assigned By	Completed Date	Completed By	Done
-----------	----------	------	-----------	---------	----------	-------------	----------------	--------------	------

No results.

View Received Message

This mail is associated with :

SJC8142L (SNM17D07025C01)

OD

Dec 9 2017 10:00PM

[XU HONGWEI]

Specialists Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 13/12/2017 17:42 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1600.00) - SJC8142L - Claim Handler: Chong Boon Sen

Approved:1600.00:Please proceed to authorize repairs at \$1,600.00 (lump sum basis) Excess WAIVED.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 12 Dec 2017

Preliminary Advice

Vehicle No	: SJC8142L	Accident Date	: 09/12/2017
Make	: NISSAN SUNNY	Policy No.	: DMPCSN9036151707
Assignment Date	: 11/12/2017	Excess	: S\$0.00
Date of Inspection	: 12/12/2017	Est. Duration of Repair	: 6.00
Inspection At	: SPECIALISTS MOTOR PTE LTD (HQ) BLK 3018A UBI ROAD 1, #01-24/25/26 SINGAPORE 408711		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,192.82
Revised Amount	:S\$	2,007.70
Check Items (Estimated)	:S\$	223.90
Total	:S\$	2,231.60

Lump Sum Repair	:S\$	1,600.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	8,500.00
COE / PARF Rebate	:S\$	6,833.00
Salvage Value	:S\$	
Margin for Repair	:S\$	1,667.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	8433E

Vehicle Details

Vehicle No.	SJC8142L
Vehicle to be Exported	No
Intended De-registration Date	12 Dec 2017
Vehicle Make	NISSAN
Vehicle Model	SUNNY 1.6EXA
Primary Colour	White
Manufacturing Year	2007
Engine No.	QG16428110
Chassis No.	JN1CFAN16Z0111260
Maximum Power Output	81.0 kW (108 bhp)
Open Market Value	\$11,923.00
Original Registration Date	29 Feb 2008
First Registration Date	29 Feb 2008
Transfer Count	1
Actual ARF Paid	\$13,116.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	28 Feb 2018
PARF Rebate Amount	\$6,558.00

Intended COE Rebate Details

COE Expiry Date	28 Feb 2018
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$12,856.00
COE Rebate Amount	\$275.00
Total Rebate Amount	\$6,833.00

The information contained herein is correct as at 12 Dec 2017

OK

Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house?

Sell it on Marketplace. Posting an advertisement is FREE!

Sign up & Get \$10 free

Email Add

Submit Qu

Sign Up New Account

Forgot Password

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



\$2800 Downpayment Monthly

From \$688 Onwards. Lowest

3.88%P.A@GV Cars Financing.

GV Credit Pte Ltd StarAd

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted

20 results/page

2 vehicles

Nissan Sunny

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan Sunny		Any	Any	2008	Any	Any	Any	Available
	Nissan Sunny	1.6A EX	\$10,800	\$7,040 /yr	21-Aug-2008	1,597 cc	-	Sedan	Available
Graded B by STB									
Low Interest At 1.99%. Fully Maintained/Service By Agent. Extremely Low Mileage! Extended Warranty Available! A Reliable Yet Affordable Sedan Built To Give You Comfort And Spacious Interior. Buy It F...									
Dickson Automobile									
Posted: 22-Nov-2017 Tags: 2008 Nissan Sunny, 2008 Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan, Sunny, Sunny, Used Nissan									
	Nissan Sunny	1.6A EX	\$9,800	N.A	03-Apr-2008	1,597 cc	98,000 km	Sedan	Available
What A Unit! 1 Single Owner Only, Low Mileage Of 98k Km Done Only, Can Also Package With 5 Years COE At \$32.8K, Durable And Lasting Japan Sedan, Easy To Maintained, Ideal For Future COE Renewal Upon E...									
Posted: 14-Nov-2017 Tags: 2008 Nissan Sunny, 2008 Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan, Sunny, Sunny, Used Nissan									

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
For old advertisements, view Expired ads									
							20 results/page		

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Nissan Sunny, Nissan Sunny Singapore, used Nissan Sunny Singapore, used Nissan Sunny, used vehicles Singapore or even buy used Nissan Sunny Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
 - New Car
 - Used Car
 - Sell Car
 - Motoring Directory
 - Products Guide
 - Article
 - Forum
 - Tool & Tip
- About Us
 - Careers
 - Contact Us
 - Sitemap

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/12/2017 10:05
Date Of Accident	09/12/2017 22:40
Exact Location Of Accident	JALAN PANDAN TOWARDS LEBUHRAYA PASIR GUDANG
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJC8142L
Insured/Policyholder	
Name Of Registered Owner	XU HONGWEI
NRIC No	S7078433E
Email Address	HOWELXU@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91167940
Alternative Phone No	OTHERS-91167940

Vehicle Particulars

Manufacturer	NISSAN
Model	SUNNY-1.6 EX (A)

Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
--------------------------------------------------------------------	-------------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
------------------------------------------------------------------------------	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN9036151707
Cover Note Number	

Driver

Name of Driver	XU HONGWEI
NRIC No	S7078433E
Date Of Birth	19/07/1970
Occupation	INDOOR
Date Of Driving Pass	26/10/2009
Driving Experience	8 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91167940
Fax Number	
Contact Number	OTHERS-91167940
EMail Address	HOWELXU@YAHOO.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

SSS 64

Policyholder's Signature


Date & Time:

11/12/2017

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20171211/2041

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20171211/2041

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/12/2017 11:40	Vide Report No.:	Station Diary No.:
--------------------------------------------	------------------	--------------------

Informant's Particulars

Name of Informant: XU HONGWEI			Address: APT BLK 210 CHOA CHU KANG CENTRAL #07-156 HDB- CHOA CHU KANG SINGAPORE 680210		
ID Type / ID No.: NRIC NO / S7078433E			Contact No.: Home/Office: Mobile: 91167940		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 47	Date of Birth: 19/07/1970	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SOLUTIONS MANAGER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 09/12/2017 22:40	Type of Location: Bend
Location: Along Road 1 JALAN PANDAN				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJC8142L	Car	NISSAN	SUNNY 1.6EXA	White	Slightly Damaged	1
WMX2569	Car				Slightly Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJC8142L	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN90361517 07	01/03/2017	28/02/2018



**SINGAPORE
POLICE FORCE**



T/20171211/2041

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20171211/2041

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
MUHAMMAD SYUKRI BIN ABU BAKAR

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt TANG SIEW PING
Contact No.: 65476430

Signature Of Informant:

Date/Time:
11/12/2017 11:40

Classification Of Case:



Authentication Stamp
NP168

Signature:

Specialists Motor Pte Ltd
Blk 3018A Ubi Road 1
#01-24/26
Singapore 408711

Claim Reference:
Assessment Number: SM100201
Version: SPECIALM/1
Date Calculated: 11/12/2017 06:58

Full Report - V1
Registration: SJC8142L
Printed: 11/12/2017 16:26

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Specialist Motor	Date of Incident:	09/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN9036151707	Quote Due Date:	
Other Reference:	SM/SJC8142L/1712314	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	NISSAN	4-DOOR	TWO COAT METALLIC
Model:	Sunny	PREPARE OFF VEHICLE	
Sub Model:	SUNNY		
Model Sheet Number:	Z34 86		
Registration:	SJC8142L		
Registration Month:			
Registration Year:			
VIN Number:			
Odometer:	Not Known		
Colour:			
Engine Number:			
Fuel Level:	%		

Not Repaired
hbk
1/5 a
6 dr.
Excess w.c
12/12/17

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	11/12/2017
Pre-Accident Damage:	

Tyres Condition:

Tread Depth LHF:
Tread Depth LHR:
Damage Areas:

Tread Depth RHF:
Tread Depth RHR:
Direction of Impact:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

Specialists Motor Pte Ltd

Claim Reference:
Assessment Number: SM100201
Version: SPECIALM/1
Date Calculated: 11/12/2017 06:58

Full Report - V1
Registration: SJC8142L
Printed: 11/12/2017 16:26



Addresses

Cost Summary

Total Labour	\$1,623.80
Total Paint/Material	\$235.79
Total Parts	\$4,328.23
Excess:	TBA
Grand Total Exc GST:	\$6,187.82
7 % GST:	\$433.15
Grand Total Inc GST:	\$6,620.97

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
8002A1	R + R REAR SCREEN	25.0	115.00 X
	INCLUDES: R + R TAILGATE MOULDINGS		
5300A1	RENEW LEFT REAR SIDE PANEL WITH REAR PANEL	103.0	473.80
	INCLUDES: R + R REAR CUSHION AND REST, WEATHERSTRIPS, TAILLAMPS, BUMPER AND ALL TRIMS IN REPAIR AREA		
5010A1	RENEW REAR BUMPER (REMOVED)	1.0	4.60
6711A1	R + R BOOTLID	4.0	18.40 X
5410A1	RENEW BOOTLID (REMOVED)	17.0	78.20 X
	INCLUDES: TRANSFER ALL ATTACHED PARTS, ADJUST BOOTLID AND APPLY RUST PROOFING		
5511A1	R + R BOTH BOOTLID HINGES	9.0	41.40 X
7701A1	R + R FILLER NECK/HOSE	5.0	23.00
6030A1	RENEW L/R OUTER WHEELHOUSE	14.0	64.40

LABOUR COST

Total Work Units	178.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	17.8HRS	\$818.80
Paint Labour	17.5HRS	\$805.00
Total Labour	35.3HRS	\$1,623.80

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
2711	REAR PANEL NEW PART PAINTING	21.0	

Specialists Motor Pte Ltd

Claim Reference:

Assessment Number: SM100201

Version: SPECIALM/1

Date Calculated: 11/12/2017 06:58

Full Report - V1

Registration: SJC8142L

Printed: 11/12/2017 16:26

3481	L/R WING NEW PART PAINTING	27.0
4161	L/R OUTER WHEELHOUSE SURFACE PAINT	4.0
2979	BOOTLID TRIM NEW PART PAINT K1R	6.0
2583	REAR BUMPER REPAIR PAINT PLASTIC	15.0
2610	CTR REAR BUMPER MLDG REPAIR PAINT PLASTIC	9.0
2611	L/R BUMPER MOULDING REPAIR PAINT PLASTIC	9.0
2612	R/R BUMPER MOULDING REPAIR PAINT PLASTIC	9.0
2721	L/END PANEL TRIM REPAIR PAINT PLASTIC	9.0
2931	BOOTLID REPAIR PAINTING >50%	17 26.0X
3482	R/R WING SURFACE PAINT	7.0

LABOUR COST - PAINT

TIME (PAINT)

Preparation Main Work Plastic	142.0
Preparation Main Work Metal	8.0
Preparation Work Multi Layer Paint	25.0
Total Work Units (10WU/HR)	0.0
Total Paintwork Labour	175.0
	17.5HRS

\$805.00

MATERIAL COST - PAINT

Cost Price

New Part Painting	\$63.25
New Part Painting - Plastic K1R	\$18.70
Material-Constant Main Work Metal	\$28.60
Surface-/Blend Paint	\$19.92
Repair Painting	\$37.53
Repair Painting Plastic	\$55.09
Material-Const Main Work Plastic	\$12.70
Total Excluding Pearlescent Uplift	\$235.79
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$235.79

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1217	2	REAR SCREEN SPACER	72714 BM400		0%	17 8.06U X
2583	1	REAR BUMPER	85022 6N626		0%	215 250.00* ✓
2610	1	CTR REAR BUMPER MLDG	85072 8M100		0%	215 85.00* ✓
2611	1	L/R BUMPER MOULDING	85075 8M100		0%	25 85.00* X
2612	1	R/R BUMPER MOULDING	85074 8M100		0%	25 85.00* X
2625	1	L/R BUMPER DAMPER	85212 4M400		0%	11 70.00* 2X
2650	2	RR BUMPER CLAMP KIT	01553 09611		0%	17 15.00* X
2711	1	REAR PANEL	79110 6N600		0%	515 250.00* ✓
2721	1	L/END PANEL TRIM	78127 8M114		0%	17 18.00* X
2931	1	BOOTLID	H4300 8N8MM		0%	17 320.00* X
2944	1	BOOT/TAILOGATE SEAL	84830 4M400		0%	17 35.00* X
2953	1	L/BOOTLID HINGE	84400 4M500		0%	17 45.00* X
2954	1	R/BOOTLID HINGE	84400 4M500		0%	17 45.00* X
2977	1	BOOT/TAILOGATE LOCK	84630 59C0C		0%	17 38.00* X
2979	1	BOOTLID TRIM	84810 8M107		0%	17 0.00 X
3151	1	REAR SCREEN	79712 4M500 JP		0%	17 850.00* X
3160	1	REAR SCREEN BOND KIT	KE150 10002		0%	17 60.00* X
3161	1	REAR SCREEN SEAL	72712 81402		0%	17 25.83U X
3166	1	REAR WINDOW MOULDING	79750 4M500		0%	17 85.00* X
3281	1	L/R OUTER LAMP	26555 5M427		0%	110 160.00* ✓
3481	1	L/R WING	78113 6N630		0%	1 320.00* X

Specialists Motor Pte Ltd

Claim Reference:

Assessment Number: SM100201

Version: SPECIALM/1

Date Calculated: 11/12/2017 06:58

Full Report - V1

Registration: SJC8142L

Printed: 11/12/2017 16:26

3783	1	L/R AIR VENT GRILLE	76805 2DR0A	0%	YW	65.00*	✓
4161	1	L/R OUTER WHEELHOUSE	76713 5M030	0%	YW	48.00*	2.8
1000	1	BUMPER RETAINER LH	Renew	0%	SW	18.00*	✓
1000	1	BUMPER RETAINER RH	Renew	0%	SW	18.00*	X
1000	1	REINFORCEMENT BEAM	Renew	0%	SW	190.00*	X
1000	1	BUMPER MUDFLAMP	Renew	0%	SW	78.00*	✓
1000	1	FENDER COWLING CLIP	Renew	0%	SW	15.00*	X
1000	1	BOOT LID CHROME UPP	Renew	0%	SW	85.00*	X
1000	1	BOOT LID CHROME LOW	Renew	0%	SW	85.00*	X
1000	1	EMBLEM (SUNNY)	Renew	0%	SW	35.00*	X
1000	1	EMBLEM (EX SALOON)	Renew	0%	SW	28.00*	X
1000	1	EMBLEM (CVTC)	Renew	0%	SW	26.00*	X
1000	1	EMBLEM (E-THROTTLE)	Renew	0%	SW	26.00*	X
1000	1	BUMPER SENSOR	Renew	0%	SW	380.00*	X
1000	1	END PANEL SEALER	Renew	0%	SW	80.00*	40
f: OEM Parts			Sub Total			\$4,026.89	
g: Original			Mark Up From Cost	(5 %)		\$201.34	
h: Secondhand			Sundry Parts	(Fixed)		\$100.00	
p: Parallel			Total Parts			\$4,328.23	
x: Exchange							

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts	\$4,328.23
Labour	
Total Panel/Mechanical	\$818.80
Total Paintwork	\$805.00
Total Labour	\$1,623.80
Total Paint/Material Costs	\$235.79
Grand Total Excludes GST	\$6,187.82
GST @ 7 %	\$433.15
Grand Total Includes GST	\$6,620.97

Assessment Notes

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Bus. Reg No: 199502604 E GST No: 19-9502604-E

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SM/SJC8142L/1712314
Policy No:	DMPCSN9036151707	Date of Loss:	09/12/2017
Vehicle Reg. No.:	SJC8142L	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	XU HONGWEI	Contact No:	+6591167940
Driver:	XU HONGWEI		

Make/Model:	NISSAN SUNNY, 1.6 EX (A)	Vehicle Reg. Date:	29/02/2008
Vehicle Colour:	WHITE		
Engine No:	QG16428110	Chassis No:	JN1CFAN16Z0111260
Odometer:	0 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) **7**

Description of Accident/Loss: ATTACHED GIA REPORT & POLICE REPORT

Present Location: SPECIALISTS MOTOR PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	4,333.23
Miscellaneous Items	0.00
Labour	1,859.59
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	6,192.82
+ GST 7.00% (\$\$)	433.50
Nett Amount (\$\$)	6,626.32

This claim is handled by: KAREN ONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

6734.82

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 11 Dec 2017)**Parts:** 143 **NISSAN SUNNY 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)****Labour:** Repairer's **(Price-denominated Standard List)****Print Code:** Specialists Motor Pte Ltd/SJC8142L/11/12/2017 15:19**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BOOT LID CHROME UPP	0.00	0.00	*85.00 F XNN
2	1	NA	*BOOT LID CHROME LOW	0.00	0.00	*85.00 F XNN
3	1	NA	*BOOT/TAILGATE LOCK	0.00	0.00	*38.00 F XNN
4	1	NA	*BOOT/TAILGATE SEAL	0.00	0.00	*35.00 F XNN
5	1	NA	*BOOTLID	0.00	0.00	*320.00 F XNN
6	1	NA	*BOOTLID TRIM	0.00	0.00	*-F XNN
7	1	NA	*BUMPER MUDFLAMP	0.00	0.00	Torn *78.00 F ✓
8	1	NA	*BUMPER RETAINER LH	0.00	0.00	Bent *18.00 F ✓
9	1	NA	*BUMPER RETAINER RH	0.00	0.00	*18.00 F XNN
10	1	NA	*BUMPER SENSOR	0.00	0.00	*380.00 F XNN
11	1	NA	*CTR REAR BUMPER MLDG	0.00	0.00	Dis *85.00 F ✓
12	1	NA	*EMBLEM (CVTC)	0.00	0.00	*26.00 F XNN
13	1	NA	*EMBLEM (E-THROTTLE)	0.00	0.00	*26.00 F XNN
14	1	NA	*EMBLEM (EX SALOON)	0.00	0.00	*28.00 F XNN
15	1	NA	*EMBLEM (SUNNY)	0.00	0.00	*35.00 F XNN
16	1	NA	*END PANEL SEALER	0.00	0.00	rec 40 *80.00 F ✓
17	1	NA	*FENDER COWLING CLIP	0.00	0.00	*15.00 F XNN
18	1	NA	*L/BOOTLID HINGE	0.00	0.00	*45.00 F XNN
19	1	NA	*L/END PANEL TRIM	0.00	0.00	*18.00 F XNN
20	1	NA	*L/R AIR VENT GRILLE	0.00	0.00	TNI *65.00 F ✓
21	1	NA	*L/R BUMPER DAMPER	0.00	0.00	*70.00 F XNN
22	1	NA	*L/R BUMPER MOULDING	0.00	0.00	*85.00 F XNN
23	1	NA	*L/R OUTER LAMP	0.00	0.00	*160.00 F CPA
24	1	NA	*L/R OUTER WHEELHOUSE	0.00	0.00	*48.00 F XNN
25	1	NA	*L/R WING	0.00	0.00	*320.00 F XR
26	1	NA	*R/BOOTLID HINGE	0.00	0.00	*45.00 F XNN
27	1	NA	*R/R BUMPER MOULDING	0.00	0.00	*85.00 F XNN
28	1	NA	*REAR BUMPER	0.00	0.00	Dis *250.00 F ✓
29	1	NA	*REAR PANEL	0.00	0.00	badly m *250.00 F ✓
30	1	NA	*REAR SCREEN	0.00	0.00	*850.00 F XNN
31	1	NA	*REAR SCREEN BOND KIT	0.00	0.00	*60.00 F XNN
32	1	NA	*REAR SCREEN SEAL	0.00	0.00	*25.83 F XNN
33	1	NA	*REAR SCREEN SPACER	0.00	0.00	*8.06 F XNN
34	1	NA	*REAR WINDOW MOULDING	0.00	0.00	*85.00 F XNN
35	1	NA	*REINFORCEMENT BEAM	0.00	0.00	*190.00 F XNN
36	1	NA	*RR BUMPER CLAMP KIT	0.00	0.00	*15.00 F XNN
37	1	NA	*SUNDRY PARTS	0.00	0.00	rec *100.00 F XNN

F=Franchise part.

Sub Total (\$\$) **4,126.89**
+ Margin on L,N Items 5.00% (\$\$) **206.34**

Total Parts (\$\$) **4,333.23**

Specialists Motor Pte Ltd/SJC8142L/11/12/2017 15:19. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New	805.00
2	Total Paint Materials	New	235.79
3	Total Panel/Mechanical Labour	New	818.80
Gross Labour Cost (S\$)			1,859.59

Specialists Motor Pte Ltd/SJC8142L/11/12/2017 15:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER
079909**

Claim Reference: SNM17D07025C01
Assessment Number: SM100201
Version: CHINATAI/2
Date Calculated: 10/01/2018 03:55

Full Report - V1
Registration: SJC8142L
Printed: 10/01/2018 11:56

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	09/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM17D07025C01	Estimated Repair Time:	
Policy Number:	DMPCSN9036151707	Quote Due Date:	
Other Reference:	SM/SJC8142L/1712314	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	NISSAN
Model:	Sunny
Sub Model:	SUNNY
Model Sheet Number:	Z34 86
Registration:	SJC8142L
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

4-DOOR	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	11/12/2017
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D07025C01

Assessment Number: SM100201



Version: CHINATAI/2

Date Calculated: 10/01/2018 03:55

Full Report - V1

Registration: SJC8142L

Printed: 10/01/2018 11:56

**Addresses****Cost Summary**

Total Labour	\$745.20
Total Paint/Material	\$141.41
Total Parts	\$1,093.30
Total of Additional Costs	\$42.00
Excess:	- \$0.00
Grand Total Exc GST:	\$2,021.91
7 % GST:	\$141.53
Grand Total Inc GST:	\$2,163.44

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR

Price/Dent = \$46.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
5540A1	RENEW REAR END PANEL	38.0	174.80
	INCLUDES: R + R BUMPER, TAIL LAMPS, TAILGATE SEAL, STRIKER PLATE AND TRIMS IN THE REPAIR SECTION		
NO NUMBER	R + R REAR NO-PLATE	1.0	4.60
5010A1	RENEW REAR BUMPER (REMOVED)	1.0	4.60
6770A1)	R + R TAIL LAMP	2.0	9.20
6770A1)	R + R LEFT OUTER TAILLAMP	2.0	9.20
6890A1	R + R LEFT REAR SPLASH SHIELD	1.0	4.60
NO NUMBER	R + R BOOTLID TRIM	1.0	4.60

LABOUR COST

Total Work Units	46.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	4.6HRS	\$211.60
Paint Labour	11.6HRS	\$533.60
Total Labour	16.2HRS	\$745.20

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number Description

		WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
2711	REAR PANEL NEW PART PAINTING	21.0	
2583	REAR BUMPER REPAIR PAINT PLASTIC	15.0	
2610	CTR REAR BUMPER MLDGREPAIR PAINT PLASTIC	9.0	

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D07025C01

Full Report - V1

Assessment Number: SM100201

Registration: SJC8142L

Version: CHINATAI/2

Printed: 10/01/2018 11:56

Date Calculated: 10/01/2018 03:55

2611	L/R BUMPER MOULDING REPAIR PAINT PLASTIC	9.0	
2612	R/R BUMPER MOULDING REPAIR PAINT PLASTIC	9.0	
2721	L/END PANEL TRIM REPAIR PAINT PLASTIC	9.0	
3482	R/R WING SURFACE PAINT	7.0	
3571	L/R LAMP PANEL SURFACE PAINT	4.0	
LABOUR COST - PAINT			
	TIME(PAINT)	83.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	116.0	
	Total Paintwork Labour	11.6HRS	\$533.60
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$25.85
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$19.17
	Repair Painting Plastic		\$55.09
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$141.41
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$141.41

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
2583	1	REAR BUMPER	85022 6N626		0% 250.00*
2610	1	CTR REAR BUMPER MLDG	85072 8M100		0% 85.00*
2711	1	REAR PANEL	79110 6N600		0% 250.00*
3281	1	L/R OUTER LAMP	26555 5M427		0% 160.00*
3783	1	L/R AIR VENT GRILLE	76805 2DR0A		0% 65.00*
1000	1	BUMPER RETAINER LH	Renew		0% 18.00*
1000	1	BUMPER MUFLAMP	Renew		0% 78.00*
1000	1	END PANEL SEALER	Renew		0% 40.00*
f: OEM Parts			Sub Total		\$946.00
g: Original			Mark Up From Cost	(5 %)	\$47.30
h: Secondhand			Sundry Parts	(Fixed)	\$100.00
p: Parallel			Total Parts		\$1,093.30
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEES	0%	\$42.00
SPECIALIST		
Total Extras		\$42.00

Final Calculation

Total Parts	\$1,093.30
Labour	
Total Panel/Mechanical	\$211.60
Total Paintwork	\$533.60
Total Labour	\$745.20
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$42.00

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D07025C01

Full Report - V1

Assessment Number: SM100201

Registration: SJC8142L

Version: CHINATAI/2

Printed: 10/01/2018 11:56

Date Calculated: 10/01/2018 03:55

Total of Additional Costs	\$42.00
Total Paint/Material Costs	\$141.41
Grand Total Excludes GST	<u>\$2,021.91</u>
GST @ 7 %	<u>\$141.53</u>
Grand Total Includes GST	<u>\$2,163.44</u>

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2017 Sendback Est	11 Dec 2017 15:19 S\$6,192.82	11 Dec 2017 17:47 Edit Adj Rpt	S\$1,600.00 Edit Estimates	S\$1,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	XU HONGWEI, ID: S7078433E, Tel: +6591167940		
Vehicle Reg. No.:	SJC8142L	Date of Loss:	09/12/2017 22:00 - :59
Claim Type:	OD / SNM17D07025C01	Policy/Cover Note No.:	DMPCSN9036151707 (Comprehensive) Coverage: 01/03/2017 - 28/02/2018
		Excess:	S\$0.00
Repairer:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26, 408711 Ubi - Tel: 6747 2112		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/12/2017]		
Driver/Custodian:	XU HONGWEI (47 / Male), NRIC: S7078433E, Tel: +6591167940		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- CHINA_TAIPIING (13/12/2017): Alert - Adj Mandate Approved (S\$1600.00) - SJC8142L - Claim Handler: Chong Boon ...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJC8142L (SNM17D07025C01)


































OD

Dec 9 2017 10:00PM

[XU HONGWEI]

Specialists Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Specialists Motor Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 15:19	Repairer Estimates	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 17:51	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Specialists Motor Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	11/12/17 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	11/12/17 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	11/12/17 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	11/12/17 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	11/12/17 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 19:42	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
3	12/12/17 19:42	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
4	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
5	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
19	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
21	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
22	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/12/17 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>

26	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	12/12/17 19:42	General View	1	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Specialists Motor Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 15:19	E-filed GIA report	1 Load TIF	
2	11/12/17 15:19	E-filed GIA report	1 Load TIF	
3	11/12/17 15:19	E-filed GIA report	1 Load TIF	
4	11/12/17 15:19	E-filed GIA report	1 Load TIF	
5	11/12/17 15:19	Police Report	1 Load TIF	
6	11/12/17 15:19	Police Report	1 Load TIF	
7	11/12/17 15:19	Police Report	1 Load TIF	
8	11/12/17 15:19	Certificate of Insurance	1 Load TIF	
9	11/12/17 15:19	Insured Persons NRIC/Passport/Work Permit	1 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 17:53	WORKSHOP ESTIMATE	1 Load PDF	
2	12/12/17 17:53	REVISED AUDATEX	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div> <div style="text-align: right;"> ^ v </div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI17023532/UQBE2

Date: 15/01/2018

REFERENCE

Insured/Claimant: XU HONGWEI Policy No: DMPCSN9036151707
Date of Loss: 09/12/2017 Nature of Claim: OD Claim No: SNM17D07025C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC8142L**
Make & Model: NISSAN SUNNY, 1.6 EX (A) Engine No: QG16428110
Reg. Date: 29/02/2008 (Man. Year: 2007) Chassis No: JN1CFAN16Z0111260
Colour: White Odometer: 128599 km
Engine Capacity: 1597 cc
Market Value/New Car Price: S\$8,500.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,333.23	1,093.30	3,239.93	74.77
Miscellaneous Items	0.00	42.00	-42.00	
Labour	1,859.59	886.61	972.98	52.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,192.82	2,021.91	4,170.91	67.35
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	6,192.82	1,600.00	4,592.82	74.16
+ GST 7.00/7.00% (S\$)	433.50	112.00	321.50	74.16
Nett Amount (S\$)	6,626.32	1,712.00	4,914.32	74.16

INSPECTION

Date of Assignment: 11/12/2017 Present Location: Specialists Motor Pte Ltd (HQ)
Date Inspected: 12/12/2017 Inspected At: Blk 3018A Ubi Road 1, #01-24/25/26
Singapore 408711
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 15 Jan 2018)
Parts: 143 **NISSAN SUNNY 1.6 EX (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJC8142L)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BOOD LID CHROME UPP (WCP)	Not Necessary	85.00 F	*- F
2	1	NA	*BOOT LID CHROME LOW (WCP)	Not Necessary	85.00 F	*- F
3	1	NA	*BOOT/TAILGATE LOCK (WCP)	Not Necessary	38.00 F	*- F
4	1	NA	*BOOT/TAILGATE SEAL (WCP)	Not Necessary	35.00 F	*- F
5	1	NA	*BOOTLID (WCP)	Not Necessary	320.00 F	*- F
6	1	NA	*BOOTLID TRIM (NPA)(WCP)	Not Necessary	0.00 F	*- F
7	1	NA	*BUMPER MUDFLAMP (WCP)	Torn	78.00 F	*78.00 F
8	1	NA	*BUMPER RETAINER LH (WCP)	Bent	18.00 F	*18.00 F
9	1	NA	*BUMPER RETAINER RH (WCP)	Not Necessary	18.00 F	*- F
10	1	NA	*BUMPER SENSOR (WCP)	Not Necessary	380.00 F	*- F
11	1	NA	*CTR REAR BUMPER MLDG (WCP)	Distorted	85.00 F	*85.00 F
12	1	NA	*EMBLEM (CVTC) (WCP)	Not Necessary	26.00 F	*- F
13	1	NA	*EMBLEM (E-THROTTLE) (WCP)	Not Necessary	26.00 F	*- F
14	1	NA	*EMBLEM (EX SALOON) (WCP)	Not Necessary	28.00 F	*- F
15	1	NA	*EMBLEM (SUNNY) (WCP)	Not Necessary	35.00 F	*- F
16	1	NA	*END PANEL SEALER (WCP)	Necessary	80.00 F	*40.00 F
17	1	NA	*FENDER COWLING CLIP (WCP)	Not Necessary	15.00 F	*- F
18	1	NA	*L/BOOTLID HINGE (WCP)	Not Necessary	45.00 F	*- F
19	1	NA	*L/END PANEL TRIM (WCP)	Not Necessary	18.00 F	*- F
20	1	NA	*L/R AIR VENT GRILLE (WCP)	Twisted	65.00 F	*65.00 F
21	1	NA	*L/R BUMPER DAMPER (WCP)	Not Necessary	70.00 F	*- F
22	1	NA	*L/R BUMPER MOULDING (WCP)	No such part	85.00 F	*- F
23	1	NA	*L/R OUTER LAMP (WCP)	Cracked	160.00 F	*160.00 F
24	1	NA		Not Necessary	48.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*L/R OUTER WHEELHOUSE (WCP)			
25	1	NA	*L/R WING (WCP)	Repair	320.00 F	*- F
26	1	NA	*R/BOOTLID HINGE (WCP)	Not Necessary	45.00 F	*- F
27	1	NA	*R/R BUMPER MOULDING (WCP)	No such part	85.00 F	*- F
28	1	NA	*REAR BUMPER (WCP)	Distorted	250.00 F	*250.00 F
29	1	NA	*REAR PANEL (WCP)	Badly Dented	250.00 F	*250.00 F
30	1	NA	*REAR SCREEN (WCP)	Not Necessary	850.00 F	*- F
31	1	NA	*REAR SCREEN BOND KIT (WCP)	Not Necessary	60.00 F	*- F
32	1	NA	*REAR SCREEN SEAL (WCP)	Not Necessary	25.83 F	*- F
33	1	NA	*REAR SCREEN SPACER (WCP)	Not Necessary	8.06 F	*- F
34	1	NA	*REAR WINDOW MOULDING (WCP)	Not Necessary	85.00 F	*- F
35	1	NA	*REINFORCEMENT BEAM (WCP)	No such part	190.00 F	*- F
36	1	NA	*RR BUMPER CLAMP KIT (WCP)	Not Necessary	15.00 F	*- F
37	1	NA	*SUNDRY PARTS	Necessary	100.00 F	*100.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,126.89	1,046.00
+ Margin on L,N Items 5.00/5.00% (\$\$)	206.34	47.30
Total Parts (\$\$)	4,333.23	1,093.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AUDATEX FEES	-	42.00
Sub Total (\$\$)			0.00	42.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	805.00	533.60
2	Total Paint Materials	New	235.79	141.41
3	Total Panel/Mechanical Labour	New	818.80	211.60
Gross Labour Cost (\$\$)			1,859.59	886.61

Report was unsubmitted during this print-out.

< END OF ESTIMATES >