

22/07/2002

ASS. REC. BY:

REF: CS/MSG17023533/466 Special Instruction:

SUPERVISOR:
Mervin

Marcus

ASSIGNMENT (Office)

From (Person): Elaine Ngu

of MSIG

Date/Time: 11/12/17 @ 5:21pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 9540J

Insured:

GV68004

at Workshop m/s

Liu's Brother

Tel:

67411730

of Blk 1 kaki Bkt Ave 6 # 01-01, 417883

Policy No:

MSD/VCT/17-002056

Claim No:

MSC/V/17/-001911

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time: 9:17am @ 12/12/17

Person Contacted:

Susan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBC 9540J - X

GV 68004 - NA/MSG16012634/K4

D.O.A. 8/07/2016

13/12-19:05 pending estimate revert.

Service: mercus

REF:

MS14/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: GBC95409
 at Workshop m/s 1.6's 3m
 of _____
 Insured: AV 68004
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: GBC95409 Yr Regn: 3 / 14
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Car
 Make: FIAT Doblo c.c. 1598
 Colour: white A/C: Insured / Std / NI / NA
 Sp.Reading: 69086 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 2FA2630000 6141970
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: NI / S/Rim / STD A/Rim or
 Tyre Size: F: 195/55R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken

Front: 6 mm Rear: 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 30/11/17 D.O.I. 12/12/17
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
24.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
3/1/18 cont. rmd 2/s @ 2400 with Susan. (red: 5287.90.68)

RECEIVED 04 JAN 2018

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

1) 3/1 Typist
 Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$) 2400

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

200

10

210

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17023533/Utb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 12-12-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GV 6800U	Veh. Inspected	GBC 9540J
Policy No.	MSD/VCT/17-002056	Coverage (\$)	0.00
Claim No.	MSC/V/17-001911	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	12/12/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/11/2017	Inspection Date	12/12/2017
Survey held at	LIU'S BROTHER AUTO WORK SHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth ed	Status
Main	01 Dec 2017		11 Dec 2017 17:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KST LEASING & SERVICING , Co. Reg. No.: 49392700W		
Main Claimant:	STVE PTE LTD , Co. Reg. No.: 198703585C		
Vehicle Reg. No.:	GBC9540J	Date of Loss:	30/11/2017 15:00 - :59
Claim Type:	TP / MSC/V/17-001911	Policy/Cover Note No.:	MSD/VCT/17-002056 (Third Party Only) Coverage: 20/09/2017 - 19/09/2018
Vehicle Reg. No. (Insured):	GV6800U	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Lius Brother Auto Workshop (HQ) Liu's Brother Auto Workshop, Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, 417883 Kaki Bukit - Tel: 67411730		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/12/2017]		
Adj Asg. Remarks:	PLS CONTACT SUSAN :67411730 FOR SURVEY.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 03 Jan 2018

Preliminary Advice

Insured Vehicle No	: GV6800U	Accident Date	: 30/11/2017
TP Vehicle No	: GBC9540J	Assignment Date	: 11/12/2017
Make	: FIAT DOBLO	Est. Duration of Repair	: 3.00
Date of Inspection	: 12/12/2017		
Inspection At	: LIUS BROTHER AUTO WORKSHOP (HQ)		
	: LIU'S BROTHER AUTO WORKSHOP, BLK 1 KAKI BT AVE 6 #01-01 AUTO BAY @ KAKI BT SINGAPORE		
	417883		
	SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,687.90
Revised Amount	:S\$	3,008.36
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,008.36
Lump Sum Repair	:S\$	2,400.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***GBC9540J (MSC/V/17-001911)**
[GV6800U]

TP

STVE PTE LTD

Nov 30 2017 3:00PM

[KST LEASING & SERVICING]

Lius Brother Auto Workshop

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 13/12/2017 19:05 PM.
To elaine_ngu@sg.msig-asia.com
Subject GBC9540J (MSC/V/17-001911) [GV6800U]

Dear Sir/Madam

Please be informed that we have inspected the vehicle GBC 9540J on 12/12/2017
We are pending estimate from repairer.

Regards,

Denise

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/12/2017 13:25
Date Of Accident	30/11/2017 15:45
Exact Location Of Accident	ENTRANCE CARPARK INTO HYFLUX BLDG BENDEMEER ROAD.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC9540J
Insured/Policyholder	
Name Of Registered Owner	STVE PTE LTD
Co Reg No	198703585C
Email Address	JOHN.GOH@SGP.FUJIXEROX.COM
Mobile Phone No	
Alternative Phone No	OFFICE-83233163

Vehicle Particulars

Manufacturer	FIAT
Model	DOBLO CARGO SX JTD 1.6MJ
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087422MFCV
Cover Note Number	NA

Driver

Name of Driver	JOHN GOH TZE YIK
NRIC No	G7639291P
Date Of Birth	07/12/1984
Occupation	OUTDOOR
Date Of Driving Pass	20/04/2010
Driving Experience	7 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83233163
Fax Number	
Contact Number	
EMail Address	JOHN.GOH@SGP.FUJIXEROX.COM

Email Address

Common Statement

ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED, I WAS ENTERING THE SAID MENTIONED CARPARK, FOLLOWING AT A DISTANCE. WHEN VEHICLE B STOPPED AT THE CARPARK BARRIER, I STOPPED BEHIND HIM. THEN SUDDENLY VEHICLE B REVERSED TOWARDS MY VEHICLE, AND HIT THE FRONT OF MY VEHICLE. THIS INCIDENT WAS CAPTURED IN MY IN CAR VIDEO WHICH I HAD SUBMITTED TO STV2, COMPANY.

NO BODY WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

1 December 2017 at 10:14 AM

Date/Time:

1 December 2017 at 10:14 AM



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 11 Dec 2017 / 14:51:46

Receipt Date/Time : 11 Dec 2017 / 14:51:46

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171211-001345

Previous Receipt No. :

S/N Item Description/
Business Transaction Reference
No.

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - GV6800U

As at 30 Nov 2017/15:45:00

Insurance Co: MSIG INSURANCE (SINGAPORE) PTE LTD

1 Insurance Enquiry - GV6800U

Enquiry Fee

20171211145041844075

5.00 0.35 5.35

Sub-Total

5.00 0.35 5.35

Total Before Rounding

5.00 0.35 5.35

Rounding Difference

0.00

Total Amount Payable

5.35

Paid By

xxxxxxxxxxxx4559

Credit Card:

Visa/MasterCard

5.35

Total

5.35

Cash Change

0.00

Tendered Amount

5.35

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK


Save as PDF

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	3585C
Vehicle Details	
Vehicle No.	GBC9540J
Vehicle to be Exported	No
Intended De-registration Date	12 Dec 2017
Vehicle Make	FIAT
Vehicle Model	DOBLO CARGO SX JTD 1.6MJ PANEL
Primary Colour	White
Manufacturing Year	2014
Engine No.	198A30007041312
Chassis No.	ZFA26300006141970
Maximum Power Output	-
Open Market Value	\$20,538.00
Original Registration Date	24 Mar 2014
First Registration Date	24 Mar 2014
Transfer Count	0
Actual ARF Paid	\$1,027.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	23 Mar 2024
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$56,302.00
COE Rebate Amount	\$35,355.00
Total Rebate Amount	\$35,355.00

The information contained herein is correct as at 12 Dec 2017

OK



Signature: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Dec 2017		11 Dec 2017 17:21 Edit Adj Rpt	S\$2,400.00 Edit Estimates	S\$2,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KST LEASING & SERVICING , Co. Reg. No.: 49392700W								
Main Claimant:	STVE PTE LTD , Co. Reg. No.: 198703585C								
Vehicle Reg. No.:	GBC9540J	Date of Loss:	30/11/2017 15:00 - :59						
Claim Type:	TP / MSC/V/17-001911	Policy/Cover Note No.:	MSD/VCT/17-002056 (Third Party Only) Coverage: 20/09/2017 - 19/09/2018						
Vehicle Reg. No. (Insured):	GV6800U	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	Liu's Brother Auto Workshop (HQ) Liu's Brother Auto Workshop, Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, 417883 Kaki Bukit - Tel: 67411730								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/01/2018]								
Adj Asg. Remarks:	PLS CONTACT SUSAN :67411730 FOR SURVEY.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC9540J (MSC/V/17-001911)
[GV6800U]
TP
STVE PTE LTD
Nov 30 2017 3:00PM
[KST LEASING & SERVICING]
Lius Brother Auto Workshop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	11/12/17 17:19	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Non Reporting Letter to OI	1	Load HTM	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	03/01/18 17:25	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice	1	Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
1	12/12/17 20:33	LKK Auto Consultants Pte Ltd (HQ) Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
2	12/12/17 20:33	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
3	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	12/12/17 20:33	General View	1	Load JPG	<input checked="" type="checkbox"/>

29	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
30	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
31	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
32	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
33	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
34	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
35	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
36	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
37	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
38	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
39	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
40	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
41	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
42	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
43	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
44	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
45	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
46	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
47	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
48	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
49	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
50	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
51	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
52	12/12/17 20:33	General View		Load JPG	<input checked="" type="checkbox"/>
53	03/01/18 12:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
54	03/01/18 12:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
55	03/01/18 12:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
56	03/01/18 12:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	11/12/17 17:17	TPD GBC9540J GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023533/UTBE2
Date: 10/01/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCT/17-002056
Claimant Vehicle No :	GBC9540J	Insured Vehicle No :	GV6800U
Date of Loss:	30/11/2017	Nature of Claim:	TP
		Claim No:	MSC/V/17-001911

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC9540J		
Make & Model:	FIAT DOBLO, 1.6 D CARGO MJ (M)	Engine No:	198A30007041312
Reg. Date:	24/03/2014 (Man. Year: 2014)	Chassis No:	ZFA26300006141970
Colour:	White	Odometer:	69086 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,087.90	2,208.36	3,879.54	63.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	800.00	800.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,687.90	3,008.36	4,679.54	60.87
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	7,687.90	2,400.00	5,287.90	68.78

INSPECTION

Date of Assignment:	11/12/2017	
Date Inspected:	12/12/2017 Inspected At:	Lius Brother Auto Workshop (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883 Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Jan 2018)	
Parts:	N/A	FIAT DOBLO 1.6 D CARGO MJ (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC9540J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,170.00 F	*- FL
2	1		*SET FRONT BONNET CORPORATE STICKER	Necessary	400.00 FS	*220.00 FS
3	1		*FRONT BUMPER	Deformed / Torn	1,245.50 F	*792.29 FL
4	1		*FRONT BUMPER CENTRE MESH	Not Necessary	287.90 F	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	475.50 F	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	117.00 F	*- FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
8	1		*FRONT BUMPER FOG GRILLE	Not Necessary	187.00 F	*- FL
9	2		*FRONT HEAD LAMP	Holder Cracked	1,317.00 F	*1,317.00 FL
10	1		*FRONT CENTRE PANEL	Repair	790.00 F	*- FL
11	1		*FRONT NUMBER PLATE AND BASE	Bent	48.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,087.90	2,419.29
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	210.93
Total Parts (S\$)	6,087.90	2,208.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	20.00
2	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	680.00	400.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	680.00	380.00
4	TO REMOVE & REFIX AIR CON, RE-FILL AIR CON GAS & TEST FOR LEAKAGES	New	100.00	0.00
5	TO APPLY RUST PROOFING, RESEAL TUFF COATING TREATMENT ON ACCIDENT AREA	New	80.00	0.00
Gross Labour Cost (S\$)			1,600.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >