

ASS. REC. BY:

REF: CS/MSG17023534/4662 Special Instructions:

SUGGESTION: Marcus

ASSIGNMENT (Office)

From (Person): Menmen Elaine Ngu of MSG Date/Time: 12/12/17 @ 9:27am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 8301Y Insured: SJT 1800Cat Workshop m/s Pegasus Engineering Tel: 68581846of 51 Defu Lane 10, 339218Policy No: 27736902Mcy Claim No: 539940

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 2/12/2017  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 9:47am @ 12/12/17 Person Contacted: Sharon Vehicle IN OUT

| Date/Time | Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate |
|-----------|---------------------------------------------------------------------|
|           | <u>SLQ 8301Y - X</u>                                                |
|           | <u>SJT 1800C - X</u>                                                |
|           |                                                                     |
|           |                                                                     |
|           |                                                                     |
|           |                                                                     |
|           |                                                                     |

Client: Marcus

REF:

MS16/

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: S2AP3014

at Workshop m/s pegosus

of SJT1800C

Insured:

Policy No.

Claims No.

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: S2AP3014 Yr Regn: 7 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: mazda

C.C. 1496

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 32670

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: YM6BN22A810153598

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/R / STD A/Rim or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 2/12/17

D.O.I. 12/12/17

Survey held at \_\_\_\_\_

Des. of Damages: Rear / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

12/12/17 checked final by #2424 with w.l.h.a. (Red: 2212.64!47%)

RECEIVED 15 DEC 2017

Date/Time: File Pass to?

1) 1512 Typist

Date/Time: File Return to?

2) \_\_\_\_\_

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee: 200

Transportation: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

: Photos

: Others

Report Format: TP

Lump Sum / V.E.I: (\$ 2424)

TOTAL

|     |
|-----|
| 200 |
|     |
|     |
| 10  |
| 210 |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                      |                                       |                          |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------------------|--------------------------|-------------------------------------------------------------------------------------|
| MSIG INSURANCE (SINGAPORE) PTE LTD                                                                                                     |                      |                                       | Ref : CS/MSG17023534/Utb |                                                                                     |
| 16 RAFFLES QUAY<br>#24-01 HONG LEONG BLDG SINGAPORE 048581                                                                             |                      |                                       | Date : 12-12-2017        |  |
|                                                                                                                                        |                      |                                       | Code : MSG               |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                      |                                       |                          |                                                                                     |
| Insured Veh.                                                                                                                           | SJT 1800C            |                                       | Veh. Inspected           | SLQ 8301Y                                                                           |
| Policy No.                                                                                                                             | 27736902MCY          |                                       | Coverage (\$)            | 0.00                                                                                |
| Claim No.                                                                                                                              | 539940               |                                       | Excess (\$)              | 0.00                                                                                |
| Assign From                                                                                                                            | MERIMEN (ELAINE NGU) |                                       | Assign Date              | 12/12/2017                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                      |                                       |                          |                                                                                     |
| Make & Model                                                                                                                           |                      |                                       | c.c                      | 0                                                                                   |
| Engine No.                                                                                                                             | HIDDEN               |                                       | Year of Reg.             |                                                                                     |
| Chassis No.                                                                                                                            |                      |                                       | Colour                   |                                                                                     |
| Odometer                                                                                                                               | -                    |                                       | Steering                 |                                                                                     |
| Brakes                                                                                                                                 |                      |                                       | Modification             |                                                                                     |
| General                                                                                                                                |                      |                                       |                          |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                      |                                       |                          |                                                                                     |
|                                                                                                                                        |                      | Size                                  | Make                     | Balance                                                                             |
|                                                                                                                                        | R/H Front Tyre       |                                       |                          | mm                                                                                  |
|                                                                                                                                        | L/H Front Tyre       |                                       |                          | mm                                                                                  |
|                                                                                                                                        | R/H Rear Tyre        |                                       |                          | mm                                                                                  |
|                                                                                                                                        | L/H Rear Tyre        |                                       |                          | mm                                                                                  |
| <b>4. Description of Damages</b>                                                                                                       |                      |                                       |                          |                                                                                     |
|                                                                                                                                        |                      |                                       |                          |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                      |                                       |                          |                                                                                     |
|                                                                                                                                        | Accident Date        | 02/12/2017                            | Inspection Date          | 12/12/2017                                                                          |
|                                                                                                                                        | Survey held at       | 51 DEFU LANE 10                       |                          |                                                                                     |
|                                                                                                                                        | Repairer             | PEGASUS ENGINEERING & TRADING PTE LTD |                          |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                      |                                       |                          |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                      |                                       |                          |                                                                                     |

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                                               |
|------|-------------|---------------|------------------------------------------------|---------|---------------|------------|------------------------------------------------------|
| Main | 04 Dec 2017 |               | 12 Dec 2017<br>09:27<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |                                                                                                                               |                        |                                                  |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------|------------------------|--------------------------------------------------|
| Insured:                    | <b>HOCK CHEONG ELECTRIC PTE LTD</b> , Co. Reg. No.: 199502810D                                                                |                        |                                                  |
| Main Claimant:              | <b>GRABS RENTALS 2 PTE LTD</b> , Co. Reg. No.: 201701345N                                                                     |                        |                                                  |
| Vehicle Reg. No.:           | <b>SLQ8301Y</b>                                                                                                               | Date of Loss:          | 02/12/2017 13:00 - :59                           |
| Claim Type:                 | <b>TP / 539940</b>                                                                                                            | Policy/Cover Note No.: | 27736902MCY<br>Coverage: 07/08/2017 - 06/08/2018 |
| Vehicle Reg. No. (Insured): | <b>SJT1800C</b>                                                                                                               | Policy No. (Claimant): |                                                  |
|                             |                                                                                                                               | Excess:                | S\$500.00                                        |
| Repairer:                   | <b>Pegasus Engineering &amp; Trading Pte Ltd (HQ)</b> 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846                       |                        |                                                  |
| Handling Insurer:           | <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Elaine Ngu Siau Mei</b> - 6594 2540] |                        |                                                  |
| Adjuster:                   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Imm.Advice due 13/12/2017]</b>                              |                        |                                                  |
| Adj Asg. Remarks:           | PLS CONTACT THE TP BEFORE GOING FOR SURVEY                                                                                    |                        |                                                  |

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

SM 2017 12 021

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

|               |         |
|---------------|---------|
| Owner ID Type | Company |
| Owner ID      | 1345N   |

### Vehicle Details

|                               |                         |
|-------------------------------|-------------------------|
| Vehicle No.                   | SLQ8301Y                |
| Vehicle to be Exported        | Yes                     |
| Intended De-registration Date | 02 Dec 2017             |
| Vehicle Make                  | MAZDA                   |
| Vehicle Model                 | MAZDA3 SEDAN 1.5 AT EU6 |
| Primary Colour                | Blue                    |
| Manufacturing Year            | 2017                    |
| Engine No.                    | P520445383              |
| Chassis No.                   | JM6BN22A8H0153599       |
| Maximum Power Output          | 88.0 kW (118 bhp)       |
| Open Market Value             | \$14,761.00             |
| Original Registration Date    | 24 Jul 2017             |
| First Registration Date       | 24 Jul 2017             |
| Transfer Count                | 0                       |
| Actual ARF Paid               | \$9,761.00              |

### Intended PARF Rebate Details

|                              |             |
|------------------------------|-------------|
| PARF Eligibility             | Yes         |
| PARF Eligibility Expiry Date | 23 Jul 2027 |
| PARF Rebate Amount           | \$7,320.00  |

### Intended COE Rebate Details

|                            |                                      |
|----------------------------|--------------------------------------|
| COE Expiry Date            | 23 Jul 2027                          |
| COE Category               | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years)          | 10                                   |
| QP Paid                    | \$42,801.00                          |
| COE Rebate Amount          | \$34,240.00                          |
| <b>Total Rebate Amount</b> | <b>\$41,560.00</b>                   |

The information contained herein is correct as at 02 Dec 2017

OK

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                      |
|-------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                      |
| Owner ID Type                       | Company                              |
| Owner ID                            | 1345N                                |
| <b>Vehicle Details</b>              |                                      |
| Vehicle No.                         | SLQ8301Y                             |
| Vehicle to be Exported              | No                                   |
| Intended De-registration Date       | 12 Dec 2017                          |
| Vehicle Make                        | MAZDA                                |
| Vehicle Model                       | MAZDA3 SEDAN 1.5 AT EU6              |
| Primary Colour                      | Blue                                 |
| Manufacturing Year                  | 2017                                 |
| Engine No.                          | P520445383                           |
| Chassis No.                         | JM6BN22A8H0153599                    |
| Maximum Power Output                | 88.0 kW (118 bhp)                    |
| Open Market Value                   | \$14,761.00                          |
| Original Registration Date          | 24 Jul 2017                          |
| First Registration Date             | 24 Jul 2017                          |
| Transfer Count                      | 0                                    |
| Actual ARF Paid                     | \$9,761.00                           |
| <b>Intended PARF Rebate Details</b> |                                      |
| PARF Eligibility                    | Yes                                  |
| PARF Eligibility Expiry Date        | 23 Jul 2027                          |
| PARF Rebate Amount                  | \$7,320.00                           |
| <b>Intended COE Rebate Details</b>  |                                      |
| COE Expiry Date                     | 23 Jul 2027                          |
| COE Category                        | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years)                   | 10                                   |
| QP Paid                             | \$42,801.00                          |
| COE Rebate Amount                   | \$41,144.00                          |
| <b>Total Rebate Amount</b>          | <b>\$48,464.00</b>                   |

The information contained herein is correct as at 12 Dec 2017

OK

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

**From :**  
PEGASUS ENGINEERING & TRADING PTE LTD  
C/O 51 DEFU LANE 10  
SINGAPORE 539216  
Officer in Charge : ALVIN LOW WAI LUN  
Tel :  
Email :

**Customer :**  
GRAB RENTALS 2 PTE LTD  
28, SIN MING LANE,  
#07-71 MIDVIEW CITY  
SINGAPORE 573969  
Attn :  
Tel :  
Fax :  
P/P 2424/2  
LKE - Marcus  
12/12/17 @ 0935h  
12/12/17 3d?

|                                                                                                  |                                |                       |
|--------------------------------------------------------------------------------------------------|--------------------------------|-----------------------|
| Quotation No : QO17/12-1050                                                                      | Quotation Date : 05/12/2017    | Terms : 30 DAYS       |
| Vehicle No : SLQ8301Y                                                                            | Chassis No : JM6BN22A8H0153599 | Third Party Insurer : |
| Model : MAZDA 3                                                                                  |                                | Date of Accident :    |
| marks : TP INSURER: MSIG INSURANCE , INSURED VEHICLE NO: SJT1800C , DATE OF ACCIDENT: 02.12.2017 |                                |                       |

| ITEM | DESCRIPTION                                                                                 | QTY | UNIT PRICE | AMOUNT (SGD) |
|------|---------------------------------------------------------------------------------------------|-----|------------|--------------|
| 1    | REAR BUMPER 20/22                                                                           | 1   | 1,075.0000 | 1,075.00     |
| 2    | REAR BUMPER REFLECTOR 11                                                                    | 2   | 51.0000    | 102.00       |
| 3    | REAR BUMPER END SPLASHIELD COVER 11                                                         | 2   | 80.0000    | 160.00       |
| 4    | REAR BUMPER CLIPS nu                                                                        | 10  | 5.0000     | 50.00        |
| 5    | REAR BUMPER REINFORCEMENT PD                                                                | 1   | 538.0000   | 538.00       |
| 6    | REAR BUMPER PARKING SENSOR chhA                                                             | 1   | 450.8000   | 450.80       |
| 7    | REAR BUMPER SIDE RETAINER 11                                                                | 2   | 46.0000    | 92.00        |
| 8    | REAR BUMPER SIDE HOLDER 11                                                                  | 2   | 37.0000    | 74.00        |
| 9    | REAR BUMPER SIDE HOLDER RIVETS 11                                                           | 4   | 6.0000     | 24.00        |
| 10   | REAR BUMPER TOW COVER 10.1 115                                                              | 2   | 17.0000    | 34.00        |
| 11   | REAR BUMPER SCREW SPACER 11                                                                 | 2   | 8.0000     | 16.00        |
| 12   | REAR END PANEL 12                                                                           | 1   | 506.0000   | 506.00       |
| 13   | REAR END PANEL INNER TRIM 11                                                                | 1   | 86.0000    | 86.00        |
| 14   | REAR END PANEL INNER TRIM CLIPS 11                                                          | 4   | 5.0000     | 20.00        |
| 15   | BOOTLID MAZDA 3 BADGE 11                                                                    | 1   | 54.0000    | 54.00        |
| 16   | BOOTLID SKYACTIV BADGE 11                                                                   | 1   | 64.0000    | 64.00        |
| 17   | BOOTLID CENTRE EMBLEM BADGE 11                                                              | 1   | 75.0000    | 75.00        |
| 18   | LESS 20% (ITEMS 1-17)                                                                       | 1   | -684.1600  | -684.16      |
| 19   | TO REINSTALL REAR BUMPER SIMULATION TEST 1680                                               | 1   | 120.0000   | 120.00       |
| 20   | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR. 1344 | 1   | 150.0000   | 150.00       |
| 21   | TO RUST-PROOFING OF THE AFFECTED AREAS.                                                     | 1   | 120.0000   | 120.00       |
| 22   | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                     | 1   | 60.0000    | 60.00        |

C/F 0.00

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                             |
|---------------------------------------------------------------------------------------------|
| <b>From :</b>                                                                               |
| <b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b><br>C/O 51 DEFU LANE 10<br>SINGAPORE 539216 |
| Officer in Charge : ALVIN LOW WAI LUN<br>Tel :<br>Email :                                   |

|                                                                                                |
|------------------------------------------------------------------------------------------------|
| <b>Customer :</b>                                                                              |
| <b>GRAB RENTALS 2 PTE LTD</b><br>28, SIN MING LANE,<br>#07-71 MIDVIEW CITY<br>SINGAPORE 573969 |
| Attn :<br>Tel :<br>Fax :                                                                       |

|                                                                                                  |                                |                       |
|--------------------------------------------------------------------------------------------------|--------------------------------|-----------------------|
| Quotation No : QO17/12-1050                                                                      | Quotation Date : 05/12/2017    | Terms : 30 DAYS       |
| Vehicle No : SLQ8301Y                                                                            | Chassis No : JM6BN22A8H0153599 | Third Party Insurer : |
| Model : MAZDA 3                                                                                  | Date of Accident :             |                       |
| marks : TP INSURER: MSIG INSURANCE , INSURED VEHICLE NO: SJT1800C , DATE OF ACCIDENT: 02.12.2017 |                                |                       |

| ITEM | DESCRIPTION                                                                                                             | QTY | UNIT PRICE | AMOUNT (SGD) |
|------|-------------------------------------------------------------------------------------------------------------------------|-----|------------|--------------|
|      |                                                                                                                         |     |            | B/F 0.00     |
| 23   | PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. | 1   | 750.0000   | 300 750.00   |
| 24   | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                       | 1   | 700.0000   | 500 700.00   |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

|                    |          |
|--------------------|----------|
| <b>Sub Total</b>   | 4,636.64 |
| <b>GST(7.00%)</b>  | 324.56   |
| <b>Total (SGD)</b> | 4,961.20 |

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023534/UTBN2

Date: 20/12/2017

## REFERENCE

|                       |                                      |                      |             |
|-----------------------|--------------------------------------|----------------------|-------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | 27736902MCY |
| Claimant Vehicle No : | SLQ8301Y                             | Insured Vehicle No : | SJT1800C    |
| Date of Loss:         | 02/12/2017                           | Nature of Claim:     | TP          |
|                       |                                      | Claim No:            | 539940      |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SLQ8301Y                     | Engine No:  | P520445383        |
| Make & Model:               | MAZDA 3, 1.5 SEDAN EU6 (A)   | Chassis No: | JM6BN22A8H0153599 |
| Reg. Date:                  | 24/07/2017 (Man. Year: 2017) | Odometer:   | 32670 km          |
| Colour:                     | Blue                         |             |                   |
| Engine Capacity:            | 1496 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |           |                  |           |
|-------------------|-----------|------------------|-----------|
| Front Tyre Size:  | 205/60R16 | Rear Tyre Size:  | 205/60R16 |
| Front Left Side:  | Toyo 6 mm | Rear Left Side:  | Toyo 6 mm |
| Front Right Side: | Toyo 6 mm | Rear Right Side: | Toyo 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                         | 2,736.64        | 1,544.00        | 1,192.64        | 43.58        |
| Miscellaneous Items           | 0.00            | 0.00            | 0.00            |              |
| Labour                        | 1,900.00        | 880.00          | 1,020.00        | 53.68        |
| Paintwork Labour              | 0.00            | 0.00            | 0.00            |              |
| Towing                        | 0.00            | 0.00            | 0.00            |              |
| <b>Gross Total (S\$)</b>      | <b>4,636.64</b> | <b>2,424.00</b> | <b>2,212.64</b> | <b>47.72</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>324.56</b>   | <b>169.68</b>   | <b>154.88</b>   | <b>47.72</b> |
| <b>Nett Amount (S\$)</b>      | <b>4,961.20</b> | <b>2,593.68</b> | <b>2,367.52</b> | <b>47.72</b> |

## INSPECTION

|                     |            |                                                                                  |
|---------------------|------------|----------------------------------------------------------------------------------|
| Date of Assignment: | 12/12/2017 |                                                                                  |
| Date Inspected:     | 12/12/2017 | Inspected At: 51 Defu Lane 10<br>Repairer: Pegasus Engineering & Trading Pte Ltd |

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

|                                                              |                                                                                                                                                                              |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 20 Dec 2017)                                                                                                                                |
| <b>Parts:</b> 143                                            | MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)                                                                                                                  |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b> (Unsubmitted, no print-code for SLQ8301Y) |                                                                                                                                                                              |
| <b>Validity:</b>                                             | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>                                         | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |

### Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition       | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------|-----------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                      | Dented/Deformed | 1,075.00 FL | *1,075.00 FL |
| 2   | 2   |          | *REAR BUMPER REFLECTOR            | Not Necessary   | 102.00 FL   | *- FL        |
| 3   | 2   |          | *REAR BUMPER END SPLASHIELD COVER | Not Necessary   | 160.00 FL   | *- FL        |
| 4   | 10  |          | *REAR BUMPER CLIPS                | Necessary       | 50.00 FL    | *50.00 FL    |
| 5   | 1   |          | *REAR BUMPER REINFORCEMENT        | Dented          | 538.00 FL   | *538.00 FL   |
| 6   | 2   |          | *REAR BUMPER SIDE RETAINER        | Not Necessary   | 92.00 FL    | *- FL        |
| 7   | 2   |          | *REAR BUMPER SIDE HOLDER          | Not Necessary   | 74.00 FL    | *- FL        |
| 8   | 4   |          | *REAR BUMPER SIDE HOLDER RIVETS   | Not Necessary   | 24.00 FL    | *- FL        |
| 9   | 1   |          | *REAR BUMPER TOW COVER            | N/s Torn        | 34.00 FL    | *17.00 FL    |
| 10  | 2   |          | *REAR BUMPER SCREW SPACER         | Not Necessary   | 16.00 FL    | *- FL        |
| 11  | 1   |          | *REAR END PANEL                   | Repair          | 506.00 FL   | *- FL        |
| 12  | 1   |          | *REAR END PANEL INNER TRIM        | Not Necessary   | 86.00 FL    | *- FL        |
| 13  | 4   |          | *REAR END PANEL INNER TRIM CLIPS  | Not Necessary   | 20.00 FL    | *- FL        |
| 14  | 1   |          | *BOOTLID MAZDA 3 BADGE            | Not Necessary   | 54.00 FL    | *- FL        |
| 15  | 1   |          | *BOOTLID SKYACTIV BADGE           | Not Necessary   | 64.00 FL    | *- FL        |
| 16  | 1   |          | *BOOTLID CENTRE EMBLEM BADGE      | Not Necessary   | 75.00 FL    | *- FL        |
| 17  | 1   |          | *REAR BUMPER PARKING SENSOR       | Shorted         | 360.64 FS   | *200.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>3,330.64</b> | <b>1,880.00</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | <b>594.00</b>   | <b>336.00</b>   |
| <b>Total Parts (\$\$)</b>                                  | <b>2,736.64</b> | <b>1,544.00</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                                                                            | Lab.Type | Repairer's | Amount |
|-------------------------|------------------------------------------------------------------------------------------------------------------------|----------|------------|--------|
| <b>Labour Items</b>     |                                                                                                                        |          |            |        |
| 1                       | TO REINSTALL REAR BUMPER SIMULATION TEST                                                                               | New      | 120.00     | -      |
| 2                       | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR                                  | New      | 150.00     | 60.00  |
| 3                       | TO RUST-PROOFING OF THE AFFECTED AREAS                                                                                 | New      | 120.00     | -      |
| 4                       | TO CHECK ELECTRICAL LIGHTING CONCERNED                                                                                 | New      | 60.00      | 20.00  |
| 5                       | PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME | New      | 750.00     | 300.00 |
| 6                       | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION                                                                       | New      | 700.00     | 500.00 |
| Gross Labour Cost (S\$) |                                                                                                                        |          | 1,900.00   | 880.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >