

12-000

ASS. REC. BY:

REF: CS/FCI17023546/MYD3/

Special Instruction:

SUBJECT

MA

ASSIGNMENT (Office)

From (Person):

Sevone Ler

of

FCI

Date/Time:

11:31 am @ 12/12/17

Estimated Cost:

Bill to:

OD / FD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBL 8068R

Insured:

SHD 4469P

at Workshop m/s

BH Auto Services

Tel:

6559 8944

of

Blk I Bin Ming Ind. Est. - Sec. C # 01-115

Policy No:

Claim No:

D17011151MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/2/2017

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Enforcement:

Date/Time:

11:35 am @ 12/12/17

Person Contacted:

Jaelyn

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SBL 8068R - X

SHD 4469P-CC4/CS17007679/117eb392

D.O.A. 17/04/17

12/12/17

Email preli revised to FCI

4/4/18

Submit LS \$1100 (un-confirmed)

REF: FCI

ASSIGNMENT

From: Date: 14/12/17

Estimated Cost

OD / (P) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SBL 8068R

at Workshop m/s: BH Auto

of: Blk I sin Ming Ind Es f &c C #01-115

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record) 1-2pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SBL 8068R (r Reg) AUG 2016

Type: (M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: (M) LEXUS cc 2494

Colour: GREY A/C Insured / Std / NI / NA

Sp Reading: 22487 T.Radio: Insured / Std / NI / NA

Eng No:

C/No: JTHBJ 919702094976

Gen. Cond: (Good) Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 25 (S/R) R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: Rear:

R/Bal: 8 mm R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A: 1/12/2017 D.O.I: 14/12/2017

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or as body

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction

~~2 weekdays~~
No Contact

RECEIVED 08 APR 2018

Date/Time: File Pass to? : Prelim. Report : Final Report

Days Of Repair: 2 Resurvey No. of Trip:

Date/Time: File Return to? vkr - typist

Add Fee: Site Insp \$ Interview \$ Tech Insp \$ Weekend \$

Survey Fee	150
Transportation	50
Photo	10
Other	
Total	210

Report Format: CWS Lump Sum / I.B.I: \$

Survey Department Check List (Case Handler)

Reference No.: CS/FI17023546 | mivd3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (_____ **):** Case handler to make sure all information created by the assignment team are ACCURATE.

1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (_____ **):** Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 4/4/18
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023546/Kvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4469P	Veh. Inspected	SBL 8068R
Policy No.		Coverage (\$)	0.00
Claim No.	D17011151MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	12/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/12/2017	Inspection Date	
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	04-12-2017	Our Ref No. D17011151MFSH
Accident Date	01-12-2017	Claim Type. Third Party
Insured Vehicle	SHD4469P	Third Party Vehicle. SBL8068R
Survey Location	BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115	
Contact Person.	JACELYN LOH	
Contact No.	65598944/ 0	Fax No. 65153144
Survey Type	WITHOUT PREJUDICE: NO EST. (NAF)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BH AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231366)

PRI Documents

Close X

PRI Header Details

Claim No	D17011151MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & BH AUTOS
Workshop Name	BH AUTO SERVICES PTE LTD (Contact Person : JACELYN LOH)	Survey Location & Contact Details	BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-1: Mobile: 0 , Phone: 65598944 , Fax: 65153144 EmailId: JACELYN.LOH@BHAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. (NAF)		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4469P	TP Vehicle No	SBL8068R
PRI Recieved Date	11-12-2017 10:04:40 PM	Surveyor Appointed Date	12-12-2017 11:30:40 AM	Surveyor Accept Date	12-12-2017 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	12-12-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 18 December, 2017 9:22 AM
To: 'Claim Workflow System'
Cc: SERENELER@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011151MFSH/1, SBL 8068R
Attachments: SBL 8068R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SBL 8068R
Date of survey: 14/12/2017
Number of days: 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 12 December, 2017 11:38 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011151MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 12 December, 2017 11:30 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SERENELER@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011151MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Your ref: D17011151MFSH
Our ref: CS/FCII7023546/M1vd3

Date : 18/12/2017

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SBL 8068R


We thank you for your instruction on 12/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/12/2017 at the premises of M/s BH AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$7,439.19
Revised Estimate Amount	: S\$1,382.98
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

MA CHIN FOOK
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	0212J

Vehicle Details

Vehicle No.	SBL8068R
Vehicle to be Exported	No
Intended De-registration Date	11 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	LEXUS ES250 LUXURY A/T S/R
Primary Colour	Grey
Manufacturing Year	2016
Engine No.	2ARF252146
Chassis No.	JTHBJ1GG702094976
Maximum Power Output	135.0 kW (181 bhp)
Open Market Value	\$40,888.00
Original Registration Date	26 Aug 2016
First Registration Date	26 Aug 2016
Transfer Count	0
Actual ARF Paid	\$49,244.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	25 Aug 2026
PARF Rebate Amount	\$36,933.00

Intended COE Rebate Details

COE Expiry Date	25 Aug 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$57,508.00
COE Rebate Amount	\$50,056.00
Total Rebate Amount	\$86,989.00

The information contained herein is correct as at 11 Dec 2017

OK

- Harrier 2017
- Best shootout scene in movie history
- Unusual or rare cars

[Sign Up New Account](#)
[Forgot Password](#)

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Year One Mileage! Toyota Altis 1.8K



\$2800 Downpayment Monthly
 From \$638 Upward. Lowest
 1.88% APAC-GV Car Financing
 GV Credit Pte Ltd

• Free VICOM evaluation
 • Free grooming and 6 months maintenance
 • In-house workshop ensures quality service
 • Member of SVTA and hire purchase association
 • 100% deposit refund for unapproved loan


YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted

20 results/page

2 vehicles

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Lexus ES250	Any	Any	2016	Any	Any	Any	Available
	Lexus ES250	\$149,000	\$15,480 /yr	11-Mar-2016	2,494 cc	29,000 km	Luxury	Available
Car Is In Amazing Condition. Full Surround Cameras Monitoring The Vehicle. Under Warranty At Borneo Motors. Owner Upgrading. F1 Autos Pte Ltd Posted: 27-Nov-2017 Tags: 2016 Lexus ES250, 2016 Lexus ES250, Lexus ES250, Lexus ES250, Lexus ES250, ES250, Used Lexus								
	Lexus ES250 Luxury	\$159,800	\$16,450 /yr	27-Feb-2016	2,494 cc	21,695 km	Luxury	Available
Certified Borneo(Agent) Unit! Facelift Model!Agent 5 Years Warranty. *First Class Car. Experience It. Full Agent Service And Maintenance. Complimentary In-house 2 Years Maintenance Package. In-house F... Republic Auto Posted: 24-Nov-2017 Tags: 2016 Lexus ES250, 2016 Lexus ES250, Lexus ES250, Lexus ES250, Lexus ES250, ES250, Used Lexus								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Lexus ES250, Lexus ES250 Singapore, used Lexus ES250 Singapore, used Lexus ES250, used vehicles Singapore or even buy used Lexus ES250 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that the information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/12/2017 15:37
Date Of Accident	01/12/2017 17:00
Exact Location Of Accident	ALONG PORSTSDOWN FLYOVER & NORMANTON PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBL8068R
Insured/Policyholder	
Name Of Registered Owner	TEOH CHARN BENG STEPHEN
NRIC No	S7220212J
Email Address	DRSTEPHENTEOH@GMAIL.COM.SG
Mobile Phone No	(LOCAL) +65-96826579
Alternative Phone No	OFFICE-96826579

Vehicle Particulars

Manufacturer	TOYOTA
Model	LEXUS ES250 LUXURY A/T S/R
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1946501
Cover Note Number	

Driver

Name of Driver	TEOH CHARN BENG STEPHEN
NRIC No	S7220212J
Date Of Birth	09/06/1972
Occupation	INDOOR
Date Of Driving Pass	22/03/1990
Driving Experience	27 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96826579
Fax Number	
Contact Number	OFFICE-96826579
EEmail Address	DRSTEPHENTEOH@GMAIL.COM.SG

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD4469P

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan & Statement.

On 1 Dec 2017 Friday, around 1700 hrs, I was travelling along Portsdown Avenue towards Science Park Driver. I was on Portsdown Flyover and had stopped at the intersection waiting to turn right onto the slip road leading to AYE towards Jurong. I was on the 2nd lane from the right (middle lane).

A light blue taxi was on my right (right lane) awaiting to U-turn back.

When the traffic light at the intersection turned green, I started to turn right into the AYE slip road. A few seconds later during the turn when I was in the middle of the intersection, I felt a bump on the right side of my car that caused my car to swerve a bit. It appears that when I was turning right, the car has moved out too far (to U-turn back) thus hitting my rear right wheel.


Looking in my right side mirror, I can see the light blue taxi starting his U-turn. As I was then in the middle of the intersection almost onto the slip road with cars behind me. By then the taxi had U-turned and travelling back onto Portsdown Flyover towards Queensway.

For safety reasons, I was unable to stop to check the other vehicle number, or exchange details. I was thus unable to provide any information of the other car (other than it's a light blue taxi).

When I could stop my vehicle to check for damage, there were scratches on the paintwork on the body above the right rear wheel.

A2) SBL 8068 R

B3) SHD 4469P



math

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

First Capital Insurance Ltd

30 Robinson Road
#16-01 City House
Singapore (068877)
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6507 3848 Fax : 6507 3849
DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SBL8068R

MODEL : LEXUS ES250

POLICY NO : VPA/P1946501

CHASSIS NO : JTHBJGG702094976

YEAR OF MANUFACTURE : 2016

DATE / TIME OF ACCIDENT: 01/12/2017 Time: 1700Hrs ALONG PORTSDOWN

THIRD PARTY VEHICLE NO: SHD4469P

FLYOVER AND NORMANTON PARK.

Date: 13/12/2017

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price S\$	Net S\$	Amount S\$
1	1	871.20		871.20 <i>del</i>
2	1	96.20		96.20 <i>X OVC</i>
3	1	96.20		96.20 <i>X OVC</i>
4	1	70.27		70.27 <i>X OVC</i>
5	1	297.60		297.60 <i>X OVC</i>
6	1	1,076.40		1,076.40 <i>X OVC</i>
7	1	195.40		195.40 <i>X OVC</i>
8	1	1,918.75		1,918.75 <i>X OVC</i>
9	1	401.75		401.75 <i>X OVC</i>

Sub-Total: 5,023.77

Less: 10% discount - 502.38

Total Parts after 10% discount: 4,521.39

Special Nett Items

1	Rear Bumper Clips	10	3.89	38.90 <i>NIN</i>
2	Rear Fender Shield Clips	10	3.89	38.90 <i>X NIN</i>
3	Rear Bumper Sensor	1	250.00	250.00 <i>X OVC</i>
4	Windscreen sealant	1	100.00	100.00 <i>X NIN</i>
				427.80

Total Parts: 4,949.19

Labour Charges For RH Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	1,000.00 <i>250</i>
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	800.00 <i>250</i>
3	Provide skill labour to disconnect and check electrical wiring	60.00 <i>X</i>
4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs	150.00 <i>X</i>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023546/M1vd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4469P	Veh. Inspected	SBL 8068R
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17011151MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	12/12/2017
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA LEXUS	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTHBJ1GG702094976	Colour	GREY
Odometer	23487	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	YOKOHAMA	8 mm
L/H Front Tyre	215/55 R17	YOKOHAMA	8 mm
R/H Rear Tyre	215/55 R17	YOKOHAMA	8 mm
L/H Rear Tyre	215/55 R17	YOKOHAMA	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/12/2017	Inspection Date	14/12/2017
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575638		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBL 8068R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	871.20	871.20
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	96.20	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	96.20	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	70.27	-
1	REAR BUMPER LOWER GARNISH	SERVICEABLE	297.60	-
1	REAR BUMPER RH	SERVICEABLE	1,076.40	-
1	REAR FENDER SHIELD	SERVICEABLE	195.40	-
1	REAR WHEEL RIM 17 RH	SERVICEABLE	1,918.75	-
1	REAR LAMP ASSY RH	SERVICEABLE	401.75	-
	LESS 10% DISCOUNT		-502.38	-87.12
			4,521.39	784.08
SPECIAL NETT ITEMS				
10	REAR BUMPER CLIPS @\$3.89 (SN)	NECESSARY	38.90	38.90
10	REAR FENDER SHIELD CLIPS @\$3.89(SN)	NOT NECESSARY	38.90	-
1	REAR BUMPER SENSOR (SN)	SERVICEABLE	250.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
			427.80	38.90
LABOUR				
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.		1,000.00	250.00
	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES.		800.00	250.00
	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING.	NOT NECESSARY	60.00	-
	REMOVE AND REINSTALL CUSHIONS ,SEATS,BACKREST ,INNER TRIM GARNISH ,ROOF LINING AND OR UPHOLSTERY TO FACILITATE REPAIRS.	NOT NECESSARY	150.00	-
	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR /FACILITATE .	NOT NECESSARY	80.00	-

Report Ref No. CS/FC117023546/M1vd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PROVIDE SKILL LABOUR TO CHECK AND RE-ADJUST REAR WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE BUMPER SENSORS.		60.00	60.00
	PROVIDE SKILL LABOUR TO REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	200.00	-
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE WHEEL RIM WITH BALANCING.	NOT NECESSARY	80.00	-
			2,490.00	560.00
GRAND TOTAL			7,439.19	1,382.98
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CS/FCI17023546/M1vd3q2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.