

INS. CASE OWNER:

CC 3 / AIG17023551 / K1h23

LKK:

IDAC:

Surveyor:

KALVIN

DOI:

ASSIGNMENT

11/12/17


Date / Time:

11/12/17

Registered in Merimen:

12/12/17

Pre-assign / CCU / FTE



Insured Vehicle No. : SLM 2378L

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II : SS

D.O.A : 09/12/17

Place of Accident :

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No


SHC 84476

GY 701L

STQ 17522

SLM 2378L

SHA 2846M



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

COGE Clapans

Date/Time	STAGE	DATE / PIC
SHA 2846M - NS/INC12024680/H190 D.O.A 20/12/12	Non-Reporting ltr (1st):	
SLM 2378L - X	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	S\$	(days) Reduction:	%
FINAL SETTLEMENT Date/Time:		Confirm by:	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	Email ☐ Call ☐
Repair Cost:	S\$		
Loss of Rental (LOR):	S\$	(days)	
Loss of Use (LOU):	S\$	(\$ x days)	
Loss of Income (LOI):	S\$	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	S\$		
Medical:	S\$		
Disbursement:	S\$	(e.g. Tow/ Independent)	
Legal Cost	S\$		
Total:	S\$	Global Sum S\$:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	S\$	Name 1:	
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

20A, Bras Basah Road, Singapore 179570

Workshop: 45 Pandan Road, Singapore 104206

Workshop:

381, 383, 385, 387, 389, 391, 393, 395, 397, 399, 401, 403, 405, 407, 409, 411, 413, 415, 417, 419, 421, 423, 425, 427, 429, 431, 433, 435, 437, 439, 441, 443, 445, 447, 449, 451, 453, 455, 457, 459, 461, 463, 465, 467, 469, 471, 473, 475, 477, 479, 481, 483, 485, 487, 489, 491, 493, 495, 497, 499, 501, 503, 505, 507, 509, 511, 513, 515, 517, 519, 521, 523, 525, 527, 529, 531, 533, 535, 537, 539, 541, 543, 545, 547, 549, 551, 553, 555, 557, 559, 561, 563, 565, 567, 569, 571, 573, 575, 577, 579, 581, 583, 585, 587, 589, 591, 593, 595, 597, 599, 601, 603, 605, 607, 609, 611, 613, 615, 617, 619, 621, 623, 625, 627, 629, 631, 633, 635, 637, 639, 641, 643, 645, 647, 649, 651, 653, 655, 657, 659, 661, 663, 665, 667, 669, 671, 673, 675, 677, 679, 681, 683, 685, 687, 689, 691, 693, 695, 697, 699, 701, 703, 705, 707, 709, 711, 713, 715, 717, 719, 721, 723, 725, 727, 729, 731, 733, 735, 737, 739, 741, 743, 745, 747, 749, 751, 753, 755, 757, 759, 761, 763, 765, 767, 769, 771, 773, 775, 777, 779, 781, 783, 785, 787, 789, 791, 793, 795, 797, 799, 801, 803, 805, 807, 809, 811, 813, 815, 817, 819, 821, 823, 825, 827, 829, 831, 833, 835, 837, 839, 841, 843, 845, 847, 849, 851, 853, 855, 857, 859, 861, 863, 865, 867, 869, 871, 873, 875, 877, 879, 881, 883, 885, 887, 889, 891, 893, 895, 897, 899, 901, 903, 905, 907, 909, 911, 913, 915, 917, 919, 921, 923, 925, 927, 929, 931, 933, 935, 937, 939, 941, 943, 945, 947, 949, 951, 953, 955, 957, 959, 961, 963, 965, 967, 969, 971, 973, 975, 977, 979, 981, 983, 985, 987, 989, 991, 993, 995, 997, 999

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 104206

820, 822, 824, 826, 828, 830, 832, 834, 836, 838, 840, 842, 844, 846, 848, 850, 852, 854, 856, 858, 860, 862, 864, 866, 868, 870, 872, 874, 876, 878, 880, 882, 884, 886, 888, 890, 892, 894, 896, 898, 900, 902, 904, 906, 908, 910, 912, 914, 916, 918, 920, 922, 924, 926, 928, 930, 932, 934, 936, 938, 940, 942, 944, 946, 948, 950, 952, 954, 956, 958, 960, 962, 964, 966, 968, 970, 972, 974, 976, 978, 980, 982, 984, 986, 988, 990, 992, 994, 996, 998, 999

45 Pandan Road Singapore 104206

7, Selegie Road, Singapore 117073

8, Selegie Road, Singapore 117073

A member of COMFORTDELGRO

Date/Time: 11.12.2017 10:21

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO.305096473

CUSTOMER

COMPANY: COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO: 7010045
ADDRESS: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
L. (R) 65508755 (O)
(P)

REGN NO:

SHA2846M

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

10.

DATE/TIME IN
12.2017 08:00

YR OF MANU

03.09.2015

TARGET DATE

CHASSIS CODE

KMHLB41UMGU077258

COMPLETION DATE/TIME:

SCOUT CARD NO.

JOB DESCRIPTION

Accident Date: 09.12.2017

NATURE: 3P 09.12.2017

S/NO

LABOR CODE

DESCRIPTION

ALC - taxi Rear damage
LKK/Kalini -

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Signature: LARRY
Vehicle No.: SHA2846M

Exit Pass

Vehicle No.: SHA2846M

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard