

ASS. REC. BY:

REF:

CS/CT117023553/KH022

Special instruction:

Surveyor:
- Prelim

Kenneth.

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CT

Date/Time:

12/12/2017 11:26am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GT 3720Y

Insured:

SJD 3766P

at Workshop m/s

Autovexel

Tel:

6459 1630

of

160 Sin Ming Drive #06-01

Policy No:

DMPCSN1307971702

Claim No:

SNM17 D17 0U3CD.

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10.12.2017

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

12.12.2017 1:20pm

Person Contacted:

Doreen

Vehicle: ~~IN~~ / OUT

Date/Time	Action/Instruction (✓) Estimate
	GT 3720Y X
	SJD 3766P X
	11hp B550d (Red: 7929.90:59%)

ASS. REC. BY:

REF: C 72/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

G7 37204

Yr Regn:

05, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV200

c.c

1461

Colour

m. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

35752

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSK YB Am 207 0096512

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M17 S/Rim / STD A/Rim or

Tyre Size:

F:

R:

175/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

5

mm

L/Bal.

6

mm

L/Bal.

5

mm

D.O.A.

10/12/17

D.O.I.

12/12/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

NIS body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/12

File pass to Catherine

Date/Time, File Pass to?



Prel. Report

1) 7/3 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

5500/-

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17023553/Ktb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-12-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJD 3766P	Veh. Inspected	GT 3720Y
Policy No.	DMPCSN1507971702	Coverage (\$)	0.00
Claim No.	SNM17D07043C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/12/2017	Inspection Date	12/12/2017
Survey held at	AUTOEXCEL ENGINEERING PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017		12 Dec 2017 16:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant:	SOON HENG HENG ENGRG & RENOVATION, Co. Reg. No.: 52897042M		
Vehicle Reg. No.:	GT3720Y	Date of Loss:	10/12/2017 11:00 - :59
Claim Type:	TP / SNM17D07043C02	Policy/Cover Note No.:	DMPCSN1507971702
Vehicle Reg. No. (Insured):	SJD3766P	Policy No. (Claimant):	5071910298-02 (COMP)
		Excess:	S\$0.00
Repairer:	Auto Excel Engineering Pte Ltd (HQ) 160 Sin Ming Drive, Sin Ming Auto City #06-01 & #06-15, 575722 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/12/2017]		
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT TO PRS AND REVERT WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 12 December, 2017 11:26 AM
To: assignments
Cc: Admin A
Subject: FW: CTP REF NO. SJD3766P AE REF NO. GT3720Y - ACCIDENT INVOLVING SJD3766P AND GT3720Y ON 10 DECEMBER 2017

Importance: High

Hi assignment team,

FYIP.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Autoexcel Engineering [mailto:aeexcel@singnet.com.sg]
Sent: Tuesday, 12 December, 2017 10:54 AM
To: 'Irene Tay' <irene.tay@sg.cntaiping.com>
Subject: RE: CTP REF NO. SJD3766P AE REF NO. GT3720Y - ACCIDENT INVOLVING SJD3766P AND GT3720Y ON 10 DECEMBER 2017
Importance: High

Dear Irene,

We wish to appoint Kenneth Kong.

Please help us with the arrangement.

Thank you

Regards
Doreen Chan
64591630

From: Irene Tay [mailto:irene.tay@sg.cntaiping.com]
Sent: Tuesday, December 12, 2017 10:36 AM
To: aeexcel@singnet.com.sg
Cc: aeexcel@singnet.com.sg
Subject: CTP REF NO. SJD3766P AE REF NO. GT3720Y - ACCIDENT INVOLVING SJD3766P AND GT3720Y ON 10 DECEMBER 2017

Without Prejudice
Save As To Costs

Dear Sir/Mdm,

We refer to your pre-repair survey request / email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

Here are the list of surveyors ;

Tay Beng Hee
See Chew Seng
Dereck Oh Siong Wee
Kalvin Ang
Bryan Ang
Steven Foong
Adrian Ling
Marcus Chua
Kenneth Kong
Henry Ng

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/12/2017 11:05
Date Of Accident	10/12/2017 11:30
Exact Location Of Accident	ALONG BLK 278 TAMPINES STREET 22
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GT3720Y
Insured/Policyholder	
Name Of Registered Owner	SOON HENG HENG ENGRG & RENOVATION
Co Reg No	52897042M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92778801
Alternative Phone No	OFFICE-92778801
Vehicle Particulars	
Manufacturer	NISSAN
Model	NV200
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5071910298-02 (COMP)
Cover Note Number	
Driver	
Name of Driver	FAN FOOK HONG WILSON
NRIC No	S9325981E
Date Of Birth	20/07/1993
Occupation	OUTDOOR
Date Of Driving Pass	16/11/2011
Driving Experience	6 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92778801
Fax Number	
Contact Number	OTHERS-92778801
Email Address	NOEMAIL

Address BLK 279 TAMPINES STREET 22 #09-224
Postcode 520279
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number SJD3766P/
Vehicle Make/Model/Colour NISSAN CEFIRO

Details Of Properties

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



11 DEC 2017

[Signature]



IDAC SIN MING (P) LTD
385 Sin Ming Pk. Ave
Singapore 570718
Tel: 64553356 ARC: 56415243
Fax: 64526621


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS driving straight, suddenly SJD 3766P come
420
out from parking lot and never check his right and
the left of
hit onto my vehicle GT 37204.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

11 DEC 2017
IDAC SIN MING (VAC)
385 Sin Ming Drive
Singapore 575718
Tel: 64555358 (ARC), 66975243
Fax: 64526621

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: 52897042M
 Owner ID Type: Business
 Owner Name: SOON HENG HENG ENGRG & RENOVATION
 Registered Address: 5 TOA PAYOH INDUSTRIAL PARK #01-1287 SINGAPORE 319057
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: GT3720Y
 Previous Vehicle No.: -
 Effective Date of Ownership: 29 May 2015
 Original Regn Date: 29 May 2015
 Registration Date: 29 May 2015
 Year of Manufacture: 2015
 Vehicle Type: Goods (Closed) Van/Van Panel (Delivery)
 Vehicle Scheme: -
 Vehicle Attachment 1: No Attachment
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: NISSAN
 Vehicle Model: NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
 Primary Colour: Grey
 Secondary Colour: -
 Passenger Capacity: 1
 Chassis No.: VSKYBAM20Z0096512
 Engine No.: K9KC400D054411
 Engine Capacity/Power Rating: 1461 cc / -
 Maximum Power Output: -
 Propellant: Diesel
 Max Unladen Weight: 1320 kg
 Maximum Laden Weight: 2030 kg
 Open Market Value: \$20,122.00
 PARF Eligibility: No
 PARF Eligibility Expiry Date: -
 Minimum PARF Benefit: -
 No. of Transfers: 0
 IU Label No.: 1042644682
 COE No.: 2015052905000608G
 COE Expiry Date: 28 May 2025
 COE Category: C - Goods Vehicle & Bus
 COE Registration Category: C - Goods Vehicle & Bus
 Quota Premium (QP) / Prevailing Quota: - / \$56,468.00

Premium:

QP (Regn Cat):

QP during COE Bidding
Exercise:

Actual ARF Paid: \$1,007.00

CO2 Emission: 138.00 (g/km)

Message: The vehicle is registered under Early Turnover Scheme.

144

Not Authorised
1 Sup @ 5500/-
Primary After Pricing

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

DATE: 11/12/17

QUOTATION -THIRD PARTY CLAIM

CHINA TAIPING INSURANCE (S) PTE LTD

Attn: Motor Claim Department . Officer In Charge

Accident on : 10/12/2017

Claim : Third Party Claim
Veh. No : GT 3720 Y
Model : NISSAN NV 200
Insured Ins: NTUC INS

QTY	PARTICULARS	AMOUNT	SURVEYOR
Your Insurer Vehicle No : YOUR INSURED SJD 3766 P			
1PC	FRONT BUMPERS	\$ 559.00	Nett ✓
1PC	FRONT FENDER-LH	\$ 504.70	✓
1PC	FRONT HEADLAMP -LH	\$ 434.00	✓ X
1PC	FRONT FENDER-GARNISH	\$ 206.10	✓ X
1PC	FRONT DOOR ASSY	\$ 1219.70	✓
1PC	FRONT DOOR STICKER	\$ 55.00	✓
1PC	FRONT DOOR SIDE MIRROR-LH	\$ 230.00	✓ X
1PC	CENTRE PILLAR	\$ 580.00	✓ X
1PC	FRONT LOWER ARM	\$ 208.80	✓ X
1PC	FRONT SHOCK ABSORBER	\$ 252.80	✓
1PC	FRONT KUNCKLE ARM	\$ 357.20	✓
1PC	FRONT DRIVE SHAFT ASSY	\$ 861.70	✓ X
1PC	FRONT WHEEL BEARING	\$ 228.50	✓
1PC	REAR DOOR ASSY	\$ 1281.70	Nett ✓
1PC	REAR BUMPER	\$ 650.40	✓
1PC	REAR FENDER	REPAIR	
1PC	REAR WHEEL BEARING	\$ 365.60	✓ X
1PC	CENTRE PILLAR		✓
1PC	FRONT DOOR LOCK ASSY	\$ 222.00	Nett ✓
1PC	REAR DOOR LOCK ASSY	\$ 258.00	✓ X
2PCS	TYRES	NETT \$ 400.00	Nett 500.00 ✓
2PCS	FRONT AND REAR RIMS -LH	NETT \$ 300.00	Nett 400.00 ✓
2PCS	FRONT AND REAR HALF CAPS -LH	NETT \$ 427.60	Nett 500.00 ✓
LABOUR CHARGES TO DO WELDING ,ALIGN BODY ADJUST		\$ 1,450.00	800/-
REPAIR & REPLACE ON FRONT, SIDE & REAR DAMAGED AREA			
TO DO PUTTY & SPRAY PAINTING ON AFFECTED AREA		\$ 1,450.00	1000/-
INNER & OUTER			
TO REMOVE AND REFIT FRONT & REAR DOOR ACCESSORIES		\$ 550.00	1200/-
AND ALIGN POSTION			
CHECK WIRING SYSTEM		\$ 60.00	200/-
TO SPRAY ANTI-RUST		\$ 150.00	900/-
TRANSFER TAILGATE PART TO NEW TAILGATE		\$ 100.00	X
TRANSFER DOOR GLASS ACCESSORIES TO NEW DOOR		\$ 130.00	X
			13506.80

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Authorized
L1 Sing 87
Passing After Repair

DATE: 11/12/17

QUOTATION -THIRD PARTY CLAIM

CHINA TAIPING INSURANCE (S) PTE LTD

Attn: Motor Claim Department . Officer In Charge

Accident on : 10/12/2017

Claim : Third Party Claim
Veh. No : GT 3720 Y
Model : NISSAN NV 200
Insured Ins: NTUC INS

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : YOUR INSURED SJD 3766 P		
	<i>Nett for</i>		<i>car</i>
1PC	FRONT BUMPERS <i>Nett for</i>		<i>✓</i>
1PC	FRONT FENDER -LH <i>Nett</i>		<i>✓</i>
1PC	FRONT HEADLAMP -LH <i>Nett</i>		<i>X</i>
1PC	FRONT FENDER -GARNISH <i>Nett</i>		<i>X</i>
1PC	FRONT DOOR ASSY <i>Nett 1 way</i>		<i>✓</i>
1PC	FRONT DOOR STICKER <i>Nett</i>		<i>✓</i>
1PC	FRONT DOOR SIDE MIRROR -LH <i>Nett</i>		<i>X</i>
1PC	CENTRE PILLAR <i>R</i>		<i>X</i>
1PC	FRONT LOWER ARM		<i>?</i>
1PC	FRONT SHOCK ABSORBER		<i>?</i>
1PC	FRONT KUNCKLE ARM		<i>?</i>
1PC	FRONT DRIVE SHAFT ASSY <i>R</i>		<i>X</i>
1PC	FRONT WHEEL BEARING		<i>?</i>
1 PC	REAR DOOR ASSY <i>Nett 1 way</i>		<i>✓</i>
1 PC	REAR BUMPER <i>Nett for</i>		<i>✓</i>
1PC	REAR FENDER	REPAIR	
1 PC	REAR WHEEL BEARING		<i>?</i>
1 PC	CENTRE PILLAR <i>R</i>		<i>X</i>
1 PC	FRONT DOOR LOCK ASSY <i>R</i>		<i>X</i>
1 PC	REAR DOOR LOCK ASSY <i>R</i>		<i>X</i>
2PC	TYRES <i>Nett for</i> NETT	\$ 400.00	<i>500.00</i>
2PC	FRONT AND REAR RIMS -LH NETT <i>Nett for</i>	\$ 300.00	<i>400.00</i>
1set	FRONT AND REAR HALF CAPS -LH NETT <i>Nett</i>	\$ 350.00	<i>✓</i>
	LABOUR CHARGES TO DO WELDING ,ALIGN BODY ADJUST	\$ 1,450.00	<i>800.00</i>
	REPAIR & REPLACE ON FRONT, SIDE & REAR DAMAGED AREA		
	TO DO PUTTY & SPRAY PAINTING ON AFFECTED AREA	\$ 1,450.00	<i>1000.00</i>
	INNER & OUTER		
	TO REMOVE AND REFIT FRONT & REAR DOOR ACCESSORIES	\$ 550.00	<i>1200.00</i>
	AND ALIGN POSTION		
	CHECK WIRING SYSTEM	\$ 60.00	<i>200.00</i>
	TO SPRAY ANTI-RUST	\$ 150.00	<i>900.00</i>
	TRANSFER TAILGATE PART TO NEW TAILGATE <i>Nett</i>	\$ 100.00	<i>X</i>
	TRANSFER DOOR GLASS ACCESSORIES TO NEW DOOR <i>Nett</i>	\$ 130.00	<i>X</i>

...CLAIM SUBFOLDER...(Pending for Survey Report)

AIM SUBFOLDER TRACKING						Ins Auth'd	Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted		
Main	12 Dec 2017		12 Dec 2017 16:26 Edit Adj Rpt	S\$5,500.00 Edit Estimates	S\$5,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			
Insured:	-, Co. Reg. No.: -		
Main Claimant:	SOON HENG HENG ENGRG & RENOVATION, Co. Reg. No.: 52897042M		
Vehicle Reg. No.:	GT3720Y	Date of Loss:	10/12/2017 11:00 - :59
Claim Type:	TP / SNM17D07043C02	Policy/Cover Note No.:	DMPCSN1507971702
Vehicle Reg. No. (Insured):	SJD3766P	Policy No. (Claimant):	5071910298-02 (COMP)
		Excess:	S\$0.00
Repairer:	Auto Excel Engineering Pte Ltd (HQ) 160 Sin Ming Drive, Sin Ming Auto City #06-01 & #06-15, 575722 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/12/2017]		
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT TO PRS AND REVERT WITH YOUR RECOMMENDATION		
			<div>View All</div> <div>Compose Case Mail</div>

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GT3720Y (SNM17D07043C02)
[SJD3766P]
TP
SOON HENG HENG ENGRG & RENOVATION
Dec 10 2017 11:00AM
[-]
Auto Excel Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼		
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Sin Ming)		Thumbnail	Print
1	11/12/17 11:13	Accident Statement		Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Sin Ming)		Thumbnail	Print
1	11/12/17 11:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	11/12/17 11:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	11/12/17 11:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	11/12/17 11:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	11/12/17 11:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
2	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
3	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
4	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
5	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
6	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
7	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
8	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
9	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
10	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
11	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
12	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
13	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
14	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
15	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
16	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
17	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
18	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
19	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
20	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
21	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
22	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>
23	07/03/18 10:00	General View		Load JPG	<input checked="" type="checkbox"/>

24	07/03/18 10:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	07/03/18 10:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	07/03/18 10:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	07/03/18 10:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
28	07/03/18 10:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
29	07/03/18 10:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
30	07/03/18 10:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
31	07/03/18 10:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	07/03/18 10:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	07/03/18 10:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	07/03/18 10:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	07/03/18 10:03	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/12/17 16:26	EMAIL FROM AUTOEXCEL(1)	1	Load PDF	
2	12/12/17 16:26	EMAIL FROM AUTOEXCEL(2)	1	Load PDF	
No	Finalized On	VAC (Sin Ming)		Thumbnail	Print
1	11/12/17 11:11	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
2	11/12/17 11:11	Sketch Plan #2 [Linked Accident Report Documents]	1	Load TIF	
3	11/12/17 11:11	Sketch Plan #3 [Linked Accident Report Documents]	1	Load TIF	

Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)		Thumbnail	Print
1	11/12/17 11:13	Accident Statement	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)		Thumbnail	Print
1	11/12/17 11:12	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	11/12/17 11:12	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	11/12/17 11:12	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	11/12/17 11:12	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	11/12/17 11:12	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)		Thumbnail	Print
1	11/12/17 11:11	Sketch Plan	1	Load TIF	
2	11/12/17 11:11	Sketch Plan #2	1	Load TIF	
3	11/12/17 11:11	Sketch Plan #3	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

.

.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT117023553/KTBE2**Date:** 07/03/2018**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1507971702	
Claimant Vehicle No :	GT3720Y	Insured Vehicle No :	SJD3766P	
Date of Loss:	10/12/2017	Nature of Claim:	TP	Claim No: SNM17D07043C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GT3720Y		Engine No:	K9KC400D054411
Make & Model:	NISSAN NV200, 1.5 (A)		Chassis No:	VSKYBAM20Z0096512
Reg. Date:	29/05/2015 (Man. Year: 2015)		Odometer:	35752 km
Colour:	Metallic Grey			
Engine Capacity:	1461 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,616.80	4,841.04	4,775.76	49.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	2,250.00	1,920.00	46.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,786.80	7,091.04	6,695.76	48.57
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	13,786.80	5,500.00	8,286.80	60.11
+ GST 7.00/7.00% (S\$)	965.08	385.00	580.08	60.11
Nett Amount (S\$)	14,751.88	5,885.00	8,866.88	60.11

INSPECTION

Date of Assignment:	12/12/2017	Auto Excel Engineering Pte Ltd (HQ)
Date Inspected:	12/12/2017	Inspected At: 160 SIN MING DRIVE
		#06-01 SIN MING AUTOCITY SINGAPORE 575722
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Mar 2018)

Parts: N/A NISSAN NV200 1.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GT3720Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPERS	Dented / Cut	537.00 F	*537.00 FN
2	1		*FRONT FENDER - LH	Bent	504.70 F	*504.70 FL
3	1		*FRONT HEADLAMP - LH	Serviceable	434.00 F	*-FL
4	1		*FRONT FENDER - GARNISH	Serviceable	206.10 F	*-FL
5	1		*FRONT DOOR ASSY	Dented / Warped	1,219.70 F	*1,219.70 FL
6	1		*FRONT DOOR STICKER	Necessary	55.00 F	*55.00 FL
7	1		*FRONT DOOR SIDE MIRROR - LH	Serviceable	230.00 F	*-FL
8	1		*CENTRE PILLAR	Repair	580.00 F	*-FL
9	1		*FRONT LOWER ARM	Distorted	208.80 FS	*208.80 FS
10	1		*FRONT SHOCK ABSORBER	Bent	252.80 F	*252.80 FL
11	1		*FRONT KNUCKLE ARM	Bent	357.20 F	*357.20 FL
12	1		*FRONT WHEEL BEARING	Necessary	228.50 F	*228.50 FL
13	1		*REAR BUMPER	Dented / Cut	650.40 F	*650.40 FL
14	1		*REAR FENDER (NPA)	Repair	0.00 F	*-FL
15	1		*REAR WHEEL BEARING	Not Necessary	365.60 F	*-FL
16	1		*CENTRE PILLAR (NPA)	Repeated	0.00 F	*-FL
17	1		*FRONT DOOR LOCK ASSY	Repair	228.00 F	*-FN
18	1		*REAR DOOR LOCK ASSY	Repair	258.00 F	*-FL
19	1		*TYRES (50%) (2 PCS)	Frt Cut	400.00 FS	*100.00 FS
20	1		*FRONT AND REAR RIMS - LH (2 PCS)	Frt Dented	300.00 FS	*150.00 FS
21	2		*FRONT AND REAR HALF CAPS - LH	Dented	457.60 FS	*457.60 FS
22	1		*REAR DOOR ASSY	Dented / Warped	1,281.70 F	*1,281.70 FN
23	1		*FRONT DRIVE SHAFT ASSY	Repair	861.70 F	*-FL

F=Franchise part, S=SpcNett, L=ListItemDisc, N=NettItemDisc.

Sub Total (S\$)	9,616.80	6,003.40
- List Item Discount on L Items 0.00/30.00% (S\$)	0.00	980.49
- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	181.87

Total Parts (S\$)	9,616.80	4,841.04
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO DO WELDING, ALIGN BODY ADJUST REPAIR & REPLACE ON FRONT, SIDE & REAR DAMAGED AREA	New	1,450.00	800.00
2	TO DO PUTTY & SPRAY PAINTING ON AFFECTED AREA INNER & OUTER	New	1,450.00	1,000.00
3	TO REMOVE AND REFIT FRONT & REAR DOOR ACCESORIES AND ALIGN POSITION	New	550.00	120.00
4	CHECK WIRING SYSTEM	New	60.00	20.00
5	TO SPRAY ANTI-RUST	New	150.00	90.00
6	TRANSFER TAILGATE PART TO NEW TAILGATE	New	100.00	0.00
7	TRANSFER DOOR GLASS ACCESSORIES TO NEW DOOR	New	130.00	0.00
8	TO REMOVE & REFIT FRONT UNDERCARRIAGE, ALIGN AND CHECKING	New	200.00	160.00
9	TO COMPUTER WHEEL ALIGNMENT	New	80.00	60.00
Gross Labour Cost (\$\$)			4,170.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >