

INS CASE OWNER

Rashed

CC 61AIG170235741 Uka3

LKK:

IDAC:

Subsessor:

MARCUS

DOI:

12/12/17

Date / Time:

12/12/17

Registered in Merimen:

12/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLC 5598B

Claim No.:

682334297356

Name of Insured:

Sok ZHI WEI

Policy No.:

NOV469600

Insured Tel No.:

HP: 9150 9685

Make / Model:

MAZDA 2-1.5 (A7)

Excess Sec II : \$5

D.O.A: 06/12/17

Place of Accident:

LOYANG AVENUE

Is driver the owner?

(YES ☒ NO)

Nature of Accident:

If NO, Driver Name / Age: LEE XUE YING

Driver Tel No.: 9150 9685

(V/L ☒ YES / NO)OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability:

%

Final ? Yes / No

XD 8124T



INSRS:

WSP: VAX

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

19/12/17 (Zon:)

XD 8124T - X ; SLC 5598B - X

STAGE

DATE / PIC

Please obtain a copy of the video footage from TP.

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI: ? 02912017

After call Itr to OI: ?

Documentation Check List

Handler

Typed

Notification Itr (if non-pickup)

After call Itr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

17-11-18

YES, OI CHANGED TO 2ND RIGHT LANE WHERE TP WAS HEADING TOWARDS TPE, OI WAS AT FAULT.

24 01 2018

FIC P55 to

CAR: \$2,140.00.

LOA: 7.150.

mark down to

LOA: 2 x \$130: \$260.

above.

LTA: \$35.

or/s 2,400.00.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 22.01.18

Confirm with Irene.

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.: 1111 15

If NO or B 28, Ass. Lia:

Repair Cost: (WIPST)

\$5 2,140.00

(conflicting reason)

1. OI reported both merging lane.

Loss of Rental (LOR):

\$5

(

days)

2. TP reported OI changed lane.

Loss of Use (LOU):

\$5 260.00 (\$130 x 2 days)

Loss of Income (LOI):

\$5

(\$

x

days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5 5.35

Medical:

\$5

Disbursement:

\$5

Legal Cost

\$5

Total:

\$5 2,405.35

Global Sum \$5: 2,400.00.

FINAL PAYMENT

Date/Time: 22.01.18

Confirm with: Irene.

Email

Call

Payee 1:

\$5 2,400.00.

Name 1:

Vfix Auto Service Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

we 18

Address	BLK 813B YISHUN RING RD #10-4447
Postcode	762813
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB6324X
Vehicle Make/Model/Colour	HYUNDAI TAXI BLUE
Details Of Properties	
Name of Driver	KASIM BIN CHHOTE RAI
NRIC/Passport Number	S0281637G
Contact Number	91497052
Address	
Postcode	
Insurance Company Name	INDIA INTERNATIONAL INSURANCE PTE LTD
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	

Customer: Morcom

REF:

ALG

ASSIGNMENT

From: _____ Date: 12/12-2017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XD 81247

at Workshop m/s: Vfx

of 60 Kaki Bukit Ave 6

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

10am

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: XD 81247 Yr Regn: 1 14

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or LM

Make: ISUZU FX 277M cc: 9839

Colour: Crimson A/C: Insured / Std / NI / NA

Sp. Reading: 402838 T. Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JALFX277MD7000027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/80R222-5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Gold type

Front

Rear

R/Bal: 6 mm

R/Bal: 6/6 6/6 mm

L/Bal: 6 mm

L/Bal: 6/6 6/6 mm

D.O.A: 6/12/17

D.O.I: 12/12/17

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S R

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

(L/sun: \$2,000.00 / red: \$3,144.75 / 61%)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

\$ - PD - \$

Photos: _____

Other: _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Invs (\$ _____)

☐ Weekend (\$ _____)

**SINGAPORE
POLICE FORCE**



Police Station Of Origin:

Traffic Police Division HQ

10 Ubi Avenue 3 SINGAPORE 408665

Tel No: 65470000

CONTINUATION OF REPORT

Report No. T/20170816/2102

2 of 3



T/20170816/2102

Brief Details.

AT THE ABOVE MENTIONED DATE, TIME AND LOCATION, I WAS TRAVELLING ALONG ANG MO KIO AVENUE 3 AT A JUNCTION OF SERANGOON NORTH AVENUE 1. I ALREADY PASSED THE JUNCTION SO I PROCEEDED FORWARD. I NOTICED A POLICE CAR ON THE LEFT SLIP ROAD SO I THOUGHT THE DRIVER OF THE CAR STOPS, SO I PROCEED FORWARD. THEN OUT OF SUDDEN, THE POLICE CAR DROVE FORWARD AND I HEARD A VERY LOUD SOUND ON MY LEFT. THEN I ON MY HAZARD LIGHTS TOGETHER WITH THE POLICE CAR, WE STOPPED ON THE LEFT AND EXCHANGE OUR PARTICULARS.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG17023574/Uka3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 12-12-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 5598B	Veh. Inspected	XD 8124T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/12/2017	Inspection Date	12/12/2017
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Copy from P103

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	4394R
Vehicle Details	
Vehicle No.	XD8124T
Vehicle to be Exported	No
Intended De-registration Date	12 Dec 2017
Vehicle Make	ISUZU
Vehicle Model	FXZ77M
Primary Colour	White
Manufacturing Year	2013
Engine No.	6UZ1477688
Chassis No.	JALFXZ77MD7000027
Maximum Power Output	-
Open Market Value	\$81,793.00
Original Registration Date	02 Jan 2014
First Registration Date	02 Jan 2014
Transfer Count	0
Actual ARF Paid	\$4,090.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	01 Jan 2024
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$48,001.00
COE Rebate Amount	\$29,058.00
Total Rebate Amount	\$29,058.00

The information contained herein is correct as at 12 Dec 2017

OK

DYNAMIC CAR RENTAL

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 6741 7244 / 6746 5405 Fax No: 6745 8520 / 6746 5786

Co. Reg No: S2928467K

TO: WONG KOK KHEE

Invoice : DCR-2017-12-01

Date : 08.12.2017

Agreement No : 19800

Payment Term : LOD

DESCRIPTION	AMOUNT
-------------	--------

Rental charges for vehicle : SGW 3568E (1217-20015)	\$ 540.00
Rental Period from 04.12.2017 to 07.12.2017	

E. & O. E.

Total \$ 540.00

Lina Pang
for Dynamic Car Rental



M/S AIG ASIA PACIFIC INS PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

ESTIMATE

DATE : 07/12/2017
ACC DATE : 06/12/2017
REF NO. : VFIX-TP20170379
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO :XD8124T ISUZU FXZ 77M

DESCRIPTION		AMOUNT \$S
1	1 FRONT BUMPER	20/sep 2,088.80
2	1 HEADLAMP L	17 747.60
3	1 SIGNAL LAMP L	17 503.60
4	1 HEADLAMP RIM L	17 115.00
5	1 STEP BOARD LOWER	17 322.00
6	1 STEP BOARD LOWER GARNISH	17 358.00
		\$ 4,135.00
LESS 20%		\$ 827.00
		\$ 3,308.00

LABOUR & MISCELLANEOUS:		AMOUNT S\$	
1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary repair/reshape dented areas	400	800.00
2	To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	300	800.00
3	To conduct headlamp alignment	20	30.00
		\$	1,630.00

GRAND TOTAL : \$ 4,938.00

SINGAPORE DOLLARS : FOUR THOUSAND NINE HUNDRED & THIRTY
EIGHT ONLY

Vfix Auto Service Pte Ltd hereby notifies the Resurveyor of the following:

- To resurvey vehicle after spray painting
- To inspect damaged panel during resurvey
- The Resurveyor is subject to confirmation
- The Resurvey is on a "Without Prejudice" basis
- No repair charges are allowed
- Supplemental claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

* 22 DEC 2017

Our Ref. No.: VFIX-TP20170379

MOTOR CLAIMS DEPT

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

vfix
Vfix Auto Service Pte Ltd
60 Kallit Bukit Ave 6
Ark@KB Singapore 417892
Email: vfixauto@gmail.com
Tel: 64489268 Fax: 64452368
Co Reg. No: 201602964H
GST Reg No: 201602964H

WITHOUT PREJUDICE

Dear Sir / Madam

PROPERTY CLAIM ONLY

**ACCIDENT INVOLVING XD8124T AND SLC5598B ON 06 DEC 2017
ALONG LOYANG AVE TOWARDS TPE**

We refer to the above-mentioned accident.

We are writing on behalf of **M/S PENG CHUAN ENGINEERING CONSTRUCTION PTE LTD**
the registered owner of motor vehicle number **XD8124T** which was involved in the above accident.

We are instructed that the above accident was caused by the negligence and management of your insured's vehicle number **SLC5598B**. As a result of the above accident, our client's vehicle was damaged and our client's has been put to loss and expense, particulars of which are as follows :-

1	Cost of Repair	:S\$	2,140.00
2	Loss of Use (2 days X \$ 150.00)	:S\$	300.00
3	LTA Fees	:S\$	5.35
TOTAL AMOUNTS		:S\$	2,445.35

We enclosed a list of the supporting documents :-

- (a) Original Final Repair Bill
- (b) LTA Tax Invoice
- (c) GIA / Police Report lodged by Our Client
- (d) Letter of Authority

Kindly acknowledge receipt of the above said documents and your favourable reply is greatly appreciated.

Any settlement reached is strictly without prejudice to and shall not affect any other claims arising from this accident. Settlement is solely for the items claimed only.

Yours Faithfully,
VFIX AUTO SERVICE PTE LTD


Kelvin Poh



Zaini (LKK Auto)

From: Zaini (LKK Auto)
Sent: Monday, 22 January 2018 5:23 PM
To: 'vfix auto'
Cc: Hsiao Tong (LKKAuto)
Subject: RE: FW: ACCIDENT INVOLVING XD8124T & SLC5598B ON 06/12/2017 *** LKK REF - CC6/AIG17023574/Uka3
Attachments: RV AIG XD8124T 06122017.pdf

WITHOUT PREJUDICE

Dear Irene,

We refer to our previous tele-conversation.

We confirmed global sum settlement @ \$2,400.00 (all in).

Thank you for acceptance.

Attach DV for your necessary actions.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: vfix auto [mailto:vfixauto@gmail.com]
Sent: Friday, 19 January 2018 11:13 AM
To: Zaini (LKK Auto) <Zaini@lkkauto.com>
Subject: Re: FW: ACCIDENT INVOLVING XD8124T & SLC5598B ON 06/12/2017 *** LKK REF - CC6/AIG17023574/Uka3

Dear Zaini

We refer to your email dated 18/01/2018.

We would like to counter proposal \$2,400.00 (all in).

Thanks
Irene

Vfix Auto Services Pte Ltd

60 Kaki Bukit Ave 6 Ark@KB Singapore 417892 | E: vfixauto@gmail.com | T: +65 64552957 | F: +65 64452368

On Thu, Jan 18, 2018 at 4:47 PM, Zaini (LKK Auto) <Zaini@lkkauto.com> wrote:

WITHOUT PREJUDICE

Your Ref: VFIX-TP20170379

Our Ref: CC6/AIG17023574/Uka3

Dear Irene,

ACCIDENT INVOLVING SLC5598B & XD8124T ON 06/12/2017

We refer to the above matter

For a quick and amicable settlement, we offer to settle global sum at **S\$ 2,340.00 (all in)**

Kindly confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zaini (LKK Auto)
Sent: Thursday, 11 January 2018 1:49 PM
To: 'vfix auto' <vfixauto@gmail.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: FW: ACCIDENT INVOLVING XD8124T & SLC5598B ON 06/12/2017 *** LKK REF - CC6/AIG17023574/Uka3

WITHOUT PREJUDICE

Dear Irene,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG17023574/Uka3

05 JANUARY 2017

SOK ZHI WEI
25 PUNGGOL FIELD WALK
#07-24
SINGAPORE 828751

Dear Sir/Madam,

ACCIDENT INVOLVING SLC 5598B AND XD 8124T ON 06.12.2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 15/01/2018, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

To: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Dear Sir / Madam,

Claimant:

ACCIDENT INVOLVING XD 8124 T AND SLC 5598 B ON 06/12/17 AT
LOYANG AVE TOWARDS THE

I/We, PENG CHUAN ENGINEERING CONSTRUCTION P.L. am/are the registered owner of
motor car no. XD 8124 T.

Please be informed that I have assigned all compensation monies due to me/us in the above
accident to VFIX AUTO SERVICE PTE LTD.

I/We hereby authorized you to release all monies pertaining to the above mentioned accident
to VFIX AUTO SERVICE PTE LTD and forward the settlement cheque to VFIX AUTO SERVICE PTE
LTD whom I/we have authorized to collect the said compensation monies.

Thank you,



X

Signature of Claimant &
Company Stamp if applicable

IC no.: 200304394 R

Date: 22/12/17

Signature of Witness

IC no.: S15275521

Date: 22/12/17

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, VFIX AUTO SERVICE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,400.00 (Global Sum) for vehicle no. XD 8124T that was damaged pursuant to the accident which occurred on 06/12/2017 (date) along LOYANG AVENUE involving vehicle no/s SLC 5598B.

This is pursuant to the inspection conducted on 12/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PENG CHUAN ENGINEERING CONSTRUCTION PTE LTD ("the third party claimant") of vehicle no. XD 8124T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to XD 8124T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 23 (day) of JAN (month) 2018 (year)



CKS

Signed by appointed surveyor



[Signature]

Signed by "the workshop" (with chop)

***This Discharge Voucher applies only to the claimant's claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim on a later date

Further, the settlement terms herein shall not be used as evidence to prejudice the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.



Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6
Ark@KB Singapore 417892
Email: vfixauto@gmail.com
Tel: 64489268 Fax: 64452368
Co Reg. No: 201602964H
GST Reg No: 201602964H

AIG ASIA PACIFIC INS PTE LTD
78 SHENTON WAY
#07-16 AIG BLDG
SINGAPORE 079120

FINAL REPAIR BILL

DATE : 22/12/2017
VEHICLE NO : XD8124T
MAKE/MODEL : ISUZU FXZ77M
ACC DATE : 06/12/2017
CLAIM NO : VFIX-TP20170379
POLICY NO :

AMOUNT S\$

LUMP SUM REPAIR COST

Repair Amount	2,000.00
7% GST	140.00
Total	<u>2,140.00</u>

SINGAPORE DOLLARS: TWO THOUSAND ONE HUNDRED
& FORTY ONLY

VFIX AUTO SERVICE PTE LTD




Kelvin Poh

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

XD 81247

Print Date/Time : 07 Dec 2017 / 15:39:47

Receipt Date/Time : 07 Dec 2017 / 15:39:37

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171207-001287

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SLC5598B As at 06 Dec 2017/16:10:00			
	Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.			
1	Insurance Enquiry - SLC5598B Enquiry Fee 20171207153848500213	5.00	0.35	5.35
	Sub-Total	5.00	0.35	5.35
	Total Before Rounding	5.00	0.35	5.35
	Rounding Difference			0.00
	Total Amount Payable			5.35
	Paid By			
	xxxxxxxxxxxx8539		Credit Card: Visa /MasterCard	5.35
	Total			5.35
	Cash Change			0.00
	Tendered Amount			5.35
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2017 Edit Reg		12 Dec 2017 00:00 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	SOK ZHI WEI , ID: S8740144H		
Main Claimant:	PENG CHUAN ENGINEERING CONSTRUCTION PTE LTD , Co. Reg. No.: 200304394R		
Vehicle Reg. No.:	XDB124T	Date of Loss:	06/12/2017 00:00 - :59
Claim Type:	TP / 6823342973SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLC5598B	Policy No. (Claimant):	DMFP17S012139
	Excess:		
Repairer:	Vfix Auto Service Pte Ltd (HQ) 60 Kaki Bukit Ave 6, ARK@KB, 417892 Kaki Bukit - Tel: 96890102		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com		
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (13/12/2017): **TP GIA REPORT**

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD8124T (6823342973SG)
[SLC5598B]

TP

PENG CHUAN ENGINEERING CONSTRUCTION PTE LTD

Dec 6 2017 12:00AM

[SOK ZHI WEI]

Vfix Auto Service Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Video						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)			Thumbnail	Print	
1	19/01/18 10:33	Video - Accident XD8124T TP VIDEO FOOTAGE				Load MP4	
Letters/Correspondences						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown				Edit	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	12/12/17 20:36	Odometer Reading				Load JPG	<input checked="" type="checkbox"/>
2	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
3	12/12/17 20:36	Chassis Number				Load JPG	<input checked="" type="checkbox"/>
4	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
5	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
6	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
7	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
8	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
9	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
10	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
11	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
12	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
13	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
14	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
15	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
16	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
17	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
18	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
19	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
20	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
21	12/12/17 20:36	General View				Load JPG	<input checked="" type="checkbox"/>
22	20/12/17 08:14	Reinspection Photo				Load JPG	<input checked="" type="checkbox"/>
23	20/12/17 08:14	Reinspection Photo				Load JPG	<input checked="" type="checkbox"/>
24	20/12/17 08:14	Reinspection Photo				Load JPG	<input checked="" type="checkbox"/>
25	20/12/17 08:14	Reinspection Photo				Load JPG	<input checked="" type="checkbox"/>
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	19/12/17 10:33	TP GIA REPORT				Load PDF	

2	19/12/17 10:33	TP ESTIMATE- MARKED	1	Load PDF	
3	29/01/18 10:05	WORKSHOP INVOICE	1	Load PDF	
4	29/01/18 10:05	AUTHORISATION TO ACT FORM	1	Load PDF	
5	29/01/18 10:05	Release Voucher	1	Load PDF	
6	29/01/18 10:05	LTA SEARCH	1	Load PDF	
7	29/01/18 10:05	LETTER TO OI	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	13/12/17 11:20	OI GIA REPORT 1	1	Load PDF	
2	13/12/17 11:20	OI GIA REPORT 2	1	Load PDF	
3	19/12/17 10:07	E-filed GIA report	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLC5598B (Insd veh)	Model:	ISUZU FXZ77M 9.8 D (M)
	XD8124T (TP veh)		
Date of Accident:	06/12/2017		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	5,504.88
Final Repair Cost	:	\$	2,400.00
Loss of Use	:	\$	2.00 days at \$130.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	2,400.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Vfix Auto Service Pte Ltd	:	\$ 2,400.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

29 Jan
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17023574/UKA3Q2

Date: 29/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No: XD8124T

Insured Vehicle No: SLC5598B

Date of Loss: 06/12/2017

Nature of Claim: TP

Claim No: 6823342973SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD8124T

Make & Model: ISUZU FXZ77M, 9.8 D (M)

Engine No: 6UZ1477688

Reg. Date: 02/01/2014 (Man. Year: 2013)

Chassis No: JALFXZ77MD7000027

Colour: Green

Odometer: 402838 km

Engine Capacity: 9839 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D/D)

Front Left Side: Gold Tyre 6 mm

Rear Left Side: Gold Tyre 6/6/6 mm

Front Right Side: Gold Tyre 6 mm

Rear Right Side: Gold Tyre 6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,514.75	1,873.23	1,641.52	46.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	720.00	910.00	55.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,144.75	2,593.23	2,551.52	49.59
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	5,144.75	2,000.00	3,144.75	61.13
+ GST 7.00/7.00% (S\$)	360.13	140.00	220.13	61.13
Nett Amount (S\$)	5,504.88	2,140.00	3,364.88	61.13
+ Loss of Use (2.0 x S\$130.00/day) (S\$)		260.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		2,405.35		
Global Sum Settlement (S\$)		2,400.00		

INSPECTION

Date of Assignment: 12/12/2017

Date Inspected: 12/12/2017 Inspected At:

Vfix Auto Service Pte Ltd (HQ)
60 Kaki Bukit Ave 6, ARK@KB
Singapore 417892

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Zaini Bin Kusaini

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Bent	2,088.80 FL	*2,088.80 FL
2	1		*HEADLAMP L	Not Necessary	747.60 FL	*- FL
3	1		*SIGNAL LAMP L	Not Necessary	503.60 FL	*- FL
4	1		*HEADLAMP RIM L	Cracked	115.00 FL	*115.00 FL
5	1		*STEP BOARD LOWER	Not Necessary	322.00 FL	*- FL
6	1		*STEP BOARD LOWER GARNISH (CUT)	Not Consistent With The Impact	358.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,135.00	2,203.80
- List Item Discount on L Items 15.00/15.00% (S\$)	620.25	330.57

Total Parts (S\$)	3,514.75	1,873.23
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED BODY PANEL WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT/WORKS WHERE NECESSARY REPAIR /RESHAPE DENTED AREAS	New	800.00	400.00
2	TO SPRAY PAINT REPLACED/ REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	800.00	300.00
3	TO CONDUCT HEADLAMP ALIGNMENT	New	30.00	20.00
Gross Labour Cost (S\$)			1,630.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

