

Surveyor

REF: CS3 / ALG17006545 / M1 V6-1

Special Instruction:

US: \$ 3500.00

ASSIGNMENT (Office)

From (Person): Narsiah of ALG Date/Time: 30-11-2017

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: Premier Appraiser

Workshop: Service @ Riverview

OD (FP Re-inspection) / Evaluation

To Inspect Vehicle No: SFJ 9189G Insured: 688 7959D

at Workshop m/s Service @ Riverview Tel:

of 10 AMK Ind Park 2A # 04-11

Policy No: Claim No: 5790248969SG

Sum Insured: Excess:

Make of Veh: D.O.A. 31-03-2017

(Client's Record) 13.12.2017 (Wednesday) @ 1pm

H.O.D. Enforcement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: 13/12/17 Confirmed with Final Fig LS \$3000 4 days (Red \$500 / 14%; Original 4 days)

Date/Time: Submit Final Fig days (Red \$ / %; Original days)

Date/Time	Action/Instruction
	Blk 12 Bedok Reservoir View #02-37 Singapore 479237 (Mrs Christine - 9362 5258)
	SFJ 9189G - CS3 / ALG17006545 / M1 V6-1
	688 7959D - CS3 / ALG17006545 / M1 V6-1
	D.O.A. 31/03/17
	D.O.A. 17/03/17
	<i>[Signature]</i>
	14/12/2017

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 14 DEC 2017

4/5 \$3000k
4w/0days
12/12/2017
Con [Signature]

Para(3) : Nett Value

Market Value :
Salvage Value :
Nett Value :

Inspected/
Evaluated by:

Fee Charged:
Basic & Add
Transport
Photos
Others
Total

Date:	200

- 1) Date/Time 14/12 - typist File Pass to
- 2) Date/Time File Return to
- 3) Date/Time File Pass to
- 4) Date/Time File Return to
- 5) Date/Time File Pass to
- 6) Date/Time File Return to

Survey Department Check List (Case Handler)

Reference No.: CS3 | AIG17006545 | Mlvb-1
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

		Y-Date	N-Date	Y-Date	N-Date
(1) Office Assign Form					
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

		Y-Date	N-Date	Y-Date	N-Date
(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)					
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form					
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)					
C	Resurvey photo Uploaded				

Check By: VERON 14/12/17
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG17006545/vb-1	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 12-12-2017	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	GBB 7959D	Veh. Inspected	SFJ 9189G
Policy No.		Coverage (\$)	0.00
Claim No.	5790248969SG	Excess (\$)	0.00
Assign From	NORSIAH	Assign Date	30/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/03/2017	Inspection Date	13/12/2017
Survey held at	BLK 12 BEDOK RESERVOIR VIEW #02-37		
Repairer	SERVICE @ RIVERVIEW PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>
Sent: Thursday, 30 November, 2017 4:50 PM
To: Nazirah Bte Salleh
Cc: Akramjeet Singh Khaira; Nicholas Ng; assignments@lkkauto.com
Subject: RE: AIG Ref: 5790248969SG, KCP Ref: AK/NN/zi/2017002403.AIG(mpd) - MC/MC 1429/2017 (NFC)
Attachments: Ltr. dated 13.11.17.pdf

Dear Nazirah,

Refer to the above.

We are appointing LKK Auto Consultants Pte Ltd to conduct physical re-inspection.

Please advise Plaintiff's lawyer to arrange for an appointment date, time and location.

Dear LKK,

FYNA please. Thank you

Thank you

Norsiah Md Noor
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419-1606 | Fax +(65) 6835-7417
Norsiah.MdNoor@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Nazirah Bte Salleh [mailto:nazirah.salleh@kcpartnership.com]
Sent: Tuesday, November 14, 2017 2:20 PM
To: Md Noor, Norsiah
Cc: Akramjeet Singh Khaira; Nicholas Ng; Nazirah Bte Salleh
Subject: AIG Ref: 5790248969SG, KCP Ref: AK/NN/zi/2017002403.AIG(mpd) - MC/MC 1429/2017 (NFC)

Sent on behalf of Akramjeet Singh Khaira/Nicholas Ng

Dear Norsiah,

We refer to the above matter.

We attached herewith a letter dated 13 November 2017 from Plaintiff's solicitors for your attention.

We trust that the contents are self-explanatory.

Please let us have your instructions.

Kind regards

AKRAMJEET SINGH KHAIRA/NICHOLAS NG

Sent by Nazirah, Secretary to Akramjeet Singh Khaira/ Sonia Khoo Meng/Nicholas Ng

Kelvin Chia Partnership | 6 Temasek Boulevard | 29th Floor | Suntec Tower Four | Singapore 038986

Telephone: (65) 6220 1911 | Facsimile: (65) 6835 9948 / (65) 6224 4118

Direct Dial: (65) 6408 7859

Website: www.kcpartnership.com

SINGAPORE | YANGON | HANOI | HO CHI MINH CITY | BANGKOK | PHNOM PENH | JAKARTA | SHANGHAI

CONFIDENTIALITY CAUTION:

This message is intended only for the use of the individual/entity to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient of this message, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify the writer immediately by return e-mail and delete the original message. Thank you.

Catherine Chong (LKK Auto)

From: Huiling <riaz@justice.com.sg>
Sent: Monday, 11 December, 2017 4:19 PM
To: 'Catherine Chong (LKK Auto)'
Subject: RE: Your ref: 509387.Q ; AIG Ref: 5790248969SG

WITHOUT PREJUDICE

Dear Catherine,

We refer to your below email.

Please note that the RI have been scheduled as follow

Date: 13.12.2017
Time: 1pm
Venue: BLK 12 BEDOK RESERVOIR VIEW # 02-37 SINGAPORE 479237
Contact: 9362 5258 Ms Christine Chang

Please let us have your confirmation urgently.

Please be inform that the above is the only time and date that our client will be available for the RI.

Thanks and Best Regards,

HUILING
RIAZ LLC
133 NEW BRIDGE ROAD
09-09 CHINATOWN POINT
SINGAPORE 059413
TEL : 6534-0110 FAX : 6534-0220

**** DISCLAIMER****

THIS EMAIL AND ANY FILES TRANSMITTED WITH IT ARE CONFIDENTIAL AND SUBJECT TO LEGAL PROFESSIONAL PRIVILEGE AND INTENDED SOLELY FOR THE USE OF THE INDIVIDUAL OR ENTITY TO WHO THEY ARE ADDRESSED. IF YOU HAVE RECEIVED THIS EMAIL IN ERROR PLEASE NOTIFY THE SYSTEM MANAGER. THIS MESSAGE CONTAINS CONFIDENTIAL INFORMATION AND IS INTENDED ONLY FOR THE INDIVIDUAL NAMED. IF YOU ARE NOT THE NAMED ADDRESSEE YOU SHOULD NOT DISSEMINATE, DISTRIBUTE OR COPY THIS EMAIL. PLEASE NOTIFY THE SENDER IMMEDIATELY BY EMAIL IF YOU HAVE RECEIVED THIS EMAIL BY MISTAKE AND DELETE THIS EMAIL FROM YOUR SYSTEM. IF YOU ARE NOT THE INTENDED RECIPIENT YOU ARE NOTIFIED THAT DISCLOSING, COPYING, DISTRIBUTING OR TAKING ANY ACTION IN RELIANCE ON THE CONTENTS OF THIS INFORMATION IS STRICTLY PROHIBITED.

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Saturday, 2 December, 2017 11:11 AM
To: 'Huiling' <riaz@justice.com.sg>
Subject: Your ref: 509387.Q ; AIG Ref: 5790248969SG

Dear In-charge,

Kindly arrange RI appointment anytime form 10.30am-2pm on 07.12.2017.



RIAZ

L.L.C

ADVOCATES AND SOLICITORS
COMMISSIONER FOR OATHS

ACRA NUMBER : 200911678H

GST REGISTRATION NUMBER : 200911678H

Your Reference : AK/NN/zi/2017002403.AIG(mpd)
Our Reference : 509387.Q

RIAZ QAYYUM (LLB HONS) NUS
(DIRECTOR)

TAN KOK SIANG (LLB HONS) LON
(ASSOCIATE)

ABDUL HALIM BIN ROSALAN (LLB HONS) UTAS
(ASSOCIATE)

13 NOV 2017

M/S KELVIN CHIA PARTNERSHIP
6 Temasek Boulevard
29th Floor Suntec Tower Four
Singapore 038986

WITHOUT PREJUDICE
BY FAX (6224 4118) ONLY

Dear Sirs

MC/MC 14188/2017

1. We refer to the above matter and the CDR on 6th November 2017.
2. At the said CDR, it is mentioned that your client has requested for a re-inspection of our client's vehicle.
3. Kindly provide us with the details of the re-inspection for us to make the necessary arrangements.

Yours faithfully

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any file reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/04/2017 14:42
Date Of Accident	31/03/2017 18:55
Exact Location Of Accident	X OF JAMPINES AVE 4 > AVE 5
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFJ9189G
Named Policyholder	
Name Of Registered Owner	CHANG HSIU FANG
NRIC No	S7137341Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93625258
Alternative Phone No	Office-93625258
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	NEW GOLF 1.4 TSI AT 5K14Q5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
Insurance Company	
Name of Insurance Company	AXA Insurance Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	VPA/P1251725
Cover Note Number	
Driver	
Name of Driver	CHANG HSIU FANG
NRIC No	S7137341Z
Date Of Birth	25/10/1971
Occupation	Indoor
Date Of Driving Pass	18/08/1993
Driving Experience	23 Years And 7 Months
Gender	Female
Mobile Number	(Local) +65-93625258
Fax Number	
Contact Number	Office-93625258
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company No
If No, Relationship of the Driver with the Insured Owner
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident Collision- Head to Rear (TP Hit Insured)
Weather Conditions Clear
Road Surface Dry
Other Information
Were any foreign vehicle involved in this accident? No
Was any body injured in the Accident? No
Was any other material or property damaged? Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No
Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? No
If Yes, Please state which Police Station
Was notice of intended Prosecution given? No
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GB97959D
Vehicle Make/Model/Colour NISSAN CABSTAR (B)
Details Of Properties
Name of Driver LI QI
NRIC/Passport Number G2148286P
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)
Details of Witness
- 3
Phone Number
Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind their policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any fines, penalties may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

I consent under the Personal Data Protection Act (PDPA) to understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the claims as well as on the external cover of envelopes/airmail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Person

31. 3.17 6:55 pm
 Junction of Tampines Ave 4
 towards Tampines Ave 5

[A]: SFJ9189G

[B]: GBB7955D



Sketch Plan Pg.2

Describe Circumstances of the Accident

on the 31.3.17 at about 655pm,
 I was driving along Tammen Ave & towards
 Tampines Ave S. My car was waiting
 stationary in the left turning lane towards
 Tampines Ave S. Suddenly Vehicle GBB7959D
 came from behind and hit my car SF39189G
 in the rear, causing damage to my car.
 My two sons were in my car at the
 time of the accident.

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

<input type="checkbox"/>	Reporting Only
<input type="checkbox"/>	Claim OD
<input type="checkbox"/>	Claim TP
<input checked="" type="checkbox"/>	Claim OD/TP at other workshop

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/04/2017 15:00
Date Of Accident	31/03/2017 18:55
Exact Location Of Accident	ALONG JUNCTION OF TAMPINES AVENUE 4 TOWARDS AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB7959D
Insured/Policyholder	
Name Of Registered Owner	MOVA AUTOMOTIVE PTE LTD
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62723892

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999995100/100783983-00000
Cover Note Number	

Driver

Name of Driver	LI QI
Passport No/FIN	G2148288P
Address	

General Information of the Accident

Type Of Accident	COLLISION- HEAD TO REAR (INSURED HIT TP)
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SFJ9189G

Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report **correctly** the details of the accident to speed up the claims process.
- 2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
- 3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. **Any false reporting may be referred to the Police for investigation**.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquires by me.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

X



[Handwritten signature]



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2

Describe Circumstances of the Accident

In 21/06/2017 (a around 1855 hours. I was travelling along junction of Empress Avenue
4 towards Ave 6. Suddenly vehicle B: SF9R96A jammed back. I stepped on my brake
immediately, but unfortunately I was unable to stop in time and collided into its
rear side. No one was injured.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO
SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY
FOR MORE INFORMATION.

Please State:

Claim Own Policy Claim Third Party Claim OD/TP at other workshop Reporting only

Declaration

I/We declare the foregoing particulars are true in every respect.

X



[Handwritten signature]

[Handwritten signature]



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

INSURANCE CERT



HOLDING TEL: (65) 6419-2000
FAX: (65) 6411-1723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 169)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1967
ROAD TRANSPORT ACT, 1967 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

M7 201

COMPREHENSIVE COMMERCIAL MOTOR	OWN DAMAGE EXCESS	SS\$1,200.00 (1)
CERTIFICATE NO. 999951001100763963-00000	WINDSCREEN EXCESS	SS\$100.00
	<small>(No policies with effect from 1st November 2007)</small>	
	SUM INSURED	SS\$1.00
	INSURING WITH COE/PARF	YES
1) VEHICLE REGISTRATION NO.	G8B7959D	
2) NAME OF INSURED	MOVA AUTOMOTIVE PTE LTD	
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT	18 Mar 2017	
4) DATE OF EXPIRY OF INSURANCE	9 Mar 2018	
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *		

Any person who is driving on the Insured's order or with their permission.
An Elderly Young and Inexperienced Driver (EYIDR) Excess of SS\$1,000 (unless otherwise stated) applies to any drivers (named and unnamed) who is above age 60, below age 70 or 75 in the case of 75 is less than 2 years driving experience. If the EYIDR is not named in the policy, an additional SS\$1,000 Unnamed Driver Excess will be applied.

DELETED

*Please refer to policy terms and conditions

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

6) LIMITATION AS TO USE *

Use for the carriage of passengers or goods in connection with the Insured's business. Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired. The Policy does not cover: 1) Use for racing, jockey-making, reliability trial or speed testing 2) Use whilst driving a trailer except the towing (other than for forward) of any one disabled mechanically propelled vehicle 3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired. SOLE AGENT'S WORKSHOP: For new vehicles less than 3 years from initial registration, you have the option for claims-related repairs to be done at Sole Agent's workshop. AIG AUTHORIZED REPAIRERS (FOR CLAIMS RELATED REPAIRS):
1. Lai Hual Meng Kee Mr - 21, Sin Meng Ind [Tel: 64538110] 2. Sin Yew Hap Wai Long - 4 Woodlands Rd [Tel: 67600816]
3. Datara Engng P L - 205 Brasell Rd [Tel: 62827116] 4. Kan Fook Sing Mr - 1009 Eunos Ave 5 [Tel: 67495660]
5. Ban Cheong Mr - 6 Pinnac Rd [Tel: 62641191] 6. Sho Fat Auto Works - 81 Moran Lane [Tel: 62730118]
7. Star Auto Co - 5 Portdown Rd [662000/97189009] 8. Progressive Automotive - 3022A Ma Rd 1 [Tel: 67416336]
10. Ready Autocare - 10 AMN AutoPoint [Tel: 96965516/4610304]

LOSS OF USE NOT INCLUDED

* NAMED DRIVER NA

HIRE PURCHASE COMPANY OCBC Bank Ltd

* Limitations mentioned hereinafter by Section 5 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 169) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings

We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 169) and Part IV of the Road Transport Act, 1967 (Malaysia)

Issued At Singapore 18 Mar 2017

AIG ASIA PACIFIC INSURANCE PTE. LTD.

39257 000
NO 11 RIVERVIEW TR
AIG BUILDING
78 SHENTON WAY #07 10
SINGAPORE 079120
AIGP-NORLIFE

Authorized Representative

ORIGINAL

0045

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	7341Z
Vehicle Details	
Vehicle No.	SFJ9189G
Vehicle to be Exported	No
Intended De-registration Date	14 Dec 2017
Vehicle Make	VOLKSWAGEN
Vehicle Model	NEW GOLF 1.4 TSI AT 5K14Q5
Primary Colour	White
Manufacturing Year	2009
Engine No.	CAV095404
Chassis No.	WWZZZ1KZAW013053
Maximum Power Output	118.0 kW (158 bhp)
Open Market Value	\$25,014.00
Original Registration Date	02 Oct 2009
First Registration Date	02 Oct 2009
Transfer Count	0
Actual ARF Paid	\$25,014.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	01 Oct 2019
PARF Rebate Amount	\$13,757.00
Intended COE Rebate Details	
COE Expiry Date	01 Oct 2019
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$18,020.00
COE Rebate Amount	\$3,238.00
Total Rebate Amount	\$16,995.00

The information contained herein is correct as at 14 Dec 2017

OK



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No:

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items:

Assessor:

2 days

This claim will be authorized on the insurer's behalf.
Letter of Offer/DV has been verified by CHING on 20 Apr 2017 09:40.

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561. Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17006545/M18F2
Date: 20/04/2017

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SF39189G	Insured Vehicle No :	G887959D
Date of Loss:	31/03/2017	Nature of Claim:	TP
		Claim No:	5790248969SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SF39189G	Engine No:	CAV095404
Make & Model:	VOLKSWAGEN GOLF, 1.4 (5K1405) (A)	Chassis No:	WVWZZZ1KZAW013653
Reg. Date:	02/10/2009 (Man. Year: 2009)	Odometer:	151229 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/04/2017	Inspected At:	Service@riverview Pte Ltd (HQ) 10 ANG MO KIO AUTOPOINT #04-07/11/15 ANG MO KIO IND. PARK 2A Singapore 568047
Date Inspected:	04/04/2017		
Estimated Period of Repair:	2.0 days		

Adjuster: MA CHIN FOOK

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE LAMP	Distorted	0.00 F	*-F
2	1		*REAR BUMPER	Deformed	0.00 F	*-F
3	1		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*-F
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*-F
5	1		*REAR BUMPER BEAM	Distorted	0.00 F	*-F
6	1		*REVERSE SENSOR	Shorted	0.00 F	*-F
Total Parts (S\$)					0.00	0.00

F - Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items
There are no new miscellaneous items selected.

Recommended Labour
There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

PREMIER APPRAISER SERVICES

VEHICLE INSPECTION REPORT

To: Ms. Chang Hsiu Fang
10 Ang Mo Kio Ind Park 2A
#04-11 AMK Autopoint
Singapore 568047

Our Ref. : PT1704001-L
Policy No. :
Claim No. :
Sum Insured :
Type of Claims : T/P Claim
Date : 11th Apr 2017

Assigned By : Ms. Chang Hsiu Fang
Date of Assignment : 04th Apr 2017
Date of Accident : 31st Mar 2017
Date of Inspection : 04th Apr 2017 Follow-up inspections were also conducted.
Name of Workshop : Service @ Riverview Pte Ltd
Place of Inspection : 10 Ang Mo Kio Ind Park 2A #04-11 AMK Autopoint
Singapore 568047

PARTICULARS OF VEHICLE

Registration No. : SFJ 9189 G
Make/Model : Volkswagen Golf 1.4 TSI
Type Of Body : 5 Door H/Back
Year of Manuf./Regn. : 2009
Colour : White

Odometer/km : 151229
Chassis No. : WVVZZZ1KZAW013053
Engine No. : CAV095404
Engine Cap. : 1390 cc
Carrying Cap. : 3 Passengers

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good	Market Value	: N/A
Footbrake	: Serviceable	Paint Work	: Good	Scrap Value	: -
Steering	: Serviceable	Modifications	: None	Others	: -

CONDITION OF TYRES

	Size	N/s - Tread Depth/Make	O/s - Tread Depth/Make
Front Tread	: 225/45 - R17	7mm - Michelin	7mm - Michelin
Rear Tread (inner)	:		
Rear Tread (outer)	: 225/45 - R17	7mm - Michelin	7mm - Michelin

The above represent an estimated remaining life of the tyre treads in mm.

POINT OF IMPACT/GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained an impact on the rear portion.

The boot lid, rear end panel, rear bumper, bumper reinforcement were dented/ buckled/ damaged.

For details of damages please refer to our schedule attached.

REMARKS :

This survey was conducted strictly without prejudice.

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

9669625

PREMIER APPRAISER SERVICES

Our Ref : PT1704001-L


Vehicle No : SFJ 9189 G

Qty	Parts Descriptions	Conditions	Repairer's Est.	Our Revised
LIST ITEMS:				
1	tailgate lock	chafed/damaged	S\$ 160.00	S\$ 160.00 X N/C 19
1	tailgate " GOLF " emblem	damaged	58.00	58.00
1	tailgate " TSI " emblem	damaged	52.00	52.00
1	tailgate n/s reflector	serviceable	470.00	-
1	rear end panel	dented - repair	352.00	-
1	rear end panel inner garnish	serviceable	215.00	-
1	rear bumper	chafed/distorted	785.00	785.00
1	rear bumper lower spoiler	warped	325.00	325.00
1	rear bumper tow cover	damaged	48.00	48.00
1	rear bumper reinforcement	dented/distorted	428.00	428.00
1	rear bumper n/s bracket	damaged	156.00	156.00
1	rear bumper n/s side bracket	damaged	186.00	186.00
4	reverse sensors	damaged	692.00	692.00
1	reverse sensor wire harness	necessary	188.00	188.00
			S\$ 4,115.00	S\$ 3,078.00
		LESS 0%	-	10% 307.80
			4,115.00	2,770.20
S/NETT ITEMS:				
1	rear number plate w casing	damaged	50.00	50.00 340
1	rear bumper clips	necessary	40.00	40.00
	TOTAL S/PARTS		S\$ 4,205.00	S\$ 2,860.20
	To remove/re-install rear luggage trims & garnish to facilitate repairs.		120.00	70.00 40
	Labour charges to repair, panel beat and straighten damaged parts and replace the above-mentioned parts.		660.00	450.00 400
	To replace reverse sensors.		60.00	40.00
	To check wiring functions.		50.00	30.00
	To putty, apply primer & spray-paint the affected areas. <i>(Boot lid, rear end panel, rear bumper).</i>		1,000.00	700.00 600
	To apply rust-roofoing on repaired/replaced panels.		80.00	-
	TOTAL		S\$ 6,175.00	S\$ 4,150.20

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **S\$ 3,500.00 lump sum** corresponding to supply of parts, labour and spray painting charges.
The estimated period of repairs is **FOUR (4) days**. Pursuant to your instruction we have **not** authorised repairs on your behalf.

HS \$3000
4w days

PREMIER APPRAISER SERVICES



LESLIE K C LIM CAE (UK), MIMI (UK)
 MSAAA, Automotive Appraiser
 Dip.MTM. Automotive Engineer



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17006545/M1vbs2-1

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120
ATTN: NORSIAH

Date : 18-12-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	GBB 7959D	Veh. Inspected	SFJ 9189G
Policy No.	999995100/100783983-0000	Coverage (\$)	0.00
Claim No.	5790248969SG	Excess (\$)	0.00
Assign From	NORSIAH	Assign Date	30/11/2017

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF 1.4	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WVWZZZ1KZAW013053	Colour	WHITE
Odometer	162398	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45R17	MICHELIN	8 mm
L/H Front Tyre	225/45R17	MICHELIN	8 mm
R/H Rear Tyre	225/45R17	MICHELIN	8 mm
L/H Rear Tyre	225/45R17	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	31/03/2017	Inspection Date	13/12/2017
Survey held at	BLK 12 BEDOK RESERVOIR VIEW #02-37 S(479237)		
Repairer	SERVICE @ RIVERVIEW PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFJ 9189G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE LOCK	NOT CHANGED	160.00	-
1	TAILGATE "GOLF" EMBLEM	REPLACED	58.00	58.00
1	TAILGATE "TSI" EMBLEM	REPLACED	52.00	52.00
1	TAILGATE N/S REFLECTOR	SERVICEABLE	470.00	-
1	REAR END PANEL	REPAIRED SEE LABOUR	352.00	-
1	REAR END PANEL INNER GARNISH	SERVICEABLE	215.00	-
1	REAR BUMPER	REPLACED	785.00	785.00
1	REAR BUMPER LOWER SPOILER	REPLACED	325.00	325.00
1	REAR BUMPER TOW COVER	REPLACED	48.00	48.00
1	REAR BUMPER REINFORCEMENT	REPLACED	428.00	428.00
1	REAR BUMPER N/S BRACKET	REPLACED	156.00	156.00
1	REAR BUMPER N/S SIDE BRACKET	REPLACED	186.00	186.00
4	REVERSE SENSORS	REPLACED	692.00	692.00
1	REVERSE SENSOR WIRE HARNESS	REPLACED	188.00	188.00
	LESS 10% DISCOUNT		-	-291.80
			4,115.00	2,626.20
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE W CASING (SN) }	REPLACED	50.00	40.00
1	REAR BUMPER CLIPS (SN)	REPLACED	40.00	-
			90.00	40.00
<u>LABOUR</u>				
	TO REMOVE / RE-NSTALL REAR LUGGAGE TRIMS & GARNISH TO FACILITATE REPAIRS.		120.00	40.00
	LABOUR CHARGES TO REPAIR, PANEL BEAT AND STRAIGHTEN DAMAGED PARTS AND REPLACE THE ABOVE-MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		660.00	400.00
	TO REPLACE REVERSE SENSORS.		60.00	40.00
	TO CHECK WIRING FUNCTIONS.		50.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS. (BOOT LID, REAR END PANEL, REAR BUMPER)	NOT NECESSARY	1,000.00	600.00
	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS.		80.00	-
			1,970.00	1,110.00
GRAND TOTAL			6,175.00	3,776.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,000.00

Report Ref No. CS3/AIG17006545/M1vbs2-1

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.