

Survivor:

Wilson

ASSIGNMENT (Office)

Merimen

From (Person):

Muhd Ashik

of

MSIG

Date/Time: 12/12/17 @ 4:25 pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 7857S

Insured:

SJQ 6689R

at Workshop n/s

Kent Auto Services

Tel:

9754 7573

of

Blk 2 Kaki Bukit Ave 2, #01-21

Policy No:

B27497548SMP

Claim No:

540443

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/12/2017

CA / REV / REP. / REV 24 HRS

(wp)

13/12/2017

H.O.D. Endorsement:

Date/Time:

4:53pm @ 12/12/17

Person Contacted:

Mr. Kent

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SKE 7857S - X

SJQ 6689R - X

Dismantle Part: 19.12.2017

After Repair: 21.12.2017

20.01.18 12:22pm email to muhd ashik thru merimen.

PRS
Silva

REF: MSIG

ASSIGNMENT

From: Date: 13/12/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKE7857S

at Workshop m/s: Kent Auto Services

of Blk 2 Kaki Bukit Ave 2 #01-21

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Range

#17900

#18900

RECEIVED 09 APR 2018

Signature

9/10/2018

Date/Time: File Pass to?

☐

: Prel. Report

1) 09042018

☐

: Final Report

Date/Time: File Return to?

2)

Report Format: PRS.

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Weekend (\$)

Survey Fee

Transportation

1) S - FE (\$)

Photos

Times

120

50

10

180

Veh No: SKE7857S Yr Regn: 30/3/2012

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Jaguar

2967

Colour:

White

A/C Insured / Std / NI / NA

Sp Reading

138601

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SAJAC05D8CFS39094

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/45 R18

R: 245/45 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli (LF)

Front

Rear

R/Bal:

4

mm

R/Bal:

4

mm

L/Bal:

4

mm

L/Bal:

4

mm

D.O.A:

9/12/2017 P.O.I.

13/12/17

Survey held at

As Above @ 10.26am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Left Frnt

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17023597/Wb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 12-12-2017	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SJQ 6689R	Veh. Inspected	SKE 7857S
Policy No.	B27497548SMP	Coverage (\$)	0.00
Claim No.	540443	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	12/12/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/12/2017	Inspection Date	13/12/2017
Survey held at	KENT AUTO SERVICES 2 KAKI BUKIT AVE 2 #01-21 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2017		12 Dec 2017 16:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]


Insured:	KHUA SOH KHIM, ID: S1683286C, Tel: +6596821515		
Main Claimant:	LIAN HOE LEONG & BROTHERS PTE LTD, Co. Reg. No.: 198202357C		
Vehicle Reg. No.:	SKE7857S	Date of Loss:	09/12/2017 16:00 - :59
Claim Type:	TP / 540443	Policy/Cover Note No.:	B27497548SMP (Comprehensive) Coverage: 19/04/2017 - 18/04/2018
Vehicle Reg. No. (Insured):	SJQ6689R	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/12/2017]		
Driver/Custodian (Insured):	LIM KAY WEE ELVIS (), NRIC: S9313683G, Tel: +6582826148		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Daniel Poon & Co.**Advocates & Solicitors
Commissioners for Oaths
Notary PublicDaniel Poon Choon Kow
LL.B. (Hons), LL.M133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
Tel: +65 6227-2469
Fax: +65 6225-2579
Email: law@dpco.com.sg
(UEN: S3130838C)

Our Ref: DP.sl.isk.10268.17.KAS

Your Ref: -----

Please quote our reference number when replying

Date: 12 DECEMBER 2017

M/S MSIG INSURANCE (S) PTE LTD
4 SHENTON WAY
#23-01
SGX CENTRE 2
SINGAPORE 068807
ATTN: MOTOR CLAIMS DEPARTMENTFAX (6225-7402) ONLY

DEAR SIRs,

PRE-REPAIR INSPECTION

YOUR INSURED VEHICLE REGISTRATION NO: SJQ 6689R
ACCIDENT ON 09 DECEMBER 2017 INVOLVING SKE 7857S AND SJQ 6689R
ALONG TELOK KURAU ROAD TOWARDS LORONG M TELOK KURAU ROAD

We are instructed by Lian Hoe Leong & Brothers Pte Ltd to notify you of a road traffic accident on 09th December 2017 at about 17:00 along Telok Kurau Road towards Lorong M Telok Kurau Road involving our client's vehicle registration number SKE 7857S and vehicle registration number SJQ 6689R driven by your insured at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair inspection of the vehicle, by the attached list of ten (10) surveyor which our client deemed suitable to be appointed.

If the aforesaid is not agreeable, kindly therefore instruct your appointed surveyor for a pre-repair inspection of our client's vehicle at by making a prior appointment with the repairer stated below:-

M/S KENT AUTO SERVICES
2 KAKI BUKIT AVENUE 2
#01-21,
KAKI BUKIT AUTOHUB
SINGAPORE 417921
ATTN: MR KENT TAN (9754-7573)

... 2/-

Page 2

Date: 12th December 2017

Messrs Daniel Poon & Co.

Our Ref: DP.sl.isk.10268.17.KAS

If we do not receive any agreement from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,



c.c. M/S KENT-AUTO SERVICES

FAX (6741-2539) ONLY

Survey Department Check List (Case Handler)

Reference No: _____

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (_____ **)**: Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (_____ **)**: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By: _____
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/12/2017 11:25
Date Of Accident	09/12/2017 17:00
Exact Location Of Accident	369 TELOK KURAU ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE7857S
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	LIAN HOE LEONG & BROTHERS PTE LTD
Co Reg No	198202357C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97622202

Vehicle Particulars

Manufacturer	JAGUAR
Model	XF-3.0 V6 LUXURY (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC17A00087501
Cover Note Number	

Driver

Name of Driver	LIM SIOW LONG, LOUIS (LIN XIAOLONG, LOUIS)
NRIC No	S8031696H
Date Of Birth	15/10/1980
Occupation	INDOOR
Date Of Driving Pass	20/02/2006
Driving Experience	11 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97622202
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	18 FLORA DRIVE #01-32 SINGAPORE
Postcode	506946
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MARINE PARADE NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4428999 - FAX NO: 62447678
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ6689R
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	LIM KAY WEE ELVIS
NRIC/Passport Number	S9313683G
Contact Number	82826148
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
------	--



Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 11/12/17 2pm


Reporting Centre Personnel's Signature
Name: Retwan
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

SIARAS, SINGAPORE FORM V2

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20171210/2002

1 of 3

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No. T/20171210/2002

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/12/2017 01:08	Vide Report No.:	Station Diary No.: 8
--	------------------	-------------------------

Informant's Particulars

Name of Informant: LIM SIOW LONG, LOUIS			Address: 18 FLORA DRIVE #01-32 SINGAPORE 506946		
ID Type / ID No.: NRIC NO / S8031696H			Contact No.: Home/Office: Mobile: 97622202		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 37	Date of Birth: 15/10/1980	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Sales and marketing manager			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 09/12/2017 17:00	Type of Location: Straight Road
Location: Along Road 1 TELOK KURAU ROAD				
Along 369 Telok Kurau Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJQ6689R	Car	BMW		White	Slightly Damaged	0
SKE7857S	Car	JAGUAR		White	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20171210/2002

2 of 3

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No. T/20171210/2002

CONTINUATION OF REPORT

Driver			
Name	Lim Kay Wee Elvis		ID No. S9313683G
Related Vehicle	SJQ6689R (Car)		Contact No. 82826148
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LIM SIOW LONG, LOUIS		ID No. S8031696H
Related Vehicle	SKE7857S (Car)		Contact No. 97622202
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 09/12/2017 at about 1700hrs, I was driving along Telok Kurau Road heading towards Lorong M Telok Kurau Road. I was driving on the right side of the two lane road. As I was driving, there was another vehicle (SJQ6689R) driving beside me on the left side of the two lane road. As I was driving, suddenly the said vehicle turned right and cut in front of me. However, I managed to swerve to the right to prevent direct impact. As a result of that, the said vehicle collided onto my vehicle on the front left bumper. Thereafter, both drivers exchanged contact details.

The other vehicle sustained damage on the front right bumper. No one was injured. No ambulance and no Police Officers came down to accident location. I do not have any in-car camera in my vehicle.

My wife was with me at the point of accident whom currently complains of giddiness after the accident. However, have yet to seek medical treatment.

My wife's particulars are as follows:

Name: Wei Shu Ting
Passport Number: 306865448

POLICE REPORT PAGE 3



**SINGAPORE
POLICE FORCE**



T/20171210/2002

3 of 3

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No: T/20171210/2002

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 JEREMY GOH ZEN KIAT

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt TANG SIEW PING

Contact No: 65476430

SN

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

10/12/2017 01:08

Classification Of Case:

View Sent Message

This mail is associated with :

***SKE7857S (540443)**
[SJQ6689R]

TP
LIAN HOE LEONG & BROTHERS PTE LTD
Dec 9 2017 4:00PM
[KHUA SOH KHIM]
Kent Auto Services - Kaki Bukit

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 20/01/2018 12:22 PM.
To MSI_ASHIK
Subject Pre-repair Inspection

Dear Muhd Ashik,

Refer to your assignment on 12.12.2017 at 4.25PM.

Please be informed that we have inspected the vehicle SKE 7857S on 13.12.2017 at 10.26AM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Dec 2017		12 Dec 2017 16:25 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KHUA SOH KHIM , ID: S1683286C, Tel: +6596821515								
Main Claimant:	LIAN HOE LEONG & BROTHERS PTE LTD , Co. Reg. No.: 198202357C								
Vehicle Reg. No.:	SKE7857S	Date of Loss:	09/12/2017 16:00 - :59 [68 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 540443	Policy/Cover Note No.:	B27497548SMP (Comprehensive) Coverage: 19/04/2017 - 18/04/2018						
Vehicle Reg. No. (Insured):	SJQ6689R	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 13/12/2017]								
Driver/Custodian (Insured):	LIM KAY WEE ELVIS () , NRIC: S9313683G, Tel: +6582826148								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE7857S (540443)
[SJQ6689R]
TP
LIAN HOE LEONG & BROTHERS PTE LTD
Dec 9 2017 4:00PM
[KHUA SOH KHIM]
Kent Auto Services - Kaki Bukit

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)



















































View View in Browser



















































Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page	<input checked="" type="checkbox"/>
1	12/12/17 16:13	Accident Statement <small>From: OD - Reg. No: SJQ6689R, Claimant: KHUA SOH KHIM</small>	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;"> Thumbnail Print </div> <div style="display: flex; justify-content: space-between;"> Load HTM </div>

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	<input checked="" type="checkbox"/>
1	20/01/18 12:07	Odometer Reading		
2	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;"> Thumbnail Print </div> <div style="display: flex; justify-content: space-between;"> Load JPG <input checked="" type="checkbox"/> </div>
3	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
4	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
5	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
6	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
7	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
8	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
9	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
10	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
11	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
12	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
13	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
14	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
15	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
16	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
17	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
18	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
19	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
20	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
21	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
22	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
23	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
24	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
25	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
26	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
27	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
28	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
29	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
30	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
31	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
32	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>
33	20/01/18 12:07	General View	<div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div>	<div style="display: flex; justify-content: space-between;">Load JPG<input checked="" type="checkbox"/></div>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	20/01/18 12:07	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/01/18 12:07	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/01/18 12:07	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/01/18 12:07	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
134	20/01/18 12:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
135	20/01/18 12:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
136	20/01/18 12:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
137	20/01/18 12:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
138	20/01/18 12:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
139	20/01/18 12:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
140	20/01/18 12:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
141	20/01/18 12:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/12/17 16:20	SKE7857S E-FILE, POLICE REPORT & IC	 Load PDF	
2	12/12/17 16:27	PRI from Daniel Poon & Co	 Load PDF	
3	12/12/17 16:27	Survey Disagree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17023597/WBE2

Date: 10/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B27497548SMP

Claimant Vehicle No : SKE7857S

Insured Vehicle No : SJQ6689R

Date of Loss: 09/12/2017

Nature of Claim: TP

Claim No: 540443

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE7857S

Make & Model: JAGUAR XF, 3.0 V6 LUXURY (A)

Engine No: 603786334FC

Reg. Date: 30/03/2012 (Man. Year: 2012)

Chassis No: SAJAC05D8CFS39094

Colour: White

Odometer: 138601 km

Engine Capacity: 2967 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size:

245/45 R18

Front Left Side: Pirelli 4 mm

Rear Left Side:

Continental 4 mm

Front Right Side: Pirelli 4 mm

Rear Right Side:

Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/12/2017

Date Inspected: 13/12/2017 Inspected At:

Kent Auto Services - Kaki Bukit (HQ)
BLOCK 2 KAKI BUKIT AVE 2, #01-21
KAKI BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$17,900.00 - \$18,900.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2018)
Parts:	143	JAGUAR XF 3.0 V6 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE7857S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >