

INS CASE OWNER: Rian chuan CC6 / AIG170 23603 1Uyaz

LKK:
IDAC:

Surveyor: MADAMS

ASSIGNMENT
DOI: 22/12/17

Date / Time: 12/12/17
Registered in Meritins: 12/12/17

Pre-assign / CCU / FTE



Insured Vehicle No. : SGD 6696 Z
Name of Insured : LEE KONG HON
Insured Tel No. : _____ HP: 9819 2280
Express Sec II :SS _____ D.O.A: 11/12/17
Is driver the owner? (YES NO) Nature of Accident :

Claim No. : 071030301859
Policy No. : 1700050095
Make / Model : MERCEDES-BENZ B170
Place of Accident : ALONG BKE TOWARDS WOODLAND

If NO, Driver Name / Age: LEE LAI PENG
Driver Tel No.: 9819 5280 (V/L: / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability: % Final ? Yes / No

SLT 3710U



INSRS:
WSP: Hock Wah (Sedole)
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
<u>20/12/17 (Tue)</u>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

*OK completed chasing ltr & recd
evid by TP.*

*See
file
07-02-18*

RECEIVED 09 FEB 2018

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: S\$ _____ (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27
If NO or B 28, Ass. Lia : _____

Repair Cost: S\$ _____
Loss of Rental (LOR): S\$ _____ (_____ days)
Loss of Use (LOU): S\$ _____ (\$ _____ x _____ days)
Loss of Income (LOI): S\$ _____ (\$ _____ x _____ days)
LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: S\$ _____
Medical: S\$ _____
Disbursement: S\$ _____ (e.g. Tow/Independent)
Legal Cost: S\$ _____

Total: S\$ _____ Global Sum S\$: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: S\$ _____ Name 1: _____
Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____
Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____

COPY SENT
6/2/18

Similar *maius*

REP:

Ala / Ref: 17023603/0403

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SKJ 3710U*
 at Workshop m/s: *hookvale 10am*
 of _____
 Insured: *SAD6696Z*
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Est. or Market Value: *55k*
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: *4* days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS *2966E*
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Veh No: *SKJ 3710U* (r Regn) *3 14*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *(W)*
 Make: *Toyota Corolla AXIO cc 1496*
 Colour: *Maroon* A/C Insured / Std / NI / NA
 Sp. Reading: *72626* T.Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: *NZE1617050793*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In Order / Jammed / Leaked / Burnt or
 Brake: In Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Bm / STD A/Rim or
 Tyre Size: F: *195/60R15*
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Crucero*
 Front: _____ Rear: _____
 R/Bal: *6* mm R/Bal: *6* mm
 L/Bal: *6* mm L/Bal: *6* mm
 D.O.A: *11/12/12* D.O.I: *22/12/17*
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
O/S Rt.
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>27A 49030 Dep Sfo</i>
	<i>3 B + \$3,206.92</i>
	<i>check items \$ 284.11</i>
	<i>Real @ 1,296.42/29%</i>

Date/Time: File Pass 0? : Prel. Report
 : Final Report
 Date/Time: File Return 1? _____
 2) _____
 Report Format: _____
 Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: Site Insp (\$) Interview (\$) Tech. Insp (\$) Weekend (\$)

Survey Fee: _____
 Transportation: _____
 Photo: _____
 Other: _____
 TOTAL: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG17023603/Uya3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 12-12-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGD 6696Z	Veh. Inspected	SLJ 3710U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/12/2017	Inspection Date	22/12/2017
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2966E
Vehicle Details	
Vehicle No.:	SLJ3710U
Vehicle to be Exported:	No
Intended De-registration Date:	22 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	1NZE357015
Chassis No.:	NZE1617050793
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,592.00
Original Registration Date:	20 Mar 2014
First Registration Date:	20 Mar 2014
Transfer Count:	1
Actual ARF Paid:	\$5,000.00 <i>2800</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Mar 2024
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	19 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$78,602.00
COE Rebate Amount:	\$49,030.00

Jas Khine (LKKAuto)

From: Chan, Kian-Chuan <Kian-Chuan.Chan@aig.com>
Sent: Tuesday, 6 February 2018 10:43 AM
To: Jas Khine (LKKAuto)
Subject: RE: YOUR REF: 0710303018SG MANDATE REQUEST TO REJECT TP CLAIM

Importance: High

Follow Up Flag: Follow up
Flag Status: Completed

Hi Jas,

Thank you for your email.
The above matter is a clear cut head to rear against TP.
As such, please proceed to reject TP claim.

Thank you.

Warmest Regards,

KC Chan
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd
78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1945 | Fax +(65) 68357416
kian-chuan.chan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.



Please consider the environment before printing this email

From: Jas Khine (LKKAuto) [mailto:jaskhine@lkkauto.com]
Sent: Tuesday, February 06, 2018 10:05 AM
To: Chan, Kian-Chuan
Subject: YOUR REF: 0710303018SG MANDATE REQUEST TO REJECT TP CLAIM

Your Ref: 0710303018SG
Our Ref : CC6/AIG17023603/Uya3

Dear KC,

ACCIDENT INVOLVING SLJ 3710U & SGD 6696Z ON 11/12/2017

We refer to the above matter.

TP reported that OI was making a sudden lane change without checking oncoming vehicle and collided with his vehicle.

OI reported that he signalled left and filtering to the left lane. While he was filtering towards the left, the vehicle in front suddenly filtered out and stopped. He then stopped his vehicle and being hit by TP from behind which was unable to stop on time.

As per OI video footage captured by rear camera, at the time of the collision OI completed changing lane rear ended by TP vehicle.

The circumstances of the accident and available information in hand, it's more appropriate with BOLA scenario 27 and liability is against TP.

Kindly advise whether we may proceed to reject Third Party claim.

Thank you.

Best Regards,
Jas Khine | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Jas Khine (LKKAuto)

From: Jas Khine (LKKAuto)
Sent: Tuesday, 6 February 2018 3:14 PM
To: 'Hock Wah Motor Pte Ltd'
Subject: RE: TP CLAIM_SLJ3710U & SGD6696Z (AIG_DOA:11/12/2017 *** LKK REF - CC6/AIG17023603/ya3
Attachments: SGD 6696Z VIDEO.avi

WITHOUT PREJUDICE

Dear Mavis,

Further to the below matter.

We managed to obtain a copy of video footage from our insured.

As per video, our insured completed changing lane at the time of the collision and rear ended by your client's vehicle.

Based on the circumstances of the accident and available information in hands, BOLA 27 is applicable and liability is against your client.

Therefore, we have our Principal instruction to deny the liability and unable to look into your client's claim.

Enclosed herewith a copy of video footage for your perusal.

Please note that the video footage is solely for your record purpose only and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Thank you.

Best Regards,
Jas Khine | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hock Wah Motor Pte Ltd [mailto:motor@hockwah.com.sg]
Sent: Monday, 29 January 2018 5:55 PM
To: Jas Khine (LKKAuto) <jaskhine@lkkauto.com>
Subject: RE: TP CLAIM_SLJ3710U & SGD6696Z (AIG_DOA:11/12/2017 *** LKK REF - CC6/AIG17023603/ya3

Dear Jas

Any updates regarding the case liability?

Please revert to us ASAP as our client keep chasing the outcome.

Thank you.

Best Regards

Mavis Er

Customer Service Executive

Hock Wah Motor Workshop Pte Ltd

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977

Tel: 6441 5655 | Fax: 6243 8121 | Website: www.hockwah.com.sg

From: Hock Wah Motor Pte Ltd

Sent: Tuesday, 9 January, 2018 9:40 AM

To: 'Jas Khine (LKKAuto)' <jaskhine@lkkauto.com>

Subject: RE: TP CLAIM_SLJ3710U & SGD6696Z (AIG)_DOA:11/12/2017 *** LKK REF - CC6/AIG17023603/ya3

Dear Jas

Any updates regarding the case liability?

Thank you.

Best Regards

Mavis Er

Customer Service Executive

Hock Wah Motor Workshop Pte Ltd

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977

Tel: 6441 5655 | Fax: 6243 8121 | Website: www.hockwah.com.sg

From: Jas Khine (LKKAuto) [<mailto:jaskhine@lkkauto.com>]

Sent: Thursday, 28 December, 2017 10:24 AM

To: Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>

Subject: RE: TP CLAIM_SLJ3710U & SGD6696Z (AIG)_DOA:11/12/2017 *** LKK REF - CC6/AIG17023603/ya3

Dear Mavis,

Below matter is still pending instruction from our Principal as our insured is strongly disputing on liability.

We will follow up the matter and will revert to you soon.

Thank you.

“May you have a great year ahead and a wonderful Christmas with your loved ones...”



Best Regards,

Jas Khine | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hock Wah Motor Pte Ltd [<mailto:motor@hockwah.com.sg>]

Sent: Thursday, 28 December, 2017 10:14 AM

To: Jas Khine (LKKAuto) <jaskhine@lkkauto.com>

Subject: RE: TP CLAIM_SLJ3710U & SGD6696Z (AIG)_DOA:11/12/2017 *** LKK REF - CC6/AIG17023603/ya3

Dear Jas

Any updates regarding the case liability?

Thank you.

Best Regards

Mavis Er

Customer Service Executive

Hock Wah Motor Workshop Pte Ltd

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977

Tel: 6441 5655 | Fax: 6243 8121 | Website: www.hockwah.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2017 Edit Reg		22 Dec 2017 00:00 Edit Adj Rpt	S\$3,206.91 Edit Estimates	S\$3,206.91 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LEE KONG HON , ID: S14738768								
Main Claimant:	JUMA'AT BIN A HAMID , ID: S1312966E								
Vehicle Reg. No.:	SLJ3710U	Date of Loss:	11/12/2017 12:00 - :59						
Claim Type:	TP / 0710303018SG	Policy/Cover Note No.:	1700050095						
Vehicle Reg. No. (Insured):	SGD6696Z	Policy No. (Claimant):	A80422525QMX						
	Excess:								
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Chuan] Kian-Chuan.Chan@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/12/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLJ3710U (0710303018SG)
[SGD6696Z]**

TP

JUMA'AT BIN A HAMID

Dec 11 2017 12:00PM

[LEE KONG HON]

Hock Wah Motor Workshop Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	06/02/18 10:50	Video - Accident							Load AVI		
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	13/12/17 10:37	Accident Statement <small>From: SC - Reg. No: SGD6696Z, Claimant: LEE KONG HON</small>							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	22/12/17 15:07	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
2	22/12/17 15:07	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
3	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
4	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
5	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
6	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
7	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
8	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
9	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
10	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
11	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
12	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
13	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
14	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
15	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
16	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
17	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
18	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
19	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
20	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
21	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
22	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
23	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
24	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
25	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
26	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
27	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	
28	22/12/17 15:07	General View							Load JPG	<input checked="" type="checkbox"/>	

29	22/12/17 15:07	General View		Load JPG	<input checked="" type="checkbox"/>
30	22/12/17 15:07	General View		Load JPG	<input checked="" type="checkbox"/>
31	22/12/17 15:07	General View		Load JPG	<input checked="" type="checkbox"/>
32	22/12/17 15:07	General View		Load JPG	<input checked="" type="checkbox"/>
33	22/12/17 15:07	General View		Load JPG	<input checked="" type="checkbox"/>
34	22/12/17 15:07	General View		Load JPG	<input checked="" type="checkbox"/>
35	22/12/17 15:07	General View		Load JPG	<input checked="" type="checkbox"/>
36	22/12/17 15:07	General View		Load JPG	<input checked="" type="checkbox"/>
37	22/12/17 15:07	General View		Load JPG	<input checked="" type="checkbox"/>
38	22/12/17 15:07	General View		Load JPG	<input checked="" type="checkbox"/>
39	22/12/17 15:07	General View		Load JPG	<input checked="" type="checkbox"/>
Documentation					1 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 17:45	TP GIA REPORT		Load PDF	
2	27/12/17 10:50	TP ESTIMATE- MARKED		Load PDF	
3	06/02/18 15:15	EMAIL TO TP REPAIRER		Load PDF	
4	06/02/18 15:15	EMAIL APPROVAL FROM AIG OFFICER		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17023603/UYA3Q2

Date: 07/02/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700050095
 Claimant Vehicle No: SLJ3710U Insured Vehicle No: SGD6696Z
 Date of Loss: 11/12/2017 Nature of Claim: TP Claim No: 0710303018SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ3710U
 Make & Model: TOYOTA COROLLA, 1.5 X AXIO (A) Engine No: 1NZE357015
 Reg. Date: 20/03/2014 (Man. Year: 2013) Chassis No: NZE1617050793
 Colour: Maroon Odometer: 72626 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
 Front Left Side: Crucero 6 mm Rear Left Side: Crucero 6 mm
 Front Right Side: Crucero 6 mm Rear Right Side: Crucero 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,763.32	2,046.91	716.41	25.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	1,160.00	580.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,503.32	3,206.91	1,296.41	28.79
+ GST 7.00/7.00% (S\$)	315.23	224.48	90.75	28.79
Nett Amount (S\$)	4,818.55	3,431.39	1,387.16	28.79
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 22/12/2017
 Date Inspected: 22/12/2017 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
 Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
 Singapore 489977
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Jasmine Khine Phoo Wai

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented / Buckled	627.80 FL	*627.80 FL
2	1		*FRONT BONNET HINGE RH	Not Necessary	92.14 FL	*- FL
3	1		*FRONT FENDER RH	Dented / Buckled	376.82 FL	*376.82 FL
4	1		*FRONT FENDER INNER SHIELD RH	Deformed / Torn	149.26 FL	*149.26 FL
5	5		*FRONT FENDER INNER SHIELD CLIP RH	Necessary	22.95 FL	*22.95 FL
6	1		*FRONT HEADLAMP RH	Broken	852.64 FL	*852.64 FL
7	1		*FRONT BUMPER	Dented	624.31 FL	*624.31 FL
8	1		*FRONT BUMPER SIDE RETAINER RH	Bent	75.44 FL	*75.44 FL
9	1		*FRONT BUMPER REINFORCEMENT	Repair	352.78 FL	*- FL
10	1		*FRONT BUMPER TOWING COVER RH	Not Necessary	21.88 FL	*- FL
11	1		*FRONT WIPER TANK RH	Not Necessary	189.60 FL	*- FL
12	1		*FRONT WIPER TANK MOTOR RH	Not Necessary	298.81 FL	*- FL
13	1		*FRONT SUPPORT PANEL (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,684.43	2,729.22
- List Item Discount on L Items 25.00/25.00% (S\$)	921.11	682.31
Total Parts (S\$)	2,763.32	2,046.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	400.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	680.00
3	ANTI-RUST COATING	New	100.00	60.00
4	WIRING	New	40.00	20.00
Gross Labour Cost (S\$)			1,740.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >