

ASS. REC. BY:

REF: CS/AIG17023631/Ktd3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chan Yoke Shi of AIG Date/Time: 7.44am @ 13/12/17

Estimated Cost: Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF160R

Insured:

GBG7113B

at Workshop m/s

T & B Repairs Services

Tel:

6458 0296

of B1K 160 Sin Ming Drive #08-03 575722

Policy No:

Claim No:

8956492663SG003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7/12/17

18/12/17 @ 10-11 am

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time: 9.10am @ 13/12/17

Person Contacted:

Judy

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBF160R-X
	GBG7113B-X
12/4	837 8 390d email & Confirm (Red 2430, 387%)

REF: **AKG****ASSIGNMENT**From: _____ Date: **18/12/17**

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐To Inspect Vehicle No: **GBF 160R**at Workshop m/s **T&B Repairs Services**of **160 Sin Ming Drive #08-03**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

10-11 am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: **04** days Res.: Yes or NoLum Sum: **1-B.1** % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS **(wps)**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **GBF 160R**Yr Regn: **06 16**Type: M.Car / M.Cycle / Bus / Van / ☒ Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **NIS Cabrio**c.c. **2953**Colour: **White**

A/C: Insured / Std / NI / NA

Sp. Reading: **64822**

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JNISC2F2480858667**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModl: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: **195R15x8**R: **155R13x8(10)**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. **9** mmR/Bal. **3 3** mmL/Bal. **9** mmL/Bal. **3 3** mmD.O.A. **7/12/17**D.O.I. **18/12/17**

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

cls body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/12 file pass to Corbin, em not ready

RECEIVED 17 APR 2018

Date/Time, File Pass to?

1) FH Tynet

Date/Time, File Return to?

2) _____

☐ : Prel. Report
☒ : Final Report
Days Of Repair: **4**Resurvey No. of Trip: **1**

Survey Fee: _____

Transportation: _____

) S + RS _____

) Photos _____

) Other _____

TOTAL: _____

Add Fee: ☐ : Site Insp (\$ _____)☐

) Interview (\$ _____)

☐

) Tech. Insp (\$ _____)

☐

) Weekend (\$ _____)

☐

) _____

Report Format: _____

Lump Sum / I.B.I: (\$ **3900**)**250****30****270**

- Pre repair inspection request - GBF160R VS GBG7113B (OI) DOA 07/12/2017

From: Chan, Yoke Shi
To: assignments, Admin A
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Marisa; Md Ishak, Mohd Imran; Lim, Sheng Yang
Sent: Wednesday, 13 December, 2017 7:43:58 AM
Attachments:  70970 (our ltr dd 81217 - Notice of Accident).pdf

Hi,

Please refer to the enclosed request from **Cheong Hoh Lee**.

Claim no : 8956492663SG003
Case Owner : KAI JYE WUI

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com www.aig.com

From: Cheong Hoh Lee [mailto:mail@cheonghoh.sg]
Sent: Tuesday, December 12, 2017 5:17 PM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Marisa; Md Ishak, Mohd Imran; Lim, Sheng Yang
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBG7113B AND GBF160RON 07/12/2017; Our ref: LCH.my/SMTB-70970.17

Dear Sir/ Madam,

We refer to the above matter and to your email of 11 December 2017.

Our client hereby nominate Kenneth Kong from LKK Auto Consultants Pte Ltd of your said letter to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle GBF 160 R is currently laying at our client's workshop, T & B Motor Repairs Services Pte Ltd, Blk 160 Sin Ming Drive #08-03 Sin Ming Auto City Singapore 575722. Kindly proceed to do the needful and you may contact the person in charge Mr Tay at 6458 0296 before your surveyor attend at the said workshop.

Thank you.

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

On Dec 12, 2017, at 1:34 PM, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:

Dear Sir/Madam,

Reminder for pre-repair survey.
Kindly response to the email below whether agree to the appointment of any of these motor surveyors below as a single joint expert.

Thank you

Regards,

Yoke Shi @ Ashley
AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Chan, Yoke Shi
Sent: Monday, December 11, 2017 12:23 PM
To: 'Cheonghoh Law'
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBG7113B AND GBF160RON 07/12/2017

Without Prejudice

Your Reference : LCH.my/SMTB-70970.17
Our Reference : 8956492663SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list as a single joint expert.

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG17023631/Ktd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 13-12-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 7113B	Veh. Inspected	GBF 160R
Policy No.		Coverage (\$)	0.00
Claim No.	8956492663SG003	Excess (\$)	0.00
Assign From	CHAN YOKE SHI	Assign Date	13/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/12/2017	Inspection Date	13/12/2017
Survey held at	BLK 160 SIN MING DRIVE # 08-03		
Repairer	T & B MOTOR REPAIRS SERVICES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/12/2017 17:52
Date Of Accident	07/12/2017 15:15
Exact Location Of Accident	TAI SENG ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF160R
Insured/Policyholder	
Name Of Registered Owner	PRIMOTECH PACKAGING PTE LTD
Co Reg No	199203063H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62858331

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5080922715-01
Cover Note Number	

Driver

Name of Driver	FONG WAI LUN
NRIC No	G2081426N
Date Of Birth	17/11/1982
Occupation	OUTDOOR
Date Of Driving Pass	10/09/2014
Driving Experience	3 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83045487
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	61 YISHUN IND PARK A #05-01 SINGAPORE
Postcode	768767
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG7113B
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	LIM CHAN SENG
NRIC/Passport Number	
Contact Number	96817714
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 08/12/2017
14:00 HRS



Driver's Signature

(If driver is not the policyholder)

Date & Time: 08/12/2017
14:00 HRS




Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 07/12/2017 about 15:15 HRS. I was driving along Tai Seng Street toward Pagar Lebar Road. Suddenly I felt impact from behind. Then I came down to check and realized a van (GBGT113B) hit onto my van (GBF160R) box rear right side from building way out address is 26 Tai Seng Street. Nobody was injured in the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 08/12/2017
14:00 HRS

Driver's Signature

(If driver is not the policyholder)

Date & Time: 08/12/2017
14:00 HRS.

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

T & B MOTOR REPAIRS SERVICES PTE LTD

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

PRIMOTECH PACKAGING PTE LTD
61 YISHUN INDUSTRIAL PARK A
#05-01, BTH GLOBAL BUILDING (S) 768767

Attention : Motor Claim Department

Estimate : ES003290

Date : 08/12/2017

Vehicle Num. : GBF160R

Make/Model : NISSAN CABSTAR

Chassis/Eng# :

Accident Date : 07/12/2017

Claim No. :

Reference :

Policy No. : 5080922715-01

Not Noted

8390d

4 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	3	LIST ITEMS : COMPOSITE ALUMINUM PANEL	1200.00	3,600.00
		List Total S\$:		3,600.00
		LABOUR :		
		1. SUPPLY & INSTALL ONE SET OF SEALANT		280.00
		2. SPRAY PAINTING ON AFFECTED PORTIONS		1,200.00
		3. LABOUR CHARGE FOR REPAIRING, ADJUSTING, KNOCKING, WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE		1,250.00
		Labour Total S\$:		2,730.00

SingDollars : Six Thousand Three Hundred Thirty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: E. & O.E.

Total S\$: 6,330.00

for T & B MOTOR REPAIRS SERVICES PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG17023631/KTD3N2

Date: 17/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
 Claimant Vehicle No : GBF160R Insured Vehicle No : GBG7113B
 Date of Loss: 07/12/2017 Nature of Claim: TP Claim No: 8956492663SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF160R Engine No: ZD30011856N
 Make & Model: NISSAN CABSTAR, 3.0 (M) Chassis No: JN1SC2F24Z0858667
 Reg. Date: 02/06/2016 (Man. Year: 2016) Odometer: 64822 km
 Colour: White
 Engine Capacity: 2953 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15X8 Rear Tyre Size: 155R13X8 (D)
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 3/3 mm
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 3/3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,880.00	2,480.00	1,400.00	36.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,420.00	1,030.00	42.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,330.00	3,900.00	2,430.00	38.39

INSPECTION

Date of Assignment: 13/12/2017
 Date Inspected: 18/12/2017 Inspected At: T & B Motor Repairs Services Pte Ltd
 Blk 160 Sin Ming Drive #08-03, Sin Ming Auto City
 Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COMPOSITE ALUMINUM PANEL	Bent/Necessary	3,600.00 FS	*2,400.00 FS
2	1		*SET OF SEALANT	Necessary	280.00 FS	*80.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					3,880.00	2,480.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON AFFECTED PORTIONS	New	1,200.00	720.00
2	LABOUR CHARGE FOR REPAIRING,ADJUSTING,KNOCKING,WELDING THE DAMAGED PARTS,STRAIGHTEN THE ABOVE	New	1,250.00	700.00
Gross Labour Cost (\$\$)			2,450.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >