

Your ref: CMTD1704496/GPL
Our ref: CS/SMO17023643/Uvd3

Date: 8/2/2018

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. SKA 29H


We thank for your instruction on 13/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/12/2017 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$76,885.00
Revised Estimate Amount	: S\$33,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear and front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser